

# SIX MONTH CURSORY INSPECTION

Parish: Assumption Str. Type: COSLAB  
Str. # 61042320106361 Recall # 051460 Route: LA 70  
Bridge Name/Feature Crossed: Bayou Corne

Approaches:	<input checked="" type="checkbox"/>	
Roadway:	<input checked="" type="checkbox"/>	
Deck:	<input checked="" type="checkbox"/>	√ - If element of structure was inspected
Bearings:	<u>N/A</u>	N/A - If element does not apply to structure
Stringers:	<u>N/A</u>	
Girders (Conc./Steel):	<u>N/A</u>	
Piling:	<input checked="" type="checkbox"/>	
Caps/Piers:	<input checked="" type="checkbox"/>	Were Pictures Taken: YES or <input checked="" type="radio"/> NO
Backwalls:	<input checked="" type="checkbox"/>	
Wingwalls:	<u>N/A</u>	
Footings:	<u>N/A</u>	
Waterway:	<input checked="" type="checkbox"/>	
Embankment (Scour):	<input checked="" type="checkbox"/>	
Conc. Spall/Cracks:	<input checked="" type="checkbox"/>	

Any changes noted? If so what? A visual inspection was performed as well as measurements taken on both sides of the structure with a transit level. There were no changes when compared to previous inspections.

Inspected By: Brandon Magruder & Billy Ballantz  
Date: 10/26/16