Monthly CURSORY INSPECTION

Parish:	Assumption	S	itr. Type:	COSLA	В	
Str.#	61042320104611	Recall #	051440	R	oute:	LA 70
Bridge I	Name/Feature Crossed:		Bayou Choup	ique		
	Approaches:	approximate the second				
	Deck:	minimi	√- lfel	ement of st	ructure was	inspected
	Bearings: N/A	approxime.				•
	Stringers: N/A		N/A - If el	ement does	s not apply t	o structure
Girders	(Conc./Steel): NA	orania da				
	Caps/Piers:		Were Pictu	res Taken:	YES	or (NO)
	Backwalls:					and the second s
	Wingwalls: <i>N/A</i>					
	Footings: MA					
	Waterway:					
	ment (Scour):					
Conc.	Spall/Cracks:	nspowed				
well	nges noted? If so what? as measurements a transit level.	A Visua taken There	linspect on Both were n	ion W Sides O Char	AS Per of sta	formed as ructure then compared
to ore	vious inspections.				U	7
/	· · · · · · · · · · · · · · · · · · ·					
I	nspected By: Brandon Date: 10/86/	Magrud	es y B	11/ Bi	Alfan.	f ang

Bayou Choupique

Date 10/26/15

ТВМ	10.0 ft				
BS	2.15				
1-11	And the second s				

	***************************************		_
Bent	No.	BS	Elev
1	L	1,80	
	R	1,78	
2	L	1,74	
***************************************	R	1.74	
3	L	1.70	
	R	1.72	
4	L	1.72	
	R	1.75	
5	L	1.77	
	R	1.74	