Monthly CURSORY INSPECTION

| Parish: | Assumption | | Str | . Туре: | COSLAB | | | |
|------------------------------|-----------------------------|-----------------------|--|--------------------------------------|-----------------|---|--|--|
| Str. # | # 61042320104611 | | Recall # | 051440 | Rout | e: LA 70 | | |
| Bridge Name/Feature Crossed: | | | Ba | ayou Choup | ique | | | |
| | Approaches: | | _ | | | | | |
| | Roadway: | | - | 1 | , , , , | | | |
| | Deck: | <u> </u> | - | √- It ele | ement of struct | ure was inspected | | |
| Bearings | | N/A | N/A - If element does not apply to structure | | | | | |
| Girdoro | Stringers: (Conc./Steel): | NA | | IV/A - IT ele | ement aces not | t apply to structure | | |
| Glidels | (Conc./Steel). Piling: | N/A | - | | | | | |
| | Caps/Piers: | | | Were Pictur | os Takon: | YES or NO | | |
| | Backwalls: | | - | vvere i ictai | es ranen. | 123 GI (NO) | | |
| | Wingwalls: | N/10 | - | | | | | |
| | Footings: | NA | - | | | | | |
| | Waterway: | | - | | | | | |
| Embank | ment (Scour): | | • | | | | | |
| | Spall/Cracks: | | - | | | | | |
| Any char | nges noted? If surements | taken on | | nspection of struence on compa | | rformed as well with a transit previous inspections | | |
| li | nspected By: Date: | Brandon 11/23/15 | Magrude | r & Bil | ly Balt | Cantz | | |

Bayou Choupique

| TBIM | 10.0 ft |
|------|---------|
| BS | 1.45 |
| HI | · |

| Bent | No. | BS | Elev |
|------|-----|--|--|
| 1 | Į. | 1.40 | |
| | R | 1.59 | The state of the s |
| 2 | Ì., | Section of the sectio | - |
| | R | 54 | American results |
| 3 | * | 1,50 | g. composition |
| | R | 1.53 | Todate ingressorable |
| 4 | L | 1.52 | |
| | R | \$ 100 miles | |
| 5 | L. | 1.57 | |
| | R | 1.58 | |

Date <u>///23//</u>5