## Monthly CURSORY INSPECTION

Parish:	Assumption		Str. Type: C		COSL	COSLAB	
Str. #	61042320	0106361	Recall #	051460	)	Route:	LA 70
Bridge Name/Feature Crossed:				Bayou Co	rne	jene	And Colonia Advisor and Assistant Antick Colonia pages and an about the constitution of the colonia co
Girders	Approaches: Roadway: Deck: Bearings: Stringers: (Conc./Steel): Piling: Caps/Piers: Backwalls: Wingwalls: Footings: Waterway: ment (Scour):	N/A N/A N/A N/A N/A		√- If e	element of	ës not app	vas inspected lly to structure S or NO
CONC.	Spall/Cracks:						
Any changes noted? If so what?  A visual Inspection was performed as well as measurements taken on both sides of the structure with a transit level. There were no changes when compared to previous inspections.							
Inspected By: Brandon Magruder + Billy Balfantz Date: 3/20/16							
	mor and to give	2/20/16	41e000000000000000000000000000000000000	*			

Bayou Corne
Date 3/30//6

	TBM	10.0 ft				
	BS	5,53				
	MI					
Ben	t No.	BS				
1	L	2,18				
PARINKEOUSEMASCOUSEMASCOUSEMANONING ANNO 1000 CONTOURS SEGRE	R	2,14				
Language Contraction of the Cont	l <sub>u</sub>	2.18				
	R	2.19				
3	and a second	2.18				
ANNE ANTONIO ESTA ESTA ESTA ESTA ESTA ESTA ESTA ESTA	R	2,18				
halp:		2,17				
Section Control Contro	R	2,17				
5		2.16				
	R	<u>a.17</u>				
6		2.18				
	R	2.18				
O PORTO DE CONTROL DE LA C		4.18				
······································	R	2,18				
8		316				
oriente de la companya del companya del companya de la companya de		2.16				
9		2.18				
10	R	2.90				
10	L D	2,22				
11	R	3.17				
	R	<u> </u>				
12		2.18				
	R	× 17				
	l.	d./ Y				