

Monthly CURSORY INSPECTION

Parish: Assumption Str. Type: COPCSS
Str. # 61042320104941 Recall # 051450 Route: LA 70
Bridge Name/Feature Crossed: Grand Bayou

Approaches: ✓
Roadway: ✓
Deck: ✓
Bearings: N/A
Stringers: N/A
Girders (Conc./Steel): N/A
Piling: ✓
Caps/Piers: ✓
Backwalls: ✓
Wingwalls: N/A
Footings: N/A
Waterway: ✓
Embankment (Scour): ✓
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? A visual inspection was performed as well as measurements taken on both sides of structure with a transit level. There were no changes when compared to previous inspections.

Inspected By: Brandon Magruder + Billy Balfantz
Date: 9/24/15

Grand Bayou

Date 9/24/15

TBM	10.0 ft
BS	5.89
HI	

Bent No.		BS	Elev
1	L	3.92	
	R	3.87	
2	L	3.92	
	R	3.88	
3	L	3.87	
	R	3.87	
4	L	3.84	
	R	3.88	
5	L	3.87	
	R	3.86	
6	L	3.87	
	R	3.87	
7	L	3.88	
	R	3.88	
8	L	3.89	
	R	3.88	
9	L	3.92	
	R	3.94	