

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
Str. # 61042320104611 Recall # 051440 Route: LA 70  
Bridge Name/Feature Crossed: Bayou Choupique

- Approaches: ✓
- Roadway: ✓
- Deck: ✓
- Bearings: N/A
- Stringers: N/A
- Girders (Conc./Steel): N/A
- Piling: ✓
- Caps/Piers: ✓
- Backwalls: N/A
- Wingwalls: ✓
- Footings: N/A
- Waterway: ✓
- Embankment (Scour): ✓
- Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected  
N/A - If element does not apply to structure  
Were Pictures Taken: YES or NO

Any changes noted? If so what? Initial bridge elevations were taken along both sides of the bridgerail at each bent to establish a baseline for monitoring of settlement. A streambed profile was taken and a full visual inspection was performed and was compared to previous inspection reports. No changes were noted in the visual inspection and streambed profile.

Inspected By: D. L. Wan  
Date: 8-11-12

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
 Str. # 61042320104611 Recall # 051440 Route: LA 70  
 Bridge Name/Feature Crossed: Bayou Choupique

Approaches: ✓  
 Roadway: ✓  
 Deck: ✓  
 Bearings: N/A  
 Stringers: N/A  
 Girders (Conc./Steel): N/A  
 Piling: ✓  
 Caps/Piers: ✓  
 Backwalls: N/A  
 Wingwalls: ✓  
 Footings: N/A  
 Waterway: ✓  
 Embankment (Scour): ✓  
 Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Elevation readings were taken along both sides  
of bridge at railings at each bent. A visual inspection was performed. No  
changes were noted to this structure from previous inspections.

Inspected By: Roger T. Byrd  
 Date: 8-17-12

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
Str. # 61042320104611 Recall # 051440 Route: LA 70  
Bridge Name/Feature Crossed: Bayou Choupique

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: ✓  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Elevation readings were taken along both sides of the bridgerail at each bent. A full visual inspection was performed. No changes were noted in the elevation readings and visual inspection when compared to previous inspections.

Inspected By: D. L. Van  
Date: 8-30-12

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
Str. # 61042320104611 Recall # 051440 Route: LA 70  
Bridge Name/Feature Crossed: Bayou Choupique

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: N/A  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): \_\_\_\_\_  
Conc. Spall/Cracks: \_\_\_\_\_

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or NO

Any changes noted? If so what? Profile readings were taken on both sides of structure.  
at each bent. There was no visual evidence upon inspection and profile  
readings to show any change.

Inspected By: B. O. J. ; Steven Houze  
Date: 9/7/16

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
Str. # 61042320104611 Recall # 051440 Route: LA 70  
Bridge Name/Feature Crossed: Bayou Choupique

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: ✓  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or (NO)

Any changes noted? If so what? Elevation readings were taken along both sides of the bridge rail at each bent. A full visual inspection was performed. No changes were noted in the elevation readings and visual inspection when compared to previous inspections.

Inspected By: D. L. W.  
Date: 9-14-12

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
Str. # 61042320104611 Recall # 051440 Route: LA 70  
Bridge Name/Feature Crossed: Bayou Choupique

Approaches: ✓  
Roadway: ✓  
Deck: ✓  
Bearings: N/A  
Stringers: N/A  
Girders (Conc./Steel): N/A  
Piling: ✓  
Caps/Piers: ✓  
Backwalls: N/A  
Wingwalls: ✓  
Footings: N/A  
Waterway: ✓  
Embankment (Scour): ✓  
Conc. Spall/Cracks: ✓

✓ - If element of structure was inspected

N/A - If element does not apply to structure

Were Pictures Taken: YES or (NO)

Any changes noted? If so what? Elevation readings were taken along both sides of the bridge rail at each bent. A full visual inspection was performed. No changes were noted in the elevation readings and visual inspection when compared to previous inspections.

Inspected By: Dan L. Wald  
Date: 9-23-12

# WEEKLY COURSERY INSPECTION

Parish: Assumption Str. Type: COSLAB  
 Str. # 61042320104611 Recall # 051440 Route: LA 70  
 Bridge Name/Feature Crossed: Bayou Choupique

Approaches:	<u>✓</u>	
Roadway:	<u>✓</u>	
Deck:	<u>✓</u>	✓ - If element of structure was inspected
Bearings:	<u>N/A</u>	
Stringers:	<u>N/A</u>	N/A - If element does not apply to structure
Girders (Conc./Steel):	<u>N/A</u>	
Piling:	<u>✓</u>	
Caps/Piers:	<u>✓</u>	Were Pictures Taken: YES or <b>(NO)</b>
Backwalls:	<u>N/A</u>	
Wingwalls:	<u>✓</u>	
Footings:	<u>N/A</u>	
Waterway:	<u>✓</u>	
Embankment (Scour):	<u>✓</u>	
Conc. Spall/Cracks:	<u>✓</u>	

Any changes noted? If so what? Elevation readings were taken along both sides of the bridge rail at each bent. A full visual inspection was performed. No changes were noted in the elevation reading or visual inspection when compared to previous inspections.

Inspected By: Rody Jones, Steven Howze  
 Date: 9/29/2012