APPENDIX B

INTERVIEW DOCUMENTATION

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
4545	SEALS, TIMOTHY WILLIAM	14379 VENTRESS RD.	VENTRESS LA 70783	953 S. RIVER RD.
5991	BARANCO, GREGORY T.	200 ALFRED ST.	LAFAYETTE LA 70501	Null
9911	RAYMAN ASSOCIATES BATON ROUGE, L. P.	ROUTE 30	BIG ROCK IL 60511	4728 CONSTITUTION AVE.
9946	BR CAPITAL HOLDINGS, INC. ATTN: LOUIS QUINN, JR.	47W 210 US HWY. 30	BIG ROCK IL 60511	Null
12009	CHURCHES - STAR OF BETHLEHEM BAPTIST	1204 ST. JOSEPH ST.	BATON ROUGE LA 70802	Null
12149	JOSEPH, ROBERTSON &	2653 SORREL AVE.	BATON ROUGE LA 70805	Null
12351	ELLOIS, WILLARD	PO BOX 543	NEW ROADS LA 70760	Null
13579	CELESTINE REALTY, LLC	5422 GALERIA DR	BATON ROUGE LA 70816	644 S. BLVD.
14001	CHURCHES - NEW ST. LUKE BAPTIST	538 SOUTH BLVD.	BATON ROUGE LA 70802	916 MONROVIA
15989	PARKER, WILLIAM H.	4114 CANNON ST.	BATON ROUGE LA 70805	Null
16152	MIKON HOLDINGS, LLC	16226 FELICIANA AVE.	PRAIRIEVILLE LA 70769	Null
23213	CHURCHES - ST. FRANCIS XAVIER ROMAN	1143 S. 11TH ST.	BATON ROUGE LA 70802	Null
26123	BUTLER, JOSHUA	PO BOX 73	ETHEL LA 70730	1010 JULIA ST.
35068	LEVY, THOMAS ALLEN, JR.	990 MYRTLE AVE.	BATON ROUGE LA 70802	990 MYRTLE ST.
38830	KLEINPETER, MILTON H. & EVA	739 STARING LN	BATON ROUGE LA 70808	Null
41459	LEVY, THOMAS ALLEN, JR.	990 MYRTLE AVE.	BATON ROUGE LA 70802	Null
43044	WHITE, CHAVON DANIELA DESORMES	1123 TERRACE AVE.	BATON ROUGE LA 70802	1123 TERRACE AVE.
52795	PORAY, LOUIS, JR. &	1275 ROSEDALE RD.	PORT ALLEN LA 70767	Null
52809	PORAY, LOUIS, JR. &	1275 ROSEDALE RD.	PORT ALLEN LA 70767	Null
55425	LOTT, ALAN C. & ANNE M. LOTT	810 FULWAR SKIPWITH RD.	BATON ROUGE LA 70810	Null
60925	FREEDMAN, LINDA JEANNE	2280 BAYWOOD AVE	BATON ROUGE LA 70808	2280 BAYWOOD AVE.
60941	JUGE, JOSEPH D.	PO BOX 65397	BATON ROUGE LA 70896	Null
63991	DELTA INVESTMENTS BMO HARRIS	BMO 16 PO BOX 1414	MINNEAPOLIS MN 55480	Null
77739	PHILLIPS, JOANNE & ALVIN M. PHILLIPS	1154 HIGHLAND PARK DR.	BATON ROUGE LA 70808	Null
85030	NEW JAZZ ENTERPRISES, LLC	103 FRANCE ST	BATON ROUGE LA 70802	Null
85049	NEW JAZZ ENTERPRISES, LLC	103 FRANCE ST	BATON ROUGE LA 70802	Null
85057	NEW JAZZ ENTERPRISES, LLC	103 FRANCE ST	BATON ROUGE LA 70802	Null
85146	GARDNER, JUDIE MARIE; SCOTTIE	1148 NORTH 32ND ST.	BATON ROUGE LA 70802	Null
86088	ALLTEL COMMUNICATIONS, LLC D/B/A ATTN: NETWORK REAL ESTATE	180 WASHINGTON VALLEY RD	BEDMINSTER NJ 07921	110 SOUTH BLVD.
86096	STATE - STATE OF LA.	PO BOX 94095	BATON ROUGE LA 70804	Null
86118	DOUBLE RM, L.L.C.	8034 JEFFERSON HWY.	BATON ROUGE LA 70809	174 SOUTH BLVD.
86126	DOUBLE TAKE, L.L.C.	252 SOUTH BLVD.	BATON ROUGE LA 70802	Null
87874	GEORGE, CLAY	1619 THERON DR.	BATON ROUGE LA 70810	Null
90077	JABBARI, HOOSHANG	809 AMERICA ST.	BATON ROUGE LA 70802	1150 SOUTH 10TH ST.
96636	PORAY, LOUIS, JR. & ROSE L. PORAY	1275 ROSEDALE RD.	PORT ALLEN LA 70767	Null
97969	RESTORATION BATON ROUGE III, A	PO BOX 2409	ALBERTVILLE AL 35950	1239 S. 10TH ST.
100099	TEMPLE, COLLIS B., JR. &	1225 NORTH BLVD.	BATON ROUGE LA 70802	Null
100102	TEMPLE, COLLIS B., JR. &	1225 NORTH BLVD.	BATON ROUGE LA 70802	926 E.BLVD.
109320	CHENIER, CHARLES WARNER	205 N. 25TH ST.	BATON ROUGE LA 70806	Null
109681	TLC PROPERTIES, INC.	PO BOX 66338	BATON ROUGE LA 70896	Null

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
109738	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
112402	LEE, MARY JONES	923 SOUTH 16TH ST.	BATON ROUGE LA 70802	Null
113115	CHURCHES - PROGRESSIVE BAPTIST	998 JULIA ST.	BATON ROUGE LA 70802	Null
113158	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
123358	WILLIAMS, THETA MARIE MARTINEZ,	9237 STARING CT	BATON ROUGE LA 70810	Null
123374	LENGUYEN ENTERPRISE, L.L.C.	9034 LAKE RIDGE DR.	BATON ROUGE LA 70809	Null
123625	MATERISTE, PETER J., JR.; VIRGINIA	627 CARRIAGE WAY	BATON ROUGE LA 70808	Null
131989	GCHP-RBR 2002, LLC	1610-A ORETHA CASTLE HALEY BLVD	NEW ORLEANS LA 70113	962 MYRTLE AVE.
142891	WILLIAMS, LIONEL	6820 MANCHAC RD.	ST GABRIEL LA 70776	943 MAXIMILLIAN ST.
146331	WILLIAMS, SHEPHARD, 1/2 USUF 1/2 &	ADDRESS UNKNOWN	ADDRESS UNKNOWN	Null
146609	PASTIME PROPERTIES, LLC	252 SOUTH BLVD.	BATON ROUGE LA 70802	Null
146749	BUTLER, VERNELL	972 MYRTLE ST.	BATON ROUGE LA 70802	972 MYRTLE ST.
146773	MITCHELL, LAUREN L.	981 FRANCE ST.	BATON ROUGE LA 70802	Null
153397	J H J ENTERPRISES, LLC	1333 W. MCKINLEY ST.	BATON ROUGE LA 70802	Null
157783	LEVY, THOMAS ALLEN, JR.	990 MYRTLE AVE.	BATON ROUGE LA 70802	Null
160539	D & W HOLDINGS 1, LLC	913 HUEY P LONG AVE	GRETNA LA 70053	Null
165425	CHURCHES - NEW ST. LUKES BAPTIST	538 SOUTH BLVD.	BATON ROUGE LA 70802	Null
177466	SAMPSON, MONA SIMMS	742 SOUTH BLVD.	BATON ROUGE LA 70802	742 S. BLVD.
178292	TILLMAN, SAM & LIZZIE 1/2 EACH C/O GLORIA TILLMAN	820 VILLAGE CIRCLE	OAKLAND CA 94607	Null
179868	LOUISIANA WORKER'S COMPENSATION	2237 S. ACADIAN THRUWAY, STE. 102	BATON ROUGE LA 70808	2237 S. ACADIAN THWY.
182362	JOSEPH, ROBERTSON LOUIS	2653 SORREL AVE.	BATON ROUGE LA 70805	Null
183237	EMERY, WILLIE B.	941 ROYAL ST	BATON ROUGE LA 70802	Null
183725	LEVY, THOMAS A., JR.	990 MYRTLE AVE	BATON ROUGE LA 70802	Null
184705	WASHINGTON, DANIEL H., JR.; MYRTLE C/O MYRTLE L. ELLIOTT	8353 JONES ST.	BATON ROUGE LA 70807	Null
191116	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
192902	WILSON, MARY LEE	940 ST. JOSEPH ST.	BATON ROUGE LA 70802	940 ST. JOSEPH ST.
195669	CHURCHES - PROGRESSIVE BAPTIST	1128 FLORA LANE	BATON ROUGE LA 70810	Null
211591	CENTRE STRUCTURED TRUST 3, BY: STATE	TWO INTERNATIONAL PLACE	BOSTON MA 02110	2552 CORPORATE WOODS
218626	HOME BANK SUCCESSOR WITH BRITTON	PO BOX 1407	NATCHEZ MS 39121	2562 CORPORATE WOODS
219002	CENTRE STRUCTURED TRUST 7, BY: STATE	TWO INTERNATIONAL PLACE	BOSTON MA 02110	2572 CORPORATE WOODS
230057	LEVY, THOMAS A., JR.	990 MYRTLE AVE	BATON ROUGE LA 70802	Null
290653	HOLMES, JOHN MICHAEL & LISA ROSSIE	2932 BOCAGE LAKE CT	BATON ROUGE LA 70809	2932 BOCAGE LAKE CT.
293474	MILNER, CHARLES EDWARD, JR. &	2938 BOCAGE LAKE CT.	BATON ROUGE LA 70809	2938 BOCAGE LAKE CT.
313025	RAINEY, EMILIE STEFFECK, 1/2 USUF	2942 BOCAGE LAKE CT	BATON ROUGE LA 70809	2942 BOCAGE LAKE CT.
326763	SAPORITO, CRAIG ERNEST & ANNE	2948 BOCAGE LAKE CT	BATON ROUGE LA 70809	2948 BOCAGE LAKE CT.
326798	ROBINSON, MAXWELL G., JR. & BOBBIE	2952 BOCAGE LAKE CT.	BATON ROUGE LA 70809	2952 BOCAGE LAKE CT.
326828	MOORE, JAMES W., JR. & LYNN WILSON	3006 RIVER OAKS DR.	MONROE LA 71201	2958 BOCAGE LAKE CT.
326860	MACPHERSON, DOUGLAS R. & JOANN PENN	2962 BOCAGE LAKE CT.	BATON ROUGE LA 70809	2962 BOCAGE LAKE CT.
326879	MCCOY, RUTH Z.	2968 BOCAGE LAKE CT	BATON ROUGE LA 70809	2968 BOCAGE LAKE CT.
326895	SMITH, MARVIN L. & CAROL A. SMITH	2972 BOCAGE LAKE CT.	BATON ROUGE LA 70809	2972 BOCAGE LAKE CT.

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
326941	PETERSON, EARLINE RUTTER	115 DUPLESSIS ST.	METAIRIE LA 70005	Null
419605	NEW PRIVATE RESTAURANT PROPERTIES,	2202 N. WESTSHORE BLVD. #470C	TAMPA FL 33607	2415 S. ACADIAN THWY.
420530	BOCAGE LAKE PROPERTIES OWNERS	9618 JEFFERSON HWY., BOX 335	BATON ROUGE LA 70809	Null
427993	SAI ENTERPRISES, LLC	5425 BRITTANY DR.	BATON ROUGE LA 70808	4924 CONSTITUTION AVE.
428000	ERGS AIM HOTEL REALTY, LLC C/O GOLDMAN, SACHS & CO.	200 WEST ST	NEW YORK NY 10282	4914 CONSTITUTION AVE.
428043	KAVANAUGH AND TUDOR COMPANY, L.L.C.,	PO BOX 12653	ALEXANDRIA LA 71315	2313 S. ACADIAN THWY.
428051	KAVANAUGH AND TUDOR COMPANY, L.L.C.,	PO BOX 12653	ALEXANDRIA LA 71315	2323 S. ACADIAN THWY.
428078	KAVANAUGH AND TUDOR COMPANY, L.L.C.,	PO BOX 12653	ALEXANDRIA LA 71315	Null
428086	KAVANAUGH AND TUDOR COMPANY, L.L.C.,	PO BOX 12653	ALEXANDRIA LA 71315	Null
491306	ABRAMS, EULA J.	1240 SOUTH 17TH ST.	BATON ROUGE LA 70802	Null
493910	EBANKS, CHEVIS	1967 HIGHLAND RD	BATON ROUGE LA 70802	1815 VIRGINIA ST.
495263	FORLON CORPORATION	15000 CONFERENCE CENTER DR. #440	CHANTILLY VA 20151	Null
495271	FORLON CORPORATION	15000 CONFERENCE CENTER DR. #440	CHANTILLY VA 20151	4810 CONSTITUTION AVE.
495549	UTILIZE REALTY, L.L.C.	4826 ST. GERARD AVE.	BATON ROUGE LA 70805	Null
499137	ANDERSON, LARRY ROY AND DONNA J. H.	5723 TRENTON AVE.	BATON ROUGE LA 70808	5723 TRENTON AVE.
499374	ANDERSON, GREGORY ALLEN	967 COTTON ST.	BATON ROUGE LA 70802	967 COTTON ST.
499447	CHURCHES - NEELY UNITED METHODIST	929 EAST WASHINGTON ST.	BATON ROUGE LA 70802	Null
501905	ASHFORD, JOSEPH C/O MARION STEWART	44 FRANKFORT ST.	DALY CITY CA 94014	Null
502758	CAREY, SHIRLEY ANN	5611 TRENTON AVE.	BATON ROUGE LA 70808	5611 TRENTON AVE.
504068	THOMAS, JOHN H., III	2234 MARYLAND ST.	BATON ROUGE LA 70802	1930 CAROLINA ST.
505412	GORDY PROPERTIES II, LLC	5707 MAHONEY RD	ST FRANCISVILLE LA 70775	2344 BAYWOOD AVE.
505420	MOORE, JOHN J.	2358 BAYWOOD AVE.	BATON ROUGE LA 70808	2358 BAYWOOD AVE.
507148	LIROCCHI, LISA L.	2567 RHODODENDRON AVE.	BATON ROUGE LA 70808	2567 RHODODENDRON AVE.
507946	BANKS, ROOSEVELT, SR, & MARTHA T. C/O ALSIE BANKS	3815 LAVEY LANE	BAKER LA 70714	Null
508578	PARISH - PARISH OF EAST BATON ROUGE,	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
508586	PARISH - PARISH OF EAST BATON ROUGE,	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
508632	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
509868	BARNES, EDWARD & SYLVIA K.	5521 TRENTON AVE.	BATON ROUGE LA 70808	5521 TRENTON AVE.
509949	BARNES, W. J.	22192 GREENWELL SRPINGS RD.	GREENWELL SPRINGS LA 70739	Null
509957	LEE, WANDA SLAVEN	PO BOX 45418	BATON ROUGE LA 70895	Null
513385	BATES, EVERETTE, JR.; LINDA MARIE	2462 VALLEY ST.	BATON ROUGE LA 70808	Null
513415	BATES, HOLLIS	2629 VALLEY ST.	BATON ROUGE LA 70808	2629 VALLEY ST.
513474	SJAR INVESTMENTS, L.L.C.	1266 TERRACE AVE	BATON ROUGE LA 70802	1338 E. WASHINGTON ST.
513652	MANOCO, J., INC.	7513 CONESTOGA DR.	GREENWELL SPRINGS LA 70739	3030 PERKINS RD.
514888	TEMPLE, COLLIS B., JR. & SOUNDRA T	1225 NORTH BLVD.	BATON ROUGE LA 70802	2241 ELISSALDE ST.
521116	ALLEN, ROBERT, JR.	5815 TRENTON AVE	BATON ROUGE LA 70808	5815 TRENTON AVE.
521396	WHITE, SYLVIA BERTRAND & ERNEST A	1920 MARYLAND ST.	BATON ROUGE LA 70802	1920 MARYLAND ST.
521566	BESSIX, MICHAEL & BEVERLY N	5653 TRENTON AVE.	BATON ROUGE LA 70808	5653 TRENTON AVE.
528676	CHURCHES - EBENEZER BAPTIST CHURCH	1901 MISSOURI ST.	BATON ROUGE LA 70802	Null
532320	RAWLINS, KEVIN D.	16712 JEFFERSON HWY.	BATON ROUGE LA 70817	3035 GREENWOOD DR.
532991	SJAR INVESTMENTS, L.L.C.	1266 TERRACE AVE	BATON ROUGE LA 70802	Null

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
536547	RED RIVER BANK	1412 CENTRE COURT DR	ALEXANDRIA LA 71301	Null
538418	BROWN, JOSEPH M., JR. & THELMA S.	C/O BRENDA BROWN PO BOX 762	BATON ROUGE LA 70821	Null
540161	BRYANT, D'ORSAY D., III (OWNER) &	619 THOMPSON ST	EL DORADO AR 71730	2215 E. LAKESHORE DR.
540714	BUFFINGTON, MARION MATTHEWS	1851 KENTUCKY ST.	BATON ROUGE LA 70802	1851 KENTUCKY ST.
545287	WELSH, ROSE, 1/4 & ETHEL M. LIVOUS,	2679 VALLEY ST.	BATON ROUGE LA 70808	2679 VALLEY ST.
546852	HARRIS, JANICE MARIE BATISTE	1832 VIRGINIA ST.	BATON ROUGE LA 70802	1832 VIRGINIA ST.
548723	PARISH - PARISH OF EAST BATON ROUGE,	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
548731	NAGOL PROPERTIES, LLC	809 LONGWOOD DR	BATON ROUGE LA 70806	2253 CHRISTIAN ST.
553468	TEN WEST PROPERTIES, L.L.C.	8317 KENSINGTON DR	BATON ROUGE LA 70809	2550 HONEYSUCKLE AVE.
553735	CHURCHES - NEELY UNITED METHODIST	1755 THOMAS DELPIT	BATON ROUGE LA 70802	Null
562262	CLAIBORNE, MATHEW	1227 COURT ST.	PORT ALLEN LA 70767	Null
562327	CLAITOR, R.G. REALTY	3165 S. ACADIAN THRUWAY	BATON ROUGE LA 70808	3613 PERKINS RD.
565164	COLBERT, HENRIETTA SMILES	5641 TRENTON AVE.	BATON ROUGE LA 70808	5641 TRENTON AVE.
567663	COLEMAN, GEORGE, JR. & LOCAL: 1879 KENTUCKY ST.	1768 NORTH 39TH	BATON ROUGE LA 70802	1879 KENTUCKY ST.
567892	COLEMAN, SAM TRUMAN	PO BOX 431713	LOS ANGELES CA 90043	Null
578746	BROWN, SALLIE MAE, 99% & DELTA	5625 TRENTON AVE	BATON ROUGE LA 70808	5625 TRENTON AVE.
579556	DAISY, JOSEPH	2058 RUE RACINE	MARRERO LA 70072	Null
583073	ORANGE, LARRY	1117 PECAN ST.	BATON ROUGE LA 70802	1117 PECAN ST.
583138	AMBANK MORTGAGE COMPANY	ADDRESS UNKNOWN	ADDRESS UNKNOWN	Null
583146	CONSOLIDATED HOLDINGS, INC. & GEAUX	PO BOX 64777	BATON ROUGE LA 70896	1616 BRADDOCK ST.
584274	BROWN, ISIAAC; MAEBELLE BROWN	4708 TEAROSE TRAIL	FORT WORTH TX 76123	Null
584681	DAVIS, JOHN & INEZ W.	2863 BROWNLEE ST.	BATON ROUGE LA 70808	2863 BROWNLEE ST.
584835	DAVIS, LEO D.	2726 BALIS DR.	BATON ROUGE LA 70808	2726 BALIS DR.
585033	HUSKER PARTNERS US BANK	405 N 115TH ST # 100	OMAHA NE 68154	4696 CONSTITUTION AVE.
585246	DAVIS, SAMUEL, JR.	5338 CLARK ST.	BATON ROUGE LA 70811	Null
585734	ELLIS, RICHARD DAWSON & MADELINE	2440 BAYWOOD AVE.	BATON ROUGE LA 70808	2440 BAYWOOD AVE.
586617	PHILLIPS, V. R.	PO BOX 514	ZACHARY LA 70791	2372 FERNDALE AVE.
586943	HONORE, CHRISTOPHER	1229 E WASHINGTON ST	BATON ROUGE LA 70802	1229 WASHINGTON ST.
586986	RESOURCE FOUNDATION, INC. A	PO BOX 86753	BATON ROUGE LA 70879	1510 BRADDOCK ST.
586994	RESOURCE FOUNDATION, INC. A	PO BOX 86753	BATON ROUGE LA 70879	1510 BRADDOCK ST.
587001	RESOURCE FOUNDATION, INC. A	PO BOX 86753	BATON ROUGE LA 70879	1510 BRADDOCK ST.
587028	ELLIS, TRENT	24438 PLANK RD	SLAUGHTER LA 70777	1510 BRADDOCK ST.
591734	CHURCHES - NEELY UNITED METHODIST	843 & 903 EAST WASHINGTON ST.	BATON ROUGE LA 70802	Null
606243	DUVIC PROPERTIES, L.L.C.	2854 KALURAH ST.	BATON ROUGE LA 70808	2854 KALURAH ST.
606715	ROSS, RUTH E. & EARNETINE S. JOHNSON	6436 SAN JUAN DR.	BATON ROUGE LA 70811	Null
606790	ELLERSON, ALICE SCOTT 1/2 USUF 1/2,	PO BOX 872764	NEW ORLEANS LA 70187	1444 E. HARRISON
607207	ELLIS, QUENTION T.	944 SILVER SPRING CT	ST AUGUSTINE FL 32092	1420 E. HARRISON ST.
607215	ELLIS, QUENTION T.	944 SILVER SPRING CT	ST AUGUSTINE FL 32092	Null
608270	ESNAULT, HORACE J. & ANNETTE M.	1103 LOUISE	BATON ROUGE LA 70802	1103 LOUISE ST.
608378	PARKER, CASEY NICHOLE	2277 EBONY DR	BATON ROUGE LA 70808	2277 EBONY DR.

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
608459	COSEY, ANDREA N.	1723 TERRACE AVE	BATON ROUGE LA 70802	Null
610704	PREFERRED HOSPITALITY, L.L.C.	2445 S. ACADIAN THRUWAY	BATON ROUGE LA 70808	2445 S. ACADIAN THWY.
610836	PHILLIPS, ALWYN J.	PO BOX 514	ZACHARY LA 70791	2362 FERNDALE AVE.
611743	LAVERGNE, BETTY T.	1235 E. WASHINGTON ST.	BATON ROUGE LA 70802	1235 E. WASHINGTON ST.
614459	CHURCHES - EBENEZER BAPTIST CHURCH	1901 MISSOURI ST.	BATON ROUGE LA 70802	Null
614696	CUNDIFF, TIMOTHY;	410 MAGNOLIA WOODS	BATON ROUGE LA 70808	2343 FERNDALE AVE.
615218	FITZGERALD, GEORGE R. & ALICE EVELYN	2261 ELISSALDE ST.	BATON ROUGE LA 70808	2261 ELISSALDE ST.
615528	TRAVASOS, MICHAEL PAUL	2421 DOGWOOD AVE.	BATON ROUGE LA 70808	3218 S. EUGENE ST.
618411	JONES, JUDY PALMISANO	9151 INTERLINE AVE. STE. 3-B	BATON ROUGE LA 70809	3162 GREENWOOD DR.
622931	GAINES, CLAIBORNE, SR.	5603 TRENTON AVE.	BATON ROUGE LA 70808	5603 TRENTON AVE.
624217	S & L PROPERTIES OF PASS CHRISTIAN,	2727 E LAKESHORE DR	BATON ROUGE LA 70808	2547 HONEYSUCKLE AVE.
624241	LEWIS, BARBARA STEVENSON	3375 E. LAKESHORE DR.	BATON ROUGE LA 70808	3436 S. EUGENE ST.
629782	ARLEDGE, DANNY LEE	3646 LILLIAN LANE	ETHEL LA 70730	2122 CAROLINA ST.
633836	GREEN, JOSIE WILKINSON 1/2 USUF 1/2;	2847 VALLEY ST	BATON ROUGE LA 70808	2847 VALLEY ST.
636045	LOUPE, JOEL HELEN GIROD	19644 S. MUIRFIELD CIRCLE	BATON ROUGE LA 70810	3025 PERKINS RD.
636185	GLADNEY, BLANCHE TOWN	6996 RICHARDS DR	BATON ROUGE LA 70809	6996 RICHARDS DR.
638943	WEBSTER, JERRY T., 1/2 USUF 1/2;	2321 BUNKER HILL DR.	BATON ROUGE LA 70808	2321 BUNKER HILL DR.
639540	COLLEGE GAS, INC.	2018 OAKDALE DR.	BATON ROUGE LA 70810	2929 COLLEGE DR.
641103	CHURCHES - HOUSE OF GOD BATON ROUGE,	PO BOX 65316	BATON ROUGE LA 70896	Null
641278	HALL, RUTH K.	1303 EAST WASHINGTON ST	BATON ROUGE LA 70802	1305 E. WASHINGTON ST.
641286	HALL, RUTH KLEINPETER, 1/2 USUF 1/2;	1303 EAST WASHINGTON ST.	BATON ROUGE LA 70802	1303 E WASHINGTON ST.
641332	HALL, MAMYE LYNN, L.L.C.	PO BOX 14001	BATON ROUGE LA 70898	1208 E. WASHINGTON ST.
641340	HALL, MAMYE LYNN, L.L.C.	PO BOX 14001	BATON ROUGE LA 70898	Null
644862	BANKS, JASON R.	1873 CAROLINA ST	BATON ROUGE LA 70802	Null
645079	HANEY, ISAAC, JR. AND EVELYN M.	5547 TRENTON AVE.	BATON ROUGE LA 70808	5547 TRENTON AVE.
647209	HARRIS, JAMES ERIC	1234 E. WASHINGTON ST.	BATON ROUGE LA 70802	1234 E.WASHINGTON ST.
647616	HARRIS, JANICE MARIE BATISTE	1832 VIRGINIA ST.	BATON ROUGE LA 70802	1832 VIRGINIA ST.
648396	HART, WILLIAM REALTORS, LTD.	PO BOX 1786	BATON ROUGE LA 70821	Null
649589	GOURNEY, ALEXANDER RYAN & ALEXANDRA	460 S Club Ave.	ST GABRIEL LA 70776	
650137	CHURCHES - NEW PROSPECTS MISSIONARY	1174 TERRACE ST.	BATON ROUGE LA 70802	1349 MCCALOP ST.
650145	HATTER, JAMES C.	862 E. BUCKANAN ST.	BATON ROUGE LA 70802	Null
650218	SMITH, ALDREAMER GREEN	1426 EAST WASHINGTON ST.	BATON ROUGE LA 70802	1426 EAST WASHINGTON ST.
655953	THOMAS, ALVIN R.	360 W. FLANACHER RD.	ZACHARY LA 70791	2742 VALLEY ST.
661341	CONTINENTAL RESOURCES BMO HARRIS	BMO 16 PO BOX 1414	MINNEAPOLIS MN 55480	1223 EAST WASHINGTON ST.
663689	PARKER, JESSE, JR., 9/10 & JOSEPH C/O SARAH PARKER	2636 LINWOOD AVE.	BATON ROUGE LA 70805	Null
668435	INGRAM, ALTON EARL	1185 PEAR ST.	BATON ROUGE LA 70802	1185 PEAR ST.
669067	BENNETT, KENNETH KEITH ISAAC &	2527 JACKSON AVE.	BATON ROUGE LA 70802	Null
669709	COBBINS, JOYCE ANN	2605 VALLEY ST	BATON ROUGE LA 70808	2605 VALLEY ST.
669768	JACKSON, FRANK	821 JULIA	BATON ROUGE LA 70802	Null
670103	JACKSON, LUELLAMA	2641 VALLEY ST.	BATON ROUGE LA 70808	2641 VALLEY ST.

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
670898	BEAUREAU, DELORES	1950 CAROLINA ST	BATON ROUGE LA 70802	1950 CAROLINA ST.
671312	DUNCAN, WARRIE LEE C., WILLIE LEE	534 WINDING WAY DR.	BATON ROUGE LA 70810	Null
671320	DUNCAN, WARRIE LEE C., WILLIE LEE	534 WINDING WAY DR.	BATON ROUGE LA 70810	Null
671606	ST. MARTIN, EUGENE CHARLES, JR.	3464 SOUTH EUGENE ST.	BATON ROUGE LA 70808	3464 S. EUGENE ST.
675970	KINCHEN, RICHARD LEE & MARY ALICE	1538 BRADDOCK ST.	BATON ROUGE LA 70802	1538 BRADDOCK ST.
676519	S & L MANAGEMENT & INVESTMENT,	10708 LANDSBURY AVE.	BATON ROUGE LA 70809	9025 STARING COURT
676829	JOHNSON, PRESLEY	1103 HICKORY ST.	BATON ROUGE LA 70802	Null
677329	JOHNSON, ROBERTA WASHINGTON	3340 FORT MEYERS	BATON ROUGE LA 70814	Null
677728	CHURCHES - NEELY UNITED METHODIST	929 EAST WASHINGTON ST.	BATON ROUGE LA 70802	Null
680028	JOSEPH, ULYSSES & LINDA ANN C.	5533 TRENTON AVE.	BATON ROUGE LA 70808	5533 TRENTON AVE.
680052	HUEY, ROBERT DARYL	2533 HONESUCKLE AVE.	BATON ROUGE LA 70808	2533 HONESUCKLE AVE.
682691	NEW JAZZ ENTERPRISES, LLC	103 FRANCE ST	BATON ROUGE LA 70802	Null
685399	KELLY, ALBERT LIONEL & DIANA F.	5501 TRENTON AVE.	BATON ROUGE LA 70808	5501 TRENTON AVE.
685518	BANKS, JASON R.	1873 CAROLINA ST	BATON ROUGE LA 70802	2821 VALLEY ST.
687170	KIMBLE, ANNIE C/O WILLIE MAE VARNELL	3052 SARATOGA DR.	BATON ROUGE LA 70808	2112 CAROLINA ST.
688339	ROLLER, RANDALL ROYCE, 7/8 &	2278 STANFORD AVE.	BATON ROUGE LA 70808	2278 STANFORD AVE.
688371	KLEINPETER, WILLIE	2019 VIRGINIA ST.	BATON ROUGE LA 70802	2019 VIRGINIA ST.
688398	LE, BIEN K.	2935 PERKINS RD.	BATON ROUGE LA 70808	
688495	MCINTIRE, JOYCE DEARMOND	1454 APPLEWOOD RD.	BATON ROUGE LA 70808	2929 PERKINS RD.
688509	KLEINPETER, JONNIE-LU DEARMOND	5558 COLDWATER CREEK CT.	BATON ROUGE LA 70808	2919 PERKINS RD.
688576	KLEINPETER, MILTON, 1/2; LOUIS	739 STARING LANE	BATON ROUGE LA 70808	Null
692263	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
692271	CHURCHES - EBENEZER BAPTIST CHURCH	1901 MISSOURI ST.	BATON ROUGE LA 70802	Null
692360	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
694762	GUTIERREZ, ROBERT G.	3478 SOUTH EUGENE ST.	BATON ROUGE LA 70808	3478 S. EUGENE ST.
695106	TRUONG, NHAN DINH & PHI NGUYEN	2216 ESTATES RD.	BATON ROUGE LA 70808	2216 ESTATES RD.
702048	WATSON, FRANCES DEBORAH	2244 EBONY AVE.	BATON ROUGE LA 70808	2244 EBONY AVE.
702889	BATON ROUGE HOTEL INVESTORS, LLC	769 HWY 494	NATCHITOCHES LA 71457	5500 HILTON AVE.
704334	LEE, WANDA SLAVEN	PO BOX 45418	BATON ROUGE LA 70895	3412 S. EUGENE ST.
712108	LAPAM, L.L.C.	427 SOUTH VINE AVE.	TYLER TX 75702	Null
716995	LOTTEN, THEODORE R. & PEGGY J.	5821 TRENTON DR.	BATON ROUGE LA 70808	5821 TRENTON AVE.
722383	JACKSON, RONALD LEONARD & JUNE MARIE	2808 VALLEY ST.	BATON ROUGE LA 70808	2808 PARA ST.
723215	BRINKER LOUISIANA, INC., A ATTN: TAX DEPT.	6820 LBJ FREEWAY	DALLAS TX 75240	4550 CONSTITUTION AVE.
723223	STOR-ALL BATON ROUGE ATTN: MICHAEL MCGUIRE	19335 N. NINE ST.	COVINGTON LA 70433	4580 CONSTITUTION BLVD.
725366	SIMS, MICHAEL & LESLIE JOHNSON SIMS	1219 E WASHINGTON AVE.	BATON ROUGE LA 70802	1219 E WASHINGTON AVE.
725374	MARCELLE, EARL A., JR.; LAMAR A. C/O EARL MARCELLE	5716 VALLEY FORGE AVE.	BATON ROUGE LA 70808	Null
725382	MARCELLE, EARL A., JR.; LAMAR A. C/O EARL MARCELLE	5716 VALLEY FORGE AVE.	BATON ROUGE LA 70808	Null
725390	MARCELLE, EARL A., JR.; LAMAR A. C/O EARL MARCELLE	5716 VALLEY FORGE AVE.	BATON ROUGE LA 70808	Null
725404	MARCELLE, EARL A., JR.; LAMAR A. C/O EARL MARCELLE	5716 VALLEY FORGE AVE.	BATON ROUGE LA 70808	1026 E. WASHINGTON ST.
725412	MARCELLE, EARL A., JR.; LAMAR A. C/O EARL MARCELLE	5716 VALLEY FORGE AVE.	BATON ROUGE LA 70808	Null

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
725560	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
732834	MATTHEWS, FRED C., III REVOCABLE	1319 EAST WASHINGTON ST	BATON ROUGE LA 70802	1319 EAST WASHINGTON ST.
733296	T L C PROPERTIES, INC.	PO BOX 66338	BATON ROUGE LA 70896	Null
733571	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
733822	MORA, PEDRO AND LYNDA MORA LIVING	2144 ESTATES RD	BATON ROUGE LA 70808	Null
735132	BEKMET, LTD.	3 LAKEWAY CENTRE CT STE 200	AUSTIN TX 78734	4738 CONSTITUTION AVE.
738166	GULF BREEZE HOTEL CORPORATION/LNRC ATTN: DARRYL G. LAPOINTE	311 GULF BREEZE PKWY.	GULF BREEZE FL 32561	4646 CONSTITUTION AVE.
739235	SHRLA, LLC C/O SONGY HIGHROADS, LLC	6 CONCOURSE PKWY # 925	ATLANTA GA 30328	2431 S. ACADIAN THWY.
739537	KAVANAUGH AND TUDOR COMPANY, L.L.C.,	PO BOX 12653	ALEXANDRIA LA 71315	2324 S. ACADIAN THRWY.
739545	PPM INVESTMENT & MANAGEMENT COMPANY,	7035 JEFFESON HWY	BATON ROUGE LA 70806	2354 S. ACADIAN THWY.
742910	THOMAS, KENNETH ATWELL & RUTH	220 EVERGREEN DR.	BATON ROUGE LA 70806	1820 KENTUCKY ST.
743305	DONOVAN, PAUL MICHAEL & STEPHANIE	307 RIDGEWAY DR.	METAIRIE LA 70006	3154 S. EUGENE ST.
744417	MODICUT, JOE, L.L.C.	839 WOODSTONE DR.	BATON ROUGE LA 70808	Null
744603	FITZGERALD, BRYAN & SHAWANDA	2261 ELISSALDE ST.	BATON ROUGE LA 70806	1939 MISSOURI ST.
770175	BENGAL UNLIMITED, L.L.C.	829 WOODSTONE DR.	BATON ROUGE LA 70808	Null
770914	SCOTT, SHIRLEY RUSSELL	1604 BRADDOCK ST.	BATON ROUGE LA 70802	1604 BRADDOCK ST.
772909	GUIDRY, KENNETH M.	11811 OAK SHADOW DR.	BATON ROUGE LA 70810	1775 E. WASHINGTON ST.
772917	GUIDRY, KENNETH M.	11811 OAK SHADOW DR.	BATON ROUGE LA 70810	Null
781215	OWENS, DAN AND IDA J. OWENS	2665 VALLEY ST.	BATON ROUGE LA 70808	2665 VALLEY ST.
783293	BOURGEOIS, RODNEY JOSEPH	2943 PERKINS RD.	BATON ROUGE LA 70808	Null
783374	FRESH SALON BR, LLC	2265 CHRISIAN ST	BATON ROUGE LA 70808	
784117	PATTERSON, VELMA	2741 YAZOO ST.	BATON ROUGE LA 70808	2741 YAZOO ST.
784648	SATPATHI, SUCHITRA	714 S. EUGENE ST.	BATON ROUGE LA 70806	1326 E. WASHINGTON ST
784672	PAYNE, LOUIS, SR. 1/2 USUF 1/2	5515 RIVERBEND BLVD.	BATON ROUGE LA 70820	Null
790087	RUSSELL, IKESHA P.	2714 VALLEY ST.	BATON ROUGE LA 70802	2714 VALLEY ST.
793620	PIERRE, SIDNEY PORTER	253 W. WASHINGTON ST.	BATON ROUGE LA 70802	Null
793639	CHURCHES - NEELY UNITED METHODIST	843 & 903 EAST WASHINGTON ST.	BATON ROUGE LA 70802	Null
799920	BEAUCOUDRAY, DONNA ROPPOLO	2124 ESTATES RD.	BATON ROUGE LA 70808	2124 ESTATES RD.
802530	THREE PROPERTY, L.L.C.	1724 DALLAS DR. #8	BATON ROUGE LA 70806	2717 VALLEY ST.
802778	MITCHELL, LEOLA EVELYN WICKS &	6261 GABRIEL OAKS DR.	BATON ROUGE LA 70820	1855 KENTUCKY ST.
806773	QUILLINS, EARNEST & JUANITA L.	1237 E. WASHINGTON ST.	BATON ROUGE LA 70802	1237 EAST WASHINGTON ST.
809284	REDDIX, MASON & EARLEAN J.	2832 BALIS DR.	BATON ROUGE LA 70808	2832 BALIS DR.
812846	JOHNSON, PAULETTE RICARD & STEPHEN	10068 FIRE RIDGE DR	FRISCO, TX 75033	1562 BRADDOCK ST.
817597	RIDEAUX, JUDY MARIE; SHIRLEY ANN	7008 LAKELAND DR.	ZACHARY LA 70791	Null
818046	GIVENS, EUGENE, JR. & ROSIE S.	7053 CARLENE AVE.	BATON ROUGE LA 70811	Null
818607	ROAN, EMILY AUGUSTINE	2036 VIRGINIA ST.	BATON ROUGE LA 70802	Null
819425	RASHADEEN, TAMIR N.	2130 CAROLINA ST.	BATON ROUGE LA 70802	2130 CAROLINA ST.
821047	MORA, PEDRO AND LYNDA MORA LIVING	2144 ESTATES RD	BATON ROUGE LA 70808	208 NATCHITOCHES RD.
821128	WHITTAKER, RICHARD L. & BARBARA B.	2226 ESTATES RD.	BATON ROUGE LA 70808	2226 ESTATES RD.
823627	BR LAND DEVELOPMENT, L.L.C.	47W 210 US HWY. 30	BIG ROCK IL 60511	4848 CONSTITUTION AVE.

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
828998	HOOKFIN, JUANITA (A/K/A JUANITA H.	1159 E. HARRISON ST.	BATON ROUGE LA 70802	1159 E. HARRISON ST.
829005	HOOKFIN, JUANITA (A/K/A JUANITA H.	1159 E. HARRISON ST.	BATON ROUGE LA 70802	1159 E. HARRISON ST.
830690	OYEKENU, LOVIE HAMPTON	5747 TRENTON AVE.	BATON ROUGE LA 70808	5747 TRENTON AVE.
839752	SCOTT, SEYMORE AND HARRIET H.	5725 OAKWOOD DR	BATON ROUGE LA 70811	Null
848522	CHECK B, LLC	4836 CONSTITUTION AVE	BATON ROUGE LA 70808	4836 CONSTITUTION AVE.
854646	PARISH - PARISH OF EAST BATON ROUGE,	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
855332	JACOB FAMILY PROPERTIES, L.L.C.	3033 PERKINS RD	BATON ROUGE LA 70808	3033 PERKINS RD.
858234	SPRIGGS, IRENE WADE	1103 HICKORY ST.	BATON ROUGE LA 70802	Null
859567	G & C PROPERTY HOLDINGS, L.L.C.	3514 LEESBURG AVE.	BATON ROUGE LA 70814	1807-1813 GEORGIA ST.
866172	FORTH, NICHOLAS E. & WILLIAM K.	2360 DALRYMPLE DR	BATON ROUGE LA 70808	2360 DALRYMPLE DR.
866962	SHETTERLY, MARY LOUISE SWART	6435 GOODWOOD AVE.	BATON ROUGE LA 70806	Null
871680	TAYLOR, DENNIS WAYNE, SR., 5/6 USUF	5705 TRENTON AVE	BATON ROUGE LA 70808	5705 TRENTON AVE.
871931	FIERO PROPERTIES, L.L.C.	1111 S FOSTER DR STE C	BATON ROUGE LA 70806	2265 CHRISTIAN ST.
874612	WALKER, ALEAN BAKER	1923 KENTUCKY ST.	BATON ROUGE LA 70802	1923 KENTUCKY ST.
875171	CHURCHES - EBENEZER BAPTIST CHURCH	1901 MISSOURI ST	BATON ROUGE LA 70802	1935 MISSOURI ST.
875716	THOMAS, BEN 1/2, LALA DAVIS HILL 1/2	1365 BELLONIA DR.	BATON ROUGE LA 70810	1824 KENTUCKY ST.
881120	TOUSSAINT, ERNEST, JR.	5731 TRENTON AVE.	BATON ROUGE LA 70808	5731 TRENTON AVE.
881325	TRAHAN, JAMES ALLEN	9151 WOODBINE ST.	BATON ROUGE LA 70815	Null
883247	FREEMAN, ROBERTA TURNER, 1/4; ODELL	2041 VIRGINIA ST.	BATON ROUGE LA 70802	Null
883255	FREEMAN, ROBERTA TURNER, 1/4; ODELL	2041 VIRGINIA ST.	BATON ROUGE LA 70802	Null
883263	FREEMAN, ROBERTA TURNER, 1/4; ODELL	2041 VIRGINIA ST.	BATON ROUGE LA 70802	2041 VIRGINIA ST.
885479	VEAL, EDWARD & IRMA C.	3015 DENHAM ST.	BATON ROUGE LA 70805	1157 FIG ST.
891207	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891215	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891223	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891231	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891258	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891266	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891274	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
891541	HEARD, KENNETH LLOYD & DARLENE HEARD	2145 CAROLINA ST.	BATON ROUGE LA 70802	2145 CAROLINA ST.
898163	BAZILE, MALCOLM	7422 SHERINGHAM AVE.	BATON ROUGE LA 70808	7422 SHERINGHAM AVE.
898546	BANKS, JASON & HAROLD WATKINS, 1/2	1817 MISSOURI ST	BATON ROUGE LA 70802	1922 CAROLINA
899011	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
906573	TLC PROPERTIES, INC.	PO BOX 82129	BATON ROUGE LA 70884	Null
906638	MURRAY, DONALD R.	1542 UTAH ST	BATON ROUGE LA 70802	1120 PEAR ST.
906867	SCHLITTZ & GIGGLES PERKINS LOCAL: 2355 FERNDALE AVE.	2355 FERNDALE AVE	BATON ROUGE LA 70802	2355 FERNDALE AVE.
906867	SCHLITTZ & GIGGLES PERKINS LOCAL: 2355 FERNDALE AVE.	460 MAIN STREET	BATON ROUGE LA 70801	2355 FERNDALE AVE.
908568	WILLIAMS, PATRICIA ANN ROBERTSON	5513 TRENTON AVE.	BATON ROUGE LA 70808	5513 TRENTON AVE.
909939	WILLIAMS, MARY	1867 KENTUCKY ST.	BATON ROUGE LA 70802	1867 KENTUCKY ST.
909955	WILLIAMS, MARY B.; ARTHUR WILLIAMS,	C/O VIRGINIA DEBOEST PO BOX 271434	FLOWER MOUND TX 75027	Null

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
910147	MATTHEWS, FRED C., III REVOCABLE	1319 EAST WASHINGTON ST	BATON ROUGE LA 70802	1408 E. WASHINGTON AVE.
910341	PRUDHOMME, RONALD W. & CAROL	5633 TRETON AVE.	BATON ROUGE LA 70808	5633 TRETON AVE.
914037	CONCORD PARK PROPERTIES, L.L.C.	308 W. WOODSTONE CT.	BATON ROUGE LA 70808	Null
914207	WILSON, ALVIN	7603 OAKMOUNT DR.	BATON ROUGE LA 70817	2157 CAROLINE ST.
915599	WINFREY, SALLIE	851 LOUISE ST.	BATON ROUGE LA 70802	Null
916412	WILLIS, THOMAS M. & EARLINE MARIA	6900 RICHARDS DR.	BATON ROUGE LA 70809	6900 RICHARDS DR.
916501	WALKER, RONALD & IRIS BARBER WALKER	2012 ESTATES RD.	BATON ROUGE LA 70808	2012 ESTATES RD.
917729	JORDAN, AUDREY WOODS	2010 EVANS AVE.	MONROE LA 71202	1321 E. WASHINGTON ST.
919632	WICKS, THOMAS & MARY	1867 KENTUCKY ST.	BATON ROUGE LA 70802	1859 KENTUCKY ST.
923575	COLE AB BATON ROUGE (COLLEGE DR.)	C/O ALBERTSONS, INC. PROPERTY TAX P.O. BOX 990	MINNEAPOLIS MN 55440	2950 COLLEGE DR.
981036	BITT INVESTMENTS, L.L.C.	PO BOX 4033-C	LAFAYETTE LA 70502	2450 S. ACADIAN THWY.
981168	BITT INVESTMENTS, L.L.C.	PO BOX 4033-C	LAFAYETTE LA 70502	Null
1076663	S & R HOTELS, L.L.C.	2683 ENERGY DR.	BATON ROUGE LA 70808	5668 HILTON AVE.
1076701	G ENDURANCE, LLC	5630 BANKERS AVE	BATON ROUGE LA 70808	5656 HILTON AVE
1196553	TRIBUTE REAL ESTATE, L.L.C.	6901 VETERANS #31	METAIRIE LA 70003	2590 CITIPLACE CT.
1331582	GENERAL FOODS CREDIT INVESTORS	PO BOX 579	LOUISVILLE TN 37777	2421 S ACADIAN THWY
1394061	CHURCHES - NEW ST. LUKE BAPTIST	538 SOUTH BLVD.	BATON ROUGE LA 70802	538 SOUTH BLVD.
1503545	POLLARD VENTURES, LLC	2815 EDWARD AVE	BATON ROUGE LA 70808	2293 HOLLYDALE AVE. #5-B
1620304	AVR GATES PROPERTIES, L.L.C. C/O AVR REALTY CO., L.L.C.	1 EXECUTIVE BLVD.	YONKERS NY 10701	2500 GATES CIR.
1712497	STATE - STATE OF LA.	PO BOX 94095	BATON ROUGE LA 70804	Null
1781111	NATIONAL RETAIL PROPERTIES, LP.	450 S ORANGE AVE # 900	ORLANDO FL 32801	2610 CITIPLACE BLVD.
1821164	ARC HOSPITALITY SMT BTRLA001 OWNER, C/O CRESTLINE HOTELS & RESORTS	3950 UNIVERSITY DR STE 301	FAIRFAX VA 22030	4964 CONSTITUTION AVE.
1871234	Null	Null	Null	Null
2212250	IBERIA BANK	601 POYDRAS ST., #2075	NEW ORLEANS LA 70130	3555 PERKINS RD.
2212277	CH REALTY VII/R BATON ROUGE ACADIAN, ATTN: ASSET MGR-ACADIAN VILLAGE	3819 MAPLE AVE	DALLAS TX 75219	3535 PERKINS RD. BLDG. 200
2212277	CH REALTY VII/R BATON ROUGE ACADIAN, ATTN: ASSET MGR-ACADIAN VILLAGE	3819 MAPLE AVE	DALLAS TX 75219	3535 PERKINS RD. BLDG. 200
2338920	CAMPBELL, LYMAN	11720 ARCHERY DRIVE	BATON ROUGE LA 70815	Null
2339617	NAQUIN, JOHN MITCHELL	9007 HIGHLAND RD C1	BATON ROUGE LA 70810	Null
2339676	NEWMAN, HERBERT SYLVESTER C/O RESHON CLAYTON	9145 CEFALU DR.	BATON ROUGE LA 70811	Null
2340119	STERLING, RODERIC	1014 SENETTE	BATON ROUGE LA 70802	1014 SENETTE
2340151	TWO THREE SIX THREE (2363) HOLLYDALE	2363 HOLLYDALE AVE	BATON ROUGE LA 70808	2363 HOLLYDALE ST.
2391376	CHURCHES - PROGRESSIVE BAPTIST	1214 SOUTH 10TH ST.	BATON ROUGE LA 70802	Null
2391821	CHURCHES - CHRISTIAN BIBLE COLLEGE	720 SOUTH BLVD.	BATON ROUGE LA 70802	Null
2393891	PARISH - PARISH OF EAST BATON ROUGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
2394200	PARISH - CONSOLIDATED SEWERAGE	222 ST. LOUIS ST.	BATON ROUGE LA 70801	Null
2401592	CHURCHES - FAIRVIEW BAPTIST CHURCH	1636 BRADDOCK ST.	BATON ROUGE LA 70802	1636 BRADDOCK
2401606	CHURCHES - FAIRVIEW BAPTIST CHURCH	1636 BRADDOCK ST.	BATON ROUGE LA 70802	Null
2401614	CHURCHES - FAIRVIEW BAPTIST CHURCH	1636 BRADDOCK ST.	BATON ROUGE LA 70802	Null
2404982	CITY-PARISH - CITY OF BATON ROUGE &	222 ST. LOUIS ST.	BATON ROUGE LA 70801	3055 VALLEY ST.

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
2405857	PARKS - RECREATION & PARK COMMISSION	PO BOX 15887	BATON ROUGE LA 70895	2900 VALLEY ST.
2418096	SCHOOLS - EAST BATON ROUGE PARISH	1050 SOUTH FOSTER	BATON ROUGE LA 70806	Null
2418533	SCHOOLS - EAST BATON ROUGE PARISH	1050 SOUTH FOSTER	BATON ROUGE LA 70806	4510 BAWELL
2466244	SALTAMACHIA, DARRELL J. & PAMELA J.	18257 CREEK HOLLOW RD.	BATON ROUGE LA 70817	2425 FIERO ST.
2466325	GSD DEVELOPMENT COMPANY, L.L.C.	8708 JEFFERSON HWY. #B	BATON ROUGE LA 70809	2437 FIERO ST.
2466341	JOSEPH, JOSHUA A. & SALLEE T. JOSEPH	2449 FIERO ST.	BATON ROUGE LA 70808	2449 FIERO ST.
2466465	SOILEAU, KATHERINE M.	2301 FIERO ST	BATON ROUGE LA 70808	2301 FIERO ST.
2466546	BROWN, WAYNE & ELLEN D. BROWN	8610 GLEN HAVEN DR.	SHREVEPORT LA 71106	2303 FIERO ST.
2466562	TARVER, CRAIG & NANCY SHEPPARD	2305 FIERO ST. #C	BATON ROUGE LA 70808	2305 FIERO ST.
2466570	CHODACKI, DEBORAH S.	2307 FIERO ST	BATON ROUGE LA 70808	2307 FIERO ST.
2466589	RAINWATER, PAUL W. & MARY LINDA	2309 FIERO ST.	BATON ROUGE LA 70808	2309 FIERO ST.
2466600	MAHAFFEY, RANDELLE R.	11815 VILLA CREEK AVE	BATON ROUGE LA 70810	2311 FIERO ST.
2466627	GSD DEVELOPMENT COMPANY, L.L.C.	8708 JEFFERSON HWY. #B	BATON ROUGE LA 70809	Null
2571838	ENGLE, BRYAN A. & NATASHA AMAYA	2424 BAYWOOD AVE	BATON ROUGE LA 70808	2424 BAYWOOD AVE.
3003868	PRESTLY, CLARENCE C/O DELORES BEAUREAU	P.O. BOX 531	SORRENTO LA 70778	Null
3015920	LEDUFF, LUCIEN, JR., 7/8 & ELMELDA	996 TERRACE AVE.	BATON ROUGE LA 70802	7158 GLEN OAKS DR.
3019764	WALKER, RONALD & IRIS BARBER WALKER	2012 ESTATES RD	BATON ROUGE LA 70808	Null
3208028	WITTER, PHILLIP CONNELL	PO BOX 80259	BATON ROUGE LA 70898	Null
304500000200	WSM PROPERTIES LLC ETALS	7288 BOCAGE BLVD	BATON ROUGE LA 70809-0000	3191 WEBSTER LN
304500000100	MUNSON SUSAN PIPES ETALS	9018 TALLYHO AVE	BATON ROUGE LA 70806-0000	Null
304510001000	DAIGLE W J	4183 STONEWALL DR	ADDIS LA 70710-0000	Null
304510000900	LAXMI VISHNU HOSPITALITY INC	10332 PLAZA AMERICANA	BATON ROUGE LA 70816	234 LOBDELL HWY
304510000901	RACETRAC PETROLEUM INC	PO BOX 22845	OKLAHOMA CITY OK 73123-0000	234 LOBDELL HWY
304510000800	RACETRAC PETROLEUM INC#454	C/O SAVAGE, SAVAGE & BROWN, INC.	P O BOX 22845 OKLAHOMA CITY OK 73123-0000	214 LOBDELL HWY
305200008000	WESTPORT INVESTMENTS LLC	P O BOX 279	SPRINGFIELD LA 70462-0000	2524 COMMERCIAL DR
304510000700	FW MILLER #5 LLC	2363 COLLEGE DR	BATON ROUGE LA 70808-0000	112 LOBDELL HWY
304510000600	NORTH AMERICAN FINANCIAL GROUP LLC	12221 INDUSTRIPLEX BLVD	BATON ROUGE LA 70809	102 LOBDELL HWY
304510001500	COOL CONCEPTS LLC	614 WOODVALE AVE	LAFAYETTE LA 70503-0000	111 LOBDELL HWY
304510001600	HARI OM HOSPITALITY, INC.	131 LOBDELL HWY	PORT ALLEN LA 70767-0000	131 LOBDELL HWY
305200008000	WESTPORT INVESTMENTS LLC	P O BOX 279	SPRINGFIELD LA 70462-0000	2524 COMMERCIAL DR
304510002700	BK-CH, INC	B K CORP#3631	C/O RYAN P. O. BOX 460189 HOUSTON TX 77056-0000	2810 N WESTPORT DR
304510002801	CASTROGIOVANNI FAMILY LLC	ATTN: NICHOLAS B CASTROGIOVANNI	3540 N LABARRE RD METAIRIE LA 70002-0000	2830 N WESTPORT DR
304510002800	KHUSHI INVESTMENTS I LLC	2880 N WESTPORT DR	PORT ALLEN LA 70767-0000	2860 N WESTPORT DR
304510004400	DENHAM SPRINGS FIREWORKS INC	8161 RUSHING RD	DENHAM SPRINGS LA 70726-0000	2840 N WESTPORT DR
304510002802	J.L. ASSOCIATES LLC	2880 N WESTPORT DR	PORT ALLEN LA 70767	2880 N WESTPORT DR
304519003600	WEST BATON ROUGE TOURIST COMMISSION	P O BOX 757	PORT ALLEN LA 70767	2750 N WESTPORT DR

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
304510002900	OLD EVANGELINE DOWNS LC	P. O. BOX 2449	OPELOUSAS LA 70571-0000	2685 OFFICE PARK DR
305200011800	BARKER INVESTMENT COMPANY LLC	10513 SUGAR MAPLE AVE	BATON ROUGE LA 70809-0000	
305200008000	WESTPORT INVESTMENTS LLC	P O BOX 279	SPRINGFIELD LA 70462-0000	2524 COMMERCIAL DR
305200009000	BOULANGER PROPERTIES LLC	2811 SARPY AV	BATON ROUGE LA 70820	2421 COMMERCIAL DR
305200012100	HOFFMAN JEREMY P & AMY LEMOYNE	1743 LANSDOWN DR	PORT ALLEN LA 70767-0000	2289 COMMERCIAL DR
305200012600	2179 COMMERCIAL DRIVE LLC	728 CHEVELLE DR	BATON ROUGE LA 70806-0000	2179 COMMERCIAL DR
305230000600	C & A ON SITE STORAGE LLC	8675 BLUEBONNET BLVD, SUITE A	BATON ROUGE LA 70810	2099 COMMERCIAL DR
305230000500	SVENDSON INVESTMENTS LLC	728 CHEVELLE DR	BATON ROUGE LA 70806-0000	2069 COMMERCIAL DR
305200008000	WESTPORT INVESTMENTS LLC	P O BOX 279	SPRINGFIELD LA 70462-0000	2524 COMMERCIAL DR
305200012200	MULLINS REAL ESTATES INVESTMENTS LLC	2935 MUPHY DR	BATON ROUGE LA 70809-0000	2029 COMMERCIAL DR
305200008800	OLINDE HARDWARE & SUPPLY CO LLC	9536 AIRLINE HWY	BATON ROUGE LA 70815-0000	COMMERCIAL DR
305250000300	AT & T PROPERTY TAX	C/O AT&T CORP	ONE AT&T WAY BEDMINSTER, NJ 07921	COMMERCIAL DR
305250000200	AT&T NETWORK ASSETS I INC	P O BOX 7207	BEDMINSTER, NJ 07921	
305200008000	WESTPORT INVESTMENTS LLC	P O BOX 279	SPRINGFIELD LA 70462-0000	2524 COMMERCIAL DR
35250000600	WESTPORT INVESTMENTS LLC	P O BOX 279	SPRINGFIELD LA 70462-0000	2524 COMMERCIAL DR
35250000400	INO THERAPEUTICS LLC	ATTN: ACCOUNTS PAYABLE	P O BOX 9001 HAMPTON NJ 08827-0000	1060 ALLENDALE DR
30340005200	AIRGAS SPECIALTY GASES INC	C/O CORP TAX SEPT	P O BOX 6675 RADNOR PA 19087-0000	1075 CINCLARE DR
30340005600	FOX TIMOTHY W & CARRIE C	7660 RICHARDS DR	BATON ROUGE LA 70809-0000	BRIDGEVIEW DR
30340005700	FOX TIMOTHY W & CARRIE C	7660 RICHARDS DR	BATON ROUGE LA 70809-0000	1402 BRIDGEVIEW DR
30340005800	KENT & SMITH HOLDINGS LLC	2688 MAIN ST	LOTTIE LA 70756	BRIDGEVIEW DR
30340000100	KENWORTH OF SOUTH LOUISIANA LLC	P. O. BOX 1450	GRAY LA 70359-0000	1302 BRIDGEVIEW DR
30340005300	PRIME INDUSTRIAL PROPERTIES LLC	15959 FLORIDA BLVD	BATON ROUGE LA 70819	1200 LEBLANC RD
30340005302	PRIME INDUSTRIAL PROPERTIES LLC	15959 FLORIDA BLVD	BATON ROUGE LA 70819	
30340005303	CULOTTA SCOTT L	15959 FLORDIA BLVD.	BATON ROUGE LA 70819-0000	
30340005301	PRIME INDUSTRIAL PROPERTIES LLC	15959 FLORIDA BLVD	BATON ROUGE LA 70819	1150 LEBLANC RD
30389000100	GREATER BATON ROUGE PORT COMMISSION	2425 ERNEST WILSON DR	PORT ALLEN LA 70767-0000	1434 PETE RIVIERE DR
305309000100	GREATER BATON ROUGE PORT COMMISSION	2425 ERNEST WILSON DR	PORT ALLEN LA 70767-0000	1833 HWY 1 S
305300002500	MISSOURI PACIFIC RAILROAD CO	C/O UNION PACIFIC RAILROAD CO	PORPERTY TAX 1400 DOUGLAS ST, STOP 1640 OMAHA NE 68179-1640	1601 S WESTPORT DR
305300000202	INTERNATIONAL PIPING SYSTEM	C/O TURNER INDUSTRIES GROUP LLC	P O BOX 2750 BATON ROUGE LA 70821	1700 S WESTPORT DR
305300000203	NUGENT STEEL PROPERTIES LLC	7029 MONITEAU CT	BATON ROUGE LA 70809-0000	1800 S WESTPORT DR
305200008500	NUGENT STEEL PROPERTIES LLC	7029 MONITEAU CT	BATON ROUGE LA 70809-0000	S WESTPORT DR
305200008100	CHEMICAL LIME COMPANY	C/O THOMSON REUTERS, PROP TAX SERVICE	400 WEST 15 STREET, #700 AUSTIN TX 78701-1648	1785 S WESTPORT DR

OWNER QUESTIONNAIRE MAILING LIST

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS
305200007900	CASTROL INC	C/O BP AMERICA	PO BOX 1548 WARRENVILLE IL 60555	
305200007901	CASTROL N AMERICA AUTOMOTIVE	C/O BP AMERICA	P O BOX 1548 WARRENVILLE IL 60555	1981 S WESTPORT DR
305200007800	CASTROL INC	C/O BP AMERICA	PO BOX 1548 WARRENVILLE IL 60555	S WESTPORT DR
305200009400	GRIGSBY PROPERTIES LLC	15635 AIRLINE HWY	BATON ROUGE LA 70817	2307 S WESTPORT DR
305200009300	GRIGSBY PROPERTIES LLC	15635 AIRLINE HWY	BATON ROUGE LA 70817	2405 S WESTPORT DR
305200012500	RONGEY PORT ALLEN REAL ESTATE LLC	2200 CAMERON ST	LAFAYETTE LA 70506-0000	2527 S WESTPORT DR
304520001200	L & G INC OF TEXAS	C/O GROENDYKE TRANSPORTATION	P O BOX 1050 PORT ALLEN LA 70767	2723 S WESTPORT DR
304520001400	LOVE'S COUNTRY STORES INC #240	C/O BURKE & ASSOCIATES	3336 E 32ND ST#217 TULSA OK 74135-0000	801 LOBDELL HWY S
304520001000	DACAL LLC	722 LOBDELL	PORT ALLEN LA 70767	821 LOBDELL HWY S
304520000400	RIVER PORT LAND LLC	820 GARRETT ST	BOSSIER CITY LA 71171-0000	940 LOBDELL HWY
304520000300	DACAL LLC	722 LOBDELL	PORT ALLEN LA 70767	722 LOBDELL HWY S
304520000200	MOTEL 6 OPERATING LP	ATTENTION: TAX DEPARTMENT	P. O. BOX 117508 CARROLTON TX 75011-0000	2800 I-10 FRONTAGE RD
304520000100	INTREPID INVESTMENTS LLC	42693 HWY 42	PRAIRIEVILLE LA 70769-0000	2855 I-10 FRONTAGE RD
304520001300	2901 I-10 LLC	727 IBERVILLE ST	NEW ORLEANS LA 70130	2901 I-10 FRONTAGE RD
305200008000	WESTPOT INVESTMENTS LLC	P. O. BOX 279	SPRINGFIELD, LA 70462-0000	3333 I-10 FRONTAGE RD
304500003300	WESTPORT INVESTMENTS LLC	P O BOX 96	WATSON LA 70786	3133 I-10 FRONTAGE RD
304500003200	MOORE SHELLY SR & BARBARA D S	5825 STEARNS ST	BATON ROUGE LA 70811	3333 I-10 FRONTAGE RD

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 9, 2017

OWNER NAME: Henry Rideaux Heirs - Judy Rideaux, Sylvia Williams, Shirley Thomas, Clifton Rideaux, etc

ADDRESS: 2729 Valley Street (STREET) Baton Rouge (CITY) LA (STATE) 70808 (ZIP)

PARCEL NUMBER: 008-1759-7 VL South 2717 Valley St. Lot 10PT + SQ 4

PHONE: 225-288-2048 EMAIL:
225-654-4441

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Vacant residential lot

2. What are the current and past uses of the subject property? Residential - single home, vacant lot since 2005

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? not in service

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W/SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

a- single dwelling home prior to existance of city drainage system - tank filled in after conversion somewhere around 1965

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

Property has been under the ownership of 1 family since 1953?

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

None

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 9 - 17

OWNER NAME: Boulanger Properties LLC

ADDRESS: 2811 Sarpy Ave (STREET) Baton Rouge (CITY) LA. (STATE) 70820 (ZIP)

PARCEL NUMBER: 305200009000, 2421 Commercial Drive

PHONE: 225-268-6912 EMAIL: boulangertree@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   4.6 Acres of open land

2. What are the current and past uses of the subject property? Hay field

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) / N

   If yes, who supplies the service? I assume parish W.B.R or City of Port Allen

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-10-17

OWNER NAME: Joyce DeArmond McIntire

ADDRESS: 2929 Perkins Road (STREET) Baton Rouge (CITY) LA (STATE) 70808 (ZIP)

PARCEL NUMBER:

PHONE: My home - (225) 766-5186 EMAIL: N/A

QUESTIONNAIRE:

2. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

Hardware store currently, Formerly dryceaners + Bakery + small package liquor store.

1. What are the current and past uses of the subject property? See above.

One story concrete block building. Hardware store merchandise. Disconnected Laundry + Drycleaning Equip to be sold.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

If yes, who supplies the service? Baton Rouge Water Co. + EBR Sewage Dept.

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

N/A

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? N/A

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-10-17

OWNER NAME: Olinda Hardware and Supply Co, LLC

ADDRESS: 9536 Airline Hwy, Baton Rouge, LA 70815
STREET CITY STATE ZIP

PARCEL NUMBER: Westport Industrial Park, Tract F-2

PHONE: 225-615-9073 EMAIL: beau@olinda.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   vacant land

2. What are the current and past uses of the subject property? none - vacant land

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N None that know of.

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? Providence did the Phase I Environmental Site Assessment (Project No. 277-001) in May, 2006.

11. Is there any commonly known or reasonably ascertainable information about the site?
not that aware of, other than any public records & your 2006 Phase I

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?
not that aware of

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/10/17

OWNER NAME: Estate of Louis Payne Sr. - Patricia Smith

ADDRESS: 5515 Riverbend Blvd BR LA 70820
STREET CITY STATE ZIP

PARCEL NUMBER: 784672

PHONE: 225-9783405 EMAIL: phs51ebr@adl.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   strip of land left from the interstate being built. The land was ~~expropriated~~ expropriated by the state leaving a small strip.

2. What are the current and past uses of the subject property? single family structure

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-10-17

OWNER NAME: MONNIE-LU KLEINPETER

ADDRESS: 5558 COLDWATER CREEK CT.
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: (225) 766-5520 EMAIL: —

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   2919 PERKINS Rd. RAMA
   LEASED OUT AS A RESTURANT

2. What are the current and past uses of the subject property? RESTURANT

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / (N)

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No.

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: Monday July 10th 2017

OWNER NAME: Lovie Hampton Oyekenu

ADDRESS: 5747 Trenton Ave Baton Rouge Louisiana 70808
STREET CITY STATE ZIP

PARCEL NUMBER: 5747 Trenton Ave. Baton Rouge, La. 70808

PHONE: (225) 925-5522 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   The subject site is a single family dwelling house. The structure is as I bought it in 2003. No type of equipment is stored or used on the subject property.

2. What are the current and past uses of the subject property? The current and past uses of the subject property is as a single family home.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? 4 ft x 4 ft est.
   (Circle One) Y / N There is a green rectangular shaped metal box on or near this property that's used by the telephone or electric company.
   If yes, who supplies the service? I haven't looked on the back yard in a while but I think I saw a sewer or water type manhole w/metal lid.

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N) None that I've seen or noticed.

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N) None known to me.

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N) None known to me

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / (N) None known to me
b. Odors	Y / (N)
c. Pools of liquid – back yard holds water near the fence w/ heavy rain	(Y) / N
d. Drums	Y / (N) None known to me
e. Hazardous substances and petroleum product containers	Y / (N) " " " "
f. Unidentified substance containers	Y / (N) " " " "
g. Staining or corrosion	Y / (N) " " " "
h. Drains and sumps	Y / (N) " " " "
i. Pits, ponds, or lagoons	Y / (N) " " " "
j. Solid waste storage or disposal	Y / (N) " " " "
k. Wastewater treatment	Y / (N) " " " "
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / (N) " " " "
m. Water Wells/Monitoring Wells	Y / (N) " " " "

If the answer to any of the above is "yes", please state the corresponding letter and explain.

[C.] When there's a heavy rain in the backyard near the fence, waters holds into a pool for a day or two.

8. Were there any previous or current spills or releases at the property? Y / (N) None known to me.

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / (N) None known to me.

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One) Since I've been here,

a. Environmental site assessment reports	Y / (N) None known to me
b. Environmental audit reports	Y / (N) " " " "
c. Environmental permits	Y / (N) " " " "
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / (N) " " " "
e. Material Safety Data Sheets (MSDS)	Y / (N) " " " "
f. Community right to know plans	Y / (N) " " " "
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / (N) " " " "
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / (N) " " " "
i. Hazardous waste generators notices or reports	Y / (N) " " " "
j. Geotechnical studies	Y / (N) " " " "
k. Land use restrictions	Y / (N) None known to me.

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?
I do not know. I bought this place in June 2003.

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?
None known to me.

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 11 July 2017

OWNER NAME: Fiero Properties (Stafford Wood, Managing Partner)

ADDRESS: 1111 South Foster, Suite C Baton Rouge LA 70806
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-205-009 EMAIL: stafford@covalentlogic.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   2,000 sq ft freestanding Neighborhood office on the corner of Christian St + Fiero St.

2. What are the current and past uses of the subject property? Home, Home Office, Neighborhood Office

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: _____

OWNER NAME: Katherine M. Soileau

ADDRESS: 2301 Fiero St. (STREET) Baton Rouge (CITY) LA. (STATE) 70808 (ZIP)

PARCEL NUMBER: Lot #1 Maison Fiero Subdivision

PHONE: 225-763-1099 EMAIL: kathysoileau@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   A Residential Condo is located on the site. No equipment stored on property. Strictly residential.

2. What are the current and past uses of the subject property? Current use is residential. I have no prior knowledge before 2013.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? City of Baton Rouge

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. None currently. I have no knowledge prior to 2013 when I purchased property.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   I don't know of any.

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   I don't know. None in my name.

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

Not since 2013. No prior knowledge.

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. See above #7

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. See above #7

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? I don't know of any

11. Is there any commonly known or reasonably ascertainable information about the site?

NO.

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? Not to my knowledge

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 11 - 2017

OWNER NAME: College GAS INC; d/b/a College CHEVRON
OWNER PRESIDENT : NADIA ELBAR

ADDRESS: 2018 OAKDALE Drive. BATON ROUGE, La 70810
STREET CITY STATE ZIP

PARCEL NUMBER: P639540 (2929 College drive & I-10) Ward #1-3 #6506

PHONE: (225) 978-0097 cell EMAIL: Natalieshell1@netscape.net
(225) 978-9307 cell

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   GAS STATION with convinience store - CHEVRON including CANOPY CHEVRON ; 4 GAS Pumps ; 4 UST GAS TANKS

2. What are the current and past uses of the subject property? Past GAS station CHEVRON
   Current GAS STATION CHEVRON

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / (N)

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. Petroleum Products stored underground in 4 UST TANKS (2 UST for Regular UNL, 1 UST for PLUS, 1 UST for Premium)

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   LDEQ : AI 20619, UST REG20040001 (4 TANKS 6537, 6536, 6538 6539

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	(Y) / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

UST: 4 underground storage tanks

8. Were there any previous or current spills or releases at the property? Y / (N)

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / (N)

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	(Y) / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? AI# 20619 DEQ or Contact me Nadia ELBAR

11. Is there any commonly known or reasonably ascertainable information about the site?

GAS station

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

None

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-10-17

OWNER NAME: DAVIS SAMUEL JR OR EUGENE DAVIS

ADDRESS: 5338 CLARK ST BR LA 70811
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-275-2178 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   NONE

2. What are the current and past uses of the subject property? No used

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NO

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-12-17

OWNER NAME: Gregory Allen Anderson

ADDRESS: 967 Cotton Street BR. La. 70802
STREET CITY STATE ZIP

PARCEL NUMBER: P499374

PHONE: 225-247-2943 EMAIL: gandersons, nbacanderson@yahoo.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property. New Residential — Roof, paint, A/C, Landscape etc

2. What are the current and past uses of the subject property? Residential

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 07.11.17

OWNER NAME: Mikon Holdings, LLC

ADDRESS: 16226 Feliciana Ave, Prairieville, LA 70769
STREET CITY STATE ZIP

PARCEL NUMBER: Lot "W" Block 257, Suburb Swart

PHONE: 225.387 2307 EMAIL: diverarchitect@yahoo.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Cleared lot

2. What are the current and past uses of the subject property? residential; currently zoned for LC-2

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) N

   If yes, who supplies the service? BR Water Co / City of Baton Rouge

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe. None that we are aware of

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

Don't understand the question

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: _____

OWNER NAME: Dawson and Madeline Ellis

ADDRESS: 2440 Baywood Ave (STREET) Baton Rouge (CITY) LA (STATE) 70808 (ZIP)

PARCEL NUMBER: _____

PHONE: 225-333-9433 EMAIL: hello@mimosahandcrafted.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   My home is in the front of the property, 1400 sq ft. The back part of my property houses my business, in a 1200 sq ft 2 story shop. My wife and I make jewelry out of this shop for a living. It houses all our equipment to do so.

2. What are the current and past uses of the subject property? We have lived here for 5 years, before it was a single family residence as well

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? regular sewer line, City of Baton Rouge

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

There are two drains on Interstate I-10 property line that need to be cleaned on a regular basis or my business will flood. I have flooded 4 times now

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/13/2017

OWNER NAME: Marion Buffington (Marsha Harris Daughter)

ADDRESS: 1851 Kentucky St
STREET CITY STATE ZIP

PARCEL NUMBER: H.0094100.2

PHONE: 225-405-3188 EMAIL: mbuffington harris@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   3 bed room, 1 livingroom, Kitchen, 1 bathroom
   remodeled 2016.

2. What are the current and past uses of the subject property? Single family home

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site? NO

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NO

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-13-17

OWNER NAME: Emily A. Roan

ADDRESS: 2036 Virginia Street B.R. LA 70802
STREET CITY STATE ZIP

PARCEL NUMBER: 001-1860-7

PHONE: (225) 344-7904 EMAIL: emilyroan@bellsouth.net

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   A former office building used for a Plastering & construction business

2. What are the current and past uses of the subject property? Vacant Lot

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site? no

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? no

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 15, 2017

OWNER NAME: Douglas and Joanne MacPherson

ADDRESS: 2962 Bocage Lake Ct., Baton Rouge, LA 70809
STREET CITY STATE ZIP

PARCEL NUMBER: Lot 72 Bocage Lake Subdivision

PHONE: 225-924-9777 EMAIL: macp1749@bellsouth.net

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Single family townhouse with attached garage.
   No equipment stored

2. What are the current and past uses of the subject property?

   Residential subdivision

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / (N)

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 12, 2017

OWNER NAME: Mona Simms Sampson

ADDRESS: 742 South Boulevard
STREET CITY STATE ZIP

PARCEL NUMBER: P177466 WARD/Sec/Assmt # 1-1 #6958

PHONE: 225-892-7070 EMAIL: deakesamps01@aol.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   2 BD, 2 BATH Home w/ Garage (2 car) Homemade Asphalt
   No equipment - only automobile

2. What are the current and past uses of the subject property? Residence

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y N

   If yes, who supplies the service? Baton Rouge Water Co.

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? N/a

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/14/17

OWNER NAME: Annie Kimble - Deceased / Willie Mae Varnell Daughter

ADDRESS: 2112 Carolina St. BR La 70802
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-926-8368 / 456 3797 EMAIL: Willie.Varnell@Hotmail.Com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   VACANT lot

2. What are the current and past uses of the subject property? VACANT NOW / single FAMILY Dwelling

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/12/17

OWNER NAME: Goray Properties II, LLC

ADDRESS: 2344 Baywood (STREET), Baton Rouge (CITY), LA (STATE) 70808 (ZIP)

PARCEL NUMBER: ?

PHONE: 225-324-2865 EMAIL: drillingsup@msn.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   House w/ detached carport building

2. What are the current and past uses of the subject property? Rental House

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-13-12

OWNER NAME: Hollis C & Bates

ADDRESS: 2629 Valley St (STREET) BR (CITY) La (STATE) 70808 (ZIP)

PARCEL NUMBY: 931-8952

PHONE: 931-8952 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   OUT house Lawn mower

2. What are the current and past uses of the subject property?

   Don't know

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site? NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-12-17

OWNER NAME: Milton H. Kleinpeter, Sr

ADDRESS: 739 Staring Lane
STREET CITY STATE ZIP

PARCEL NUMBER: Lot 3 Sq 17 South B.R

PHONE: (225) 229-5150 EMAIL: None

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Vacant Lot

2. What are the current and past uses of the subject property? Single Family home

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y (N)

   If yes, who supplies the service? No

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? N/A

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-8-17

OWNER NAME: Henrietta S. Colbert

ADDRESS: 5641 Trenton Ave. (STREET) Baton Rouge (CITY) Louisiana (STATE) 70808 (ZIP)

PARCEL NUMBER: 5641 Trenton Ave.

PHONE: (225)-235-0941 (Cell) EMAIL: colbert660@yahoo.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   At present this is my Home, and personal my resident.

2. What are the current and past uses of the subject property? I've Live her for 40 yrs.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-12-17

OWNER NAME: JOHN MOORE

ADDRESS: 2358 BAYWOOD AVE B.R LA 70808
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225 612 7285 EMAIL: BIGCOLONEL1@COX.NET

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   SINGLE FAMILY HOME / STAND ALONE GARAGE

2. What are the current and past uses of the subject property? RESIDENTIAL

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/17/17

OWNER NAME: Louisiana Workers Compensation Corporation

ADDRESS: 2237 S. Acadian Thruway (STREET) Baton Rouge (CITY) LA. (STATE) 70808 (ZIP)

PARCEL NUMBER: see attached

PHONE: 225-231-0922 EMAIL: pgreely@LWCC.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   8 story high rise office building.
   2 emergency generators, Diesel powered.

2. What are the current and past uses of the subject property? Office space

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. off road diesel. 1500 gallons.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

Above ground diesel storage.
Rain water collection sump.

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? DEQ

11. Is there any commonly known or reasonably ascertainable information about the site?
None

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? None

PARISH OF EAST BATON ROUGE 2015 ORIGINAL PROPERTY TAX NOTICE

ONLINE PAYMENTS

snstaxpayments.com/ebr

PAYMENT LOCATIONS

BY MAIL: East Baton Rouge Parish Sheriff
Sid J. Gautreaux, III
P.O. Box 91285
Baton Rouge, LA 70821-9285

IN PERSON: 222 Saint Louis Street
2nd Floor Room 238
Baton Rouge, LA 70802-5823
(225) 389-4810

If payment is via mail and a receipt is needed, please go to snstaxpayments.com/ebr.

ATTENTION TAXPAYERS

- Taxes become due upon receipt of this notice and become delinquent December 31 of the taxable year. Interest at the rate of 1% per month or any part thereof plus cost will be added if delinquency occurs.
- If your **MORTGAGE COMPANY** usually pays your tax through an **ESCROW** account, please **FORWARD** this tax notice to them.
- If you have sold this property, please forward this notice to the new owner or EBR Sheriff P.O. Box 70 Baton Rouge, LA 70821.
- If you need to file a **homestead exemption**, change your **mailing address**, or have questions concerning your **assessment**, please contact the **Assessor's Office at 225-389-3920.**
- If the **NET ASSESSMENT/TAX** amounts in the box to the right are zero (.00), your homestead exemption has covered the entire amount of millage-based tax. If no OTHER CHARGES are due, you are not required to pay any amount or return any portion of this notice.
- **Please see the reverse side of this bill for additional information and the individual millage rates applied.**

PROPERTY # P179868 NOTICE# 2015179868

YEAR	WARD / SEC / ASSMT #
2015	1-3 #19671

PROPERTY DESCRIPTION

Ward 1-3 #19671, Lot: A-5, Subdiv: RICHLAND PLANTATION. TRACT A-5, CONT 3.462 ACRES, RESUB. OF 9.07 ACRES, FORMERLY A PORTION OF LOT 36 RICHLAND PLANTATION IN SEC. 94, T7S, R1E. IMP. 278100 PARKING GARAGE. IMP. 1109400.(R95)

DETACH AND RETURN BOTTOM

PARISH OF EAST BATON ROUGE
Sid J Gautreaux, III
Sheriff & Tax Collector
P.O. Box 70
Baton Rouge, LA 70821

NOTICE #	PROPERTY #	YEAR
2015179868	P179868	2015
WARD / SEC / ASSMT # 1-3 #19671		

217516

LOUISIANA WORKER'S COMPENSATION
2237 S ACADIAN THRUWAY STE 102
BATON ROUGE LA 70808-2371

85478

PARISH OF EAST BATON ROUGE
Sid J Gautreaux, III
PO BOX 91285
Baton Rouge, LA 70821-9285

0000201517986800179642572

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-17-17

OWNER NAME: Michael and Leslie Sims

ADDRESS: 1219 E. Washington St (STREET) Baton Rouge (CITY) LA (STATE) 70802 (ZIP)

PARCEL NUMBER: _____

PHONE: 225-371-0104 EMAIL: NA

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   3 bed room 2 full bathrooms family home with a carport and a screened in front porch.

2. What are the current and past uses of the subject property? Family Home

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps: Neighbors yard caving in. Bank wont fix it.	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

Next door the yard is caving in, contacted the bank (Chase Bank) the refuse to fix it but they own it.

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

Yes the ground has been caving in for more than 5yrs.

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/18/17

OWNER NAME: J.L. Associates LLC

ADDRESS: 2880 N. Westport Dr. (STREET) Port Allen (CITY) LA (STATE) 70767 (ZIP)

PARCEL NUMBER:

PHONE: 225-343-4300 EMAIL: dipeshjpatel@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   3 story building. Limited service hotel

2. What are the current and past uses of the subject property? Hotel

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? West Baton Rouge Parish Natural Gas + Water

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NONE

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NONE

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/18/17

OWNER NAME: Khushi Investments LLC

ADDRESS: 2860 N. Westport Dr. (STREET) Port Allen (CITY) LA (STATE) 70767 (ZIP)

PARCEL NUMBER:

PHONE: 225-343-9967 EMAIL: ashpatel07@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Limited Service Hotel - 4 story

2. What are the current and past uses of the subject property? Hotel

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) / N

   If yes, who supplies the service? West Baton Rouge Parish Natural Gas & Water

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: JULY 17, 2017

OWNER NAME: CRAIG TARVER

ADDRESS: 2305 FIERO ST (STREET) BATON ROUGE (CITY) LA (STATE) 70808 (ZIP)

PARCEL NUMBER: UNIT C

PHONE: 318 470 0071 EMAIL: CRTAR0029@AOL.COM

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   ATTACHED DWELLING EST. 2250 SQ FEET
   W. GARAGE. 1 OF 6 UNITS

2. What are the current and past uses of the subject property? NONE

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? BATON ROUGE WATER

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N NOT TO MY KNOWLEDGE

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N NOT TO MY KNOWLEDGE

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

YES

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 15, 2017

OWNER NAME: (Joseph Daisy) Debra D. Carey

ADDRESS: 2058 Rue Racine (STREET) Marrero (CITY) La. (STATE) 70072 (ZIP)

PARCEL NUMBER: P579556

PHONE: 504-615-1864 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Empty vacant lot

2. What are the current and past uses of the subject property? vacant lot
   No longer has a house on it.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

Gwendolyn S. Goings
5725 Oakwood Dr
Baton Rouge, LA 70811-6232

DATE OF COMPLETION: July 11, 2017

OWNER NAME: Harriet Hilliard Scott Estate, Executrix

ADDRESS: 4912 Essen Lane Baton Rouge, LA 70809
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225 356 4886 EMAIL: ggs14all@hotmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   used as home and church service, 4912 Essen Lane,

2. What are the current and past uses of the subject property? home and church service.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y (N)

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions commercial zone C2	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-16-17

OWNER NAME: New Prospect Missionary Baptist Church

ADDRESS: 1349 McCalop (STREET) Baton Rouge (CITY) LA (STATE) 70802 (ZIP)

PARCEL NUMBER: P650137

PHONE: 225-454-9561 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.
   Single Family House; No equipment currently stored on site.

2. What are the current and past uses of the subject property? Rental house; Currently vacant; needs renovating

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) / N

   If yes, who supplies the service? Baton Rouge Water Company

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?
Yes; Information regarding property will be at the EBRP Clerk of Court ofc.

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 19, 2017

OWNER NAME: West Baton Rouge Parish Gov't

ADDRESS: 2750 N. Westport Dr. (STREET) Port Allen (CITY) LA (STATE) 70767 (ZIP)

PARCEL NUMBER: 30451900 3600

PHONE: 225-336-2434 EMAIL: Kevin.Dorbin@WBRCouncil.org

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   This is the site of the West Baton Rouge Tourist Commission. It consists of one main building, one accessory building, a parking area and actively lawn (6.5 Ac) with a walking path

2. What are the current and past uses of the subject property? West Baton Rouge Parish Tourist Commission

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? West Baton Rouge Parish Utilities

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. None Known

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N None Known

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.). None Known

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

None Known

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. None Known

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. None Known

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

None Known

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

Zoning & Local Land Use Controls

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/19/17

OWNER NAME: St. Francis Xavier Church

ADDRESS: 1120 Myrtle Walk Baton Rouge, LA 70802
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-383-3479 EMAIL: pastor@SFXC.BR.Coxmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Church, Rectory

2. What are the current and past uses of the subject property? Church

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 15, 2017

OWNER NAME: Audrey W. Jordan 2010 Evans Ave, Monroe LA 71202

ADDRESS: 1321 E. Washington St. Baton Rouge, LA. 70802
STREET CITY STATE ZIP

PARCEL NUMBER: _____

PHONE: 318-387-2688 EMAIL: —

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Brick Home - with No stored Equipment on the property

2. What are the current and past uses of the subject property? Family dwelling - still

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / (N)

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/18/2017

OWNER NAME: Cora Reddix Burks & Family

ADDRESS: 2832 Balis Drive Baton Rouge, LA. 70808
STREET CITY STATE ZIP

PARCEL NUMBER: Lot 22PT

PHONE: 225 975 5258 EMAIL: Cora.burks18@gmail.com
stella4hma

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property. no equipment stored. 2832 Balis Dr. & 2840 Balis-remodeling. lovely yard. Large Pecan tree, fruit tree, Plants trees and flowers, Pipes in ground from old houses that were on the propt.
2. What are the current and past uses of the subject property? Family dwelling. Home's
3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?
4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N not that i am aware of. years ago there was a land fill (Dump) behind our property where the BREC park is. no telling what is in the soil and what hazardous waste we were exposed to.

   If yes, describe.
5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N not that I am aware of. Five of my neighbors were diagnosed with some form of cancer on the same street including me. a lot of people in valley park died of some form of cancer. our playground was a dump.

   If yes, what were the findings of the investigations, and can copies of the documents be provided?
6. Does the subject property have any federal, state, or local environmental permits? Y / N not that I know of.

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y/N
b. Odors	Y/N
c. Pools of liquid	Y/N
d. Drums	Y/N
e. Hazardous substances and petroleum product containers	Y/N
f. Unidentified substance containers	Y/N
g. Staining or corrosion	Y/N
h. Drains and sumps	Y/N
i. Pits, ponds, or lagoons	Y/N
j. Solid waste storage or disposal	Y/N
k. Wastewater treatment	Y/N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y/N
m. Water Wells/Monitoring Wells	Y/N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

B natural Gas leak in the front yard under the side walk street per Entergy. They worked on the leak. It ran under I-10.

8. Were there any previous or current spills or releases at the property? Y/N yes

If yes, explain. Entergy came back out remarked the ground and say that there was another possible leak.

9. Have there been any environmental cleanup activities at the property? Y/N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y/N
b. Environmental audit reports	Y/N
c. Environmental permits	Y/N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y/N
e. Material Safety Data Sheets (MSDS)	Y/N
f. Community right to know plans	Y/N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y/N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y/N
i. Hazardous waste generators notices or reports	Y/N
j. Geotechnical studies	Y/N
k. Land use restrictions	Y/N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

To the best of my knowledge - no.

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

* In the back of the property by the canal Gulf Oil Company left a metal cut off post in the ground from a sign that they had on the Property. We found them because of soil erosion.

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 19, 2017

OWNER NAME: Juanita Hookfin aka Juanita H. Johnson

ADDRESS: 1159 E. Harrison St., Baton Rouge, LA 70802
STREET CITY STATE ZIP

PARCEL NUMBER: Lots 33 and 35

PHONE: 225-338-0795 EMAIL: ajjohnson333@aol.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   One residential house. One 10x10 storage shed. Storage holds yard equipment, seasonal clothing, household items. Improvements were made to add driveway extension.

2. What are the current and past uses of the subject property? Primary home.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N N/A

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

None

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7 – 19 – 17

OWNER NAME: Ben Thomas Lala Davis Hill

ADDRESS: 1365 Bellaire Dr BR La 70810
STREET CITY STATE ZIP

PARCEL NUMBER: 0

PHONE: 225 766 3537 EMAIL: Louislavergne@bellsouth.net

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Residential

2. What are the current and past uses of the subject property? Residential

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y (N)

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y (N)

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?
Complete Remodel and a Room addition

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-17-17

OWNER NAME: Charles Milne

ADDRESS: 2938 Bocage Lake B.R LA 70809
STREET CITY STATE ZIP

PARCEL NUMBER: Not Sure

PHONE: 225 931 8579 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Home

2. What are the current and past uses of the subject property?

   Home

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? N

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. N

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 18 July 2017

OWNER NAME: Brown, Joseph - Thelma S.

ADDRESS: P O Box 762 Baton Rouge LA 70821
STREET CITY STATE ZIP
for mailing

PARCEL NUMBER:

PHONE: 225 · 223 · 2788 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Property Cleared of any structure.

2. What are the current and past uses of the subject property? House located on property

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

none

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

none

Brandy R Brown

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-19-17

OWNER NAME: Janice Marie Batiste Harris

ADDRESS: 1822 Virginia St. Baton Rouge, La. 70802
STREET CITY STATE ZIP

PARCEL NUMBER: P647616

PHONE: (225) 343-3686 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Vacant lot & run down house (unoccupied)

2. What are the current and past uses of the subject property? Vacant Property.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y (N)

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

None Known

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-19-17

OWNER NAME: Janice Marie Batiste Harris

ADDRESS: 1832 Virginia Street, Baton Rouge, La. 70802
STREET CITY STATE ZIP

PARCEL NUMBER: P5468 52

PHONE: (225) 343-3686 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   This structure is a 4 bedroom, 3 baths, Kitchen, wash room and living room, T.V. area + kitchenette split level family home. (3 bedroom + bath upstairs).

2. What are the current and past uses of the subject property? This site is used as a homestead only.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y (N)

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y (N)

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y N
b. Odors	Y N
c. Pools of liquid	Y N
d. Drums	Y N
e. Hazardous substances and petroleum product containers	Y N
f. Unidentified substance containers	Y N
g. Staining or corrosion	Y N
h. Drains and sumps	Y N
i. Pits, ponds, or lagoons	Y N
j. Solid waste storage or disposal	Y N
k. Wastewater treatment	Y N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y N
m. Water Wells/Monitoring Wells	Y N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y N
b. Environmental audit reports	Y N
c. Environmental permits	Y N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y N
e. Material Safety Data Sheets (MSDS)	Y N
f. Community right to know plans	Y N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y N
i. Hazardous waste generators notices or reports	Y N
j. Geotechnical studies	Y N
k. Land use restrictions	Y N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

None Known

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-20-17

OWNER NAME: RAE PHILLIPS

ADDRESS: 2372 FERNDALE AVE Baton Rouge LA 70808
STREET CITY STATE ZIP

PARCEL NUMBER: 00586617

PHONE: 225-571-9076 EMAIL: RAEphill@msn.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Cottage on piers - 995 sq ft - with old garage attached that is under roof - usable until the interstate was built - which cut the street off - the interstate borders on the property line - a lot of utilities run through this corider under ground.

2. What are the current and past uses of the subject property? previous owners lived in the property and has been a rental for years

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) / N Department of Public Works EBR

   If yes, who supplies the service? East Baton Rouge Parish Sanitary Sewer Station under interstate - and bordering my land - very close to my sewer return

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? (Y) / (N) currently no.

   If yes, describe: EBR Dept of Public Works repaired a sink hole under my sewer return and this has solved the problem - there was also a concern about the EBR Parish Sanitary Sewer station - but it is all better now.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? (Y) / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   the EBR Dept of Public Works has records I do not - the DPW - Waste Water Division has public records - at the Parish Attorney's office - 389-3114 area code 225

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / (N)
b. Odors	(Y) / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	(Y) / N ? - Sanitary Sewer Station next to me
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

There was a sink hole in my sewer return - water gushing off the interstate - and a DPW sewer station next to my property - All is now repaired

8. Were there any previous or current spills or releases at the property? (Y) / N

If yes, explain. All Repaired by EBR Dept of Public Works

9. Have there been any environmental cleanup activities at the property? (Y) / N

If yes, explain. DPW Waste Water Division - Parish attorney Records

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	(Y) / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? DOTD - DPW

11. Is there any commonly known or reasonably ascertainable information about the site?
the property borders on the interstate line

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?
no - not that I know of

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 20, 2017

OWNER NAME: Willard Ellois

ADDRESS: 1006 Julia St. Baton Rouge La.
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-638-9581 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Single Dwelling

2. What are the current and past uses of the subject property? Rental

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 18, 2017

OWNER NAME: Edward Barnes & Sylvia K. Barnes

ADDRESS: 5521 Trenton Ave (STREET) Baton Rouge (CITY), LA (STATE) 70806 (ZIP)

PARCEL NUMBER:

PHONE: 225-928-1831; Cell 936-8489 EMAIL: ed_ebskb@cox.net

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Metal storage structure (16x24); tools; art prints.
   Plastic storage structure ( ) for riding lawn mower

2. What are the current and past uses of the subject property? Residential use

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? (Y) / N

   If yes, describe. Petroleum used for lawn maintenance.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

no

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

no

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 19, 2017

OWNER NAME: Willie Emery

ADDRESS: 941 Royal Street (STREET) Baton Rouge (CITY) LA (STATE) 70802 (ZIP)

PARCEL NUMBER: 183237

PHONE: 225-226-2193 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   [redacted]

2. What are the current and past uses of the subject property?

   grow and sell okra

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

none

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

Not that we know of

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/19/17

OWNER NAME: Alsie Banks

ADDRESS: 3815 Lavey Ln Baker LA 70714
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: (225) 774-3222 EMAIL: banksml@hotmail.com
ONE

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   All properties are lots only. No houses on the.

2. What are the current and past uses of the subject property? Rental properties. Now empty Lots

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? No

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. No

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   No

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   No

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

No

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? No

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 2007

OWNER NAME: B. Wayne Brown

ADDRESS: 2302 Flero (STREET) Baton Rouge (CITY) La (STATE) 70808-2128 (ZIP)

PARCEL NUMBER: _____

PHONE: _____ EMAIL: _____

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Don't know about any below
   We need a Sound Barrier between
   our property and I-10

2. What are the current and past uses of the subject property? _____

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N.

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-20-2017

OWNER NAME: CIRCLE K STORES INC

ADDRESS: 2300 S. ACADIAN THWY BATON ROUGE 70808
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 850-549-2879 EMAIL: sjanashae@circlek.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   GAS STATION

2. What are the current and past uses of the subject property? GAS STATION

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? NO

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. UST's - AI # 71560

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   NO

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   LDEQ AI # 71560

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

UST FUEL SYSTEM IS ACTIVE

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. VOS

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. NFA IN 2013

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? EDMS

11. Is there any commonly known or reasonably ascertainable information about the site?

EDMS

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7.20.2017

OWNER NAME: CIRCLE K STORES INC

ADDRESS: 2959 COLLEGE DRIVE (STREET) BATON ROUGE (CITY) (STATE) 70808 (ZIP)

PARCEL NUMBER:

PHONE: 850.549.2879 EMAIL: sjanasha@circlek.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   GAS STATION

2. What are the current and past uses of the subject property? GAS STATION

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? NO

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. UST's AI # 13684

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   NO

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   LDEQ AI # 13684

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

UST FUEL SYSTEM IS ACTIVE

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. NFA ISSUED

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. NEW RELEASE IS PENDING - BENZENE IN GW

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? EDMS

11. Is there any commonly known or reasonably ascertainable information about the site?

EDMS

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-21-17

OWNER NAME: ROBERT GUTIERREZ

ADDRESS: 3478 S EUGENE (STREET) BATON ROUGE (CITY) LA (STATE) 70808 (ZIP)

PARCEL NUMBER: P694762

PHONE: 225-715-9349 EMAIL: gutcon@cox.net

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   HOUSE

2. What are the current and past uses of the subject property? HOME

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/22/17

OWNER NAME: Martina Rowe Three Property, LLC

ADDRESS: 1724 Dallas Dr. Suite 8 B.R. La. 70806
STREET CITY STATE ZIP

PARCEL NUMBER: 1724

PHONE: (225) 362-1744 EMAIL: msrowe@rowesaccounting.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.
   New Roof 2015, Remodeled 2016, Rental Property, Tenant lives in property, 3 bedroom, 2 full bath, Den, Diningroom, bonus room, utility room, outside storage.

2. What are the current and past uses of the subject property? this is a Rental Property investment

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

N/A None

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

N/A None

(2) parcel # Lot 61 Squ. 18 SBR Ward 1-3

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/20/17

OWNER NAME: Sameerah R. Castle (Rashadeen)(Tamir) DEC as.

ADDRESS: 2130 Carolina st. Baton Rouge, La. 70808 70802
STREET CITY STATE ZIP

PARCEL NUMBER: (1) Property # 008-1942-5, Lot 59 Squ. 18

2 PHONE: 225-620-5359 EMAIL: SameerahCastle@Yahoo.Com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   One family dwelling, 4 bedroom - 2 baths sitting on 2 lots,

2. What are the current and past uses of the subject property? House on lot

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site? No

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? No

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 21, 2017

OWNER NAME: Isiaac & Maebell Brown / Mary Johnson

ADDRESS: 2665 Yazoo Baton Rouge, LA 70808
STREET CITY STATE ZIP

PARCEL NUMBER: P584274 Notice 2015 584274

PHONE: (817) 988-6501 EMAIL: maebellbrown@yahoo.com
(817) 718-3900

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   This site is a residential site. A home once existed here but has been removed-demolished.

2. What are the current and past uses of the subject property? Used as a home at one time - then, later as a Rental Property

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? City of Baton Rouge provided the service when the home existed

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. Not when we owned the property

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   We have not been provided w/ any reports of PCBs or any other hazardous substances

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

Please Note: We can only answer questions based on our knowledge; We do not know about previous owners.

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. Not that we are aware of

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. Not that we are aware of

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 24, 2017

OWNER NAME: Clay A. George

ADDRESS: 1619 Theron Dr (STREET) Baton Rouge (CITY), Louisiana (STATE) 70810 (ZIP)

PARCEL NUMBER:

PHONE: 225-757-8014 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   The site is a vacant property that I purchased in 1999

2. What are the current and past uses of the subject property? Residential Site only

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-20-2017

OWNER NAME: Mary W Johnson

ADDRESS: 940 St Joseph Baton Rouge La 70802
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-344-5933 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   House

2. What are the current and past uses of the subject property? Livingston Property

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

no

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

no

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 25, 2017

OWNER NAME: Ave' Frazier-Honore'

ADDRESS: 996 Terrace Ave (STREET) Baton Rouge (CITY) LA (STATE) 70802 (ZIP)

PARCEL NUMBER: _____

PHONE: 225-454-5600 EMAIL: avehonore@yahoo.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   N/A

2. What are the current and past uses of the subject property? N/A

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

Project no. 040-012-001

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-24-2017

OWNER NAME: Alwyn J Phillips

ADDRESS: 2362 Ferndale Ave Baton Rouge LA 70808
STREET CITY STATE ZIP

PARCEL NUMBER: 3156 Greenwood Dr Baton Rouge LA 70808 (connected property)

PHONE: 225 654-0012 wk EMAIL: al@alphillipsagency.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   1) Frame 1 story frame dwelling (Ferndale)
   2) Concrete Block 1½ story garage apartment (Greenwood)

2. What are the current and past uses of the subject property? Family occupied or rental dwg. both always residential dwellings

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N city sewer

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

no

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

no

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: _____

OWNER NAME: Bien K Le.

ADDRESS: 2931 + 2935 Perkins Road Baton Rouge LA 70808
STREET CITY STATE ZIP

PARCEL NUMBER: _____

PHONE: 225-205-7364 EMAIL: 2a2abatonrouge@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   NO

2. What are the current and past uses of the subject property? Retail + Services.

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

No

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PROVIDENCE

July 7, 2017

7/20/17
&
Leola Mitchell
7-21-17

Re: Phase I Environmental Site Assessment (ESA) Questionnaire
State Project Number H.004100.2
Federal Aid Project Number H004100
I-10: LA 415 to Essen Lane on I-10 and I-12
East and West Baton Rouge Parishes, Louisiana

Dear Property Owner or Property Owner Representative:

Providence Engineering and Environmental Group LLC (Providence) is conducting an environmental study for the above referenced project in East and West Baton Rouge Parishes, Louisiana. The purpose of this letter is to obtain certain information regarding properties adjoining the route from the current landowners through a questionnaire.

According to the East and West Baton Rouge Parish Tax Assessor's records, you have been identified as the owner of a property along the portion of I-10 and associated interchanges included in the project study area. The attached map shows the limits of I-10 in the project study area.

As part of the environmental study, Providence is conducting a Phase I ESA for all properties along the portion of I-10 included in the project study area. An important aspect of performing a Phase I ESA is conducting an interview or completing a questionnaire with the current landowner regarding any environmentally-related issues at the property. The purpose of the attached questionnaire is to identify any potential environmental conditions at the property.

As the owner of property along I-10 or project area associated interchanges, we ask that you complete the entire enclosed questionnaire and place it in the mail by July 21, 2017. When completing the questionnaire, please indicate the physical address and parcel number in the respective fields. Your assistance by completing the questionnaire is greatly appreciated. Should you have any questions or need additional information, please contact Cory Hunter or me at (225) 766-7400.

Sincerely,

Melanie Hanks

Melanie Hanks
Site Evaluation and Remediation Services Director
Providence Engineering and Environmental Group LLC
1201 Main Street
Baton Rouge, LA 70802

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: July 20, 2017

OWNER NAME: Melvin & Leola Mitchell

ADDRESS: 6261 Gabriel Oaks Dr Brla 70820
STREET (1855 Ky St Brla) CITY STATE ZIP

PARCEL NUMBER: P802778 & P919632 → (1859 Ky St Brla)

PHONE: 225-614-5065 / 225 769-5968 EMAIL: mitch.mitchell999@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Two Rental Houses one ~~one~~ each Parcel. Fencing & Storage & Landscaping & outdoor Sun Area

2. What are the current and past uses of the subject property? Homes & Dwellings

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? Water is Provided to BR Water Company

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N) NO

   If yes, describe. NONE

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / (N) NO

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   NONE

6. Does the subject property have any federal, state, or local environmental permits? Y / N NO

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   NONE

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

A a.- OLD UNDERGROUND SEPTIC TANK IN GROUND - FILLED IN NO LONGER IN USE. K. OLD SEPTIC TANK

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? NONE

11. Is there any commonly known or reasonably ascertainable information about the site?
NONE

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? NONE

PROVIDENCE
1201 Main Street
Baton Rouge LA 70802

MITCHELL, LEOLA EVELYN WICKS &
6261 GABRIEL OAKS DR.
BATON ROUGE LA 70820

70820$5706 C048



PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-26-17

OWNER NAME: Larry Roy & Donna J.H. Anderson

ADDRESS: 5723 Trenton Ave (STREET) Baton Rouge, La (CITY, STATE) 70808 (ZIP)

PARCEL NUMBER: (Lot # 223) 499137

PHONE: (225) 927-3942 EMAIL: lander48@aol.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Residential - one story building

2. What are the current and past uses of the subject property? Residential

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) (Y) N

   If yes, who supplies the service? Baton Rouge Water Works

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / (N)

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y (N)

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y (N)

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

Don't Know

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

No

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: _____

OWNER NAME: Christian Bible College of B.R.

ADDRESS: 720 South Blvd, Baton Rouge, LA
STREET CITY STATE ZIP

PARCEL NUMBER: _____

PHONE: _____ EMAIL: jasper1937@att.net

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Church Building w/ Class Rooms

2. What are the current and past uses of the subject property? Teaching & worship

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

None

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

None

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7-27-17

OWNER NAME: Mathew Claiborne Sr

ADDRESS: 1227 Court St Port Allen LA 70767
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225 270 0633 EMAIL:

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   Cleared Lot

2. What are the current and past uses of the subject property? Rental property

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 1-17

OWNER NAME: NEW St Luke B.C.

ADDRESS: 638 So. BLVD. (STREET) BATON ROUGE (CITY) LA (STATE) 70802 (ZIP)

PARCEL NUMBER:

PHONE: 2253434411 EMAIL: NA

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

2. What are the current and past uses of the subject property? MUSUM — CHURCH 4 HOUSES

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

_____

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 8/2/17

OWNER NAME: IBERIABANK

ADDRESS: _____
STREET CITY STATE ZIP

PARCEL NUMBER: _____

PHONE: (225) 505-3222 EMAIL: clay.peterson@iberiabank.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   offic building

2. What are the current and past uses of the subject property? bank

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? _____

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. _____

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

   not that I am aware of

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

   not that I am aware of

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property? Not that I am aware of.

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. not that we know of

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

don't know for sure

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site? ?

_____

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

no.

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 8/14/17

OWNER NAME: Chavon D. White

ADDRESS: 1123 Terrace Ave. Baton Rouge LA 70802
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225 978 4657 EMAIL: chavondwhite@gmail.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.
   1123 Terrace Ave. Baton Rouge, LA 70802

2. What are the current and past uses of the subject property? residence, in home daycare

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service?

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe.

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

N/A

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

N/A

PHASE I ENVIRONMENTAL SITE ASSESSMENT
OWNER INQUIRY INTERVIEW

DATE OF COMPLETION: 7/24/17

OWNER NAME: Mamye L. Hall, LLC

ADDRESS: 1208-10-14-16 E. Washington Street BR, LA 70802
STREET CITY STATE ZIP

PARCEL NUMBER:

PHONE: 225-922-9391 EMAIL: mamyeh@aol.com

QUESTIONNAIRE:

1. Describe the subject site. Include structures or improvements to the subject site and quantity and type of equipment stored or used on the subject property.

   2-1 Bedroom duplex buildings
   There is also advertising space leased
   to Lamar Advertising (Billboard)

2. What are the current and past uses of the subject property? Residential

3. Are there any potable water or sewage disposal capabilities associated with the subject property? (Circle One) Y / N

   If yes, who supplies the service? N/A

4. Are there any hazardous substances, petroleum products, or PCBs stored or used on site currently or previously? Y / N

   If yes, describe. N/A

5. Do any reports or investigations regarding the potential presence of PCBs exist for the subject property? Y / N

   If yes, what were the findings of the investigations, and can copies of the documents be provided?

6. Does the subject property have any federal, state, or local environmental permits? Y / N

   If yes, provide permit number(s) and entity (LDEQ, EPA, etc.).

7. Are there now, or has there ever been, any of the following located on the property : (Circle One)

a. Storage tanks (UST/AST/O/W SEP)	Y / N
b. Odors	Y / N
c. Pools of liquid	Y / N
d. Drums	Y / N
e. Hazardous substances and petroleum product containers	Y / N
f. Unidentified substance containers	Y / N
g. Staining or corrosion	Y / N
h. Drains and sumps	Y / N
i. Pits, ponds, or lagoons	Y / N
j. Solid waste storage or disposal	Y / N
k. Wastewater treatment	Y / N
l. Oil/Gas Wells or Petroleum/Gas Pipelines	Y / N
m. Water Wells/Monitoring Wells	Y / N

If the answer to any of the above is "yes", please state the corresponding letter and explain.

_____

_____

8. Were there any previous or current spills or releases at the property? Y / N

If yes, explain. _____

9. Have there been any environmental cleanup activities at the property? Y / N

If yes, explain. _____

10. Do any of the following reports or documents exist for the subject property? (Circle One)

a. Environmental site assessment reports	Y / N
b. Environmental audit reports	Y / N
c. Environmental permits	Y / N
d. Underground or Aboveground Storage tank (UST or AST) registrations?	Y / N
e. Material Safety Data Sheets (MSDS)	Y / N
f. Community right to know plans	Y / N
g. Safety plans, Spill Prevention, Control, & Countermeasure (SPCC) Plan, *etc.*	Y / N
h. Notices or other correspondence from regulatory agencies relating to current or past environmental violations	Y / N
i. Hazardous waste generators notices or reports	Y / N
j. Geotechnical studies	Y / N
k. Land use restrictions	Y / N

If so, how can copies of the documents be obtained? _____

11. Is there any commonly known or reasonably ascertainable information about the site?

NO

12. Are there any environmental liens, engineering controls, institutional controls, or land use restrictions on the subject property?

NO

OWNER QUESTIIONNAIRE RESPONSES RECEIVED

PROPERTY NO.	TAXPAYER	TAXPAYER ADDRESS	TAXPAYER CITY	PHYSICAL ADDRESS	DESCRIPTION	NOTES
12351	ELLOIS, WILLARD	PO BOX 543	NEW ROADS LA 70760	1006 JULIA ST	Single dwelling	
16152	MIKON HOLDINGS, LLC	16226 FELICIANA AVE.	PRAIRIEVILLE LA 70769	Null	Cleared lot, residential, zoned for LC2	
23213	CHURCHES - ST. FRANCIS XAVIER ROMAN	1143 S. 11TH ST.	BATON ROUGE LA 70802	1120 MYRTLE WALK	Church and rectory	
38830	KLEINPETER, MILTON H. & EVA	739 STARING LN	BATON ROUGE LA 70808	Null	Vacant lot, former single-family home	
87874	GEORGE, CLAY	1619 THERON DR.	BATON ROUGE LA 70810	Null	Vacant, former residential site	
177466	SAMPSON, MONA SIMMS	742 SOUTH BLVD.	BATON ROUGE LA 70802	742 S. BLVD.	Residence with 2-car garage	Drain/sump
179868	LOUISIANA WORKER'S COMPENSATION	2237 S. ACADIAN THRUWAY, STE. 102	BATON ROUGE LA 70808	2237 S. ACADIAN THWY.	8-story high rise office building	2 diesel-powered emergency generators, 1,500 gallons of diesel stored above ground, rainwater collection sump
183237	EMERY, WILLIE B.	941 ROYAL ST	BATON ROUGE LA 70802	Null	Grow and sell okra	
192902	WILSON, MARY LEE	940 ST. JOSEPH ST.	BATON ROUGE LA 70802	940 ST. JOSEPH ST.	Residence	
293474	MILNER, CHARLES EDWARD, JR. &	2938 BOCAGE LAKE CT.	BATON ROUGE LA 70809	2938 BOCAGE LAKE CT.	Residence	
326860	MACPHERSON, DOUGLAS R. & JOANN PENN	2962 BOCAGE LAKE CT.	BATON ROUGE LA 70809	2962 BOCAGE LAKE CT.	Single-family townhouse with attached garage, in residential subdivision	
499137	ANDERSON, LARRY ROY AND DONNA J. H.	5723 TRENTON AVE.	BATON ROUGE LA 70808	5723 TRENTON AVE.	Residence	
499374	ANDERSON, GREGORY ALLEN	967 COTTON ST.	BATON ROUGE LA 70802	967 COTTON ST.	Residential	
505412	GORDY PROPERTIES II, LLC	5707 MAHONEY RD	ST FRANCISVILLE LA 70775	2344 BAYWOOD AVE.	Rental house with detached carport	
505420	MOORE, JOHN J.	2358 BAYWOOD AVE.	BATON ROUGE LA 70808	2358 BAYWOOD AVE.	Single-family home with standalone garage	
507946	BANKS, ROOSEVELT, SR, & MARTHA T. C/O ALSIE BANKS	3815 LAVEY LANE	BAKER LA 70714	Null	Empty lots, formerly rental properties	
509868	BARNES, EDWARD & SYLVIA K.	5521 TRENTON AVE.	BATON ROUGE LA 70808	5521 TRENTON AVE.	Two storage sheds, one metal and the other plastic	Petroleum-powered lawn maintenance equipment
513415	BATES, HOLLIS	2629 VALLEY ST.	BATON ROUGE LA 70808	2629 VALLEY ST.	Outhouse	
538418	BROWN, JOSEPH M., JR. & THELMA S.	C/O BRENDA BROWN PO BOX 762	BATON ROUGE LA 70821	Null	Empty lot, former house on property	
540714	BUFFINGTON, MARION MATTHEWS	1851 KENTUCKY ST.	BATON ROUGE LA 70802	1851 KENTUCKY ST.	Single-family home, remodeled in 2016	
546852	HARRIS, JANICE MARIE BATISTE	1822 VIRGINIA ST.	BATON ROUGE LA 70802	1822 VIRGINIA ST.	Vacant lot with unoccupied house	
562262	CLAIBORNE, MATHEW	1227 COURT ST.	PORT ALLEN LA 70767	Null	Cleared lot, rental property	
565164	COLBERT, HENRIETTA SMILES	5641 TRENTON AVE.	BATON ROUGE LA 70808	5641 TRENTON AVE.	Residence	
579556	DAISY, JOSEPH	2058 RUE RACINE	MARRERO LA 70072	Null	Empty vacant lot	
584274	BROWN, ISIAAC; MAEBELLE BROWN	4708 TEAROSE TRAIL	FORT WORTH TX 76123	2665 YAZOO	Demolished home, former rental property	
585246	DAVIS, SAMUEL, JR.	5338 CLARK ST.	BATON ROUGE LA 70811	Null	Not in use, no structures or equipment	
585734	ELLIS, RICHARD DAWSON & MADELINE	2440 BAYWOOD AVE.	BATON ROUGE LA 70808	2440 BAYWOOD AVE.	1,400 sq. foot single-family residence with 1,200 sq foot 2-story shop in back	Two drains on I-10 property line, back of property floods on regular basis
586617	PHILLIPS, V. R.	PO BOX 514	ZACHARY LA 70791	2372 FERNDALE AVE.	Cottage on piers with attached garage	Lots of underground utilities, sink hole in sewer return was repaired
610836	PHILLIPS, ALWYN J.	PO BOX 514	ZACHARY LA 70791	2362 FERNDALE AVE.	1-story frame dwelling with concrete block garage apartment, both occupied	
639540	COLLEGE GAS, INC.	2018 OAKDALE DR.	BATON ROUGE LA 70810	2929 COLLEGE DR.	Chevron gas station with convenience store	4 gas pumps, 4 UST gas tanks (2 for regular unleaded, 1 for Plus, 1 for Premium), LDEQ AI # 20619, UST permit # REG20040001 (Tank # 6536-6539)
647616	HARRIS, JANICE MARIE BATISTE	1832 VIRGINIA ST.	BATON ROUGE LA 70802	1832 VIRGINIA ST.	Split-level family home	
650137	CHURCHES - NEW PROSPECTS MISSIONARY	1174 TERRACE ST.	BATON ROUGE LA 70802	1349 MCCALOP ST.	Single-family house, currently vacant	
687170	KIMBLE, ANNIE C/O WILLIE MAE VARNELL	3052 SARATOGA DR.	BATON ROUGE LA 70808	2112 CAROLINA ST.	Vacant lot, former single-family dwelling	
688495	MCINTIRE, JOYCE DEARMOND	1454 APPLEWOOD RD.	BATON ROUGE LA 70808	2929 PERKINS RD.	One story concrete block building, currently a hardware store	Former dry cleaners, still contains laundry and dry cleaning equipment
688509	KLEINPETER, JONNIE-LU DEARMOND	5558 COLDWATER CREEK CT.	BATON ROUGE LA 70808	2919 PERKINS RD.	Leased out as restaurant	
694762	GUTIERREZ, ROBERT G.	3478 SOUTH EUGENE ST.	BATON ROUGE LA 70808	3478 S. EUGENE ST.	House	
725366	SIMS, MICHAEL & LESLIE JOHNSON SIMS	1219 E WASHINGTON AVE.	BATON ROUGE LA 70802	1219 E WASHINGTON AVE.	Residence with carport	Yard next door is caving in
784672	PAYNE, LOUIS, SR. 1/2 USUF 1/2	5515 RIVERBEND BLVD.	BATON ROUGE LA 70820	Null	Single family structure on strip of land expropriated by state after interstate was built	
802530	THREE PROPERTY, L.L.C.	1724 DALLAS DR. #8	BATON ROUGE LA 70806	2717 VALLEY ST.	Rental property, remodeled 2016	
802778	MITCHELL, LEOLA EVELYN WICKS &	6261 GABRIEL OAKS DR.	BATON ROUGE LA 70820	1855 KENTUCKY ST.	Two rental houses on separate parcels	Old underground septic tank still in ground, filled and no longer in use

OWNER QUESTIIONNAIRE RESPONSES RECEIVED

809284	REDDIX, MASON & EARLEAN J.	2832 BALIS DR.	BATON ROUGE LA 70808	2832 BALIS DR.	Family dwelling	Former landfill behind property on BREC park (Nairn Park) site, natural gas leak in front yard under sidewalk and street (fixed by Entergy)
818607	ROAN, EMILY AUGUSTINE	2036 VIRGINIA ST.	BATON ROUGE LA 70802	Null	Vacant lot, former office building	
819425	RASHADEEN, TAMIR N.	2130 CAROLINA ST.	BATON ROUGE LA 70802	2130 CAROLINA ST.	Single-family dwelling on 2 lots	
828998	HOOKFIN, JUANITA (A/K/A JUANITA H.	1159 E. HARRISON ST.	BATON ROUGE LA 70802	1159 E. HARRISON ST.	Residence with storage shed	
830690	OYEKENU, LOVIE HAMPTON	5747 TRENTON AVE.	BATON ROUGE LA 70808	5747 TRENTON AVE.	Single family dwelling, bought in 2003, no equipment stored or use	Rainwater pools in backyard
839752	SCOTT, SEYMORE AND HARRIET H.	5725 OAKWOOD DR	BATON ROUGE LA 70811	Null	N/A	
871931	FIERO PROPERTIES, L.L.C.	1111 S FOSTER DR STE C	BATON ROUGE LA 70806	2265 CHRISTIAN ST.	2,000 sq. foot freestanding neighborhood office	Home office
875716	THOMAS, BEN 1/2, LALA DAVIS HILL 1/2	1365 BELLONIA DR.	BATON ROUGE LA 70810	1824 KENTUCKY ST.	Residence	
917729	JORDAN, AUDREY WOODS	2010 EVANS AVE.	MONROE LA 71202	1321 E. WASHINGTON ST.	Single-family brick home	
2391821	CHURCHES - CHRISTIAN BIBLE COLLEGE	720 SOUTH BLVD.	BATON ROUGE LA 70802	Null	Church building with classroom	
2466465	SOILEAU, KATHERINE M.	2301 FIERO ST	BATON ROUGE LA 70808	2301 FIERO ST.	Residential condo, no equipment stored, purchased in 2013	
2466546	BROWN, WAYNE & ELLEN D. BROWN	8610 GLEN HAVEN DR.	SHREVEPORT LA 71106	2302 FIERO ST.	N/A	
2466562	TARVER, CRAIG & NANCY SHEPPARD	2305 FIERO ST. #C	BATON ROUGE LA 70808	2305 FIERO ST.	2,250 sq. foot dwelling with garage	
3015920	LEDUFF, LUCIEN, JR., 7/8 & ELMELDA	996 TERRACE AVE.	BATON ROUGE LA 70802	7158 GLEN OAKS DR.	N/A	
304510002800	KHUSHI INVESTMENTS I LLC	2880 N WESTPORT DR	PORT ALLEN LA 70767-0000	2860 N WESTPORT DR	4-story limited service hotel	
304510002802	J.L. ASSOCIATES LLC	2880 N WESTPORT DR	PORT ALLEN LA 70767	2880 N WESTPORT DR	3-story building, limited service hotel	
304519003600	WEST BATON ROUGE TOURIST COMMISSION	P O BOX 757	PORT ALLEN LA 70767	2750 N WESTPORT DR	Site of West Baton Rouge Tourist Commission, one main building, one accessory building, parking area, activity lawn with a walking path	Has zoning and local land use controls
305200009000	BOULANGER PROPERTIES LLC	2811 SARPY AVE	BATON ROUGE LA 70820	2421 COMMERCIAL DR	4.6 Acres, Open Land, Hay field	
305200008800	OLINDE HARDWARE & SUPPLY CO LLC	9536 AIRLINE HWY	BATON ROUGE LA 70815-0000	COMMERCIAL DR	Vacant land	Phase I ESA conducted in May 2006, no RECs
688398	LE, BIEN K.	2935 PERKINS RD.	BATON ROUGE LA 70808	2935 PERKINS RD.	Retail and services	
817597	RIDEAUX, JUDY MARIE; SHIRLEY ANN	7008 LAKELAND DR.	ZACHARY LA 70791	2729 VALLEY ST	Vacant (since 2005) residential lot	Septic Tank
2212250	IBERIA BANK	601 POYDRAS ST., #2075	NEW ORLEANS LA 70130	3555 PERKINS RD.	Office building, currently a bank	
14001	CHURCHES - NEW ST. LUKE BAPTIST	538 SOUTH BLVD.	BATON ROUGE LA 70802	916 MONROVIA	Currently a church, former museum	
428086	CIRCLE K STORES INC	P O BOX 12653	BATON ROUGE LA 70808	2300 S. ACADIAN THWY	Gas Station	LDEQ AI # 71560, active UST fuel system, previous spills, NFA in 2013
702218	CIRCLE K STORES INC	221 PINE ST 4TH FLOOR	BATON ROUGE LA 70808	2959 COLLEGE DR	Gas Station	LDEQ AI # 13684, active UST fuel system, new release is pending - benzene in groundwater
641332	HALL, MAMYE LYNN, L.L.C.	PO BOX 14001	BATON ROUGE LA 70898	1208 E. WASHINGTON ST.	Residence	
641340	HALL, MAMYE LYNN, L.L.C.	PO BOX 14001	BATON ROUGE LA 70898	Null	Billboard	
43044	WHITE, CHAVON DANIELA DESORMES	1123 TERRACE AVE.	BATON ROUGE LA 70802	1123 TERRACE AVE.	Residence, in home daycare	

*** Received 2 completed Forms from Circle K Stores, Inc, one on College Drive, and one located on Acadian Thwy.

*** Received 1 response that could not be recorded because it did not have an address listed

PHASE I ENVIRONMENTAL SITE ASSESSMENT
USER QUESTIONNAIRE

DATE OF COMPLETION: 9/11/2017

USER/USER REPRESENTATIVE NAME/ RELATION: Robert Lott / DOTD Environmental Section

ADDRESS: PO Box 94245 (STREET) Baton Rouge (CITY) LA (STATE) 70804 (ZIP)

PHONE: (225) 242-4505 EMAIL: Robert.Lott@la.gov

QUESTIONNAIRE:

1. Are there any environmental liens filed or recorded against the subject property? (Y/N) If yes, please explain.

   Unknown

2. Are there any activity and use limitations that are in place on the subject property or that have been filed or recorded against the subject property? (Y/N) If yes, please explain.

   Unknown

3. Do you have any specialized knowledge or experience related to the subject property or nearby properties? (Y/N) If yes, please explain.

   No

4. Are you aware of commonly known or reasonably ascertainable information about the subject property that would help the environmental professional identify conditions indicative of releases or threatened releases? (Y/N) If yes, please explain.

   No

5. Does the purchase price reasonably reflect the fair market value of the property? If not, have you considered whether the lower purchase price is because contamination is known or believed to be present at the property? (Y/N)

   Yes

6. Based on your knowledge and experience related to the subject property, are there any obvious indicators that point to the presence or likely presence of releases at the property?(Y/N)

   No

APPENDIX C

EDR REGULATORY DATABASE SEARCH

EDR DataMap®
Corridor Study

I-10 Right of Way



EDR® Environmental Data Resources, Inc

Copyright © 2017 EDR, Inc. © 2015 TomTom Rel. 2015.

4970821.2s - 19 Jun 17

I-10 Right of Way
Baton Rouge, LA 70802

Inquiry Number: 4970821.2s
June 19, 2017

EDR DataMap™ Corridor Study

6 Armstrong Road, 4th floor
Shelton, CT 06484
Toll Free: 800.352.0050
www.edrnet.com

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer - Copyright and Trademark Notice

This Report contains certain information obtained from a variety of public and other sources reasonably available to Environmental Data Resources, Inc. It cannot be concluded from this Report that coverage information for the target and surrounding properties does not exist from other sources. **NO WARRANTY EXPRESSED OR IMPLIED, IS MADE WHATSOEVER IN CONNECTION WITH THIS REPORT. ENVIRONMENTAL DATA RESOURCES, INC. SPECIFICALLY DISCLAIMS THE MAKING OF ANY SUCH WARRANTIES, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE OR PURPOSE. ALL RISK IS ASSUMED BY THE USER. IN NO EVENT SHALL ENVIRONMENTAL DATA RESOURCES, INC. BE LIABLE TO ANYONE, WHETHER ARISING OUT OF ERRORS OR OMISSIONS, NEGLIGENCE, ACCIDENT OR ANY OTHER CAUSE, FOR ANY LOSS OF DAMAGE, INCLUDING, WITHOUT LIMITATION, SPECIAL, INCIDENTAL, CONSEQUENTIAL, OR EXEMPLARY DAMAGES. ANY LIABILITY ON THE PART OF ENVIRONMENTAL DATA RESOURCES, INC. IS STRICTLY LIMITED TO A REFUND OF THE AMOUNT PAID FOR THIS REPORT.** Purchaser accepts this Report "AS IS". Any analyses, estimates, ratings, environmental risk levels or risk codes provided in this Report are provided for illustrative purposes only, and are not intended to provide, nor should they be interpreted as providing any facts regarding, or prediction or forecast of, any environmental risk for any property. Only a Phase I Environmental Site Assessment performed by an environmental professional can provide information regarding the environmental risk for any property. Additionally, the information provided in this Report is not to be construed as legal advice.

Copyright 2017 by Environmental Data Resources, Inc. All rights reserved. Reproduction in any media or format, in whole or in part, of any report or map of Environmental Data Resources, Inc., or its affiliates, is prohibited without prior written permission.

EDR and its logos (including Sanborn and Sanborn Map) are trademarks of Environmental Data Resources, Inc. or its affiliates. All other trademarks used herein are the property of their respective owners.

EXECUTIVE SUMMARY

TARGET PROPERTY INFORMATION

ADDRESS

BATON ROUGE, LA 70802
BATON ROUGE, LA 70802

DATABASES WITH NO MAPPED SITES

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records within the requested search area for the following databases:

FEDERAL RECORDS

NPL	National Priority List
Proposed NPL	Proposed National Priority List Sites
Delisted NPL	National Priority List Deletions
NPL LIENS	Federal Superfund Liens
CORRACTS	Corrective Action Report
RCRA-TSDF	RCRA - Treatment, Storage and Disposal
US ENG CONTROLS	Engineering Controls Sites List
US INST CONTROL	Sites with Institutional Controls
HMIRS	Hazardous Materials Information Reporting System
DOT OPS	Incident and Accident Data
US CDL	National Clandestine Laboratory Register
DOD	Department of Defense Sites
FUDS	Formerly Used Defense Sites
LUCIS	Land Use Control Information System
CONSENT	Superfund (CERCLA) Consent Decrees
ROD	Records Of Decision
UMTRA	Uranium Mill Tailings Sites
ODI	Open Dump Inventory
DEBRIS REGION 9	Torres Martinez Reservation Illegal Dump Site Locations
US MINES	Mines Master Index File
FTTS	FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)
HIST FTTS	FIFRA/TSCA Tracking System Administrative Case Listing
SSTS	Section 7 Tracking Systems
PADS	PCB Activity Database System
MLTS	Material Licensing Tracking System
RADINFO	Radiation Information Database
RAATS	RCRA Administrative Action Tracking System
RMP	Risk Management Plans
COAL ASH EPA	Coal Combustion Residues Surface Impoundments List
LEAD SMELTERS	Lead Smelter Sites
FEDERAL FACILITY	Federal Facility Site Information listing
FEMA UST	Underground Storage Tank Listing
FUELS PROGRAM	EPA Fuels Program Registered Listing
DOCKET HWC	Hazardous Waste Compliance Docket Listing

EXECUTIVE SUMMARY

UXO..... Unexploded Ordnance Sites
FUSRAP..... Formerly Utilized Sites Remedial Action Program
COAL ASH DOE..... Steam-Electric Plant Operation Data
2020 COR ACTION..... 2020 Corrective Action Program List
EPA WATCH LIST..... EPA WATCH LIST
US FIN ASSUR..... Financial Assurance Information
PCB TRANSFORMER..... PCB Transformer Registration Database
US HIST CDL..... Delisted National Clandestine Laboratory Register
SCRD DRYCLEANERS..... State Coalition for Remediation of Drycleaners Listing
IHS OPEN DUMPS..... Open Dumps on Indian Land
ABANDONED MINES..... Abandoned Mines

STATE AND LOCAL RECORDS

LA HIST DEBRIS..... LDEQ Approved Debris Sites
LA UIC..... Underground Injection Wells Listing
LA LIENS..... Environmental Liens
LA CDL..... Clandestine Drug Lab
LA COAL ASH..... Coal Ash Disposal Sites

TRIBAL RECORDS

INDIAN RESERV..... Indian Reservations
INDIAN ODI..... Report on the Status of Open Dumps on Indian Lands
INDIAN LUST..... Leaking Underground Storage Tanks on Indian Land
INDIAN UST..... Underground Storage Tanks on Indian Land
INDIAN VCP..... Voluntary Cleanup Priority Listing

EDR PROPRIETARY RECORDS

LA RGA HWS..... Recovered Government Archive State Hazardous Waste Facilities List

SURROUNDING SITES: SEARCH RESULTS

Surrounding sites were identified.

Page numbers and map identification numbers refer to the EDR Radius Map report where detailed data on individual sites can be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

Unmappable (orphan) sites are not considered in the foregoing analysis.

FEDERAL RECORDS

SEMS: SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the SEMS list, as provided by EDR, and dated 02/07/2017 has revealed that there are 3

SEMS sites within the searched area.

Site	Address	Map ID	Page
DEVIL'S LAKE	***HWY 61***	***4***	***177***
CLEARWATER FLUIDS RE	***1001 SOUTH FIRST ST.***	***17***	***364***
MCKINLEY HIGH SCHOOL	800 E. MCKINLEY STRE	33	573

SEMS-ARCHIVE: SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

A review of the SEMS-ARCHIVE list, as provided by EDR, and dated 02/07/2017 has revealed that there are 3 SEMS-ARCHIVE sites within the searched area.

Site	Address	Map ID	Page
GILMAR MARINE SERVIC	1500 RIVER ROADS,	17	339
VALLEY PARK SCHOOL	4510 BAWELL ST.	23	465
2011 MISSISSIPPI RIV	10930 HWY 67	29	567

LIENS 2: A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

A review of the LIENS 2 list, as provided by EDR, and dated 02/18/2014 has revealed that there is 1 LIENS 2 site within the searched area.

Site	Address	Map ID	Page
CLEARWATER FLUIDS RE	***1001 SOUTH FIRST ST.***	***17***	***364***

RCRA-LQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

A review of the RCRA-LQG list, as provided by EDR, and dated 12/12/2016 has revealed that there are 2 RCRA-LQG sites within the searched area.

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
AIRGAS SPECIALTY GAS	1075 CINCLARE DRIVE	9	232
EBR CITY PARISH PROP	600 OKLAHOMA ST	17	339

RCRA-SQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

A review of the RCRA-SQG list, as provided by EDR, and dated 12/12/2016 has revealed that there are 16 RCRA-SQG sites within the searched area.

Site	Address	Map ID	Page
WEST BATON ROUGE PAR	553A LOBDELL HWY	3	57
BONNIE & CLYDE WAREH	***711 S 14TH ST***	***4***	***100***
LA DEPT OF REVENUE L	***617 N THIRD ST***	***4***	***150***
SIMPSONS SVC CTR INC	1225 NORTH BLVD	4	152
CAJUN VALVE SERVICES	1605 COMMERCIAL DR	9	245
BP LUBRICANTS USA IN	***1981 S WESTPORT DR***	***15***	***313***
LOVE'S TRAVEL STOP 2	***751 LOBDELL EXT S***	***16***	***332***
FRANKLIN PRESS INC	***1391 HIGHLAND RD***	***17***	***346***
LA VOTECH JAMES M FR	***555 JULIA ST***	***17***	***369***
CVS PHARMACY	3651 PERKINS RD	24	472
EXXON CO USA 51052	***3191 S ACADIAN HWY***	***24***	***488***
BONE & JOINT CLINIC	***5630 BANKERS AVE***	***27***	***563***
WALMART SUPERCENTER	3132 COLLEGE DR	34	600
STAR ENT	***2959 COLLEGE DR***	***34***	***613***
SAGE REHABILITATION	***8000 SUMMA AVENUE***	***42***	***723***
MARY BIRD PERKINS CA	***4950 ESSEN LANE***	***42***	***759***

RCRA-CESQG: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

A review of the RCRA-CESQG list, as provided by EDR, and dated 12/12/2016 has revealed that there are 67 RCRA-CESQG sites within the searched area.

Site	Address	Map ID	Page
WALMART STORE #1136	***2808 COURT ST***	***3***	***40***
REDDY ICE #335	1140 MYRTLE	4	87
ENTERGY CORPORATION	***1509 GOVERNMENT***	***4***	***121***
MACS BODY SHOP	***1244 N BLVD***	***4***	***139***
USPS VEHICLE MAINTEN	899 CONVENTION ST	4	159
QUIK PRINT	***638 FLORIDA ST***	***4***	***161***
USPS BATON ROUGE VMF	***750 FLORIDA ST***	***4***	***162***
BATON ROUGE FIRE DEP	***1100 LAUREL ST***	***4***	***181***
LUNDIN ROOFING CO IN	***1301 COMMERCIAL DR***	***9***	***249***

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
SOUTHWEST STAINLESS	1510 COMMERCIAL DR	9	251
MALLINCKRODT MANF LL	***1060 ALLENDALE DR***	***9***	***254***
UNITED PARCEL SVC	***1111 COMERICAL DR***	***13***	***282***
LHOIST NORTH AMERICA	***1785 S WESTPORT DR***	***15***	***298***
NUGENT STEEL & SUPPL	***1800 S WESTPORT DR***	***15***	***310***
GRAHAM PACKAGING CO	1981B S WESTPORT DR	15	312
DIVISION OF ADMIN ST	***950 BRICKYARD LN***	***17***	***372***
BATON ROUGE POLICE D	***704 MAYFLOWER RM 205***	***17***	***378***
LUNAR GRAPHICS INC	***655 ST FERDINAND***	***17***	***380***
RICHARDS PRINTING	***603 ST CHARLES ST***	***17***	***381***
COMPLETE AUTO TRANSI	***1300 LEBLANC RD STE***	***18***	***432***
ALLIED SYSTEMS LTD	***1300 LEBLANC RD***	***18***	***434***
INTERNATIONAL PIPING	***1700 S WESTPORT DR***	***19***	***435***
SOUTHERN RECYCLING L	***1367 MAHAFFEY RD***	***20***	***440***
BRAND SCAFFOLE SVCS	***946 MAHAFFEY RD***	***20***	***446***
COMMUNITY COFFEE INC	1833 HWY 1 S	21	448
DISTRIBUTION INTERNA	950 MAHAFFEY RD	21	452
GORDON & SANDIFER AU	***3825 PERKINS RD***	***24***	***468***
CITY PARISH DEPT OF	***3075 VALLEY***	***24***	***475***
MIDAS MUFFLER SHOP	***2358 COLLEGE***	***25***	***541***
A FAMILY DENTAL CARE	***4616 CONCORD AVE***	***34***	***588***
PRINTING TECH OF BAT	***3112 F COLLEGE DR***	***34***	***589***
PETCO STORE 1580	***3535 PERKINS RD, STE***	***34***	***592***
COLORTEC IMAGING INC	***3084 COLLEGE DR***	***34***	***611***
ALBERTSONS 2709	***2950 COLLEGE DR***	***34***	***625***
CHEVRON #109060	***2929 COLLEGE DR***	***34***	***632***
RONALD D LANDRY DDS	***2726 CONTINENTAL DR***	***36***	***636***
PARKWAY LIMITED PART	***2726 CONTINENTAL DR***	***36***	***637***
THOMAS J KIEBACH DDS	***2726 CONTINENTAL DR***	***36***	***639***
CONNELLY PRESS & COP	***8737 JEFFERSON HWY***	***38***	***659***
REHABILITATION HOSPI	***8595 UNITED PLAZA BL***	***41***	***672***
LA SECRETARY OF STAT	***3851 ESSEN LN***	***41***	***678***
RITE AID 7318	***2159 STARING LN***	***42***	***682***
BR VA OUTPATIENT CLI	7850 ANSELMO LANE	42	687
EXXON CO 56174	***5857 ESSEN LN***	***42***	***689***
ALBERTSONS 2711	***7515 PERKINS RD***	***42***	***696***
MED AID WALK IN MEDI	***5475 ESSEN LANE***	***42***	***705***
BATON ROUGE CLINIC	7373 PERKINS RD	42	707
DIGITAL DIAGNOSTIC C	***7703 PICARDY AVE***	***42***	***708***
WILLIAM A COUVILLION	***7612 PICARDY SUITE C***	***42***	***710***
KATHY M WOODY DDS	***7612 PICARDY AVE STE***	***42***	***711***
ORTHOPAEDIC SURGERY	***5408 FLANDERS DR.***	***42***	***713***
BATON ROUGE CLINIC	***5304 FLANDERS DR***	***42***	***714***
DRS BRYAN HATCHER VI	5345 BRITTANY DR	42	716
DRS BRYAN HATCHER VI	***5345 BRITTANY DR***	***42***	***717***
DRS WALL TOWNS & HOR	***5227 FLANDERS DR***	***42***	***720***
KIRBY PERRY DDS LLC	***5211 ESSEN LN STE 5***	***42***	***721***
STEPHEN L SHERMAN DD	***7922 SUMMA STE A3***	***42***	***726***
WALGREEN DRUG STORE	***5112 ESSEN LN***	***42***	***731***
BATON ROUGE CARDIOLO	***5231 BRITTANY DR***	***42***	***734***
SURGI CTR OF BATON R	***5222 BRITTANY DR***	***42***	***736***
NEURO MEDICAL CENTER	***7777 HENNESSY STE 10***	***42***	***742***
BATON ROUGE UROLOGY	7777 HENNESSY BLVD,	42	743
CHARLIE H BRIDGES MD	***7777 HENNESSY BLVD S***	***42***	***745***
EYE SURGERY CENTER L	***7777 HENNESSY BLVD,***	***42***	***747***
JACOBS PLAZA	***4949 ESSEN LN***	***42***	***756***

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
BATON ROUGE VA OUTPA	7968 ESSEN PARK AVE	42	760
NATIONAL TIRE & BATT	***4675 ESSEN LN***	***42***	***764***

RCRA NonGen / NLR: RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

A review of the RCRA NonGen / NLR list, as provided by EDR, and dated 12/12/2016 has revealed that there are 40 RCRA NonGen / NLR sites within the searched area.

Site	Address	Map ID	Page
QUALITY CARRIERS INC	420 LOBDELL HWY	3	52
ERRANDS AIR EXPRESS	***956 S 15TH ST***	***4***	***95***
E HAYES TRUCKING INC	***225 EDDIE ROBINSON D***	***4***	***133***
LA DOA LPAA	***125 S 14TH ST***	***4***	***134***
ECONOMY CAR CARE CNT	1350 NORTH BLVD	4	141
AMERICAN CATALYST SE	***4545 SCALLAN RD***	***5***	***198***
OHM CORPORATION PORT	***1090 CINCLARE DR***	***9***	***230***
ROLLINS LEASING CORP	***1585 COMMERCIAL DR***	***9***	***243***
BOWMAN TRANSPORTATIO	***770 ALLENDALE DR***	***9***	***256***
TSD REMEDIAL SVC COR	***1780 COMMERCIAL DR***	***11***	***267***
GROENDYKE TRANSPORT	***2723 S WESTPORT DR***	***12***	***269***
CHEM RAIL TRANSPORTI	***1001 BRICKYARD LN***	***17***	***371***
ILLINOIS CTRL GULF R	***111 FRANCIS ST***	***17***	***388***
IT CORP	***1150 LEBLANC RD***	***18***	***426***
ANCO SHEET METAL	950 MAHAFFEY RD BLDG	21	451
BRIDGES PEST CONTROL	***2169 MYRTLEDALE AVE***	***24***	***471***
ACADIAN INTERSTATE M	***3192 S ACADIAN***	***24***	***491***
STAR ENT	***3375 PERKINS RD***	***24***	***501***
LILLS CAR CARE	***3155 PERKINS RD***	***24***	***515***
PERKINS ROAD HARDWAR	3043 PERKINS RD	24	526
CONFEDERATE MOTOR WO	***2311 CHRISTIAN ST***	***24***	***533***
NEUROMEDICAL CTR	***2237 S ACADIAN STE 4***	***26***	***555***
AMERICAN CATALYST SV	***4884 CONSTITUTION SU***	***27***	***557***
C & R ENVIRONMENTAL	***5555 HILTON AVE STE***	***27***	***559***
CHURCHILL ENVIRONMEN	***5420 CORPORATE BLVD***	***27***	***560***
COMMERCIAL PROPERTIE	***3535 PERKINS RD***	***34***	***594***
PARKLAND HOSPITAL	***2414 BUNKER HILL DR***	***37***	***640***
SOUTHERN ENVIRONMENT	***8922 JEFFERSON HWY***	***38***	***644***
TUNE UP 2 INC	***8859 JEFFERSON HWY***	***38***	***649***
JEFFERSON ANIMAL HOS	8774 JEFFERSON HWY	38	651
KADAIRS CAMERA AUDIO	***5713 ESSEN LN***	***42***	***699***
RAPID LUBE & TUNE UP	***5615 ESSEN LN***	***42***	***701***
KWIK KOPY PRINTING	5555 ESSEN LN STE B	42	704
HANSBROUGH PETERS AM	***5344 BRITTANY DR***	***42***	***728***
LLOYD PAUL CHAMPAGNE	***5131 ESSEN LN***	***42***	***730***
PULMONARY DISEASE CL	***7777 HENNESSY STE 70***	***42***	***750***
LYNN J PHILIPPE	7777 HENNESSY BLVD S	42	752
DRS BRAUD & BREAUX M	***7777 HENNESSY BLVD #***	***42***	***754***
GULF INTERCOASTAL MA	***8116 ONE CALAIS SUIT***	***42***	***768***
EXXONMOBIL OIL CORP	***4555 ESSEN LANE***	***42***	***779***

EXECUTIVE SUMMARY

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 09/26/2016 has revealed that there are 4 ERNS sites within the searched area.

Site	Address	Map ID	Page
Not reported	960 I-10 WEST	4	100
Not reported	1785 SOUTH WESTPORT	15	297
Not reported	1785 SOUTH WESTPORT	15	304
Not reported	1785 SOUTH WESTPORT	15	308

US BROWNFIELDS: The EPA's listing of Brownfields properties from the Cleanups in My Community program, which provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

A review of the US BROWNFIELDS list, as provided by EDR, and dated 03/02/2017 has revealed that there are 29 US BROWNFIELDS sites within the searched area.

Site	Address	Map ID	Page
BR 132 SPANISH TOWN	***SPANISH TOWN ROAD AT***	***2***	***4***
BR 149 HOPE VI 1533	***1533 THOMAS H DELPIT***	***4***	***71***
BR 147 HOPE VI JULIA	***V THOMAS H DELPIT DR***	***4***	***76***
BR 177 EBRRA LINCOLN	1305 MYRTLE WALK ADD	4	89
BR - 178 LINCOLN THE	***1305 MYRTLE WALK***	***4***	***92***
EBR-RDA GOVERNEMNT S	1509 GOVERNMENT STRE	4	108
BR 131 O'BRIEN HOUSE	***1217 LAUREL ST.***	***4***	***183***
BR 161 SPANISH TOWN	1104 MAIN ST. BETWEE	4	190
MAIN STREET USA, INC	***1201 MAIN STREET***	***4***	***193***
SPAIN STREET AT 19TH	***SPAIN STREET AT 19TH***	***8***	***225***
LOTS 8 & 9 SQUARE 6	***216 SOUTH 19TH STREE***	***8***	***228***
NICHOLSON DRIVE SHOP	1600 BLOCK, NICHOLSO	17	334
BR 169 OSBR DUANE &	***1349 DUANE STREET***	***17***	***340***
BR 166 OSBR TURKISH	***208 OKLAHOMA ST.***	***17***	***343***
PERSONAL TOUCH CAR W	1320 HIGHLAND ROAD	17	350
BATON ROUGE MUNICIPA	***1100 - 1300 RIVER RO***	***17***	***361***
CAPITAL PARK CDC BR1	***500 ST LOUIS ST***	***17***	***395***
5321 GREENWELL SPRIN	***500 ST LOUIS ST***	***17***	***398***
DEFRANCES MARBLE	***500 ST LOUIS ST***	***17***	***400***
HUE'S SEAFOOD	***500 ST LOUIS ST***	***17***	***403***
BROUSSARD PAINT	***500 ST LOUIS ST***	***17***	***406***
CAPITAL PARK CDC BR1	***500 ST LOUIS ST***	***17***	***408***
NOLAN LOUIS	***500 ST LOUIS ST***	***17***	***411***
DOC, INC.	***500 ST LOUIS ST***	***17***	***414***
VACANT BS/1/36-7	***500 ST LOUIS ST***	***17***	***416***
MAC'S BODY SHOP	***500 ST LOUIS ST***	***17***	***419***
C AND T CONTRACTORS	***500 ST LOUIS ST***	***17***	***422***
LOTS 14-19, C & 21 O	***1705 HIGHLAND ROAD***	***22***	***457***
1705 HIGHLAND ROAD	***1705 HIGHLAND ROAD***	***22***	***462***

EXECUTIVE SUMMARY

TRIS: The Toxic Chemical Release Inventory System identifies facilities that release toxic chemicals to the air, water, and land in reportable quantities under SARA Title III, Section 313. The source of this database is the U.S. EPA.

A review of the TRIS list, as provided by EDR, and dated 12/31/2014 has revealed that there is 1 TRIS site within the searched area.

Site	Address	Map ID	Page
BP LUBRICANTS USA IN	***1981 S WESTPORT DR***	***15***	***313***

TSCA: The Toxic Substances Control Act identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. The United States Environmental Protection Agency has no current plan to update and/or re-issue this database.

A review of the TSCA list, as provided by EDR, and dated 12/31/2012 has revealed that there are 2 TSCA sites within the searched area.

Site	Address	Map ID	Page
CHEMICAL LIME CO - P	1785 S. WESTPORT DRI	15	296
CHEMICAL LIME CO - P	1785 S. WESTPORT DRI	15	298

ICIS: The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

A review of the ICIS list, as provided by EDR, and dated 11/18/2016 has revealed that there are 7 ICIS sites within the searched area.

Site	Address	Map ID	Page
CASH'S CASINO, INC.	***420 LOBDELL HWY***	***3***	***53***
THE DOW CHEMICAL COM	PLAQUEMINES COGENERA	4	81
DEVIL'S LAKE	***HWY 61***	***4***	***177***
LHOIST NORTH AMERICA	***1785 S WESTPORT DR***	***15***	***298***
BP LUBRICANTS USA IN	***1981 S WESTPORT DR***	***15***	***313***
GROUNDWATER TECHNOLO	***2314 S ACADIAN THRWY***	***26***	***545***
JET 24 FOOD STORE #4	***2313 ACADIAN THRUWAY***	***26***	***551***

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 04/04/2017 has revealed that there are 138

EXECUTIVE SUMMARY

FINDS sites within the searched area.

Site	Address	Map ID	Page
BR 132 SPANISH TOWN	SPANISH TOWN ROAD AT	2	4
CASH'S CASINO, INC.	420 LOBDELL HWY	3	53
BR 149 HOPE VI 1533	1533 THOMAS H DELPIT	4	71
BR 147 HOPE VI JULIA	V THOMAS H DELPIT DR	4	76
SPRINGLAKE @ BLUEBON	HIGHLANDS SUBDIVISIO	4	82
TONY'S SEAFOOD	UNKNOWN	4	83
BRADY WILSON CONSTRU	NICHOLSON LAKES SUBD	4	83
GARDNER HOME BUILDER	NICHOLSON LAKES SUBD	4	84
ALPAN DEVELOPMENTS L	16248 WOODLAND TRAIL	4	84
TPT DEVELOPMENT LLC	NICHOLSON LAKES SUBD	4	85
BISHOP CONST. CO., I	NICHOLSON LAKES SUBD	4	85
KANEB PIPELINE OPERA	ERSHIP LB - STATEWID	4	86
BR - 178 LINCOLN THE	1305 MYRTLE WALK	4	92
ERRANDS AIR EXPRESS	956 S 15TH ST	4	95
BONNIE & CLYDE WAREH	711 S 14TH ST	4	100
ENTERGY CORPORATION	1509 GOVERNMENT	4	121
E HAYES TRUCKING INC	225 EDDIE ROBINSON D	4	133
LA DOA LPAA	125 S 14TH ST	4	134
MACS BODY SHOP	1244 N BLVD	4	139
LA DEPT OF REVENUE L	617 N THIRD ST	4	150
QUIK PRINT	638 FLORIDA ST	4	161
USPS BATON ROUGE VMF	750 FLORIDA ST	4	162
BATON ROUGE FIRE DEP	1100 LAUREL ST	4	181
BR 131 O'BRIEN HOUSE	1217 LAUREL ST.	4	183
MAIN STREET USA, INC	1201 MAIN STREET	4	193
AMERICAN CATALYST SE	4545 SCALLAN RD	5	198
SPAIN STREET AT 19TH	SPAIN STREET AT 19TH	8	225
LOTS 8 & 9 SQUARE 6	216 SOUTH 19TH STREE	8	228
OHM CORPORATION PORT	1090 CINCLARE DR	9	230
ROLLINS LEASING CORP	1585 COMMERCIAL DR	9	243
LUNDIN ROOFING CO IN	1301 COMMERCIAL DR	9	249
MALLINCKRODT MANF LL	1060 ALLENDALE DR	9	254
BOWMAN TRANSPORTATIO	770 ALLENDALE DR	9	256
LOUISIANA SCRAP META	2527 S. WESTPORT DR.	10	265
TSD REMEDIAL SVC COR	1780 COMMERCIAL DR	11	267
GROENDYKE TRANSPORT	2723 S WESTPORT DR	12	269
UNITED PARCEL SVC	1111 COMERICAL DR	13	282
PORTA BATCH LIME SRY	1785 SOUTH WESTPORT	15	296
LHOIST NORTH AMERICA	1785 S WESTPORT DR	15	298
CHEMICAL LIME CO OF	1785 S WESTPORT DR	15	308
NUGENT STEEL & SUPPL	1800 S WESTPORT DR	15	310
BP LUBRICANTS USA IN	1981 S WESTPORT DR	15	313
LOVE'S TRAVEL STOP 2	751 LOBDELL EXT S	16	332
BR 169 OSBR DUANE &	1349 DUANE STREET	17	340
BR 166 OSBR TURKISH	208 OKLAHOMA ST.	17	343
FRANKLIN PRESS INC	1391 HIGHLAND RD	17	346
BATON ROUGE MUNICIPA	1100 - 1300 RIVER RO	17	361
LA VOTECH JAMES M FR	555 JULIA ST	17	369
CHEM RAIL TRANSPORTI	1001 BRICKYARD LN	17	371
DIVISION OF ADMIN ST	950 BRICKYARD LN	17	372
BATON ROUGE POLICE D	704 MAYFLOWER RM 205	17	378
LUNAR GRAPHICS INC	655 ST FERDINAND	17	380
RICHARDS PRINTING	603 ST CHARLES ST	17	381
ILLINOIS CTRL GULF R	111 FRANCIS ST	17	388
CAPITAL PARK CDC BR1	500 ST LOUIS ST	17	395

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
5321 GREENWELL SPRIN	500 ST LOUIS ST	17	398
DEFRANCES MARBLE	500 ST LOUIS ST	17	400
HUE'S SEAFOOD	500 ST LOUIS ST	17	403
BROUSSARD PAINT	500 ST LOUIS ST	17	406
CAPITAL PARK CDC BR1	500 ST LOUIS ST	17	408
NOLAN LOUIS	500 ST LOUIS ST	17	411
DOC, INC.	500 ST LOUIS ST	17	414
VACANT BS/1/36-7	500 ST LOUIS ST	17	416
MAC'S BODY SHOP	500 ST LOUIS ST	17	419
C AND T CONTRACTORS	500 ST LOUIS ST	17	422
IT CORP	1150 LEBLANC RD	18	426
COMPLETE AUTO TRANSI	1300 LEBLANC RD STE	18	432
ALLIED SYSTEMS LTD	1300 LEBLANC RD	18	434
INTERNATIONAL PIPING	1700 S WESTPORT DR	19	435
SOUTHERN RECYCLING L	1367 MAHAFFEY RD	20	440
BRAND SCAFFOLE SVCS	946 MAHAFFEY RD	20	446
LOTS 14-19, C & 21 O	1705 HIGHLAND ROAD	22	457
1705 HIGHLAND ROAD	1705 HIGHLAND ROAD	22	462
GORDON & SANDIFER AU	3825 PERKINS RD	24	468
BRIDGES PEST CONTROL	2169 MYRTLEDALE AVE	24	471
CITY PARISH DEPT OF	3075 VALLEY	24	475
EXXON CO USA 51052	3191 S ACADIAN HWY	24	488
ACADIAN INTERSTATE M	3192 S ACADIAN	24	491
STAR ENT	3375 PERKINS RD	24	501
LILLS CAR CARE	3155 PERKINS RD	24	515
CONFEDERATE MOTOR WO	2311 CHRISTIAN ST	24	533
MIDAS MUFFLER SHOP	2358 COLLEGE	25	541
GROUNDWATER TECHNOLO	2314 S ACADIAN THRWY	26	545
JET 24 FOOD STORE #4	2313 ACADIAN THRUWAY	26	551
NEUROMEDICAL CTR	2237 S ACADIAN STE 4	26	555
AMERICAN CATALYST SV	4884 CONSTITUTION SU	27	557
C & R ENVIRONMENTAL	5555 HILTON AVE STE	27	559
CHURCHILL ENVIRONMEN	5420 CORPORATE BLVD	27	560
BONE & JOINT CLINIC	5630 BANKERS AVE	27	563
LAKES @ CARRIAGEWOOD	ESTATES	30	567
A FAMILY DENTAL CARE	4616 CONCORD AVE	34	588
PRINTING TECH OF BAT	3112 F COLLEGE DR	34	589
PETCO STORE 1580	3535 PERKINS RD, STE	34	592
COMMERCIAL PROPERTIE	3535 PERKINS RD	34	594
COLORTEC IMAGING INC	3084 COLLEGE DR	34	611
STAR ENT	2959 COLLEGE DR	34	613
ALBERTSONS 2709	2950 COLLEGE DR	34	625
CHEVRON #109060	2929 COLLEGE DR	34	632
RONALD D LANDRY DDS	2726 CONTINENTAL DR	36	636
PARKWAY LIMITED PART	2726 CONTINENTAL DR	36	637
THOMAS J KIEBACH DDS	2726 CONTINENTAL DR	36	639
PARKLAND HOSPITAL	2414 BUNKER HILL DR	37	640
SOUTHERN ENVIRONMENT	8922 JEFFERSON HWY	38	644
TUNE UP 2 INC	8859 JEFFERSON HWY	38	649
CONNELLY PRESS & COP	8737 JEFFERSON HWY	38	659
TOWNHOMES OF SHERWOO	FOREST	39	666
REHABILITATION HOSPI	8595 UNITED PLAZA BL	41	672
LA SECRETARY OF STAT	3851 ESSEN LN	41	678
RITE AID 7318	2159 STARING LN	42	682
EXXON CO 56174	5857 ESSEN LN	42	689
ALBERTSONS 2711	7515 PERKINS RD	42	696

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
KADAIRS CAMERA AUDIO	*5713 ESSEN LN*	*42*	*699*
RAPID LUBE & TUNE UP	*5615 ESSEN LN*	*42*	*701*
MED AID WALK IN MEDI	*5475 ESSEN LANE*	*42*	*705*
DIGITAL DIAGNOSTIC C	*7703 PICARDY AVE*	*42*	*708*
WILLIAM A COUVILLION	*7612 PICARDY SUITE C*	*42*	*710*
KATHY M WOODY DDS	*7612 PICARDY AVE STE*	*42*	*711*
ORTHOPAEDIC SURGERY	*5408 FLANDERS DR.*	*42*	*713*
BATON ROUGE CLINIC	*5304 FLANDERS DR*	*42*	*714*
DRS BRYAN HATCHER VI	*5345 BRITTANY DR*	*42*	*717*
DRS WALL TOWNS & HOR	*5227 FLANDERS DR*	*42*	*720*
KIRBY PERRY DDS LLC	*5211 ESSEN LN STE 5*	*42*	*721*
SAGE REHABILITATION	*8000 SUMMA AVENUE*	*42*	*723*
STEPHEN L SHERMAN DD	*7922 SUMMA STE A3*	*42*	*726*
HANSBROUGH PETERS AM	*5344 BRITTANY DR*	*42*	*728*
LLOYD PAUL CHAMPAGNE	*5131 ESSEN LN*	*42*	*730*
WALGREEN DRUG STORE	*5112 ESSEN LN*	*42*	*731*
BATON ROUGE CARDIOLO	*5231 BRITTANY DR*	*42*	*734*
SURGI CTR OF BATON R	*5222 BRITTANY DR*	*42*	*736*
NEURO MEDICAL CENTER	*7777 HENNESSY STE 10*	*42*	*742*
CHARLIE H BRIDGES MD	*7777 HENNESSY BLVD S*	*42*	*745*
EYE SURGERY CENTER L	*7777 HENNESSY BLVD,*	*42*	*747*
PULMONARY DISEASE CL	*7777 HENNESSY STE 70*	*42*	*750*
DRS BRAUD & BREAUX M	*7777 HENNESSY BLVD #*	*42*	*754*
JACOBS PLAZA	*4949 ESSEN LN*	*42*	*756*
MARY BIRD PERKINS CA	*4950 ESSEN LANE*	*42*	*759*
GULF INTERCOASTAL MA	*8116 ONE CALAIS SUIT*	*42*	*768*
EXXONMOBIL OIL CORP	*4555 ESSEN LANE*	*42*	*779*

US AIRS: The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

A review of the US AIRS list, as provided by EDR, has revealed that there are 3 US AIRS sites within the searched area.

Site	Address	Map ID	Page
GROENDYKE TRANSPORT	*2723 S WESTPORT DR*	*12*	*269*
Database: US AIRS MINOR, Date of Government Version: 10/12/2016			
LHOIST NORTH AMERICA	*1785 S WESTPORT DR*	*15*	*298*
Database: US AIRS MINOR, Date of Government Version: 10/12/2016			
BP LUBRICANTS USA IN	*1981 S WESTPORT DR*	*15*	*313*
Database: US AIRS MINOR, Date of Government Version: 10/12/2016			

EXECUTIVE SUMMARY

ECHO: ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

A review of the ECHO list, as provided by EDR, and dated 03/19/2017 has revealed that there are 113 ECHO sites within the searched area.

Site	Address	Map ID	Page
CASH'S CASINO, INC.	*420 LOBDELL HWY*	*3*	*53*
SPRINGLAKE @ BLUEBON	*HIGHLANDS SUBDIVISIO*	*4*	*82*
TONY'S SEAFOOD	*UNKNOWN*	*4*	*83*
BRADY WILSON CONSTRU	*NICHOLSON LAKES SUBD*	*4*	*83*
GARDNER HOME BUILDER	*NICHOLSON LAKES SUBD*	*4*	*84*
ALPAN DEVELOPMENTS L	*16248 WOODLAND TRAIL*	*4*	*84*
TPT DEVELOPMENT LLC	*NICHOLSON LAKES SUBD*	*4*	*85*
BISHOP CONST. CO., I	*NICHOLSON LAKES SUBD*	*4*	*85*
KANEB PIPELINE OPERA	*ERSHIP LB - STATEWID*	*4*	*86*
ERRANDS AIR EXPRESS	*956 S 15TH ST*	*4*	*95*
BONNIE & CLYDE WAREH	*711 S 14TH ST*	*4*	*100*
ENTERGY CORPORATION	*1509 GOVERNMENT*	*4*	*121*
E HAYES TRUCKING INC	*225 EDDIE ROBINSON D*	*4*	*133*
LA DOA LPAA	*125 S 14TH ST*	*4*	*134*
MACS BODY SHOP	*1244 N BLVD*	*4*	*139*
LA DEPT OF REVENUE L	*617 N THIRD ST*	*4*	*150*
QUIK PRINT	*638 FLORIDA ST*	*4*	*161*
USPS BATON ROUGE VMF	*750 FLORIDA ST*	*4*	*162*
BATON ROUGE FIRE DEP	*1100 LAUREL ST*	*4*	*181*
AMERICAN CATALYST SE	*4545 SCALLAN RD*	*5*	*198*
OHM CORPORATION PORT	*1090 CINCLARE DR*	*9*	*230*
ROLLINS LEASING CORP	*1585 COMMERCIAL DR*	*9*	*243*
LUNDIN ROOFING CO IN	*1301 COMMERCIAL DR*	*9*	*249*
MALLINCKRODT MANF LL	*1060 ALLENDALE DR*	*9*	*254*
BOWMAN TRANSPORTATIO	*770 ALLENDALE DR*	*9*	*256*
LOUISIANA SCRAP META	*2527 S. WESTPORT DR.*	*10*	*265*
TSD REMEDIAL SVC COR	*1780 COMMERCIAL DR*	*11*	*267*
GROENDYKE TRANSPORT	*2723 S WESTPORT DR*	*12*	*269*
UNITED PARCEL SVC	*1111 COMERICAL DR*	*13*	*282*
PORTA BATCH LIME SRY	*1785 SOUTH WESTPORT*	*15*	*296*
LHOIST NORTH AMERICA	*1785 S WESTPORT DR*	*15*	*298*
NUGENT STEEL & SUPPL	*1800 S WESTPORT DR*	*15*	*310*
BP LUBRICANTS USA IN	*1981 S WESTPORT DR*	*15*	*313*
LOVE'S TRAVEL STOP 2	*751 LOBDELL EXT S*	*16*	*332*
FRANKLIN PRESS INC	*1391 HIGHLAND RD*	*17*	*346*
LA VOTECH JAMES M FR	*555 JULIA ST*	*17*	*369*
CHEM RAIL TRANSPORTI	*1001 BRICKYARD LN*	*17*	*371*
DIVISION OF ADMIN ST	*950 BRICKYARD LN*	*17*	*372*
BATON ROUGE POLICE D	*704 MAYFLOWER RM 205*	*17*	*378*
LUNAR GRAPHICS INC	*655 ST FERDINAND*	*17*	*380*
RICHARDS PRINTING	*603 ST CHARLES ST*	*17*	*381*
ILLINOIS CTRL GULF R	*111 FRANCIS ST*	*17*	*388*
IT CORP	*1150 LEBLANC RD*	*18*	*426*
COMPLETE AUTO TRANSI	*1300 LEBLANC RD STE*	*18*	*432*
ALLIED SYSTEMS LTD	*1300 LEBLANC RD*	*18*	*434*
INTERNATIONAL PIPING	*1700 S WESTPORT DR*	*19*	*435*
SOUTHERN RECYCLING L	*1367 MAHAFFEY RD*	*20*	*440*
BRAND SCAFFOLE SVCS	*946 MAHAFFEY RD*	*20*	*446*
GORDON & SANDIFER AU	*3825 PERKINS RD*	*24*	*468*
BRIDGES PEST CONTROL	*2169 MYRTLEDALE AVE*	*24*	*471*
CITY PARISH DEPT OF	*3075 VALLEY*	*24*	*475*

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
EXXON CO USA 51052	3191 S ACADIAN HWY	24	488
ACADIAN INTERSTATE M	3192 S ACADIAN	24	491
STAR ENT	3375 PERKINS RD	24	501
LILLS CAR CARE	3155 PERKINS RD	24	515
CONFEDERATE MOTOR WO	2311 CHRISTIAN ST	24	533
MIDAS MUFFLER SHOP	2358 COLLEGE	25	541
GROUNDWATER TECHNOLO	2314 S ACADIAN THRWY	26	545
JET 24 FOOD STORE #4	2313 ACADIAN THRUWAY	26	551
NEUROMEDICAL CTR	2237 S ACADIAN STE 4	26	555
AMERICAN CATALYST SV	4884 CONSTITUTION SU	27	557
C & R ENVIRONMENTAL	5555 HILTON AVE STE	27	559
CHURCHILL ENVIRONMEN	5420 CORPORATE BLVD	27	560
BONE & JOINT CLINIC	5630 BANKERS AVE	27	563
LAKES @ CARRIAGEWOOD	ESTATES	30	567
A FAMILY DENTAL CARE	4616 CONCORD AVE	34	588
PRINTING TECH OF BAT	3112 F COLLEGE DR	34	589
PETCO STORE 1580	3535 PERKINS RD, STE	34	592
COMMERCIAL PROPERTIE	3535 PERKINS RD	34	594
COLORTEC IMAGING INC	3084 COLLEGE DR	34	611
STAR ENT	2959 COLLEGE DR	34	613
ALBERTSONS 2709	2950 COLLEGE DR	34	625
CHEVRON #109060	2929 COLLEGE DR	34	632
RONALD D LANDRY DDS	2726 CONTINENTAL DR	36	636
PARKWAY LIMITED PART	2726 CONTINENTAL DR	36	637
THOMAS J KIEBACH DDS	2726 CONTINENTAL DR	36	639
PARKLAND HOSPITAL	2414 BUNKER HILL DR	37	640
SOUTHERN ENVIRONMENT	8922 JEFFERSON HWY	38	644
TUNE UP 2 INC	8859 JEFFERSON HWY	38	649
CONNELLY PRESS & COP	8737 JEFFERSON HWY	38	659
TOWNHOMES OF SHERWOO	FOREST	39	666
REHABILITATION HOSPI	8595 UNITED PLAZA BL	41	672
LA SECRETARY OF STAT	3851 ESSEN LN	41	678
RITE AID 7318	2159 STARING LN	42	682
ALBERTSONS 2711	7515 PERKINS RD	42	696
KADAIRS CAMERA AUDIO	5713 ESSEN LN	42	699
RAPID LUBE & TUNE UP	5615 ESSEN LN	42	701
MED AID WALK IN MEDI	5475 ESSEN LANE	42	705
DIGITAL DIAGNOSTIC C	7703 PICARDY AVE	42	708
WILLIAM A COUVILLION	7612 PICARDY SUITE C	42	710
KATHY M WOODY DDS	7612 PICARDY AVE STE	42	711
ORTHOPAEDIC SURGERY	5408 FLANDERS DR.	42	713
BATON ROUGE CLINIC	5304 FLANDERS DR	42	714
DRS BRYAN HATCHER VI	5345 BRITTANY DR	42	717
DRS WALL TOWNS & HOR	5227 FLANDERS DR	42	720
KIRBY PERRY DDS LLC	5211 ESSEN LN STE 5	42	721
SAGE REHABILITATION	8000 SUMMA AVENUE	42	723
STEPHEN L SHERMAN DD	7922 SUMMA STE A3	42	726
HANSBROUGH PETERS AM	5344 BRITTANY DR	42	728
LLOYD PAUL CHAMPAGNE	5131 ESSEN LN	42	730
WALGREEN DRUG STORE	5112 ESSEN LN	42	731
BATON ROUGE CARDIOLO	5231 BRITTANY DR	42	734
SURGI CTR OF BATON R	5222 BRITTANY DR	42	736
NEURO MEDICAL CENTER	7777 HENNESSY STE 10	42	742
CHARLIE H BRIDGES MD	7777 HENNESSY BLVD S	42	745
EYE SURGERY CENTER L	7777 HENNESSY BLVD,	42	747
PULMONARY DISEASE CL	7777 HENNESSY STE 70	42	750

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
DRS BRAUD & BREAUX M	***7777 HENNESSY BLVD #***	***42***	***754***
JACOBS PLAZA	***4949 ESSEN LN***	***42***	***756***
MARY BIRD PERKINS CA	***4950 ESSEN LANE***	***42***	***759***
NATIONAL TIRE & BATT	***4675 ESSEN LN***	***42***	***764***
GULF INTERCOASTAL MA	***8116 ONE CALAIS SUIT***	***42***	***768***
EXXONMOBIL OIL CORP	***4555 ESSEN LANE***	***42***	***779***

PRP: A listing of verified Potentially Responsible Parties

A review of the PRP list, as provided by EDR, and dated 10/25/2013 has revealed that there is 1 PRP site within the searched area.

Site	Address	Map ID	Page
CLEARWATER FLUIDS RE	***1001 SOUTH FIRST ST.***	***17***	***364***

STATE AND LOCAL RECORDS

LA SHWS: Potential and Confirmed Sites List

A review of the LA SHWS list, as provided by EDR, and dated 10/18/2016 has revealed that there are 2 LA SHWS sites within the searched area.

Site	Address	Map ID	Page
BATON ROUGE GAS WORK Facility Status: Confirmed Facility Id: 9911	LAUREL ST & N 12TH S	4	181
GILMAR MARINE SERVIC Facility Status: Potential* Facility Id: 8003	***1500 RIVER RD***	***17***	***337***

LA SWF/LF: The Solid Waste Facilities/Landfill Sites records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. The data come from the Department of Environmental Quality's Louisiana's Solid Waste Facilities list.

A review of the LA SWF/LF list, as provided by EDR, and dated 12/12/2016 has revealed that there is 1 LA SWF/LF site within the searched area.

Site	Address	Map ID	Page
LSU AGRICULTURE CENT Facility Id: 163330	4560 ESSEN LN	42	773

EXECUTIVE SUMMARY

LA DEBRIS: A listing of LDEQ Approved Debris Sites where hurricane debris is dumped.

A review of the LA DEBRIS list, as provided by EDR, and dated 11/29/2016 has revealed that there is 1 LA DEBRIS site within the searched area.

Site	Address	Map ID	Page
WEST BATON ROUGE PAR AI #: 184683	TURNER RD	1	4

LA AUL: A notice of contamination (nature and levels of contaminants) and restriction of property to non-residential use are placed in the conveyance records for the property.

A review of the LA AUL list, as provided by EDR, and dated 10/18/2010 has revealed that there are 3 LA AUL sites within the searched area.

Site	Address	Map ID	Page
NORTH BLVD IMPROVEME Facility Id: 86103	***TENTH ST TO 19TH ST***	***4***	***146***
EXXON CO USA #5-1052 Facility Id: 22413	***3191 S ACADIAN HWY***	***24***	***480***
COLLEGE CHEVRON Facility Id: 20619	***2929 COLLEGE DR & I-***	***34***	***627***

LA SWRCY: Recycling Directory of the Department of Environmental Quality.

A review of the LA SWRCY list, as provided by EDR, and dated 09/14/2010 has revealed that there are 3 LA SWRCY sites within the searched area.

Site	Address	Map ID	Page
BATTERY CLINIC	970 GOVERNMENT STREE	14	286
COMPUTERS FOR LA KID	800 ST. PHILLIP STRE	17	376
LA LUBRICANTS DBA JI	4815 PERKINS ROAD	40	667

LA LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data come from the Department of Environmental Quality's list: LDEQ's Leaking UST Database.

A review of the LA LUST list, as provided by EDR, and dated 10/18/2016 has revealed that there are 2 LA LUST sites within the searched area.

Site	Address	Map ID	Page
CIRCLE K #2709733 Facility Id: 66396	***650 S ALEXANDER AVE***	***7***	***211***
LA STATE RETIREMENT Facility Id: 79956	8401 UNITED PLAZA BL	41	676

EXECUTIVE SUMMARY

LA HIST LUST: Department of Environmental Quality's Underground Storage Tank Case History Incidents database.

A review of the LA HIST LUST list, as provided by EDR, and dated 11/01/1999 has revealed that there are 39 LA HIST LUST sites within the searched area.

Site	Address	Map ID	Page
CRACKER BARREL STORE Facility Id: 61-002395	133 LOBDELL HWY # 41	3	10
WILLIAM TRAVEL CENTE Facility Id: 61-006212	123 LOBDELL HWY # I-	3	19
AM MART Facility Id: 61-010247	330 LOBDELL HWY # 41	3	48
BUTLER'S GAS STATION Facility Id: 17-001184	1776 THOMAS DELPIT D	4	65
1509 GOVERNMENT ST P Facility Id: 17-004624	***1509 GOVERNMENT***	***4***	***124***
CONOCO WAREHOUSE FAC Facility Id: 17-014522	***115 S 14TH ST***	***4***	***136***
GREYHOUND LINES INC Facility Id: 17-004566	***1253 FLORIDA BLVD***	***4***	***172***
FIFTH STREET MAIN GU Facility Id: 17-006367	501 MAIN ST	4	188
PARKING GARAGE Facility Id: 17-015464	220 CONVENTION ST	6	200
CHEVRON FOOD MART Facility Id: 61-013538	***704 S ALEXANDER ST***	***7***	***202***
CIRCLE K #9733 Facility Id: 61-011327	***650 S ALEXANDER AVE***	***7***	***207***
EXXON STATION 52061 Facility Id: 61-004062	520 S. ALEXANDER DR.	7	216
MCCARTY CORP Facility Id: 61-013766	***1405 COMMERCIAL DR***	***9***	***247***
BOWMAN TRANSPORTATIO Facility Id: 61-000945	***770 ALLENDALE DR***	***9***	***259***
UNITED PARCEL SERVIC Facility Id: 61-010798	***1111 COMMERCIAL DR***	***13***	***284***
WESTPORT TEXACO Facility Id: 61-002612	***841 LOBDELL SOUTH EX***	***16***	***329***
HIGHLAND GULF INC. Facility Id: 17-012599	***1320 HIGHLAND RD***	***17***	***357***
BATON ROUGE CHECK CA Facility Id: 17-013648	***602 ST CHARLES***	***17***	***383***
CATFISH TOWN CHEVRON Facility Id: 17-000729	510 SAINT FERDINAND	17	393
UNION PACIFIC RAILRO Facility Id: 61-014155	***1300 LEBLANC RD***	***18***	***428***
STANFORD EXXON STORE	3191 S ACADIAN THRUW	24	485

Facility Id: 17-004226			
ROGER A. BARIELLE Facility Id: 17-013030	3235 PERKINS RD	24	506
ZIPPY'S LLC Facility Id: 17-013437	***3155 PERKINS RD***	***24***	***510***
GULF OIL CORP. Facility Id: 17-001943	7930 JEFFERSON HWY.	28	565
AM MART II Facility Id: 17-010249	***2400 HIGHLAND***	***31***	***568***
EXXON STATION 53838 Facility Id: 17-004220	***4527 PERKINS RD***	***34***	***574***
SOUTHDOWNS MOBIL Facility Id: 17-007261	***4485 PERKINS RD***	***34***	***584***
CIRCLE K 8031 Facility Id: 17-008770	***4435 PERKINS RD***	***34***	***585***
COMMERCIAL PROPERTIE Facility Id: 17-013356	***3535 PERKINS RD***	***34***	***598***
TEXACO 44-398-0101 Facility Id: 17-011411	***2959 COLLEGE DR***	***34***	***619***
COLLEGE CHEVRON Facility Id: 17-001998	***2929 COLLEGE DR & I-***	***34***	***627***
CIRCLE K #9726 Facility Id: 17-011412	***3536 DRUSILLA LN***	***38***	***656***
JIFFY LUBE #470 Facility Id: 17-007209	***3311 DRUSILLA LN***	***38***	***663***
JIFFY LUBE #468 Facility Id: 17-007212	***4815 PERKINS RD***	***40***	***667***
FORMER SIMPLE SIMON Facility Id: 17-012634	***2157 STARING LN***	***42***	***681***
TAU CENTER Facility Id: 17-014316	***8080 MARGARET ANN DR***	***42***	***739***
EXXON STATION 5-0608 Facility Id: 17-004224	4555 ESSEN LN	42	774
ESSEN CHEVRON Facility Id: 17-010765	7931 ONE CALAIS AVE	42	783
TEXACO #44-398-0034 Facility Id: 17-011408	***1831 STARING LN***	***43***	***792***

LA UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data come from the Department of Environmental Quality's Louisiana Underground Storage Tank Database.

A review of the LA UST list, as provided by EDR, and dated 10/18/2016 has revealed that there are 90 LA UST sites within the searched area.

Site	Address	Map ID	Page
CRACKER BARREL STORE	***133 LOBDELL HWY 415***	***3***	***12***

Tank Status: Removed Tank Status: Active Master Agency Id: 74892			
MATRIX FOOD STORE Tank Status: Active Master Agency Id: 18777	***111 LOBDELL HWY***	***3***	***16***
NINO'S CASINO LLC Tank Status: Removed Tank Status: Active Master Agency Id: 31055	***123 LOBDELL HWY***	***3***	***25***
RACETRAC #365 Tank Status: Removed Master Agency Id: 71928	214 HWY 415	3	34
LA EXPRESS #9 / EXXO Tank Status: Active Master Agency Id: 76897	222 HWY 415	3	35
WALMART STORE #1136 Tank Status: Removed Master Agency Id: 20907	***2808 COURT ST***	***3***	***40***
EMERALD PALACE TRUCK Tank Status: Removed Tank Status: Active Master Agency Id: 69283	***347 LOBDELL HWY***	***3***	***43***
AM MART #1 Tank Status: Closed Master Agency Id: 76344	330 LOBDELL HWY 415	3	50
CASH'S CASINO, INC. Tank Status: Active Master Agency Id: 79784	***420 LOBDELL HWY***	***3***	***53***
BUTLER GAS Tank Status: Removed Master Agency Id: 26960	1776 EAST BLVD	4	62
PEL STATE OIL CO #43 Tank Status: Closed Master Agency Id: 72133	1492 EAST BLVD	4	74
WILLIAMS ELECTRIC CO Tank Status: Removed Master Agency Id: 68780	945 S 13TH ST	4	98
KANSAS CITY SOUTHERN Tank Status: Removed Master Agency Id: 79505	GOVERNMENT ST & S 14	4	103
1509 GOVERNMENT ST P Tank Status: Removed Master Agency Id: 6290	1509 GOVERNMENT	4	105
GLAZERS CO Tank Status: Closed Master Agency Id: 67846	340 S 14TH ST	4	131
CONOCO WAREHOUSE FAC Tank Status: Removed	***115 S 14TH ST***	***4***	***136***

Master Agency Id: 77420			
BATON ROUGE CITY OF Tank Status: Removed Master Agency Id: 8353	1350 NORTH BLVD	4	142
CITY OF BATON ROUGE Tank Status: Removed Master Agency Id: 115848	1101 NORTH BLVD	4	148
HCI MAINTENANCE Tank Status: Active Tank Status: Temp Out of Service Tank Status: Deferred Master Agency Id: 6866	1225 NORTH BLVD	4	154
US POSTAL SERVICE - Tank Status: Removed Master Agency Id: 69815	717 CONVENTION ST	4	157
US POSTAL SERVICE - Tank Status: Removed Master Agency Id: 78073	210 SEVENTH ST	4	158
US POSTAL SERVICE - Tank Status: Removed Master Agency Id: 9001	750 FLORIDA ST	4	166
SIMPSON'S SERVICE CE Tank Status: Active Master Agency Id: 86511	1334 FLORIDA BLVD	4	170
GREYHOUND LINES INC Tank Status: Closed Tank Status: Active Master Agency Id: 41665	***1253 FLORIDA BLVD***	***4***	***172***
CHEVRON FOOD MART Tank Status: Active Master Agency Id: 76572	***704 S ALEXANDER ST***	***7***	***202***
CIRCLE K #2709733 Tank Status: Removed Tank Status: Active Master Agency Id: 66396	***650 S ALEXANDER AVE***	***7***	***211***
EXXON CO USA #52061 Tank Status: Removed Master Agency Id: 13392	***520 S ALEXANDER AVE***	***7***	***220***
THE MARTIN BROWER CO Tank Status: Removed Master Agency Id: 42412	1585 COMMERCIAL DR	9	242
MCCARTY CORP Tank Status: Removed Master Agency Id: 76794	***1405 COMMERCIAL DR***	***9***	***247***
CONSOLIDATED FREIGHT Tank Status: Removed Master Agency Id: 18131	770 ALLENDALE DR	9	261
GUARANTY INCOME LIFE Tank Status: Closed	2373 S WESTPORT	10	263

Master Agency Id: 77754			
UNITED PARCEL SERVIC	***1111 COMMERCIAL DR***	***13***	***280***
Tank Status: Active Tank Status: Removed Master Agency Id: 43711			
CLOSED STATION	403 FAST BLVD	14	289
Tank Status: Removed Master Agency Id: 78088			
LHOIST NORTH AMERICA	***1785 S WESTPORT DR***	***15***	***293***
Tank Status: Closed Master Agency Id: 6264			
WESTPORT TEXACO	***841 LOBDELL SOUTH EX***	***16***	***329***
Tank Status: Removed Master Agency Id: 74791			
COTERIE BUILDERS INC	1429 - 1435 NICHOLSO	17	337
Tank Status: Removed Master Agency Id: 86420			
FRANKLIN PRESS INC	***1391 HIGHLAND RD***	***17***	***346***
Tank Status: Closed Master Agency Id: 10136			
HIGHLAND TERRACE AMO	1375 HIGHLAND RD	17	348
Tank Status: Removed Master Agency Id: 20637			
OSBR LAND LLC - SOUT	1320 HIGHLAND RD	17	355
Tank Status: Removed Master Agency Id: 20655			
VBC BUILDING	800 ST PHILLIPS ST	17	376
Tank Status: Closed Master Agency Id: 68619			
BATON ROUGE CHECK CA	***602 ST CHARLES***	***17***	***383***
Tank Status: Removed Tank Status: Closed Master Agency Id: 76669			
CATFISH TOWN	100 FRANCE ST	17	387
Tank Status: Removed Master Agency Id: 79575			
CHEVRON FOOD MART #2	510 ST FERDINAND ST	17	389
Tank Status: Removed Tank Status: Active Master Agency Id: 76172			
UNION PACIFIC RAILRO	***1300 LEBLANC RD***	***18***	***428***
Tank Status: Removed Master Agency Id: 68541			
SOUTHERN RECYCLING L	***1367 MAHAFFEY RD***	***20***	***443***
Tank Status: Removed Master Agency Id: 17683			
COMMUNITY COFFEE CO	1833 HWY 1 S	21	449
Tank Status: Closed Master Agency Id: 9503			
DISTRIBUTION INTERNA	***950 MAHAFFEY RD***	***21***	***454***

Tank Status: Closed Master Agency Id: 52309			
B-QUIK #3 Tank Status: Active Master Agency Id: 89658	4105 PERKINS RD	24	467
BATON ROUGE CITY OF Tank Status: Active Tank Status: Closed Master Agency Id: 69686	3075 VALLEY ST	24	477
EXXON CO USA #5-1052 Tank Status: Closed Tank Status: Removed Master Agency Id: 22413	***3191 S ACADIAN HWY***	***24***	***480***
ACADIAN INTERSTATE M Tank Status: Removed Master Agency Id: 15665	***3192 S ACADIAN***	***24***	***491***
CIRCLE K #9717 Tank Status: Active Master Agency Id: 70017	***3375 PERKINS RD***	***24***	***497***
ROGER A BARIELLE Tank Status: Removed Master Agency Id: 20656	3235 PERKINS RD	24	504
ACADIAN CENTRE Tank Status: Closed Master Agency Id: 89345	2431 S ACADIAN THRUW	24	508
ZIPPY'S LLC Tank Status: Removed Master Agency Id: 20657	***3155 PERKINS RD***	***24***	***512***
CRACKER BARREL #48 Tank Status: Removed Tank Status: Active Master Agency Id: 69357	3030 PERKINS RD	24	523
PERKINS RD HARDWARE Tank Status: Removed Master Agency Id: 79088	3043 PERKINS RD	24	528
AK & CO INVESTMENTS Tank Status: Active Master Agency Id: 74019	2385 COLLEGE DR	25	537
RACETRAC Tank Status: Closed Master Agency Id: 71938	2300 COLLEGE DR	25	543
CIRCLE K #9730 Tank Status: Active Master Agency Id: 71560	2300 S ACADIAN THWY	26	546
JET 24 FOOD STORE #4 Tank Status: Removed Tank Status: Active Master Agency Id: 20620	***2313 ACADIAN THRUWAY***	***26***	***551***
LWCC	2237 S ACADIAN THRUW	26	557

Tank Status: Removed Master Agency Id: 163707			
LAMAR BUILDING Tank Status: Removed Master Agency Id: 78911	5321 CORPORATE BLVD	27	562
AM MART II Tank Status: Removed Master Agency Id: 76343	***2400 HIGHLAND***	***31***	***568***
CIRCLE K #7655 Tank Status: Removed Tank Status: Active Master Agency Id: 15667	***4527 PERKINS RD***	***34***	***577***
K-MART #3012 Tank Status: Removed Master Agency Id: 20638	3121 COLLEGE DR	34	591
WALMART STORE #1206 Tank Status: Removed Master Agency Id: 12712	3535 PERKINS RD	34	597
CIRCLE K #9725 Tank Status: Active Master Agency Id: 13684	2959 COLLEGE DR	34	617
COLLEGE CHEVRON Tank Status: Removed Tank Status: Active Master Agency Id: 20619	***2929 COLLEGE DR & I-***	***34***	***627***
BATON ROUGE COUNTRY Tank Status: Active Master Agency Id: 78826	BRENTWOOD DR	35	635
CENIKOR Tank Status: Removed Master Agency Id: 10125	2414 BUNKER HILL DR	37	642
CIRCLE K #3778 Tank Status: Removed Master Agency Id: 75283	8894 JEFFERSON HWY	38	647
ACTION TUNE UP Tank Status: Removed Master Agency Id: 78252	8759 JEFFERSON HWY	38	654
CIRCLE K #8040 Tank Status: Removed Master Agency Id: 75236	8731 JEFFERSON HWY	38	660
JIFFY LUBE #470 Tank Status: Closed Master Agency Id: 7457	***3311 DRUSILLA LN***	***38***	***663***
JIFFY LUBE #468 Tank Status: Removed Tank Status: Active Master Agency Id: 7642	***4815 PERKINS RD***	***40***	***667***
FRANCISCAN MISSIONAR Tank Status: Removed	4200 ESSEN LN	41	674

Master Agency Id: 113876			
TWO UNITED PLAZA Tank Status: Removed Master Agency Id: 78770	8550 UNITED PLAZA BL	41	674
UNITED COS Tank Status: Removed Master Agency Id: 79892	4041 ESSEN LN	41	675
LA STATE RETIREMENT Tank Status: Removed Master Agency Id: 79956	8401 UNITED PLAZA BL	41	676
LA SECRETARY OF STAT Tank Status: Active Master Agency Id: 7621	3851 ESSEN LN	41	677
CIRCLE K #7656 Tank Status: Removed Tank Status: Active Master Agency Id: 22658	***5857 ESSEN LN***	***42***	***690***
VALERO CORNER STORE Tank Status: Active Master Agency Id: 89100	7515 PERKINS RD	42	698
WVLA-TV STUDIOS Tank Status: Removed Master Agency Id: 76525	5220 ESSEN LN	42	728
HEALTHSOUTH SURGI CE Tank Status: Removed Master Agency Id: 35811	5222 BRITTANY DR	42	738
TAU CENTER Tank Status: Closed Master Agency Id: 77177	***8080 MARGARET ANN DR***	***42***	***739***
RT #492 ESSEN LANE Tank Status: Active Master Agency Id: 78516	4665 ESSEN LN	42	771
EXXONMOBIL OIL CORP Tank Status: Removed Master Agency Id: 13366	***4555 ESSEN LN***	***42***	***777***
ESSEN CHEVRON Tank Status: Removed Master Agency Id: 70297	7931 ONE CALAIS AVE	42	790
TEXACO #44-398-0034 Tank Status: Closed Master Agency Id: 70019	***1831 STARING LN***	***43***	***792***

LA DEL SHWS: A listing of sites removed from the Potential and Confirmed Listing.

A review of the LA DEL SHWS list, as provided by EDR, and dated 10/18/2016 has revealed that there is 1 LA DEL SHWS site within the searched area.

Site	Address	Map ID	Page
CHEVRON USA BATON RO	1059 BRICKYARD LN	17	371

EXECUTIVE SUMMARY

AI #: 1429

NY MANIFEST: Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

A review of the NY MANIFEST list, as provided by EDR, and dated 01/30/2017 has revealed that there is 1 NY MANIFEST site within the searched area.

Site	Address	Map ID	Page
AIRCO INDUSTRIAL GAS EPA ID: LAD094178050	1075 CINCLARE DR	9	241

LA SPILLS: Spills and/or releases, to land, reported to the Emergency Response Section.

A review of the LA SPILLS list, as provided by EDR, and dated 08/24/2016 has revealed that there are 55 LA SPILLS sites within the searched area.

Site	Address	Map ID	Page
NINO'S CASINO LLC Incident Id: 124895 Incident Status: Closed	***123 LOBDELL HWY***	***3***	***25***
CASH'S CASINO, INC. Incident Id: 108407 Incident Status: Pending Review	***420 LOBDELL HWY***	***3***	***53***
BUTLER GAS Incident Id: 55519 Incident Status: Open	1776 THOMAS H. DELPI	4	61
LDEQ Incident Id: 163712 Incident Status: Closed	1776 THOMAS H DELPIT	4	64
SNOWFLAKES RESTAURAN Incident Id: 42012 Incident Status: Closed	1425 E. WASHINGTON	4	67
1509 GOVERNMENT ST P Incident Id: 106957 Incident Status: Open	***1509 GOVERNMENT***	***4***	***124***
GREYHOUND LINES INC Incident Id: 111006 Incident Status: Closed	***1253 FLORIDA BLVD***	***4***	***172***
CIRCLE K #9733 Incident Id: 137023 Incident Status: Closed	***650 S ALEXANDER AVE***	***7***	***207***
BOWMAN TRANSPORTATIO Incident Id: 120774 Incident Status: Open	***770 ALLENDALE DR***	***9***	***259***
LOUISIANA SCRAP META	HWY 190 AND LA 1	10	264

Incident Id: 94804 Incident Status: Closed			
1075 GOVERNMENT ST Incident Id: 160268 Incident Status: Open	***1075 GOVERNMENT ST***	***14***	***288***
Not reported Incident Id: 155839 Incident Status: Closed	1785 S WESTPORT DR	15	292
Not reported Incident Id: 158453 Incident Status: Closed	1785 S WESTPORT DR	15	293
LHOIST NORTH AMERICA Incident Id: 60927 Incident Id: 156579 Incident Status: Closed	***1785 S WESTPORT DR***	***15***	***293***
CHEMICAL LIME Incident Id: 45846 Incident Status: Closed	1785 SOUTH WESTPORT	15	297
Not reported Incident Id: 83533 Incident Status: Closed	1785 SOUTH WESTPORT	15	297
Not reported Incident Id: 156894 Incident Status: Closed	1785 S WESTPORT DR	15	305
Not reported Incident Id: 159230 Incident Status: Open	1785 S WESTPORT DR	15	307
Not reported Incident Id: 156101 Incident Status: Closed	1785 S WESTPORT DR	15	308
CHEMICAL LINE Incident Id: 45487 Incident Status: Closed	1785 S. WESTPORT DRI	15	309
GRAHAM PACKAGING Incident Id: 115906 Incident Status: Closed	NEAR 1981 SOUTH WEST	15	328
Not reported Incident Id: 72309 Incident Status: Closed	746 HIGHLAND PLANTAT	17	375
SOUTHERN RECYCLING L Incident Id: 72252 Incident Status: Closed	***1367 MAHAFFEY RD***	***20***	***443***
VALLEY PARK SCHOOL Incident Id: 95016 Incident Status: Closed	***4510 BAWELL ST***	***23***	***466***
Not reported Incident Id: 52798 Incident Status: Open	3191 S. ACADIAN THRU	24	484
ACADIAN INTERSTATE M	***3192 S ACADIAN***	***24***	***496***

Incident Id: 126454 Incident Status: Referred to Remediation			
CIRCLE K #9717 Incident Id: 70392 Incident Id: 109562 Incident Id: 86293 Incident Status: Closed	***3375 PERKINS RD***	***24***	***497***
Not reported Incident Id: 41320 Incident Status: Closed	2431 SOUTH ACADIAN B	24	509
Not reported Incident Id: 84929 Incident Status: Closed	3172 GREENWOOD	24	520
Not reported Incident Id: 48098 Incident Status: Closed	3162 GREENWOOD	24	521
CRACKER BARREL #48 Incident Id: 101634 Incident Id: 155625 Incident Status: Pending Review Incident Status: Referred to USTD for TL Assignment	***3030 PERKINS RD***	***24***	***521***
Not reported Incident Id: 139014 Incident Status: Closed	S. EUGENE @ HONEYSUC	24	529
GEORGE'S RESTAURANT Incident Id: 128520 Incident Status: Closed	2943 PERKINS RD (UND	24	530
Not reported Incident Id: 48976 Incident Status: Closed	3127 GREENWOOD	24	531
Not reported Incident Id: 40879 Incident Status: Open	3047 GREENWOOD	24	531
Not reported Incident Id: 36412 Incident Status: Open	3047 GREENWOOD	24	532
CIRCLE K #9730 Incident Id: 108018 Incident Id: 86368 Incident Status: Closed Incident Status: Referred to Enforcement	***2300 S ACADIAN THWY***	***26***	***549***
EXXON STATION 53838 Incident Id: 131458 Incident Id: 131461 Incident Id: 41763 Incident Status: Closed Incident Status: Open	***4527 PERKINS RD***	***34***	***574***
CIRCLE K 8031 Incident Id: 67715 Incident Status: Referred to Remediation	***4435 PERKINS RD***	***34***	***585***
FORMER UNIVERSITY MO	***4395 PERKINS RD***	***34***	***587***

Incident Id: 116523 Incident Status: Closed			
CIRCLE K STORES, INC Incident Id: 172096 Incident Status: Open	2959 COLLEGE DR	34	612
CIRCLE K STORES, INC Incident Id: 115181 Incident Status: Closed	2959 COLLEGE DR BATO	34	616
TEXACO 44-398-0101 Incident Id: 113597 Incident Id: 86292 Incident Status: Referred to USTD for TL Assignment Incident Status: Referred to Remediation	***2959 COLLEGE DR***	***34***	***619***
CIRCLE K #9726 Incident Id: 86291 Incident Status: Closed	***3536 DRUSILLA LN***	***38***	***656***
ARBOR TECH Incident Id: 105669 Incident Status: Closed	3769 SHOLAR COURT	39	666
JIFFY LUBE #468 Incident Id: 66293 Incident Status: Closed	***4815 PERKINS RD***	***40***	***667***
Not reported Incident Id: 84493 Incident Status: Closed	4200 ESSEN LN	41	673
STATE ARCHIVES BLDG. Incident Id: 64015 Incident Status: Closed	3851 ESSEN LANE	41	680
LOUISIANA EDUCATIONA Incident Id: 132200 Incident Status: Open	***7733 PERKINS RD***	***42***	***680***
Not reported Incident Id: 38233 Incident Status: Open	4900 ESSEN LANE AND	42	762
CITY OF BATON ROUGE/ Incident Id: 115289 Incident Status: Closed	4898 ESSEN LANE BATO	42	763
SUMMA PLACE Incident Id: 38040 Incident Status: Open	4898 ESSEN LANE	42	763
CITY OF BATON ROUGE Incident Id: 120296 Incident Status: Closed	4890 ESSEN LANE	42	764
Not reported Incident Id: 98710 Incident Status: Closed	ESSEN LANE BETWEEN M	42	767
CALAIS EXXON Incident Id: 78436 Incident Id: 85625	4555 ESSEN LANE	42	775

Incident Id: 83584
Incident Status: Referred to Remediation
Incident Status: Closed

LA VCP: Sites that have entered Department of Environmental Quality's Voluntary Remediation Program

A review of the LA VCP list, as provided by EDR, and dated 10/11/2016 has revealed that there are 6 LA VCP sites within the searched area.

Site	Address	Map ID	Page
1509 GOVERNMENT ST P Status: Withdrew DEQ AI #: 6290 Date Closed: 09/12/2013	***1509 GOVERNMENT***	***4***	***124***
NORTH BLVD IMPROVEME Status: NFA/COC DEQ AI #: 86103 Date Closed: 12/15/2005	***TENTH ST TO 19TH ST***	***4***	***146***
HIGHLAND GULF INC. Status: NFA/COC DEQ AI #: 20655 Date Closed: 09/28/2010	***1320 HIGHLAND RD***	***17***	***357***
HOPE VI Status: COC DEQ AI #: 93917 Date Closed: 04/02/2009	***1705 HIGHLAND RD***	***22***	***456***
WHITNEY BANK - BOCAG Status: COC DEQ AI #: 33815 Date Closed: 01/07/2002	***8006 JEFFERSON HWY***	***28***	***564***
DRUSILLA CLEANER Status: Active DEQ AI #: 5567	***3406 DRUSILLA LN***	***38***	***662***

LA DRYCLEANERS: Drycleaner Facility Listing.

A review of the LA DRYCLEANERS list, as provided by EDR, and dated 10/07/2016 has revealed that there are 10 LA DRYCLEANERS sites within the searched area.

Site	Address	Map ID	Page
CAPITOL CLEANERS Facility Id: 39238	1642 THOMAS H DELPIT	4	68
DRY CLEANERS	3627 PERKINS ROAD	24	475
KEAN'S THE CLEANER Facility Id: 39372	***3109 PERKINS RD***	***24***	***519***
OVERPASS CLEANERS	2929 PERKINS RD	24	533

Facility Id: 39434			
SUPERB CLEANERS Facility Id: 39529	2626 BALIS DR	32	571
WELSHS CLEANERS Facility Id: 5485	***4479 PERKINS RD***	***34***	***583***
FASHION CLNR Facility Id: 39314	8895 JEFFERSON HWY	38	649
EASTERN LAUNDRY & CL Facility Id: 39302	8883 JEFFERSON HWY	38	649
DRUSILLA CLEANER Facility Id: 5567	***3406 DRUSILLA LN***	***38***	***662***
FETTER'S CLEANERS Facility Id: 39318	7777 HENNESSY BLVD	42	754

LA BROWNFIELDS: Brownfields are abandoned, idled, or underused industrial or commercial real property, the expansion, redevelopment or reuse of which may be complicated by the presence of or potential presence of a hazardous substance, pollutant, or contaminant.

A review of the LA BROWNFIELDS list, as provided by EDR, and dated 10/18/2016 has revealed that there is 1 LA BROWNFIELDS site within the searched area.

Site	Address	Map ID	Page
LINCOLN THEATER	***1305 MYRTLE WALK***	***4***	***91***

TX Ind. Haz Waste: The Industrial and Hazardous Waste Database contains summary reports by waste handlers, generators and shippers in Texas.

A review of the TX Ind. Haz Waste list, as provided by EDR, and dated 01/11/2017 has revealed that there are 4 TX Ind. Haz Waste sites within the searched area.

Site	Address	Map ID	Page
TSD REMEDIAL SERVICE Registration Number: 41331	1780 COMMERCIAL DR	11	265
IT CORPORATION OF LO Registration Number: 40979	1150 LE BLANC RD	18	424
SOUTHERN ENVIRONMENT Registration Number: 40683	8922 JEFFERSON HWY	38	645
GULF INTRACOASTAL MA Registration Number: 40616	8116 ONE CALAIS AVE	42	769

EXECUTIVE SUMMARY

LA NPDES: A listing of sites with a Louisiana Pollutant Discharge Elimination System (LPDES) program issued permit.

A review of the LA NPDES list, as provided by EDR, and dated 10/24/2016 has revealed that there are 34 LA NPDES sites within the searched area.

Site	Address	Map ID	Page
CRACKER BARREL STORE Facility Id: 74892	***133 LOBDELL HWY 415***	***3***	***12***
MATRIX FOOD STORE Facility Id: 18777	***111 LOBDELL HWY***	***3***	***16***
NINO'S CASINO LLC Facility Id: 31055 Facility Id: 151656	***123 LOBDELL HWY***	***3***	***25***
MCBR MANAGEMENT CO I Facility Id: 18806	***150 LOBDELL HWY***	***3***	***38***
WALMART STORE #1136 Facility Id: 20907 Facility Id: 129406	***2808 COURT ST***	***3***	***40***
EMERALD PALACE TRUCK Facility Id: 69283	***347 LOBDELL HWY***	***3***	***43***
CASH'S CASINO, INC. Facility Id: 79784	***420 LOBDELL HWY***	***3***	***53***
MCKINLEY MIDDLE SCHO Facility Id: 5253	1557 MCCALOP ST	4	70
USPS BATON ROUGE VMF Facility Id: 9001	***750 FLORIDA ST***	***4***	***162***
GREYHOUND LINES INC Facility Id: 41665	***1253 FLORIDA BLVD***	***4***	***172***
CIRCLE K #9733 Facility Id: 66396	***650 S ALEXANDER AVE***	***7***	***207***
CIRCLE K #2709733 Facility Id: 66396	***650 S ALEXANDER AVE***	***7***	***211***
EXXON CO USA #52061 Facility Id: 13392	***520 S ALEXANDER AVE***	***7***	***220***
LA SCRAP METAL RECYC Facility Id: 175591	S WESTPORT DR	10	264
LOUISIANA SCRAP META Facility Id: 180689	2527 S WESTPORT DR	10	264
UNITED PARCEL SERVIC Facility Id: 43711	***1111 COMMERCIAL DR***	***13***	***280***
UNITED PARCEL SERVIC Facility Id: 43711	***1111 COMMERCIAL DR***	***13***	***284***
LHOIST NORTH AMERICA Facility Id: 6264	***1785 S WESTPORT DR***	***15***	***293***
HIGHLAND GULF INC. Facility Id: 20655	***1320 HIGHLAND RD***	***17***	***357***
SOUTHERN RECYCLING L	***1367 MAHAFFEY RD***	***20***	***443***

Facility Id: 17683			
DISTRIBUTION INTERNA Facility Id: 39166 Facility Id: 52309	***950 MAHAFFEY RD***	***21***	***454***
HOPE VI Facility Id: 93917	***1705 HIGHLAND RD***	***22***	***456***
RCS CONTRACTORS INC Facility Id: 168452	PERKINS RD & STANFOR	24	479
CIRCLE K #9717 Facility Id: 70017	***3375 PERKINS RD***	***24***	***497***
ZIPPY'S LLC Facility Id: 20657	***3155 PERKINS RD***	***24***	***510***
ZIPPY'S LLC Facility Id: 20657	***3155 PERKINS RD***	***24***	***512***
CIRCLE K #7655 Facility Id: 15667	***4527 PERKINS RD***	***34***	***577***
COMMERCIAL PROPERTIE Facility Id: 185726 Facility Id: 185727	***3535 PERKINS RD***	***34***	***598***
COLLEGE CHEVRON Facility Id: 20619	***2929 COLLEGE DR & I-***	***34***	***627***
CIRCLE K #9726 Facility Id: 70008	***3536 DRUSILLA LN***	***38***	***656***
CIRCLE K #7656 Facility Id: 22658	***5857 ESSEN LN***	***42***	***690***
OLOL EAST TOWER & ED Facility Id: 177088	5050 ESSEN LN (E TOW	42	739
JACOBS PLAZA Facility Id: 20321	***4949 ESSEN LN***	***42***	***756***
EXXONMOBIL OIL CORP Facility Id: 13366	***4555 ESSEN LN***	***42***	***777***

LA AIRS: A listing of facilities with air permits issued by the Air Permits Division

A review of the LA AIRS list, as provided by EDR, and dated 11/17/2016 has revealed that there are 9 LA AIRS sites within the searched area.

Site	Address	Map ID	Page
LHOIST NORTH AMERICA Permit Number: 3120-00041-03	1785 S WESTPORT DR	15	304
LHOIST NORTH AMERICA Permit Number: 3120-00041-02	1785 S WESTPORT DR	15	305
LHOIST NORTH AMERICA Permit Number: 3120-00041-04	1785 S WESTPORT DR	15	306
LHOIST NORTH AMERICA	1785 S WESTPORT DR	15	306

Permit Number: 3120-00041-06			
LHOIST NORTH AMERICA Permit Number: 3120-00041-05	1785 S WESTPORT DR	15	307
PORTA-BATCH SLURRY # Permit Number: 7777-00409-00	STATEWIDE - 1785 S W	15	309
PORTA-BATCH SLURRY # Permit Number: 7777-00408-00	STATEWIDE - 1785 S W	15	309
SOUTHERN RECYCLING L Permit Number: 3120-00010-00	***1367 MAHAFFEY RD***	***20***	***443***
HIT & RUN FOOD STORE Permit Number: 0840-00121-00	2313 S ACADIAN THRWY	26	555

Asbestos demolition and renovation notification projects locations in the state.

A review of the LA ASBESTOS list, as provided by EDR, and dated 12/31/2015 has revealed that there are 6 LA ASBESTOS sites within the searched area.

Site	Address	Map ID	Page
LINCOLN THEATER ADVF #: ADVF-0029415	***1305 MYRTLE WALK***	***4***	***91***
BREC EXPRESSWAY PARK ADVF #: ADVF-0029417	935 S 11TH ST	4	97
1509 GOVERNMENT ST P ADVF #: ADVF-0028757 ADVF #: ADVF-0031972 ADVF #: ADVF-0031971 ADVF #: ADVF-0031970	***1509 GOVERNMENT***	***4***	***124***
USPS BATON ROUGE VMF ADVF #: 13879	***750 FLORIDA ST***	***4***	***162***
KEAN'S THE CLEANER ADVF #: ADVF-0031134	***3109 PERKINS RD***	***24***	***519***
ENTERGY SERVICE CENT ADVF #: ADVF-0032117	5564 ESSEN LN	42	703

LA REM: Facilities or sites come to the Underground Storage Tank and Remediation Divison either through self notification or referral. These sites are designated for remediation via the following regulatory paths: Solid Waste (SW), Hazardous Waste (Haz Waste), Groundwater (Grwater), Inactive & Abandoned Sites (Confirmed or Potential), or Underground Storage Tanks (UST).

A review of the LA REM list, as provided by EDR, and dated 10/18/2016 has revealed that there are 43 LA REM sites within the searched area.

Site	Address	Map ID	Page
MATRIX FOOD STORE AI Num: 18777	111 LOBDELL HWY	3	16
NINO'S CASINO LLC	***123 LOBDELL HWY***	***3***	***25***

AI Num: 31055			
RACETRAC #365 AI Num: 71928	214 HWY 415	3	33
MCBR MANAGEMENT CO I AI Num: 18806	***150 LOBDELL HWY***	***3***	***38***
LINCOLN THEATER AI Num: 169406	***1305 MYRTLE WALK***	***4***	***91***
1509 GOVERNMENT ST P AI Num: 6290	***1509 GOVERNMENT***	***4***	***124***
NORTH BLVD IMPROVEME AI Num: 86103	***TENTH ST TO 19TH ST***	***4***	***146***
BOB DEAN ENTERPRISES AI Num: 120463	1034 MAIN ST	4	193
HUDSON RESIDENCE AI Num: 190708	310 CONVENTION ST	6	200
MAPP PROPERTIES SITE AI Num: 47367	350 THIRD ST	6	202
CIRCLE K #2709733 AI Num: 66396	650 S ALEXANDER AVE	7	210
EXXON CO USA #52061 AI Num: 13392	***520 S ALEXANDER AVE***	***7***	***220***
UNITED PARCEL SERVIC AI Num: 43711	1111 COMMERCIAL DR	13	280
1075 GOVERNMENT ST AI Num: 194644	***1075 GOVERNMENT ST***	***14***	***288***
GILMAR MARINE SERVIC AI Num: 8003	***1500 RIVER RD***	***17***	***337***
HIGHLAND GULF INC. AI Num: 20655	***1320 HIGHLAND RD***	***17***	***357***
CHEVRON USA BATON RO AI Num: 1429	1059 BRICKYARD LN	17	371
HOPE VI AI Num: 93917	***1705 HIGHLAND RD***	***22***	***456***
VALLEY PARK SCHOOL AI Num: 9151	***4510 BAWELL ST***	***23***	***466***
EXXON CO USA #5-1052 AI Num: 22413	***3191 S ACADIAN HWY***	***24***	***480***
ACADIAN INTERSTATE M AI Num: 15665	***3192 S ACADIAN***	***24***	***496***
CIRCLE K #9717 AI Num: 70017	***3375 PERKINS RD***	***24***	***497***
ZIPPY'S LLC AI Num: 20657	***3155 PERKINS RD***	***24***	***512***
KEAN'S THE CLEANER AI Num: 39372	***3109 PERKINS RD***	***24***	***519***
CRACKER BARREL #48	***3030 PERKINS RD***	***24***	***521***

AI Num: 69357			
RACETRAC AI Num: 71938	2300 COLLEGE DR	25	544
CIRCLE K #9730 AI Num: 71560	***2300 S ACADIAN THWY***	***26***	***549***
WHITNEY BANK - BOCAG AI Num: 33815	***8006 JEFFERSON HWY***	***28***	***564***
CIRCLE K #7655 AI Num: 15667	***4527 PERKINS RD***	***34***	***577***
WELSHS CLEANERS AI Num: 5485	***4479 PERKINS RD***	***34***	***583***
SOUTHDOWNS MOBIL AI Num: 1499	***4485 PERKINS RD***	***34***	***584***
RACE EXPRESS AI Num: 75226	4435 PERKINS RD	34	587
FORMER UNIVERSITY MO AI Num: 165894	***4395 PERKINS RD***	***34***	***587***
TEXACO 44-398-0101 AI Num: 13684	***2959 COLLEGE DR***	***34***	***619***
COLLEGE CHEVRON AI Num: 20619	***2929 COLLEGE DR & I-***	***34***	***627***
CIRCLE K #9726 AI Num: 70008	***3536 DRUSILLA LN***	***38***	***656***
DRUSILLA CLEANER AI Num: 5567	***3406 DRUSILLA LN***	***38***	***662***
LA STATE RETIREMENT AI Num: 79956	8401 UNITED PLAZA BL	41	676
LOUISIANA EDUCATIONA AI Num: 172470	***7733 PERKINS RD***	***42***	***680***
N-N-OUT AI Num: 75234	2147 STARING LN	42	681
FORMER SIMPLE SIMON AI Num: 69183	***2157 STARING LN***	***42***	***681***
CIRCLE K #7656 AI Num: 22658	***5857 ESSEN LN***	***42***	***690***
EXXONMOBIL OIL CORP AI Num: 13366	***4555 ESSEN LN***	***42***	***777***

PA AIRS: Permit and emissions inventory data.

A review of the PA AIRS list, as provided by EDR, and dated 12/31/2014 has revealed that there is 1 PA AIRS site within the searched area.

Site	Address	Map ID	Page
SHAW ENV & INFRASTRU	4171 ESSEN LN	41	671

EXECUTIVE SUMMARY

Primary Facility Id: 512949

EDR PROPRIETARY RECORDS

EDR MGP: The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

A review of the EDR MGP list, as provided by EDR, has revealed that there is 1 EDR MGP site within the searched area.

Site	Address	Map ID	Page
BATON ROUGE GAS WORK	LAUREL STREET	4	188

EDR Hist Auto: EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Auto list, as provided by EDR, has revealed that there are 107 EDR Hist Auto sites within the searched area.

Site	Address	Map ID	Page
NINOS CASINO	121 LOBDELL HWY	3	10
AMERICAN GEN INVESTM	133 LOBDELL HWY 415	3	15
ARDES INC	111 LOBDELL HWY	3	15
MAPCO INC	123 LOBDELL HWY	3	25
RACETRAC PETROLEUM I	214 HIGHWAY 415	3	33
UNIVERSAL INNS INC	215 LOBDELL HWY	3	39
WAL MART DISCOUNT CI	2808 COURT ST	3	39
LEES AUTO REPR SHOP	721 HARRISON ST E	4	59
SAMPSON BURT C AUTO	821 HARRISON ST E	4	59
MARCELLES EXXON SERV	1026 E WASHINGTON	4	59
MARCELLE S ESSO SERV	1001 WASHINGTON ST E	4	60
MARCELLES ESSO SERVI	1001 WASHINGTON ST E	4	61
MERCURY GASOLINE CO	1776 EAST BLVD	4	62
BUTLERS GAS	1776 THOMAS H DELPIT	4	62
MID CITY OIL CO INC	1413 WASHINGTON ST E	4	66
MID CITY OIL CO	1413 WASHINGTON ST E	4	67
KINGS GARAGE AUTO RE	653 EDUCATION ST	4	69

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
KINGS GARAGE	653 EDUCATION ST	4	69
KING JAS W AUTO REPR	924 HOWARD ST	4	69
KING JAS W C AUTO RE	924 HOWARD ST	4	69
KING JAMES W AUTO RE	924 HOWARD ST	4	69
TRAHANS AUTO REPAIR	1588 BRADDOCK ST	4	70
TRAHANS PAINT & REPR	1588 BRADDOCK ST	4	70
TRAHANS GARAGE AUTO	1534 BADDOCK ST	4	71
ELMOS GARAGE C AUTO	938 LOUISE ST	4	71
HANKS AUTO REPAIR	938 LOUISE ST	4	71
PEL STATE OIL CO NO	1492 EAST BLVD	4	74
GIAMMERSE SAM	1306 EAST BLVD	4	79
HOME OIL CO INC	1304 EAST BLVD	4	79
ALLEN ESSO SERV STA	1302 EAST BLVD	4	79
DILWORTH AUTO SERVIC	1328 TERRACE ST	4	81
TILLMAN SAM AUTO REP	1146 10TH ST S	4	87
MID CITY AUTO SERVIC	1102 13TH ST S	4	87
ROBERSONS ESSO GAS S	1045 MYRTLE ST	4	88
WILLIAMS JOS C AUTO	944 13TH ST S	4	97
CITY SHELL SERV STA	1150 SOUTH ST	4	99
HORATIOS ESSO STATIO	1150 SOUTH BLVD	4	99
TOLBERT ARTH C AUTO	854 13TH ST S	4	99
FORBES TONY S FILLIN	1268 GOVERNMENT ST	4	102
MANUEL RADIO & T V R	1202 AMERICA ST	4	134
TAYLOR WESLEY GARAGE	135 12TH ST S	4	139
MORGAN AUTO SERVICE	1112 NORTH BLVD	4	139
PETIGO COMPETITION C	1038 NORTH BLVD	4	146
HAYS SERVICE	1057 NORTH BLVD	4	147
MID CONTINENT OIL AN	801 NORTH BLVD	4	147
CAPITOL CITY AUTO CO	1111 NORTH BLVD	4	149
EXPRESSWAY ESSO SERV	120 10TH ST N	4	151
DIXON BROS QUICK STO	120 N 10TH ST	4	152
SIMPSONS SERVICE CEN	1225 NORTH BLVD	4	153
DOYLES AUTO REPAIRIN	1118 CONVENTION ST	4	158
T AND T SERVICES	1142 CONVENTION ST	4	158
CAJUN KENWORTH INC	2723 S WEST PORT DR	12	280
BATTERY CLINIC THE	970 GOVERNMENT ST	14	286
DONS AUTO CLINIC	800 GOVERNMENT ST	14	287
STEWARTS SHELL SERV	962 GOVERNMENT ST	14	287
PEL-STATE OIL COMPAN	521 EAST BLVD	14	287
HANEY AUTOMOTIVE INC	918 GOVERNMENT ST	14	288
CENTRAL ESSO SERV	959 GOVERNMENT ST	14	288
CENTRAL ESSO SERVICE	403 EAST BLVD	14	289
BP HOLLY COLEMAN	1981 S WESTPORT DR	15	312
WESTPORT TEXACO	841 LOBDELL EXT S	16	332
LOVES TRVL STOPS CNT	751 LOBDELL EXT S	16	334
PIPES JAS M C O	452 TERRACE ST	17	361
DAVIS LIONEL ESSO SE	1254 HIGHLAND	17	361
VAUGHN MARSHALL AUTO	1200 HIGHLAND RD	17	364
PORTER DAVID B MECH	501 JULIA ST	17	368
CAPONES AUTOMOTIVE S	510 MYRTLE ST	17	370
HERBS TEXACO SERVICE	605 S ALEXANDER ST	17	375
GULF SERVICE STATION	701 ST FERDINAND ST	17	380
ROBERTS ESSO SERVICE	3725 PERKINS RD	24	470
STANFORD EXXON MCFEA	3191 S ACADIAN THRUW	24	490
GIVENS SOUTHSIDE MOB	3192 S ACADIAN TRWY	24	496
TEXACO SELF SERVICE	3375 PERKINS RD	24	503

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
ROBERTSON AUTO SERVI	2575 N ACADIAN THRUW	24	504
HANEYS SPUR SERVICE	3235 PERKINS RD	24	508
ULLS PHILUPS	3155 PERKINS RD	24	515
AMERICAN GEN INVESTM	3030 PERKINS RD	24	523
RALPHS TEXACO SERVIC	3063 PERKINS RD	24	526
EXPERT AUTO SERVICE	2311 CHRISTIAN ST	24	535
LANDRYS IMPORT SERVI	2890 GREENWOOD DR	24	536
OVERPASS SERVICE STA	2540 PERKINS RD	24	536
SPEEDWAY SUPERAMERIC	2385 COLLEGE DR	25	536
ECOL SERVICE CENTER	2373 COLLEGE DR	25	540
ECOL SELF SERVICE GA	2375 COLLEGE DR	25	540
COLLEGE DRIVE EXXON	2372 COLLEGE DR	25	540
MIDAS AUTO SYSTEMS E	2358 COLLEGE DR	25	540
RACEWAY SELF SERVICE	2330 COLLEGE DR	25	542
PARSONS INC	2300 ACADIAN THRUWAY	26	548
ACADIAN SHELL SERVIC	2300 S ACADIAN THRWY	26	548
RAINBOW MARKETERS IN	2313 S ACADIAN TRWY	26	550
TEXACO SELF SERVICE	2959 COLLEGE DR	34	615
JOHNSON MELVIN 0 AUT	2982 BALIS DR	34	624
MAGINNIS IMPORTS INC	2857 COLLEGE DR	34	624
COLLEGE CHEVRON	2929 COLLEGE DR	34	634
GULF COAST UTILITIES	8664 FOREST HILL DR	38	644
AUTOMOTIVE LIQUIDATO	8658 QUARTERS LAKE R	38	644
LOUISIANA LUBRICANTS	8768 QUARTERS LAKE R	38	647
GULF SOUTH RECOVERY	3490 SAN FELIPE DR	38	653
ACTION TUNE INSPECTI	8775 JEFFERSON HWY S	38	653
ACTION TUNE	8759 JEFFERSON HWY	38	653
SHAW TRANSM DIST SVC	4171 ESSEN LN	41	671
Not reported	5615 ESSEN LN	42	703
SCOTT LEONARD F	4912 ESSEN LN	42	762
RACETRAC PETROLEUM I	4665 ESSEN LN	42	772
GULF SOUTH LTD	8048 ONE CALAIS AVE	42	773
Not reported	4555 ESSEN LN	42	776
Not reported	7931 ONE CALAIS AVE	42	782

EDR Hist Cleaner: EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

A review of the EDR Hist Cleaner list, as provided by EDR, has revealed that there are 52 EDR Hist Cleaner sites within the searched area.

Site	Address	Map ID	Page
PARAMOUNT CLNS DCLO	806 HARRISON ST E	4	59
PARAMOUNT CLEANERS	906 HARRISON ST E	4	59
BAMA CLNRS DCLO CLNR	690 WASHINGTON ST E	4	60
BAMA CLN	690 WASHINGTON ST E	4	60
BOONE MILTON CLO CLN	1220 WASHINGTON ST	4	60

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
BOONE MILTON C DCLO	1220 WASHINGTON ST	4	60
GREEN ANTHONY C DCLO	1313 WASHINGTON ST	4	61
MARGARET VALLET MUSI	724 EDUCATION ST	4	67
ROTOLO SHELBY & ANTH	1642 E BLVD	4	68
CAPITOL CLEANERS	1642 THOMAS H DELPI	4	68
X RAY CLNS	1533 EAST BLVD	4	70
X RAY CLEANERS	1510 UTAH ST	4	71
WHITE STAR CLN & LND	1429 EAST BLVD	4	78
NOLAN CLNRS & DYERS	1401 EAST BLVD	4	78
CASH PRESSING CLUB	1319 EAST BLVD	4	79
A B C CLEANERS & LAU	1303 EAST BLVD	4	79
BOBS CLEANERS	1303 THOMAS H DELPIT	4	80
BATON ROUGE HAT CLEA	1020 TERRACE ST	4	80
BATON ROUGE HATTERS	1062 TERRACE ST	4	80
STANLEY SHERMAN R	1232 TERRACE ST	4	80
SUPERB CLNS BR	1266 TERRACE ST	4	80
WIFE SAVER U WASH IT	1286 TERRACE ST	4	81
DAY AND NIGHT LAUNDR	1206 EAST BLVD	4	86
WILLIAMS HILNER C C	921 11TH ST S	4	98
JACOBS LARRY J C DCL	859 13TH ST S	4	99
COTTONS CLEANERS	1308 GOVERNMENT ST	4	102
COTTON ODEA CLO CLNR	1306 GOVERNMENT ST	4	102
A B C CLEANERS & LAU	1322 GOVERNMENT ST	4	103
MC CRAY FRANK R C BA	1355 GOVERNMENT ST	4	104
MC CRAY DAVID C DCLO	1349 GOVERNMENT ST	4	104
GEORGE CLEANERS C DC	1347 GOVERNMENT ST	4	104
WILLIS WM H C DCLO C	302 13TH ST S	4	131
KEMP LUKE C DCLO CLN	172 12TH ST S	4	134
PEERLESS CLEANERS &	1225-29 N BLVD	4	157
DOWNTOWN SPEED WASH	1050 CONVENTION ST	4	157
SANCHEZ EUPHEMIA MRS	1109 CONVENTION ST	4	160
SICARDS CLEANERS & D	1105 CONVENTION ST	4	160
JOHNNYS WASHETTE	633 MYRTLE ST	17	370
RIDLEY JOE TAILOR &	1005 HIGHLAND RD	17	374
RIDLEY JOS C DCLO CL	1005 ST FERDINAND S	17	375
DRY CLEANERS CLEANER	3627 PERKINS RD	24	475
WIFE SAVER LAUND O M	3109 PERKINS RD	24	518
KEANS CLNS & LNDRY B	3103 PERKINS RD	24	519
WHITE STAR AUTOMATIC	3043 PERKINS RD	24	527
DIXIES MONO WASH LAU	2275 CHRISTIAN ST	24	530
OVERPASS CLEANERS	2929 PERKINS RD	24	532
PREFERRED CARPET CLE	2603 E LAKESHORE DR	30	567
SUPERB CLEANERS	2626 BALIS DR	32	572
1 HR COLOR DEVELOPME	3084 COLLEGE DR F	34	612
ACOSTA CLEANERS	5743 ESSEN LN	42	699
DRY CLEANING ONE	5703 ESSEN LN	42	701
L & L FETTERS INC	7777 HENNESSY BLVD	42	752

EXECUTIVE SUMMARY

LA RGA LF: The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

A review of the LA RGA LF list, as provided by EDR, has revealed that there is 1 LA RGA LF site within the searched area.

Site	Address	Map ID	Page
LSU AGRICULTURE CENT Facility ID: 163330	4560 ESSEN LN	42	773

LA RGA LUST: The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

A review of the LA RGA LUST list, as provided by EDR, has revealed that there are 12 LA RGA LUST sites within the searched area.

Site	Address	Map ID	Page
BUTLER GAS Facility ID: 26960 Facility ID: 26960.0	1776 EAST BLVD	4	61
EXXON CO USA #51052 Facility ID: 22413.0	3191 S ACADIAN HWY	24	484
EXXON CO USA #5-1052 Facility ID: 22413	3191 S ACADIAN HWY	24	490
CIRCLE K #9730 Facility ID: 71560	2300 S ACADIAN THWY	26	546
SHELL #142059 Facility ID: 71560	2300 S ACADIAN THWY	26	548
CIRCLE K #2709730 Facility ID: 71560	2300 S ACADIAN THWY	26	550
CIRCLE K #2709729 Facility ID: 71560	2300 S ACADIAN THWY	26	550
SHELL #101218 Facility ID: 13684	2959 COLLEGE DR	34	615
CIRCLE K #2709725 Facility ID: 13684	2959 COLLEGE DR	34	617
EXXONMOBIL OIL CORP Facility ID: 13366	4555 ESSEN LN	42	776
EXXONMOBIL OIL CORP Facility ID: 13366.0	4555 ESSEN LN	42	782
EXXONMOBIL OIL CORP Facility ID: 13366	4555 ESSEN LN	42	782

EXECUTIVE SUMMARY

Please refer to the end of the findings report for unmapped orphan sites due to poor or inadequate address information.

MAP FINDINGS SUMMARY

Database	Total Plotted
FEDERAL RECORDS	
NPL	0
Proposed NPL	0
Delisted NPL	0
NPL LIENS	0
SEMS	3
SEMS-ARCHIVE	3
LIENS 2	1
CORRACTS	0
RCRA-TSDF	0
RCRA-LQG	2
RCRA-SQG	16
RCRA-CESQG	67
RCRA NonGen / NLR	40
US ENG CONTROLS	0
US INST CONTROL	0
ERNS	4
HMIRS	0
DOT OPS	0
US CDL	0
US BROWNFIELDS	29
DOD	0
FUDS	0
LUCIS	0
CONSENT	0
ROD	0
UMTRA	0
ODI	0
DEBRIS REGION 9	0
US MINES	0
TRIS	1
TSCA	2
FTTS	0
HIST FTTS	0
SSTS	0
ICIS	7
PADS	0
MLTS	0
RADINFO	0
FINDS	138
RAATS	0
RMP	0
COAL ASH EPA	0
US AIRS	3
LEAD SMELTERS	0
FEDERAL FACILITY	0
FEMA UST	0
ECHO	113
FUELS PROGRAM	0

MAP FINDINGS SUMMARY

Database	Total Plotted
DOCKET HWC	0
UXO	0
FUSRAP	0
COAL ASH DOE	0
2020 COR ACTION	0
PRP	1
EPA WATCH LIST	0
US FIN ASSUR	0
PCB TRANSFORMER	0
US HIST CDL	0
SCRD DRYCLEANERS	0
IHS OPEN DUMPS	0
ABANDONED MINES	0

STATE AND LOCAL RECORDS

LA SHWS	2
LA SWF/LF	1
LA DEBRIS	1
LA AUL	3
LA HIST DEBRIS	0
LA UIC	0
LA SWRCY	3
LA LUST	2
LA HIST LUST	39
LA UST	90
LA DEL SHWS	1
LA LIENS	0
NY MANIFEST	1
LA SPILLS	55
LA VCP	6
LA DRYCLEANERS	10
LA BROWNFIELDS	1
LA CDL	0
TX Ind. Haz Waste	4
LA NPDES	34
LA AIRS	9
LA ASBESTOS	6
LA REM	43
LA COAL ASH	0
PA AIRS	1

TRIBAL RECORDS

INDIAN RESERV	0
INDIAN ODI	0
INDIAN LUST	0
INDIAN UST	0
INDIAN VCP	0

EDR PROPRIETARY RECORDS

EDR MGP	1

MAP FINDINGS SUMMARY

Database	Total Plotted
EDR Hist Auto	107
EDR Hist Cleaner	52
LA RGA HWS	0
LA RGA LF	1
LA RGA LUST	12

NOTES:

Sites may be listed in more than one database

1 **WEST BATON ROUGE PARISH COUNCIL - TURNER RD DEBRIS** **LA DEBRIS** **S112272098**
TURNER RD **N/A**
PORT ALLEN, LA

DEBRIS:

Latitude:	30.456272
Longitude:	-91.238822
Region:	Capital
AI #:	184683
Previously Used AI #:	Not reported
PEDS #:	Not reported
Approved Activities:	Vegetative burning open,Vegetative staging,Woodwaste staging
Responsible Party:	Not reported
Updated Status:	Not reported
Shared Same Location:	Not reported
Contact Information:	Jason Manola (225) 383-4755
Approval Conditions:	Not reported
Issue Date:	Not reported

Latitude:	30.45627200
Longitude:	-91.23882200
Region:	Capital
AI #:	184683
Previously Used AI #:	Not reported
PEDS #:	Not reported
Approved Activities:	Vegetative burning open,Vegetative staging,Woodwaste staging
Responsible Party:	Not reported
Updated Status:	Not reported
Shared Same Location:	Not reported
Contact Information:	Jason Manola (225) 383-4755
Approval Conditions:	Not reported
Issue Date:	Not reported

Latitude:	30.45627200
Longitude:	-91.23882200
Region:	Capital
AI #:	184683
Previously Used AI #:	Not reported
PEDS #:	Not reported
Approved Activities:	Vegetative burning open,Vegetative staging,Woodwaste staging
Responsible Party:	Not reported
Updated Status:	Not reported
Shared Same Location:	Not reported
Contact Information:	Jason Manola (225) 383-4755
Approval Conditions:	Not reported
Issue Date:	Not reported

---

2 **BR 132 SPANISH TOWN SITE 'B'** **US BROWNFIELDS FINDS** **1016356318**
SPANISH TOWN ROAD AT CANAL ST. **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 132 SPANISH TOWN SITE 'B'
Property #:	830340741-830340752, 830340756-830340763
Parcel size:	1.73
Property Description:	The site consists of 20 lots which are mostly undeveloped with some residential structures and uses. The subject property is surrounded by light commercial and residential properties. An occupied large

BR 132 SPANISH TOWN SITE 'B' (Continued) **1016356318**

	commercial/ office building is adjacent to the site. Mr. Joseph Atiyah was the property owner at the time of the Phase I and II ESA s.
	Not reported
Latitude:	30.4548735
Longitude:	-91.1793421
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	114501
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	12577
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Phase II Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	96637101
Ownership entity:	Private
Current owner:	Donnie Jarreau Companies
Did owner change:	Y
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported

BR 132 SPANISH TOWN SITE 'B' (Continued) **1016356318**

Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1.73
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	1.73
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Y
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported

BR 132 SPANISH TOWN SITE 'B' (Continued) **1016356318**

Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	689
% Below Poverty:	2.4%
# Low Income:	1142
% Low Income:	1.5%
Meidan Income:	2871
# Unemployed:	81
% Unemployed:	20.8%
# Vacant Housing:	196
% Vacant Housing:	8.6%
Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 132 SPANISH TOWN SITE 'B'
Property #:	830340741-830340752, 830340756-830340763
Parcel size:	1.73
Property Description:	The site consists of 20 lots which are mostly undeveloped with some residential structures and uses. The subject property is surrounded by light commercial and residential properties. An occupied large commercial/ office building is adjacent to the site. Mr. Joseph Atiyah was the property owner at the time of the Phase I and II ESA s.
	Not reported
Latitude:	30.4548735
Longitude:	-91.1793421
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	114501
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	4740
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Private
Current owner:	Donnie Jarreau Companies
Did owner change:	Y
Cleanup required:	No
Video available:	No

BR 132 SPANISH TOWN SITE 'B' (Continued) **1016356318**

Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	1.73
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	1.73
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Y
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

BR 132 SPANISH TOWN SITE 'B' (Continued) **1016356318**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	689
% Below Poverty:	2.4%
# Low Income:	1142
% Low Income:	1.5%
Meidan Income:	2871
# Unemployed:	81
% Unemployed:	20.8%
# Vacant Housing:	196
% Vacant Housing:	8.6%

FINDS:

Registry ID: 110042111899

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

3 **NINOS CASINO** **EDR Hist Auto** **1021654983**
121 LOBDELL HWY **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
2008	NINOS CASINO	Gambling And Lottery Services
2009	NINOS CASINO	Gambling And Lottery Services
2010	NINOS CASINO	Gambling And Lottery Services
2011	NINOS CASINO	Gambling And Lottery Services
2012	NINOS CASINO	Gambling And Lottery Services
2013	NINOS CASINO	Gambling And Lottery Services
2014	NINOS CASINO	Gambling And Lottery Services

---

3 **CRACKER BARREL STORES, #28** **LA HIST LUST** **S106033671**
133 LOBDELL HWY # 415 **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-002395
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	5-6 GAL
Quantity 2:	Not reported
Date Confirmed:	07/19/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0146
Incident Date:	07/19/1990
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	RICHARD JOHNSON/ EMER RESP.
Reported By 2:	Not reported
Owner ID:	00075100
Owner Name:	CRACKER BARREL STORES, INC
Owner Address:	12221 INDUSTRIPLEX BLVD
Owner City,St,Zip:	BATON ROUGE, LA 70809
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	08/07/1991
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

CRACKER BARREL STORES, #28 (Continued) **S106033671**

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: A PUMP HAS BEEN SHUT DOWN DUE TO A LEAK. SOMEONE RAN INTO THEDISPENSER AND CREATED A LINE LEAK UNDER THE DISPENSER. DEQ LETTER2/15/91 REQUESTED ASSESSMENT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	61-002395
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	90-2-0146
Incident Date:	07/19/1990
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00075100
Owner Name:	CRACKER BARREL STORES, INC
Owner Address:	12221 INDUSTRIPLEX BLVD
Owner City,St,Zip:	BATON ROUGE, LA 70809
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	08/07/1991
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: A PUMP HAS BEEN SHUT DOWN DUE TO A LEAK. SOMEONE RAN INTO THEDISPENSER AND CREATED A LINE LEAK UNDER THE DISPENSER. DEQ LETTER2/15/91 REQUESTED ASSESSMENT.

LA HIST LUST CORRECTIVE ACTION:

CRACKER BARREL STORES, #28 (Continued) **S106033671**

Comments: Not reported

---

3 CRACKER BARREL STORES INC #28 **LA UST** **U003925181**
133 LOBDELL HWY 415 **LA NPDES** **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	74892
Subject Item ID:	2
UST Tank Num:	3892
Tank Status:	**Removed**
Install Date:	05/01/1982
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Yes
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	3893
Tank Status:	**Removed**
Install Date:	05/01/1982
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported

CRACKER BARREL STORES INC #28 (Continued) **U003925181**

Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Yes
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	3894
Tank Status:	**Removed**
Install Date:	05/01/1982
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Yes
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	57327
Tank Status:	**Active**
Install Date:	07/01/2007
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported

CRACKER BARREL STORES INC #28 (Continued) **U003925181**

Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	57328
Tank Status:	**Active**
Install Date:	07/01/2007
Total Capacity:	15000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NPDES:

Facility Id:	74892
Facility Phone:	2253819421

CRACKER BARREL STORES INC #28 (Continued) **U003925181**

Issued Date:	03/07/2008
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20080001

Facility Id:	74892
Facility Phone:	2253819421
Issued Date:	12/14/2004
Title Description:	LAG531726 Permit
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20040001

Facility Id:	74892
Facility Phone:	2253819421
Issued Date:	08/30/2013
Title Description:	Renewal
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20120001

---

3 **AMERICAN GEN INVESTMENTS LLC** **EDR Hist Auto** **1022059925**
133 LOBDELL HWY 415 **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1994	CRACKER BARREL STORES INC	Gasoline Service Stations
1995	CRACKER BARREL STORES INC	Gasoline Service Stations
1996	CRACKER BARREL STORES INC	Gasoline Service Stations
1997	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations
1998	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations
1999	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations
2000	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations
2001	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2002	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2003	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2004	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2005	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2006	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2007	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2008	AMERICAN GEN INVESTMENTS LLC	Convenience Stores
2009	AMERICAN GEN INVESTMENTS LLC	Convenience Stores

---

3 **ARDES INC** **EDR Hist Auto** **1021675568**
111 LOBDELL HWY **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1991	BROUSSARDS CHEVRON	Gasoline Service Stations, NEC
1992	BROUSSARDS CHEVRON	Gasoline Service Stations, NEC
1993	BROUSSARDS CHEVRON	Gasoline Service Stations, NEC

ARDES INC (Continued) **1021675568**

1994	BROUSSARDS CHEVRON	Gasoline Service Stations, NEC
1995	ARDES INC	Gasoline Service Stations, NEC
1996	ARDES INC	Gasoline Service Stations, NEC
1997	ARDES INC	Gasoline Service Stations, NEC
1998	ARDES INC	Gasoline Service Stations, NEC
1999	ARDES INC	Gasoline Service Stations, NEC
2000	ARDES INC	Gasoline Service Stations, NEC
2001	ARDES INC	Gasoline Service Stations, NEC
2002	ARDES INC	Gasoline Service Stations, NEC
2003	ARDES INC	Gasoline Service Stations, NEC
2004	ARDES INC	Gasoline Service Stations, NEC
2005	ARDES INC	Gasoline Service Stations, NEC
2006	ARDES INC	Gasoline Service Stations, NEC
2007	ARDES INC	Gasoline Service Stations, NEC
2008	ARDES INC	Gasoline Service Stations, NEC
2009	ARDES INC	Gasoline Service Stations, NEC

---

3 **MATRIX FOOD STORE** **LA REM** **S118246541**
111 LOBDELL HWY **N/A**
PORT ALLEN, LA 70767

REM:

AI Num:	18777
Evaluated And Closed:	11/22/2005
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 5195325

---

3 **MATRIX FOOD STORE** **LA UST** **U003921844**
111 LOBDELL HWY **LA NPDES** **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	18777
Subject Item ID:	2
UST Tank Num:	35672
Tank Status:	**Active**
Install Date:	04/28/1988
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported

MATRIX FOOD STORE (Continued) **U003921844**

Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	35673
Tank Status:	**Active**
Install Date:	04/28/1988
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	35674
Tank Status:	**Active**
Install Date:	04/28/1988
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported

MATRIX FOOD STORE (Continued) **U003921844**

MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NPDES:

Facility Id:	18777
Facility Phone:	2253438891
Issued Date:	02/08/2008
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20080001

Facility Id:	18777
Facility Phone:	2253438891
Issued Date:	04/09/1998
Title Description:	Fiscal Migration: LAG530126
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN19930001

Facility Id:	18777
Facility Phone:	2253438891
Issued Date:	11/20/2002
Title Description:	LAG530126
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20020001

Facility Id:	18777
Facility Phone:	2253438891
Issued Date:	02/28/2005
Title Description:	LAG530126 Transfer of Permit
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20050001

Facility Id:	18777
Facility Phone:	2253438891
Issued Date:	07/01/2013
Title Description:	Renewal
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water

MATRIX FOOD STORE (Continued) **U003921844**

Activity Number: GEN20120001

---

3 WILLIAM TRAVEL CENTERS #3060 **LA HIST LUST** **S106034375**
123 LOBDELL HWY # I-10 **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-006212
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	11/26/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0248
Incident Date:	11/26/1990
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00184600
Owner Name:	MAPCO PETROLEUM
Owner Address:	1101 KERMIT DR, SUITE 800
Owner City,St,Zip:	NASHVILLE, TN 37217
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	08/14/1992
Assessment Approved Date:	06/23/1993
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	04/13/1995
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: AN INSPECTION WAS MADE AT THE ABOVE SITE IN REPONSE TO A REPORT OF ALEAK. A CRACK IN THE LINE MADE THE LEAK DETECTOR TRIP BUT INVENTORYRECORDS INDICATED NO LOSS OF PRODUCT. LINE WAS REPAIRED. SEE INCIDENTNO. 92-2-0174. DEQ LETTER 9/1/93 APPROVED FURTHER INVESTIGATION.

LA HIST LUST CORRECTIVE ACTION:
Comments: REC'D CAP ON 4-13-95. REC'D LETTER FROM CONSULTANT 6/7/95 WILLIMPLEMENT

WILLIAM TRAVEL CENTERS #3060 (Continued) **S106034375**

CORRECTIVE ACTION ON/ABOUT -/11/95. WAITING ON WASTEWATERDISCHARGE PERMIT. QTLY REPORTS SUBMITTED. REC'D TIGHTNESS TESTCERTIFICATE FOR 2 DIESEL FUEL LINES ON 7/16/96. RECEIVED CONSULTANTLETTER 4/13/99: COST ESIMATE FOR CONTINUED PERFORMANCE OF REMEDIATIONACTIVITIES.

Facility ID:	61-006212
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	90-2-0248
Incident Date:	11/26/1990
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00184600
Owner Name:	MAPCO PETROLEUM
Owner Address:	1101 KERMIT DR, SUITE 800
Owner City,St,Zip:	NASHVILLE, TN 37217
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	08/14/1992
Assessment Approved Date:	06/23/1993
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	04/13/1995
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: AN INSPECTION WAS MADE AT THE ABOVE SITE IN REPONSE TO A REPORT OF ALEAK. A CRACK IN THE LINE MADE THE LEAK DETECTOR TRIP BUT INVENTORYRECORDS INDICATED NO LOSS OF PRODUCT. LINE WAS REPAIRED. SEE INCIDENTNO. 92-2-0174. DEQ LETTER 9/1/93 APPROVED FURTHER INVESTIGATION.

LA HIST LUST CORRECTIVE ACTION:
Comments: REC'D CAP ON 4-13-95. REC'D LETTER FROM CONSULTANT 6/7/95 WILLIMPLEMENT CORRECTIVE ACTION ON/ABOUT -/11/95. WAITING ON WASTEWATERDISCHARGE PERMIT. QTLY REPORTS SUBMITTED. REC'D TIGHTNESS TESTCERTIFICATE FOR 2 DIESEL FUEL LINES ON

WILLIAM TRAVEL CENTERS #3060 (Continued) **S106034375**

7/16/96. RECEIVED CONSULTANTLETTER 4/13/99: COST ESIMATE FOR CONTINUED PERFORMANCE OF REMEDIATIONACTIVITIES.

Facility ID:	61-006212
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	07/15/1992
Date Confirmed 2:	Not reported
Incident Number:	92-2-0174
Incident Date:	Not reported
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	MARK SCHUTT/MAPCO PETROLEUM
Reported By 2:	Not reported
Owner ID:	00184600
Owner Name:	MAPCO PETROLEUM
Owner Address:	1101 KERMIT DR, SUITE 800
Owner City,St,Zip:	NASHVILLE, TN 37217
Assessment Pending Info:	No
Assessment Request Date:	08/20/1992
Assessment Plan Due Date:	11/10/1992
Assessment Plan Received Date:	06/24/1993
Assessment Approved Date:	06/24/1993
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	12/29/1993
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	04/08/1995
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	05/31/1995
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: VACUUM ENHANCED PUMPING TO RECOVER SOIL VAPORS, FREE-PHASE PRODUCT ANDGROUNDWATER SIMULTANEOUSLY UTILIZING A SINGLE PUMP APPROVED 5/31/95.REC'D LETTER FROM CONSULTANT DATED 6/7/95 WILL IMPLEMENT CAP DURINGTHE WEEK OF 9/11/95 WAITING ON PERMITS. DEQ LETTER 1-96 DO NOTSAMPLE FOR TPH BUT CONTINUE QT. MONITORING. DEQ LETTER 5/14/97CONTINUE QTLY REPORTS. REC'D SCOPE OF WORK AND EST COST TO EXPAND THEGW REMEDIATION SYSTEM ON 8/18/97. DEQ APPROVED WORK PLAN ON 9/23/97.REC'D ANNUAL REPORT 1/15/99: RECOMMEND REMEDIATION SYSTEM BE TURNEDOFF AND ALL SITE WELLS BE MONITORED MONTHLY AND SAMPLED QUARTERLY.

LA HIST LUST ASSESMENT:

Comments: TANK FAILED TIGHTNESS TEST ON 3/3/92. IT CORPORATION HIRED TO DOAN ASSESSMENT FOR MAPCO AND DISCOVERED PRODUCT. SEE INCIDENT NO.90-2-0248. DEQ LETTER 9/1/93 APPROVAL FOR FURTHER INVESTIGATION.REC'D PHASE II ASSESSMENT ON 12/29/93.

WILLIAM TRAVEL CENTERS #3060 (Continued) **S106034375**

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 1/12/94 REQUESTING 4 QUARTERS OF MONTHLY MONITORING ANDSAMPLING OF WELLS. DEQ LETTER 10/7/94 APPROVING CONSULTANT'S TO PLUGAND ABANDON MW-10. DEQ LETTER 11/1/94 CONTINUE MONTHLY MONITORING ANDQTLY REPORTS. GW EXCAVATION AND DISPOSAL PROPOSAL APPROVED 11/29/94.

Facility ID:	61-006212
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	92-2-0174
Incident Date:	Not reported
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00184600
Owner Name:	MAPCO PETROLEUM
Owner Address:	1101 KERMIT DR, SUITE 800
Owner City,St,Zip:	NASHVILLE, TN 37217
Assessment Pending Info:	No
Assessment Request Date:	08/20/1992
Assessment Plan Due Date:	11/10/1992
Assessment Plan Received Date:	06/24/1993
Assessment Approved Date:	06/24/1993
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	04/08/1995
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	05/31/1995
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	EXCAVATION, VACUUM ENHANCED PUMP
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: VACUUM ENHANCED PUMPING TO RECOVER SOIL VAPORS, FREE-PHASE PRODUCT ANDGROUNDWATER SIMULTANEOUSLY UTILIZING A SINGLE PUMP APPROVED 5/31/95.REC'D LETTER FROM CONSULTANT DATED 6/7/95 WILL IMPLEMENT CAP DURINGTHE WEEK OF 9/11/95 WAITING ON PERMITS. DEQ LETTER 1-96 DO NOTSAMPLE FOR TPH BUT CONTINUE QT. MONITORING. DEQ LETTER 5/14/97CONTINUE QTLY REPORTS. REC'D SCOPE OF WORK AND EST COST TO EXPAND THEGW REMEDIATION SYSTEM ON 8/18/97. DEQ APPROVED WORK PLAN ON 9/23/97.REC'D ANNUAL REPORT 1/15/99: RECOMMEND REMEDIATION SYSTEM BE TURNEDOFF AND ALL SITE WELLS BE MONITORED MONTHLY AND SAMPLED QUARTERLY.

WILLIAM TRAVEL CENTERS #3060 (Continued) **S106034375**

LA HIST LUST ASSESMENT:
Comments: TANK FAILED TIGHTNESS TEST ON 3/3/92. IT CORPORATION HIRED TO DOAN ASSESSMENT FOR MAPCO AND DISCOVERED PRODUCT. SEE INCIDENT NO.90-2-0248. DEQ LETTER 9/1/93 APPROVAL FOR FURTHER INVESTIGATION.REC'D PHASE II ASSESSMENT ON 12/29/93.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ LETTER 1/12/94 REQUESTING 4 QUARTERS OF MONTHLY MONITORING ANDSAMPLING OF WELLS. DEQ LETTER 10/7/94 APPROVING CONSULTANT'S TO PLUGAND ABANDON MW-10. DEQ LETTER 11/1/94 CONTINUE MONTHLY MONITORING ANDQTLY REPORTS. GW EXCAVATION AND DISPOSAL PROPOSAL APPROVED 11/29/94.

Facility ID:	61-006212
Facility Parish:	WEST BATON ROUGE
Substance Name:	DIESEL
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	06/26/1996
Date Confirmed 2:	Not reported
Incident Number:	96-2-0054
Incident Date:	06/26/1996
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	WAYNE COLLEY/PETRON
Reported By 2:	Not reported
Owner ID:	00184600
Owner Name:	MAPCO PETROLEUM
Owner Address:	1101 KERMIT DR, SUITE 800
Owner City,St,Zip:	NASHVILLE, TN 37217
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ENGINEERING ASSOCIATES, INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	07/29/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: PETRON WAS INSTALLING SUMPS AT THE ABOVE LOCATION. AS THEYWERE PRESSURING THE DIESEL LINE, IT STARTED LEAKING. LINE WILL BETESTED ONCE SOURCE OF LEAK IS

WILLIAM TRAVEL CENTERS #3060 (Continued) **S106034375**

FOUND. REC' 7 DAY WRITTEN NOTIFICATIONREPORT ON 7/9/96: PIN HOLE FOUND IN DIESEL PRODUCT LINE.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	61-006212
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	96-2-0054
Incident Date:	06/26/1996
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00184600
Owner Name:	MAPCO PETROLEUM
Owner Address:	1101 KERMIT DR, SUITE 800
Owner City,St,Zip:	NASHVILLE, TN 37217
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ENGINEERING ASSOCIATES, INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	07/29/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: PETRON WAS INSTALLING SUMPS AT THE ABOVE LOCATION. AS THEYWERE PRESSURING THE DIESEL LINE, IT STARTED LEAKING. LINE WILL BETESTED ONCE SOURCE OF LEAK IS FOUND. REC' 7 DAY WRITTEN NOTIFICATIONREPORT ON 7/9/96: PIN HOLE FOUND IN DIESEL PRODUCT LINE.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

3 **MAPCO INC** **EDR Hist Auto** **1021610389**
123 LOBDELL HWY **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1985	MAPCO INC	Gasoline Service Stations
1986	MAPCO INC	Gasoline Service Stations
1987	MAPCO INC	Gasoline Service Stations
1988	MAPCO INC	Gasoline Service Stations
1989	MAPCO INC	Gasoline Service Stations
1990	MAPCO INC	Gasoline Service Stations
1991	MAPCO INC	Gasoline Service Stations
1992	MAPCO INC	Gasoline Service Stations
1993	MAPCO INC	Gasoline Service Stations
1994	MAPCO INC	Gasoline Service Stations
1995	MAPCO INC	Gasoline Service Stations
1996	MAPCO PETROLEUM INC	Gasoline Service Stations
1997	MAPCO PETROLEUM INC	Gasoline Service Stations
1998	MAPCO PETROLEUM INC	Gasoline Service Stations
1999	WILLIAMS EXPRESS INC	Gasoline Service Stations
2000	WILLIAMS EXPRESS INC	Gasoline Service Stations
2001	WILLIAMS EXPRESS INC	Gasoline Service Stations
2002	WILLIAMS EXPRESS INC	Gasoline Service Stations
2003	PILOT TRAVEL CENTERS LLC	Gasoline Service Stations
2004	PILOT TRAVEL CENTERS LLC	Gasoline Service Stations
2005	PILOT TRAVEL CENTERS LLC	Gasoline Service Stations
2006	PILOT TRAVEL CENTERS LLC	Gasoline Service Stations
2007	PILOT TRAVEL CENTERS LLC	Gasoline Service Stations

---

3 **NINO'S CASINO LLC** **LA UST** **U003986940**
123 LOBDELL HWY **LA SPILLS** **N/A**
PORT ALLEN, LA 70767 **LA NPDES**
LA REM

UST:

Master Agency Id:	31055
Subject Item ID:	2
UST Tank Num:	17012
Tank Status:	**Removed**
Install Date:	01/01/1981
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes

NINO'S CASINO LLC (Continued) **U003986940**

Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	17013
Tank Status:	**Removed**
Install Date:	01/01/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	17014
Tank Status:	**Removed**
Install Date:	01/01/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported

NINO'S CASINO LLC (Continued) **U003986940**

MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	17015
Tank Status:	**Removed**
Install Date:	01/01/1981
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	17016
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported

NINO'S CASINO LLC (Continued) **U003986940**

Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	17017
Tank Status:	**Removed**
Install Date:	01/01/1981
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NINO'S CASINO LLC (Continued) **U003986940**

UST Tank Num:	17018
Tank Status:	**Removed**
Install Date:	01/01/1981
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	57589
Tank Status:	**Active**
Install Date:	07/01/2006
Total Capacity:	14000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

NINO'S CASINO LLC (Continued) **U003986940**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	57590
Tank Status:	**Active**
Install Date:	07/01/2006
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	57591
Tank Status:	**Active**
Install Date:	07/01/2006
Total Capacity:	14000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

NINO'S CASINO LLC (Continued) **U003986940**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

SPILLS:

Region Code:	CR
Date Rec:	07/15/2010
Date Initiated:	07/19/2010
aiid:	31055
Incident Id:	124895
Incident Date:	07/15/2010
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Nino's Truck Stop 123 Lobdell Hwy Port Allen
Incident Source Name:	Nino's Casino LLC
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	UST Release, Dispenser / Physical or Mechanical Damage
Comments:	This site visit was made in response to incident # 124895 in which this facility self-reported a spill of gasoline. This spill occurred when a customer impacted dispenser # 5 & 6 with his vehicle. This impact caused the gasoline sheer valve to dislodge slightly causing a temporary release of gasoline. Apparently, there was insufficient separation at this sheer valve to cause it to engage. Facility personell responded by shutting down all dispensers with the emergency shut off switch located inside the main building. The diesel sheer valve, located in the same dispenser, was not affected. Energy Equipment, Inc. was called and responded by replacing and setting the sheer valve top assembly. Energy Equipment called Gator Environmental to the remove a total of 24 gallons of gasoline which had collected in the dispenser sump. There was no impact to the native soil or groundwater as all spilled product was contained in the dispenser sump or confined to the surrounding concrete surface. LP
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0

Region Code:	CR
Date Rec:	07/15/2010
Date Initiated:	Not reported
aiid:	31055

NINO'S CASINO LLC (Continued) **U003986940**

Incident Id:	124895
Incident Date:	07/15/2010
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Nino's Truck Stop 123 Lobdell Hwy Port Allen
Incident Source Name:	Nino's Casino LLC
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	UST Release, Dispenser / Physical or Mechanical Damage
Comments:	This site visit was made in response to incident # 124895 in which this facility self-reported a spill of gasoline. This spill occurred when a customer impacted dispenser # 5 & 6 with his vehicle. This impact caused the gasoline sheer valve to dislodge slightly causing a temporary release of gasoline. Apparently, there was insufficient separation at this sheer valve to cause it to engage. Facility personell responded by shutting down all dispensers with the emergency shut off switch located inside the main building. The diesel sheer valve, located in the same dispenser, was not affected. Energy Equipment, Inc. was called and responded by replacing and setting the sheer valve top assembly. Energy Equipment called Gator Environmental to the remove a total of 24 gallons of gasoline which had collected in the dispenser sump. There was no impact to the native soil or groundwater as all spilled product was contained in the dispenser sump or confined to the surrounding concrete surface. LP
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0

NPDES:

Facility Id:	31055
Facility Phone:	2253830799
Issued Date:	03/03/1999
Title Description:	Fiscal Migration: LAG750232
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN19970001

Facility Id:	31055
Facility Phone:	2253830799
Issued Date:	05/07/2004
Title Description:	LAG750232 Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20040001

Facility Id:	151656
Facility Phone:	2253448669
Issued Date:	12/13/2007
Title Description:	Permit LAG541615
Permit Type Description:	Gen-LAG54-Sanitary Class II

NINO'S CASINO LLC (Continued) **U003986940**

Program: Water
Activity Number: GEN20070001

REM:
AI Num: 31055
Evaluated And Closed: 10/02/2007
Program: UST
EAC Type: Approve CA NFA w/ BOD
Comments: EDMS ID 5913685.

---

3 **RACETRAC PETROLEUM INC** **EDR Hist Auto** **1020214064**
214 HIGHWAY 415 **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1994	RACETRAC	Gasoline Service Stations
1995	RACETRAC INC	Gasoline Service Stations
1999	RACETRAC PETROLEUM INC	Gasoline Service Stations
2000	RACETRAC PETROLEUM INC	Gasoline Service Stations
2001	RACETRAC PETROLEUM INC	Gasoline Service Stations
2002	RACETRAC PETROLEUM INC	Gasoline Service Stations
2003	RACETRAC PETROLEUM INC	Gasoline Service Stations
2004	RACETRAC PETROLEUM INC	Gasoline Service Stations
2005	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2006	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2007	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2008	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2009	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2010	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2011	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2012	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2013	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2014	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC

---

3 **RACETRAC #365** **LA REM** **S110052281**
214 HWY 415 **N/A**
PORT ALLEN, LA 70767

REM:
AI Num: 71928
Evaluated And Closed: 03/27/2014
Program: UST
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 9247674

3 **RACETRAC #365** **LA UST** **U004156363**
214 HWY 415 **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	71928
Subject Item ID:	2
UST Tank Num:	32563
Tank Status:	**Removed**
Install Date:	10/17/1988
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	32564
Tank Status:	**Removed**
Install Date:	10/17/1988
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

RACETRAC #365 (Continued) **U004156363**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	32565
Tank Status:	**Removed**
Install Date:	10/17/1988
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

3 **LA EXPRESS #9 / EXXON** **LA UST** **U001894264**
222 HWY 415 **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	76897
Subject Item ID:	2

UST Tank Num:	40385
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported

LA EXPRESS #9 / EXXON (Continued) **U001894264**

Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	40386
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

LA EXPRESS #9 / EXXON (Continued) **U001894264**

UST Tank Num:	40387
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	40388
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes

LA EXPRESS #9 / EXXON (Continued) **U001894264**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	40389
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

3 **MCBR MANAGEMENT CO INC - MCDONALD'S** **LA NPDES** **S108334418**
150 LOBDELL HWY **LA REM** **N/A**
PORT ALLEN, LA 70767

NPDES:

Facility Id:	18806
Facility Phone:	2259296488
Issued Date:	04/28/2003
Title Description:	LAG530361 Renewed Permit Cov
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20020001

Facility Id:	18806
Facility Phone:	2259296488
Issued Date:	12/21/2007
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20070001

MCBR MANAGEMENT CO INC - MCDONALD'S (Continued) **S108334418**

Facility Id:	18806
Facility Phone:	2259296488
Issued Date:	08/30/2013
Title Description:	Renewal
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20120001

Facility Id:	18806
Facility Phone:	2259296488
Issued Date:	06/24/1998
Title Description:	LAG530361 Permit
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN19980001

REM:

AI Num:	18806
Evaluated And Closed:	03/15/2013
Program:	UST
EAC Type:	No Further Interest
Comments:	EDMS ID 8769622.

---

3 **UNIVERSAL INNS INC** **EDR Hist Auto** **1020939417**
215 LOBDELL HWY **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1980	UNIVERSAL DEV MANAGEMENT	Gasoline Service Stations
1982	UNIVERSAL DEV MANAGEMENT	Gasoline Service Stations
1983	UNIVERSAL DEV MNGMNT INC	Gasoline Service Stations
1985	UNIVERSAL DEV MNGMNT INC	Gasoline Service Stations
1986	UNIVERSAL INNS INC	Gasoline Service Stations
1987	UNIVERSAL INNS INC	Gasoline Service Stations
1988	UNIVERSAL INNS INC	Gasoline Service Stations
1989	UNIVERSAL INNS OF AMERICA INC	Gasoline Service Stations, NEC
1990	UNIVERSAL INNS OF AMERICA INC	Gasoline Service Stations, NEC
1991	UNIVERSAL DEVELOPMENT MGT	Gasoline Service Stations, NEC
1998	PORT ALLEN TRUCKSTOP & CASINO	Gasoline Service Stations, NEC
1999	PORT ALLEN TRUCKSTOP & CASINO	Gasoline Service Stations, NEC
2000	PORT ALLEN TRUCKSTOP & CASINO	Gasoline Service Stations, NEC

---

3 **WAL MART DISCOUNT CITIES** **EDR Hist Auto** **1021537476**
2808 COURT ST **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1994	WAL MART DISCOUNT CITIES	General Automotive Repair Shops
1995	WAL MART DISCOUNT CITIES	General Automotive Repair Shops

3 WALMART STORE #1136 — **RCRA-CESQG, LA UST, LA NPDES** — **1004711220, LAD985204338**
2808 COURT ST
PORT ALLEN, LA 70767

RCRA-CESQG:

Date form received by agency:	01/15/2009
Facility name:	WALMART STORE #1136
Facility address:	2808 COURT ST PORT ALLEN, LA 70767
EPA ID:	LAD985204338
Mailing address:	SW EIGHTH ST BENTONVILLE, AR 727160555
Contact:	PAM WILMOTT
Contact address:	SW EIGHTH ST BENTONVILLE, AR 727160555
Contact country:	US
Contact telephone:	(479) 204-2280
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	WALMART LOUISIANA LLC
Owner/operator address:	702 SW 8TH ST TWYLA GARVEY 0555 BENTONVILLE, AR 72716
Owner/operator country:	Not reported
Owner/operator telephone:	(479) 273-6840
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	WAL MART
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/17/2006
Owner/Op end date:	10/17/2006

Handler Activities Summary:
U.S. importer of hazardous waste: No

WALMART STORE #1136 (Continued) **1004711220**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 10/17/2006
Site name: WALMART STORE #1136
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 09/14/2004
Site name: WALMART STORE #1136
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 06/29/2001
Site name: WALMART STORE 1136
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 04/29/1991
Site name: WALMART STORE 1136

WALMART STORE #1136 (Continued) **1004711220**

Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

UST:

Master Agency Id:	20907
Subject Item ID:	1
UST Tank Num:	38627
Tank Status:	**Removed**
Install Date:	05/01/1988
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Gravity Feed

NPDES:

Facility Id:	20907
Facility Phone:	4792042280
Issued Date:	05/16/1996
Title Description:	Fiscal Migration: WP4346
Permit Type Description:	Not reported
Program:	Water
Activity Number:	PER19930001
Facility Id:	129406
Facility Phone:	4792042231
Issued Date:	07/01/2005
Title Description:	LAR10D083 Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20050001
Facility Id:	129406

WALMART STORE #1136 (Continued) **1004711220**

Facility Phone:	4792042231
Issued Date:	09/21/2005
Title Description:	LAR10D186 Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20050002

---

3 EMERALD PALACE TRUCK & CASINO PLAZA LLC **LA UST** **U000879389**
347 LOBDELL HWY **LA NPDES** **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	69283
Subject Item ID:	2
UST Tank Num:	35763
Tank Status:	**Removed**
Install Date:	07/28/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35764
Tank Status:	**Removed**
Install Date:	07/28/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported

EMERALD PALACE TRUCK & CASINO PLAZA LLC (Continued) **U000879389**

MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35765
Tank Status:	**Removed**
Install Date:	07/28/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35766
Tank Status:	**Removed**
Install Date:	07/28/1980
Total Capacity:	10000

EMERALD PALACE TRUCK & CASINO PLAZA LLC (Continued) **U000879389**

Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35767
Tank Status:	**Removed**
Install Date:	07/28/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported

EMERALD PALACE TRUCK & CASINO PLAZA LLC (Continued) **U000879389**

Pipe Method Description:	Not reported

UST Tank Num:	54877
Tank Status:	**Active**
Install Date:	03/02/1998
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	54878
Tank Status:	**Active**
Install Date:	03/02/1998
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes

EMERALD PALACE TRUCK & CASINO PLAZA LLC (Continued) **U000879389**

Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	54879
Tank Status:	**Active**
Install Date:	03/02/1998
Total Capacity:	16000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NPDES:

Facility Id:	69283
Facility Phone:	Not reported
Issued Date:	05/16/2014
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG54-Sanitary Class II
Program:	Water
Activity Number:	GEN20130001

Facility Id:	69283
Facility Phone:	Not reported
Issued Date:	12/12/2008
Title Description:	Permit
Permit Type Description:	Gen-LAG54-Sanitary Class II
Program:	Water
Activity Number:	GEN20080001

EMERALD PALACE TRUCK & CASINO PLAZA LLC (Continued) **U000879389**

Facility Id:	69283
Facility Phone:	Not reported
Issued Date:	02/24/2003
Title Description:	LAG541085
Permit Type Description:	Gen-LAG54-Sanitary Class II
Program:	Water
Activity Number:	GEN20030001

Facility Id:	69283
Facility Phone:	Not reported
Issued Date:	06/19/2002
Title Description:	LAG541085 Permit
Permit Type Description:	Gen-LAG54-Sanitary Class II
Program:	Water
Activity Number:	GEN20020001

---

3 **AM MART** **LA HIST LUST** **S106033494**
330 LOBDELL HWY # 415 **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-010247
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	10/26/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0227
Incident Date:	10/26/1990
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	W.D. SCOTT GROUP/GRETNA LA
Reported By 2:	Not reported
Owner ID:	00006600
Owner Name:	AM MART
Owner Address:	330 LOBDELL HWY. 415
Owner City,St,Zip:	PORT ALLEN, LA 70767
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported

AM MART (Continued) **S106033494**

Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: W.D. SCOTT GROUP OF GRETNA REPORTED THE POSSIBILITY OF A UST LEAK ATTHIS SITE. THE SCOTT GROUP WS EMPLOYED BY PELICAN HOMESTEAD OF NEWORLEANS (MORTGAGE HOLDER) TO PERFORM THE INVESTIGATION. FURTHERINVESTIGATION FOUND EVIDENCE OF A LEAK, AND PROMPTED DEQ TO ISSUE ACOMPLIANCE ORDER TO THE OWNER OF THE PROPERTY, ADIB SHAHLA. DEQINSPECTION 4/12/96 ABANDON TANKS FOUND.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 61-010247
Facility Parish: WEST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 90-2-0227
Incident Date: 10/26/1990
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00006600
Owner Name: AM MART
Owner Address: 330 LOBDELL HWY. 415
Owner City,St,Zip: PORT ALLEN, LA 70767
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

AM MART (Continued) **S106033494**

Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: W.D. SCOTT GROUP OF GRETNA REPORTED THE POSSIBILITY OF A UST LEAK ATTHIS SITE. THE SCOTT GROUP WS EMPLOYED BY PELICAN HOMESTEAD OF NEWORLEANS (MORTGAGE HOLDER) TO PERFORM THE INVESTIGATION. FURTHERINVESTIGATION FOUND EVIDENCE OF A LEAK, AND PROMPTED DEQ TO ISSUE ACOMPLIANCE ORDER TO THE OWNER OF THE PROPERTY, ADIB SHAHLA. DEQINSPECTION 4/12/96 ABANDON TANKS FOUND.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

---

3 **AM MART #1** **LA UST** **U003925623**
330 LOBDELL HWY 415 **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	76344
Subject Item ID:	1
UST Tank Num:	27377
Tank Status:	**Closed**
Install Date:	01/01/1982
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	27378
Tank Status:	**Closed**
Install Date:	01/01/1982
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported

AM MART #1 (Continued) **U003925623**

Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	27379
Tank Status:	**Closed**
Install Date:	01/01/1982
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

3 QUALITY CARRIERS INC — **RCRA NonGen / NLR** — **1010318396**
420 LOBDELL HWY — **LAR000043018**
PORT ALLEN, LA 70767

RCRA NonGen / NLR:

Date form received by agency:	04/07/2006
Facility name:	QUALITY CARRIERS INC
Facility address:	420 LOBDELL HWY PORT ALLEN, LA 70767
EPA ID:	LAR000043018
Mailing address:	E PENNSYLVANIA AVE, STE 430 DOWNINGTON, PA 19335
Contact:	JAMES A RAKITSKY
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	(800) 276-2608
Telephone ext.:	3121
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	QUALITY CARRIERS
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/07/2006
Owner/Op end date:	Not reported

Owner/operator name:	CASH'S TRUCK STOP
Owner/operator address:	LOBDELL HWY PORT ALLEN, LA 70767
Owner/operator country:	US
Owner/operator telephone:	(225) 387-0627
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	04/07/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

QUALITY CARRIERS INC (Continued) **1010318396**

Used oil transfer facility: No
Used oil transporter: No

. Waste code: D018
. Waste name: BENZENE

. Waste code: D023
. Waste name: O-CRESOL

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D025
. Waste name: P-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: U051
. Waste name: CREOSOTE

Violation Status: No violations found

---

3 **CASH'S CASINO, INC.**
420 LOBDELL HWY
PORT ALLEN, LA 70767

ICIS **1005640916**
FINDS **N/A**
LA UST
LA SPILLS
LA NPDES
ECHO

ICIS:

Enforcement Action ID:	06-2000-0327
FRS ID:	110010696844
Action Name:	CASH'S CASINO
Facility Name:	CASH'S CASINO
Facility Address:	420 LOBDELL HWY PORT ALLEN, LA 70767
Enforcement Action Type:	RCRA 9006 Field Citation (UST)
Facility County:	WEST BATON ROUGE
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	9006FC
Facility SIC Code:	5541
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.454398
Longitude in Decimal Degrees:	-91.247587
Permit Type Desc:	Not reported
Program System Acronym:	20234
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	CASH'S CASINO
Address:	420 LOBDELL HWY
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	5541

CASH'S CASINO, INC. (Continued) **1005640916**

Facility Name:	CASH'S CASINO
Address:	420 LOBDELL HWY
Tribal Indicator:	N
Fed Facility:	No
NAIC Code:	Not reported
SIC Code:	7999

FINDS:

Registry ID: 110010696844

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UST:

Master Agency Id:	79784
Subject Item ID:	2
UST Tank Num:	52431
Tank Status:	**Active**
Install Date:	06/01/1998
Total Capacity:	14000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

CASH'S CASINO, INC. (Continued) **1005640916**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	52433
Tank Status:	**Active**
Install Date:	01/01/1998
Total Capacity:	14000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	52434
Tank Status:	**Active**
Install Date:	06/01/1998
Total Capacity:	14000
Number Of Compartments:	1

CASH'S CASINO, INC. (Continued) **1005640916**

Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

SPILLS:

Region Code:	Not reported
Date Rec:	08/27/2008
Date Initiated:	Not reported
aiid:	83605
Incident Id:	108407
Incident Date:	08/27/2008
Incident Status:	**Pending Review**
Media Desc:	Air
Location Description:	Cash's 420 Lobdell Hwy (LA 415) Port Allen
Incident Source Name:	West Baton Rouge Parish
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s08-3295 Cash's Truck Stop--smell of natural gas leaking from truck...jd
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

NPDES:

Facility Id:	79784
Facility Phone:	Not reported
Issued Date:	05/16/2014
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG54-Sanitary Class II

CASH'S CASINO, INC. (Continued) **1005640916**

Program:	Water
Activity Number:	GEN20130001
Facility Id:	79784
Facility Phone:	Not reported
Issued Date:	03/13/2003
Title Description:	LAG541105 Permit
Permit Type Description:	Gen-LAG54-Sanitary Class II
Program:	Water
Activity Number:	GEN20020001
Facility Id:	79784
Facility Phone:	Not reported
Issued Date:	08/22/2008
Title Description:	Renewed Permit LAG541105
Permit Type Description:	Gen-LAG54-Sanitary Class II
Program:	Water
Activity Number:	GEN20080001

ECHO:

Envid:	1005640916
Registry ID:	110010696844
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110010696844

---

3 **WEST BATON ROUGE PARISH COUNCIL** **RCRA-SQG** **1000159638**
553A LOBDELL HWY **LAD981586241**
PORT ALLEN, LA 70767

RCRA-SQG:

Date form received by agency:	04/07/2000
Facility name:	WEST BATON ROUGE PARISH COUNCIL
Facility address:	553A LOBDELL HWY PORT ALLEN, LA 70767
EPA ID:	LAD981586241
Mailing address:	P.O. BOX 757 PORT ALLEN, LA 70767
Contact:	TED DENSTEL
Contact address:	P.O. BOX 757 PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 383-4755
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WBR POLICE JURY
Owner/operator address:	553 LOBDELL HWY PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 383-4755

WEST BATON ROUGE PARISH COUNCIL (Continued) **1000159638**

Legal status: County
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/01/1987
Date achieved compliance: 09/30/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/04/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/30/1988
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/01/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/30/1988
Evaluation lead agency: State

4 **PARAMOUNT CLNS DCLO CLNS** **EDR Hist Cleaner** **1013783176**
806 HARRISON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1955	PARAMOUNT CLNS DCLO CLNS	CLEANERS AND DYERS

---

4 **PARAMOUNT CLEANERS** **EDR Hist Cleaner** **1013777850**
906 HARRISON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	PARAMOUNT CLEANERS	CLEANERS AND DYERS

---

4 **LEES AUTO REPR SHOP** **EDR Hist Auto** **1013775948**
721 HARRISON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1955	LEES AUTO REPR SHOP	AUTOMOBILE REPAIRING

---

4 **SAMPSON BURT C AUTO REPR** **EDR Hist Auto** **1013772289**
821 HARRISON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	SAMPSON BURT C AUTO REPR	AUTOMOBILE REPAIRING
1950	FIELD COLLINS C AUTO REPR	AUTOMOBILE REPAIRING

---

4 **MARCELLES EXXON SERVICE STA** **EDR Hist Auto** **1013760952**
1026 E WASHINGTON **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1966	MARCELLES ESSO SERVICENTER	GASOLINE STATIONS
1969	MARCELLES ESSO SERVICE STATION	Gasoline Service Stations
1970	MARCELLES ESSO SERVICENTER	GASOLINE STATIONS
1970	MARCELLES ESSO SERVICE STATION	Gasoline Service Stations
1971	MARCELLES ESSO SERVICE STATION	Gasoline Service Stations
1972	MARCELLES ESSO SERVICE STATION	Gasoline Service Stations
1973	MARCELLES EXXON SERVICE STA	Gasoline Service Stations
1974	MARCELLES EXXON SERVICE STA	Gasoline Service Stations
1975	MARCELLES EXXON SERVICENTER	GASOLINE STATIONS
1975	MARCELLES EXXON SERVICE STA	Gasoline Service Stations
1976	MARCELLES EXXON SERVICE STA	Gasoline Service Stations

MARCELLES EXXON SERVICE STA (Continued) **1013760952**

1977	MARCELLES EXXON SERVICE STA	Gasoline Service Stations
1980	MARCELLES EXXON SERVICENTER	GASOLINE STATIONS

---

4 **BAMA CLNRS DCLO CLNRS** **EDR Hist Cleaner** **1013783949**
690 WASHINGTON ST E **N/A**
S BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	BAMA CLNRS DCLO CLNRS	CLEANERS AND DYERS

---

4 **BAMA CLN** **EDR Hist Cleaner** **1013777236**
690 WASHINGTON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1955	BAMA CLN	CLEANERS AND DYERS

---

4 **BOONE MILTON CLO CLNR** **EDR Hist Cleaner** **1013785366**
1220 WASHINGTON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1945	BOONE MILTON CLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

4 **BOONE MILTON C DCLO CLNR** **EDR Hist Cleaner** **1013781332**
1220 WASHINGTON ST **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1940	BOONE MILTON C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

4 **MARCELLE S ESSO SERV FILL STA** **EDR Hist Auto** **1013769969**
1001 WASHINGTON ST E **N/A**
S BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	MARCELLE S ESSO SERV FILL STA	GASOLINE STATIONS

4 **MARCELLES ESSO SERVICENTER** **EDR Hist Auto** **1013757875**
1001 WASHINGTON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1955	MARCELLES ESSO SERVICENTER	GASOLINE SERVICE STATIONS
1960	MARCELLES ESSO SERVICENTER	GASOLINE STATIONS

---

4 **GREEN ANTHONY C DCLO CLNR** **EDR Hist Cleaner** **1013779559**
1313 WASHINGTON ST **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1936	GREEN ANTHONY C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

4 **BUTLER GAS** **LA SPILLS** **S108592944**
1776 THOMAS H. DELPIT (EAST BLVD.) **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	10/01/2002
Date Initiated:	Not reported
aiid:	26960
Incident Id:	55519
Incident Date:	10/01/2002
Incident Status:	**Open**
Media Desc:	Not reported
Location Description:	Butler Gas 1776 Thomas H. Delpit (East Blvd.) Baton Rouge
Incident Source Name:	Butler Gas
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s02-3536 Abandoned UST site. col
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

4 **BUTLER GAS** **LA RGA LUST** **S115490667**
1776 EAST BLVD **N/A**
BATON ROUGE, LA

RGA LUST:

2004	BUTLER GAS	1776 EAST BLVD
2003	BUTLER GAS	1776 EAST BLVD
2002	BUTLER GAS	1776 EAST BLVD

4 **MERCURY GASOLINE CO INC** **EDR Hist Auto** **1013774816**
1776 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1960	MERCURY GASOLINE CO INC	GASOLINE STATIONS
1970	BUTLERS MERCURY GAS	GASOLINE STATIONS
1975	BUTLERS MERCURY GAS	GASOLINE STATIONS
1980	BUTLERS GAS	GASOLINE STATIONS

---

4 **BUTLERS GAS** **EDR Hist Auto** **1013765705**
1776 THOMAS H DELPIT DR **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1990	BUTLERS GAS	GASOLINE STATIONS
1995	BUTLERS GAS	GASOLINE STATIONS

---

4 **BUTLER GAS** **LA UST** **U004222112**
1776 EAST BLVD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	26960
Subject Item ID:	1
UST Tank Num:	4348
Tank Status:	**Removed**
Install Date:	05/03/1978
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported

BUTLER GAS (Continued) **U004222112**

Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	4349
Tank Status:	**Removed**
Install Date:	05/03/1978
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	4350
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported

BUTLER GAS (Continued) **U004222112**

A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

4 **LDEQ** **LA SPILLS** **S118157401**
1776 THOMAS H DELPIT DR **N/A**
BATON ROUGE, LA 70802

SPILLS:

Region Code:	CR
Date Rec:	05/15/2015
Date Initiated:	Not reported
aiid:	115957
Incident Id:	163712
Incident Date:	05/15/2015
Incident Status:	**Closed**
Media Desc:	Not reported
Location Description:	1776 Thomas H. Delpit Dr.
Incident Source Name:	A2Z Towing & Auto Salvage LLC
Reporter Name:	Jeffrey Stansberry
Mailing Address 1:	2225 College Dr Apt 6
Mailing City:	Baton Rouge
Mailing State:	LA
Mailing Zip:	70808
Incident Desc:	c15-60802unregistered tire sales & unknown tire disposal methods; Automotive Parts Solutions. col
Incident Type Desc:	Complaint, Miscellaneous
Comments:	On 05/20/2015, April Wallace and Sheena Brauer investigated incident # 163712 at 1776 Thomas H. Delpit Drive, Baton Rouge. Jeffrey Stansberry of the Waste Tire Audit section of LDEQ submitted the complaint. The complaint states that Automotive Parts Solutions Incorporated is not registered and that the tire disposal methods are unknown. Upon arrival, Inspectors observed that the name of the active business was A2Z Towing and Auto Salvage. Inspectors spoke with facility personnel who stated that Automotive Parts Solutions had closed approximately a year ago. Inspectors conducted a waste tire inspection of the current business. Refer to tempo activity number INS20150002 for AI#115957. On 06/02/2015, Sheena Bares spoke with Jeffrey Stansberry to inform him of the findings of the investigation. SAB
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

4 BUTLER'S GAS STATION **LA HIST LUST** **S106033545**
1776 THOMAS DELPIT DR. **N/A**
BATON ROUGE, LA 70802

HIST LUST:

Facility ID:	17-001184
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	05/24/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0171
Incident Date:	05/24/1991
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	BRAD MORRIS/CK ASS
Reported By 2:	Not reported
Owner ID:	00049100
Owner Name:	BUTHON, FRANK
Owner Address:	1776 THOMAS DELPIT DR.
Owner City,St,Zip:	BATON ROUGE, LA 70802
Assessment Pending Info:	No
Assessment Request Date:	07/16/1991
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: LEL FOUND IN SCB MANHOLE. SC BELL EMPLOYEES FOUND GASOLINEIN MANHOLE AT E. WASHINGTON AND THOMAS DELPIT ST. NATIONALOIL TO PUMP OIL OUT OF MANHOLE

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-001184
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported

BUTLER'S GAS STATION (Continued) **S106033545**

Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0171
Incident Date:	05/24/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00049100
Owner Name:	BUTHON, FRANK
Owner Address:	1776 THOMAS DELPIT DR.
Owner City,St,Zip:	BATON ROUGE, LA 70802
Assessment Pending Info:	No
Assessment Request Date:	07/16/1991
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: LEL FOUND IN SCB MANHOLE. SC BELL EMPLOYEES FOUND GASOLINEIN MANHOLE AT E. WASHINGTON AND THOMAS DELPIT ST. NATIONALOIL TO PUMP OIL OUT OF MANHOLE

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

---

4 **MID CITY OIL CO INC** **EDR Hist Auto** **1013769893**
1413 WASHINGTON ST E **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1955	MID CITY OIL CO	GASOLINE SERVICE STATIONS
1960	MID CITY OIL CO INC	GASOLINE STATIONS

4 **MID CITY OIL CO** **EDR Hist Auto** **1013766897**
1413 WASHINGTON ST E **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1969	MID-CITY OIL CO INC	Gasoline Service Stations
1970	MID CITY OIL CO	GASOLINE STATIONS
1970	MID-CITY OIL CO INC	Gasoline Service Stations
1971	MID-CITY OIL CO INC	Gasoline Service Stations
1972	MID-CITY OIL CO INC	Gasoline Service Stations
1973	MID-CITY OIL CO INC	Gasoline Service Stations
1974	MID-CITY OIL CO INC	Gasoline Service Stations
1975	MID CITY OIL CO	GASOLINE STATIONS
1975	MID-CITY OIL CO INC	Gasoline Service Stations

---

4 **SNOWFLAKES RESTAURANT** **LA SPILLS** **S110101911**
1425 E. WASHINGTON **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	05/01/2001
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	42012
Incident Date:	05/01/2001
Incident Status:	**Closed**
Media Desc:	Not reported
Location Description:	Snowflakes Restaurant 1425 E. Washington Baton Rouge
Incident Source Name:	Snowflakes Restaurant
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c01-1303 dumping of waste oil, etc. in sewer
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	cooking grease

---

4 **MARGARET VALLET MUSIC INC** **EDR Hist Cleaner** **1018437627**
724 EDUCATION ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
2011	MARGARET VALLET MUSIC INC	Laundry And Drycleaner Agents
2012	MARGARET VALLET MUSIC INC	Laundry And Drycleaner Agents
2013	MARGARET VALLET MUSIC INC	Laundry And Drycleaner Agents
2014	MARGARET VALLET MUSIC INC	Laundry And Drycleaner Agents

4 **CAPITOL CLEANERS** **LA DRYCLEANERS** **S107446495**
1642 THOMAS H DELPIT DR **N/A**
BATON ROUGE, LA 70802

DRYCLEANERS:

Facility ID:	39238
Owner:	Anthony Rotolo
Owner Telephone:	Not reported
Store Telephone:	--
Mailing Address:	1642 Thomas H Delpit Dr
Mailing City,St,Zip:	Baton Rouge, LA 70802
Contact:	Not reported

Facility ID:	39238
Owner:	ANTHONY ROTOLO
Owner Telephone:	Not reported
Store Telephone:	225-343-1881
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact:	Not reported

---

4 **ROTOLO SHELBY & ANTHONY** **EDR Hist Cleaner** **1013782692**
1642 E BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1940	CAPITOL CLEANERS DCLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1945	CAPITAL CLEANERS CLO CLNRS	CLOTHES PRESSERS AND CLEANERS
1955	CAPITOL CLNS	CLEANERS AND DYERS
1960	CAPITOL CLNS	CLOTHES PRESSERS AND CLEANERS
1966	CAPITOL CLEANERS	CLEANERS AND DYERS
1970	CAPITOL CLEANERS	CLEANERS AND DYERS
1975	CAPITOL CLEANERS	CLEANERS AND DYERS
1975	ROTOLO SHELBY LAUNDROMAT	LAUNDRIES-SELF SERVE
1980	CAPITOL CLEANERS	CLEANERS-SELF SERVE
1987	ROTOLO SHELBY & ANTHONY	Miscellaneous Personal Services
1988	ROTOLO SHELBY & ANTHONY	Miscellaneous Personal Services

---

4 **CAPITOL CLEANERS** **EDR Hist Cleaner** **1013781387**
1642 THOMAS H DELPIT DR **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1990	CAPITOL CLEANERS	CLEANERS-SELF SERVE
1994	CAPITOL CLEANERS	Garment Pressing And Cleaners' Agents
1995	CAPITOL CLEANERS	CLEANERS
1995	CAPITOL CLEANERS	Garment Pressing And Cleaners' Agents
1996	CAPITOL CLEANERS	Garment Pressing And Cleaners' Agents
1997	CAPITOL CLEANERS	Garment Pressing And Cleaners' Agents
1998	CAPITOL CLEANERS	Garment Pressing And Cleaners' Agents
1999	CAPITOL CLEANERS	Garment Pressing And Cleaners' Agents
2000	CAPITOL CLEANERS PICKUP STA LAU	CLEANERS

Map ID Direction Distance Distance (ft.)	Site	Database(s)	EDR ID Number EPA ID Number
4	**KINGS GARAGE AUTO REPRS** **653 EDUCATION ST** **SOUTH BATON ROUGE, LA**	**EDR Hist Auto**	**1013769805** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1955	KINGS GARAGE	AUTOMOBILE REPAIRING
1960	KINGS GARAGE AUTO REPRS	AUTOMOBILE REPAIRING

4	**KINGS GARAGE** **653 EDUCATION ST** **BATON ROUGE, LA 70802**	**EDR Hist Auto**	**1013757713** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1970	KINGS GARAGE	AUTOMOBILE REPAIRING

4	**KING JAS W AUTO REPR** **924 HOWARD ST** **SOUTH BATON ROUGE, LA**	**EDR Hist Auto**	**1013754688** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1955	KING JAS W AUTO REPR	AUTOMOBILE REPAIRING
1960	KING JAS W AUTO REPR	AUTOMOBILE REPAIRING

4	**KING JAS W C AUTO REPR** **924 HOWARD ST** **S BATON ROUGE, LA**	**EDR Hist Auto**	**1013757710** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1950	KING JAS W C AUTO REPR	AUTOMOBILE REPAIRING

4	**KING JAMES W AUTO REPR** **924 HOWARD ST** **BATON ROUGE, LA 70802**	**EDR Hist Auto**	**1013763789** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1966	KING JAMES W AUTO REPR	AUTOMOBILE REPAIRING
1970	KING JAMES W AUTO REPR	AUTOMOBILE REPAIRING
1975	KING JAMES W AUTO REPR	AUTOMOBILE REPAIRING

4 **MCKINLEY MIDDLE SCHOOL** **LA NPDES** **S108338204**
1557 MCCALOP ST **N/A**
BATON ROUGE, LA 70802

NPDES:

Facility Id:	5253
Facility Phone:	Not reported
Issued Date:	01/06/2005
Title Description:	LAR10C805 permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20040001

---

4 **TRAHANS AUTO REPAIR** **EDR Hist Auto** **1013767810**
1588 BRADDOCK ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1960	TRAHANS AUTO REPR	AUTOMOBILE REPAIRING
1966	TRAHANS AUTO REPAIR	AUTOMOBILE REPAIRING
1970	TRAHANS AUTO REPAIR	AUTOMOBILE REPAIRING

---

4 **TRAHANS PAINT & REPR SHOP** **EDR Hist Auto** **1013767811**
1588 BRADDOCK ST **N/A**
S BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	TRAHANS GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1955	TRAHANS PAINT & REPR SHOP	AUTOMOBILE REPAIRING

---

4 **X RAY CLNS** **EDR Hist Cleaner** **1013783181**
1533 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1955	X RAY CLNS	CLEANERS AND DYERS
1960	PARAMOUNT X RAY CINS	CLOTHES PRESSERS AND CLEANERS
1966	PARAMOUNT X RAY CLEANERS	CLEANERS AND DYERS
1970	PARAMOUNT X RAY CLEANERS	CLEANERS AND DYERS
1971	BANKS ROOSEVELT	Drycleaning Plants, Except Rugs
1972	BANKS ROOSEVELT	Drycleaning Plants, Except Rugs
1973	BANKS ROOSEVELT	Drycleaning Plants, Except Rugs
1974	BANKS ROOSEVELT	Drycleaning Plants, Except Rugs

4 **TRAHANS GARAGE AUTO REPRS** **EDR Hist Auto** **1013752946**
1534 BADDOCK ST **N/A**
SOUTH BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1945	TRAHANS GARAGE AUTO REPRS	AUTOMOBILE REPAIRING
1945	ACME SERV BODY & FENDER WORKS	AUTOMOBILE REPAIRING

---

4 **X RAY CLEANERS** **EDR Hist Cleaner** **1013786217**
1510 UTAH ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	X RAY CLEANERS	CLEANERS AND DYERS

---

4 **ELMOS GARAGE C AUTO REPRS** **EDR Hist Auto** **1013760229**
938 LOUISE ST **N/A**
S BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	ELMOS GARAGE C AUTO REPRS	AUTOMOBILE REPAIRING

---

4 **HANKS AUTO REPAIR** **EDR Hist Auto** **1013765300**
938 LOUISE ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1960	ATKINS AUTO SERV REPRS	AUTOMOBILE REPAIRING
1970	ELMOS GARAGE	AUTOMOBILE REPAIRING
1975	ELMOS GARAGE	AUTOMOBILE REPAIRING
1980	ROBERTSONS GARAGE	AUTOMOBILE REPAIRING
1990	HANK AUTO REPAIR AUTO REPR	AUTOMOBILE REPAIRING
1995	HANKS AUTO REPAIR	AUTOMOBILE REPAIRING & SERVICE

---

4 **BR 149 HOPE VI 1533 THOMAS H DELPIT BUTLER PLACE** **US BROWNFIELDS FINDS** **1016356354**
1533 THOMAS H DELPIT & 1503 UTAH ST. **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 149 HOPE VI 1533 THOMAS H DELPIT BUTLER PLACE
Property #:	840353423 & 840353429
Parcel size:	.18
Property Description:	The property was formerly utilized by a dry cleaning facility.
Latitude:	30.434131
Longitude:	-91.178500

BR 149 HOPE VI 1533 THOMAS H DELPIT BUTLER PLACE (Continued) **1016356354**

HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	50401
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	6257
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Government
Current owner:	East Baton Rouge Parish Housing Authority
Did owner change:	N
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported

BR 149 HOPE VI 1533 THOMAS H DELPIT BUTLER PLACE (Continued) **1016356354**

PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	.18
Future use greenspace acreage:	Not reported
Future use residential acreage:	.18
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported

BR 149 HOPE VI 1533 THOMAS H DELPIT BUTLER PLACE (Continued) **1016356354**

IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	1254
% Below Poverty:	2.9%
# Low Income:	2334
% Low Income:	1.6%
Meidan Income:	7407
# Unemployed:	259
% Unemployed:	14.0%
# Vacant Housing:	402
% Vacant Housing:	9.0%

FINDS:

Registry ID: 110042112326

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

4 **PEL STATE OIL CO NO** **EDR Hist Auto** **1013766278**
1492 EAST BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1955	PEL STATE OIL CO NO 3 FILL STA	GASOLINE SERVICE STATIONS
1966	PEL STATE OIL CO NO	GASOLINE STATIONS
1970	PEL STATE OIL CO NO	GASOLINE STATIONS
1975	PEL STATE OIL CO NO	GASOLINE STATIONS
1980	FINA SERVICE STATION	GASOLINE STATIONS
1990	FINA SERVICE STATION	GASOLINE STATIONS
1995	PEL STATE OIL	GASOLINE STATIONS

---

4 **PEL STATE OIL CO #43** **LA UST** **U004052129**
1492 EAST BLVD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	72133
Subject Item ID:	1
UST Tank Num:	19626
Tank Status:	**Closed**
Install Date:	04/30/1961
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes

PEL STATE OIL CO #43 (Continued) **U004052129**

Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	19627
Tank Status:	**Closed**
Install Date:	04/30/1961
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

4 BR 147 HOPE VI JULIA ST. SUBURB SWART, LOTS 1&2 — **US BROWNFIELDS** — **1016356355**
V THOMAS H DELPIT DR. — **FINDS** — **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 147 HOPE VI JULIA ST. SUBURB SWART, LOTS 1&2
Property #:	840352650 & 840352651
Parcel size:	.1
Property Description:	Former dry cleaners on adjacent property.
Latitude:	30.434747
Longitude:	-91.1790981
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	World Geodetic System of 1984
ACRES property ID:	50421
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	6257
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Government
Current owner:	East Baton Rouge Parish Housing Authority
Did owner change:	N
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported

BR 147 HOPE VI JULIA ST. SUBURB SWART, LOTS 1&2 (Continued) **1016356355**

Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	.1
Future use greenspace acreage:	Not reported
Future use residential acreage:	.1
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported

BR 147 HOPE VI JULIA ST. SUBURB SWART, LOTS 1&2 (Continued) **1016356355**

Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	1216
% Below Poverty:	2.9%
# Low Income:	2289
% Low Income:	1.6%
Meidan Income:	6938
# Unemployed:	265
% Unemployed:	13.5%
# Vacant Housing:	381
% Vacant Housing:	9.4%

FINDS:

Registry ID: 110042112335

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

4 **WHITE STAR CLN & LNDRY BR** **EDR Hist Cleaner** **1013784877**
1429 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1955	WHITE STAR CLN & LNDRY BR	LAUNDRIES

---

4 **NOLAN CLNRS & DYERS CLDO CLNRS** **EDR Hist Cleaner** **1013785874**
1401 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1940	NOLAN CLNRS & DYERS CLDO CLNRS	CLOTHES PRESSERS AND CLEANERS

4 **CASH PRESSING CLUB** **EDR Hist Cleaner** **1013786706**
1319 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1931	CASH PRESSING CLUB	CLOTHES PRESSERS AND CLEANERS

---

4 **GIAMMERSE SAM** **EDR Hist Auto** **1022158252**
1306 EAST BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1969	GIAMMERSE SAM	Grocery Stores
1970	GIAMMERSE SAM	Grocery Stores
1971	GIAMMERSE SAM	Grocery Stores
1972	GIAMMERSE SAM	Grocery Stores
1973	GIAMMERSE SAM	Grocery Stores

---

4 **HOME OIL CO INC** **EDR Hist Auto** **1013766428**
1304 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1931	HOME OIL CO	GASOLINE AND OIL SERVICE STATIONS
1940	HOME OIL CO INC	GASOLINE AND OIL SERVICE STATIONS
1945	HOME OIL CO STATION NO 1 FILLIN	GASOLINE AND OIL SERVICE STATIONS

---

4 **ALLEN ESSO SERV STA** **EDR Hist Auto** **1013765195**
1302 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1955	ALLEN ESSO SERV STA	GASOLINE SERVICE STATIONS
1960	ALLENS ESSO SERV STA	GASOLINE STATIONS
1966	ALLENS ESSO SERVICE STATION	GASOLINE STATIONS

---

4 **A B C CLEANERS & LAUNDRY** **EDR Hist Cleaner** **1013779847**
1303 EAST BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1966	A B C CLEANERS INC	CLEANERS AND DYERS
1970	A B C CLEANERS & LAUNDRY	CLEANERS AND DYERS
1975	DUKES CLEANERS	CLEANERS AND DYERS
1980	CLEANING WORLD	CLEANERS AND DYERS

4 **BOBS CLEANERS** **EDR Hist Cleaner** **1018441720**
1303 THOMAS H DELPIT DR **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1994	BOBS CLEANERS	Garment Pressing And Cleaners' Agents
1995	BOBS CLEANERS	Garment Pressing And Cleaners' Agents
1996	BOBS CLEANERS	Garment Pressing And Cleaners' Agents

---

4 **BATON ROUGE HAT CLEANERS** **EDR Hist Cleaner** **1013778664**
1020 TERRACE ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1945	BATON ROUGE HAT CLEANERS	HAT CLEANERS AND BLOCKERS

---

4 **BATON ROUGE HATTERS** **EDR Hist Cleaner** **1013778665**
1062 TERRACE ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	BATON ROUGE HATTERS	HAT CLEANERS AND BLOCKERS
1955	BATON ROUGE HATTERS	HAT CLEANERS AND BLOCKERS
1960	BATON ROUGE HATTERS	HAT CLEANERS AND BLOCKERS

---

4 **STANLEY SHERMAN R** **EDR Hist Cleaner** **1013786375**
1232 TERRACE ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1945	STANLEY SHERMAN R	CLOTHES PRESSERS AND CLEANERS

---

4 **SUPERB CLNS BR** **EDR Hist Cleaner** **1013781253**
1266 TERRACE ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	BAKERS CLEANERS	CLEANERS AND DYERS
1955	BAKERS CLNS	CLEANERS AND DYERS
1960	SUPERB CLNS BR	CLEANERS AND DYERS

4 WIFE SAVER U WASH IT SELF — **EDR Hist Cleaner** — **1013785806**
1286 TERRACE ST — **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1955	NABORHUD WASHWOMAN	LAUNDRIES-SELF SERVE
1960	NABORHUD WASHWOMAN	LAUNDRIES-SELF SERVE
1966	WIFE SAVER U WASH IT SELF	LAUNDRIES-SELF SERVE
1970	WIFE SAVER U WASH IT SELF SERV	LAUNDRIES-SELF SERVE

---

4 DILWORTH AUTO SERVICE AUTO REPR — **EDR Hist Auto** — **1013762911**
1328 TERRACE ST — **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1945	HUNTER BODY & FENDER WKS	AUTOMOBILE REPAIRING
1945	DILWORTH AUTO SERVICE AUTO REPR	AUTOMOBILE REPAIRING
1955	TAYLOR WESLEY GARAGE REPR	AUTOMOBILE GARAGES
1955	TAYLOR WESLEY GARAGE REPR	AUTOMOBILE REPAIRING

---

4 THE DOW CHEMICAL COMPANY — **ICIS** — **1018287633**
PLAQUEMINES COGENERATION PLANT — **N/A**
PLAQUEMINE, LA 70000

ICIS:

Enforcement Action ID:	LA-N00018327
FRS ID:	110001244724
Action Name:	WEL070290
Facility Name:	THE DOW CHEMICAL COMPANY
Facility Address:	PLAQUEMINES COGENERATION PLANT PLAQUEMINE, LA 70000
Enforcement Action Type:	Letter of Violation/ Warning Letter
Facility County:	IBERVILLE
Program System Acronym:	NPDES
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	LOVWL
Facility SIC Code:	4931
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.436389
Longitude in Decimal Degrees:	-91.177222
Permit Type Desc:	NPDES Individual Permit
Program System Acronym:	LA0116602
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Enforcement Action ID:	LA-N00015353
FRS ID:	110001244724
Action Name:	THE DOW CHEMICAL COMPANY (Permit LA0116602) Qncr Comment
Facility Name:	THE DOW CHEMICAL COMPANY
Facility Address:	PLAQUEMINES COGENERATION PLANT PLAQUEMINE, LA 70000
Enforcement Action Type:	Under Review
Facility County:	IBERVILLE
Program System Acronym:	NPDES

THE DOW CHEMICAL COMPANY (Continued) **1018287633**

Enforcement Action Forum Desc: Administrative - Informal
EA Type Code: UNDREV
Facility SIC Code: 4931
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.436389
Longitude in Decimal Degrees: -91.177222
Permit Type Desc: NPDES Individual Permit
Program System Acronym: LA0116602
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

---

4 **SPRINGLAKE @ BLUEBONNET HIGHLANDS SUBDIVISION**
BATON ROUGE, LA 70802
FINDS 1010015376
ECHO N/A

FINDS:

Registry ID: 110028290668

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Registry ID: 110032826690

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1010015376
Registry ID: 110028290668
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110028290668

4 TONY'S SEAFOOD — **FINDS** — **1009680265**
UNKNOWN — **ECHO** — **N/A**
BATON ROUGE, LA 70802

FINDS:

Registry ID: 110027857736

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1009680265
Registry ID: 110027857736
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110027857736

---

4 BRADY WILSON CONSTRUCTION, LLC — **FINDS** — **1010013942**
NICHOLSON LAKES SUBD — **ECHO** — **N/A**
BATON ROUGE, LA 70802

FINDS:

Registry ID: 110027988471

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1010013942
Registry ID: 110027988471
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110027988471

4 GARDNER HOME BUILDERS INC — **FINDS** — **1010013943**
NICHOLSON LAKES SUBD — **ECHO** — **N/A**
BATON ROUGE, LA 70802

FINDS:

Registry ID: 110027988480

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1010013943
Registry ID: 110027988480
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110027988480

---

4 ALPAN DEVELOPMENTS LLC — **FINDS** — **1010013945**
16248 WOODLAND TRAIL AVE. — **ECHO** — **N/A**
BATON ROUGE, LA 70810

FINDS:

Registry ID: 110064300849

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Registry ID: 110027988514

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

ALPAN DEVELOPMENTS LLC (Continued) **1010013945**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010013945
Registry ID:	110064300849
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110064300849

Envid:	1010013945
Registry ID:	110027988514
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110027988514

---

4 TPT DEVELOPMENT LLC **FINDS 1010013944**
NICHOLSON LAKES SUBD **ECHO N/A**
BATON ROUGE, LA 70802

FINDS:

Registry ID: 110027988499

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010013944
Registry ID:	110027988499
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110027988499

---

4 BISHOP CONST. CO., INC. **FINDS 1010013941**
NICHOLSON LAKES SUBD **ECHO N/A**
BATON ROUGE, LA 70802

FINDS:

Registry ID: 110027988444

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting

BISHOP CONST. CO., INC. (Continued) **1010013941**

requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010013941
Registry ID:	110027988444
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110027988444

---

4 **KANEB PIPELINE OPERATING PARTN** **FINDS** **1010048082**
ERSHIP LB - STATEWIDE **ECHO** **N/A**
BATON ROUGE, LA 70802

FINDS:

Registry ID: 110028274622

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010048082
Registry ID:	110028274622
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110028274622

---

4 **DAY AND NIGHT LAUNDROMAT** **EDR Hist Cleaner** **1013777334**
1206 EAST BLVD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1960	DAY AND NIGHT LAUNDROMAT	LAUNDRIES-SELF SERVE
1966	CAY 6 NIGHT LAUNDROMAT	LAUNDRIES-SELF SERVE
1970	DAY & NIGHT LAUNDROMAT	LAUNDRIES-SELF SERVE
1975	DAY & NIGHT LAUNDROMAT	LAUNDRIES-SELF SERVE
1980	DAY & NIGHT LAUNDROMAT	LAUNDRIES-SELF SERVE
1990	DAY & NIGHT LAUNDROMAT	LAUNDRIES-SELF SERVE

4 **TILLMAN SAM AUTO REPR** — **EDR Hist Auto** — **1013755588**
1146 10TH ST S — **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1960	TILLMAN SAM AUTO REPR	AUTOMOBILE REPAIRING

---

4 **MID CITY AUTO SERVICE** — **EDR Hist Auto** — **1013763886**
1102 13TH ST S — **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1975	MID CITY AUTO REPR	AUTOMOBILE REPAIRING
1980	MID CITY AUTO SERVICE	AUTOMOBILE REPAIRING

---

4 **REDDY ICE #335** — **RCRA-CESQG** — **1008195059**
1140 MYRTLE — **LAR000057208**
BATON ROUGE, LA 70821

RCRA-CESQG:

Date form received by agency:	10/15/2007
Facility name:	REDDY ICE #335
Facility address:	1140 MYRTLE BATON ROUGE, LA 70821
EPA ID:	LAR000057208
Mailing address:	N CENTRAL EXPWY, STE 1800 DALLAS, TX 75231
Contact:	VINCE STARNES
Contact address:	N CENTRAL EXPWY, STE 1800 DALLAS, TX 75231
Contact country:	US
Contact telephone:	(337) 433-7806
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	REDDY ICE GROUP
Owner/operator address:	Not reported Not reported

REDDY ICE #335 (Continued) **1008195059**

Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 12/31/1997
Owner/Op end date: Not reported

Owner/operator name: REDDY ICE GROUP
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 12/31/1997
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:
Date form received by agency: 03/09/2005
Site name: REDDY ICE #335
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

---

4 **ROBERSONS ESSO GAS STA** **EDR Hist Auto** **1013764459**
1045 MYRTLE ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1960	ROBERSONS ESSO GAS STA	GASOLINE STATIONS

4 BR 177 EBRRA LINCOLN THEATER VICINITY SURVEY **US BROWNFIELDS** **1014933209**
1305 MYRTLE WALK ADDRESS IS FOR LINCOLN THEATER **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 177 EBRRA LINCOLN THEATER VICINITY SURVEY
Property #:	840352048 Lincoln Theater
Parcel size:	90
Property Description:	Multiple properties within the survey vicinity in various stages of use and conditions. The area was once a prosperous historically black community, which has since experienced disinvestment and abandonment in general.
Latitude:	30.4362298
Longitude:	-91.1785016
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	114361
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	9000
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Supplemental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Unknown
Video available:	No
Photo available:	Yes
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported

BR 177 EBRRA LINCOLN THEATER VICINITY SURVEY (Continued) **1014933209**

Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported

BR 177 EBRRA LINCOLN THEATER VICINITY SURVEY (Continued) **1014933209**

Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	1091
% Below Poverty:	3.2%
# Low Income:	2002
% Low Income:	1.8%
Meidan Income:	6044
# Unemployed:	162
% Unemployed:	21.8%
# Vacant Housing:	419
% Vacant Housing:	8.4%

---

4 **LINCOLN THEATER** **LA BROWNFIELDS** **S112658667**
1305 MYRTLE WALK **LA ASBESTOS** **N/A**
BATON ROUGE, LA **LA REM**

LA_BROWNFIELD:

Facility Status:	Not reported
Web ID:	Not reported
Last Action:	Not reported
Program:	IAS-TBA
AI Number:	169406

ASBESTOS:

Asbestos Disposal Facility Id:	RAL-015
Site Location:	site wide
Issue Date:	10/14/2013
Expire Date:	01/12/2014
Qty Rec By Disposal Facility (CY):	5.00
AI#:	169406
Contractor AI Id:	147041
Alternate AI Id:	42261
Amount:	10
Unit:	CUBIC YARDS
Scheduled Start:	10/24/2013
Scheduled End:	10/28/2013
Asbestos Contractors:	ARC Abatement I Ltd
Transporter Name:	ARC Abatement I Ltd
SW Disposal Facility Name:	Waste Management of Louisiana LLC - Woodside Sanitary Landfill & Recycling Center
SW Disposal Facility AI Id:	11767
SW Disposal Facility Address:	29340 Woodside Dr
SW Disposal Facility City:	Walker

LINCOLN THEATER (Continued) **S112658667**

SW Disposal Facility State:	LA
SW Disposal Facility Zip:	70785-
Parish:	EAST BATON ROUGE
Deq Copy Received:	True
Days Elapsed Since Issuance:	178
Days To Expiration:	EXPIRED
Type Of Notification:	REVISED
Type Of Operation:	RENO
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	2
Age In Years:	25
Present Use:	vacant
Prior Use:	theater
Mailing Address Line 1:	11661 Investors Ave
Mailing Address City/State/Zip:	Baton Rouge, LA 70809-
Transporter AI Id:	147041
Transporter Id:	T-017-12635
Transporter Address:	Lead Contractor
Transporter Physical Address Line 2:	Solid Waste Transporter
Transporter City/Statae/Zip:	Statewide, LA 70000-
Total ADVFs Issued:	29781
Total Emergency ADVFs Issued:	4658
Total Emergency ADVF Revenue Generated:	$1,658,118.00
ADVF #:	ADVF-0029415
Total Non-Emergency ADVFs Issued:	25123
Total Non-Emergency ADVF Revenue Generated:	$1,658,118.00
Total ADVF Revenue Generated:	$2,119,260.00
Comments:	Transporter changed to Work Box, #T-121-12770

REM:

AI Num:	169406
Evaluated And Closed:	Not reported
Program:	IAS-TBA
EAC Type:	Not reported
Comments:	Not reported

---

4 **BR - 178 LINCOLN THEATER** **US BROWNFIELDS** **1016159126**
1305 MYRTLE WALK **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge-Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR - 178 LINCOLN THEATER
Property #:	Not reported
Parcel size:	.2
Property Description:	The Lincoln Theater is a vacant building near downtown Baton Rouge at 1305 Myrtle Walk, Baton Rouge, LA. It was formally a thriving historical performing arts venue. The Lincoln Theater was acquired by the Louisiana Black History Hall of Fame. The two story building includes the main theater and projector room, a concessions area, a retail area, a former barber shop, five offices and associated lavatories and storage areas
Latitude:	30.4384105
Longitude:	-91.17542120000001
HCM label:	Address Matching-House Number

BR - 178 LINCOLN THEATER (Continued) **1016159126**

Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	156931
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	7785
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Cleanup Planning
Accomplishment count:	1
Cooperative agreement #:	00F18701
Ownership entity:	Private
Current owner:	Not reported
Did owner change:	N
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported

BR - 178 LINCOLN THEATER (Continued) **1016159126**

PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported

BR - 178 LINCOLN THEATER (Continued) **1016159126**

Redev Completition Date:	Not reported
# Below Poverty:	1091
% Below Poverty:	3.2%
# Low Income:	2002
% Low Income:	1.8%
Meidan Income:	6044
# Unemployed:	162
% Unemployed:	21.8%
# Vacant Housing:	419
% Vacant Housing:	8.4%

FINDS:

Registry ID: 110042111853

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

4 ERRANDS AIR EXPRESS **RCRA NonGen / NLR** **1000152129**
956 S 15TH ST **FINDS** **LAD146467683**
BATON ROUGE, LA 70802 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	04/13/1987
Facility name:	ERRANDS AIR EXPRESS
Facility address:	956 S 15TH ST BATON ROUGE, LA 70802
EPA ID:	LAD146467683
Mailing address:	S 15TH ST BATON ROUGE, LA 70802
Contact:	JOE NORRIS
Contact address:	956 S 15TH ST BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 334-0347
Contact email:	Not reported
EPA Region:	06
Land type:	Other land type
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JOE NORRIS
Owner/operator address:	956 S 15TH ST BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

ERRANDS AIR EXPRESS (Continued) **1000152129**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date:	07/14/1988
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

FINDS:

Registry ID: 110003284927

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000152129
Registry ID:	110003284927
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003284927

4 **WILLIAMS JOS C AUTO REPR** **EDR Hist Auto** **1013767928**
944 13TH ST S **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	WILLIAMS JOS C AUTO REPR	AUTOMOBILE REPAIRING

---

4 **BREC EXPRESSWAY PARK** **LA ASBESTOS** **S116492180**
935 S 11TH ST **N/A**
BATON ROUGE, LA 70802

ASBESTOS:

Asbestos Disposal Facility Id:	RAL-010
Site Location:	rec center
Issue Date:	10/15/2013
Expire Date:	01/13/2014
Qty Rec By Disposal Facility (CY):	2.00
AI#:	189405
Contractor AI Id:	162297
Alternate AI Id:	18938
Amount:	2
Unit:	CUBIC YARDS
Scheduled Start:	10/28/2013
Scheduled End:	11/30/2013
Asbestos Contractors:	Insulation Technologies Inc
Transporter Name:	Insulation Technologies Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	25491
SW Disposal Facility Address:	Hwy 190
SW Disposal Facility City:	Livonia
SW Disposal Facility State:	LA
SW Disposal Facility Zip:	70755-
Parish:	EAST BATON ROUGE
Deq Copy Received:	True
Days Elapsed Since Issuance:	177
Days To Expiration:	EXPIRED
Type Of Notification:	ORIGINAL
Type Of Operation:	RENO
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	2
Age In Years:	53
Present Use:	park
Prior Use:	park
Mailing Address Line 1:	PO Box 98
Mailing Address City/State/Zip:	Harvey, LA 70059-0098
Transporter AI Id:	162297
Transporter Id:	T-075-8099
Transporter Address:	120 Herman Dr
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Belle Chasse, LA 70037-
Total ADVFs Issued:	29781
Total Emergency ADVFs Issued:	4658
Total Emergency ADVF Revenue Generated:	$1,658,118.00
ADVF #:	ADVF-0029417
Total Non-Emergency ADVFs Issued:	25123
Total Non-Emergency ADVF Revenue Generated	$1,658,118.00
Total ADVF Revenue Generated:	$2,119,260.00

BREC EXPRESSWAY PARK (Continued) **S116492180**

Comments: Not reported

---

4 **WILLIAMS HILNER C C DO** **EDR Hist Cleaner** **1013782146**
921 11TH ST S **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1936	WILLIAMS HILNER C	CLOTHES PRESSERS AND CLEANERS
1940	WILLIAMS HILNER C C DO	CLOTHES PRESSERS AND CLEANERS

---

4 **WILLIAMS ELECTRIC CO** **LA UST** **U000876557**
945 S 13TH ST **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	68780
Subject Item ID:	1
UST Tank Num:	38852
Tank Status:	**Removed**
Install Date:	06/01/1957
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

Map ID Direction Distance Distance (ft.)	Site	Database(s)	EDR ID Number EPA ID Number
4	**CITY SHELL SERV STA** **1150 SOUTH ST** **BATON ROUGE, LA**	**EDR Hist Auto**	**1013762712** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1960	CITY SHELL SERV STA	GASOLINE STATIONS
1966	ROBERSON SHELL SERVICE STATION	GASOLINE STATIONS

4	**HORATIOS ESSO STATION NO 1** **1150 SOUTH BLVD** **BATON ROUGE, LA**	**EDR Hist Auto**	**1013774569** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1940	HORATIOS ESSO STATION & TAXI LI	AUTOMOBILE REPAIRING
1940	HORATIOS ESSO STATION & TAXI LI	GASOLINE AND OIL SERVICE STATIONS
1945	HORATIOS ESSO STATION NO 1	AUTOMOBILE REPAIRING
1945	HORATIOS ESSO STATION NO 1	GASOLINE AND OIL SERVICE STATIONS
1970	WALKERS ESSO SERVICE STATION	GASOLINE STATIONS
1975	BILLYS EXXON SERVICE STA	GASOLINE STATIONS

4	**TOLBERT ARTH C AUTO REPR** **854 13TH ST S** **BATON ROUGE, LA**	**EDR Hist Auto**	**1013761732** **N/A**

EDR Hist Auto

Year:	Name:	Type:
1940	TOLBERT ARTH C AUTO REPR	AUTOMOBILE REPAIRING
1945	TOLBERT ARTH	AUTOMOBILE REPAIRING

4	**JACOBS LARRY J C DCLO CLNR** **859 13TH ST S** **BATON ROUGE, LA**	**EDR Hist Cleaner**	**1013777104** **N/A**

EDR Hist Cleaner

Year:	Name:	Type:
1931	JACOBS LARRY J C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1936	1/2 JACOBS LARRY J C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1940	JACOBS LARRY J C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1945	JACOBS LARRY J CLO CLNR	CLOTHES PRESSERS AND CLEANERS
1950	JACOBS THE CLEANER C DO	CLEANERS AND DYERS
1955	JACOBS THE CLN DCLO CLN	CLEANERS AND DYERS
1960	JACOBS THE CLN	CLOTHES PRESSERS AND CLEANERS

4 **ERNS** **2004711576**
960 I-10 WEST **N/A**
WEST LAKE, LA

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

4 **BONNIE & CLYDE WAREHOUSE** **RCRA-SQG** **1016141776**
711 S 14TH ST **FINDS** **LAR000079400**
BATON ROUGE, LA 70802 **ECHO**

RCRA-SQG:

Date form received by agency:	05/29/2013
Facility name:	BONNIE & CLYDE WAREHOUSE
Facility address:	711 S 14TH ST BATON ROUGE, LA 70802
EPA ID:	LAR000079400
Mailing address:	W WASHINGTON BLVD BURNS 274 CULVER CITY, CA 90232
Contact:	CAROL REYNOLDS
Contact address:	W WASHINGTON BLVD BURNS 274 CULVER CITY, CA 90232
Contact country:	US
Contact telephone:	(310) 244-8866
Contact email:	Not reported
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	LOUIS & LEE
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	09/01/1996
Owner/Op end date:	Not reported

Owner/operator name:	YANDR PROD
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/01/2013
Owner/Op end date:	Not reported

Handler Activities Summary:

BONNIE & CLYDE WAREHOUSE (Continued) **1016141776**

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110055446619

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BONNIE & CLYDE WAREHOUSE (Continued) **1016141776**

ECHO:
Envid: 1016141776
Registry ID: 110055446619
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055446619

---

4 **FORBES TONY S FILLING STA** **EDR Hist Auto** **1013772439**
1268 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1940	GULF COAST OIL CO BR FILLING	GASOLINE AND OIL SERVICE STATIONS
1945	FORBES TONY S FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1950	JEFFERSON OIL CO FILL STA	GASOLINE STATIONS
1955	JEFF OIL CO GAS STA	GASOLINE SERVICE STATIONS
1966	JEFFERSON OIL CO INC SERV	GASOLINE STATIONS
1970	JEFFERSON OIL CO INC SERV ST	GASOLINE STATIONS

---

4 **COTTONS CLEANERS** **EDR Hist Cleaner** **1013784163**
1308 GOVERNMENT ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1960	COTTONS CLNS	CLOTHES PRESSERS AND CLEANERS
1966	COTTONS CLEANERS	CLEANERS AND DYERS
1970	COTTONS CLEANERS	CLEANERS AND DYERS
1975	COTTONS CLEANERS	CLEANERS AND DYERS

---

4 **COTTON ODEA CLO CLNR** **EDR Hist Cleaner** **1013778852**
1306 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1931	COTTON MATTHEW S C TAILOR	CLOTHES PRESSERS AND CLEANERS
1936	COTTON MATTHEWS S C CLDO	CLOTHES PRESSERS AND CLEANERS
1940	COTTON MATTHEWS S C CDO	CLOTHES PRESSERS AND CLEANERS
1945	COTTON ODEA CLO CLNR	CLOTHES PRESSERS AND CLEANERS
1950	COTTON MATTHEW S C CLDO	CLEANERS AND DYERS

4 **A B C CLEANERS & LAUNDRY** **EDR Hist Cleaner** **1013779848**
1322 GOVERNMENT ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1966	A B C CLEANERS INC	CLEANERS AND DYERS
1970	A B C CLEANERS & LAUNDRY	CLEANERS AND DYERS

---

4 **KANSAS CITY SOUTHERN RAILWAY CO** **LA UST** **U003926497**
GOVERNMENT ST & S 14TH **N/A**
BATON ROUGE, LA 70000

UST:

Master Agency Id:	79505
Subject Item ID:	1
UST Tank Num:	51506
Tank Status:	**Removed**
Install Date:	01/01/1950
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	51507
Tank Status:	**Removed**
Install Date:	01/01/1950
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported

KANSAS CITY SOUTHERN RAILWAY CO (Continued) **U003926497**

New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

4 **MC CRAY FRANK R C BARBER AND HAT CLNR** **EDR Hist Cleaner** **1013779045**
1355 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1936	MC CRAY FRANK R C BARBER AND HA	HAT CLEANERS AND BLOCKERS

---

4 **MC CRAY DAVID C DCLO CLNR** **EDR Hist Cleaner** **1013782996**
1349 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1936	MC CRAY DAVID C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

4 **GEORGE CLEANERS C DCLO CLNRS** **EDR Hist Cleaner** **1013786186**
1347 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1940	GEORGE CLEANERS C DCLO CLNRS	CLOTHES PRESSERS AND CLEANERS

4 **1509 GOVERNMENT ST PROJECT** **LA UST** **U004222013**
1509 GOVERNMENT **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	6290
Subject Item ID:	1
UST Tank Num:	12868
Tank Status:	**Removed**
Install Date:	09/21/1979
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	12869
Tank Status:	**Removed**
Install Date:	09/21/1968
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes

1509 GOVERNMENT ST PROJECT (Continued) **U004222013**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	12870
Tank Status:	**Removed**
Install Date:	09/21/1972
Total Capacity:	1300
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	12871
Tank Status:	**Removed**
Install Date:	09/21/1967
Total Capacity:	1300
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

1509 GOVERNMENT ST PROJECT (Continued) **U004222013**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35657
Tank Status:	**Removed**
Install Date:	09/21/1983
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

4 EBR-RDA GOVERNEMNT STREET SITE **US BROWNFIELDS** **1018273128**
1509 GOVERNMENT STREET **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge-Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	EBR-RDA GOVERNEMNT STREET SITE
Property #:	830341450, 830341451, 830341452, 830341698
Parcel size:	6
Property Description:	The property is currently vacant and unused. The property had a wholesale hay and feed store developed in the northwest corner of the property in 1908 until 1911. A lumber yard operated on the western portion of the property from 1911 until the 1940s. Baton Rouge Electric Light Plant operated an electrical generation plant from 1916 until the 1940s. Gulf States Utilities Co. operated an electrical substation at hte property from the 1940s until the 1970s. Gulf States Utilities Co. used the property for storage, day to day operations, and business operations from the 1970s until the 1990s. Entergy used the property for financial, business, and paperwork activities, maintenance and repair operations, and storage from the 1990s until 2011. The property has been vacant and unused since the end of 2011.
Latitude:	30.4437314
Longitude:	-91.17287599999997
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	155441
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	8130
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous & Petroleum
Accomplishment type:	Cleanup Planning
Accomplishment count:	0
Cooperative agreement #:	00F18601
Ownership entity:	Not reported
Current owner:	East Baton Rouge Redevelopment Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

IC in place:	Not reported
State/tribal program date:	09/04/2012 00:00:00
State/tribal program ID:	6290
State/tribal NFA date:	01/20/2015 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	6
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	945
% Below Poverty:	3.5%
# Low Income:	1722
% Low Income:	1.9%
Meidan Income:	2554
# Unemployed:	215
% Unemployed:	15.4%
# Vacant Housing:	340
% Vacant Housing:	9.7%
Recipient name:	Louisiana Department of Environmental Quality
Grant type:	Section 128(a) State/Tribal
Property name:	EBR-RDA GOVERNEMNT STREET SITE
Property #:	830341450, 830341451, 830341452, 830341698
Parcel size:	6
Property Description:	The property is currently vacant and unused. The property had a wholesale hay and feed store developed in the northwest corner of the property in 1908 until 1911. A lumber yard operated on the western portion of the property from 1911 until the 1940s. Baton Rouge Electric Light Plant operated an electrical generation plant from 1916 until the 1940s. Gulf States Utilities Co. operated an electrical substation at hte property from the 1940s until the 1970s. Gulf States Utilities Co. used the property for storage, day to day operations, and business operations from the 1970s until the 1990s. Entergy used the property for financial, business, and paperwork activities, maintenance and repair operations, and storage from the 1990s until 2011. The property has been vacant and unused since the end of 2011.
Latitude:	30.4437314
Longitude:	-91.17287599999997
HCM label:	Address Matching-House Number
Map scale:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	155441
Start date:	09/02/2014 00:00:00
Completed date:	10/23/2014 00:00:00
Acres cleaned up:	6
Cleanup funding:	200000
Cleanup funding source:	US EPA - State & Tribal Section 128(a) Funding
Assessment funding:	5449
Assessment funding source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	EPA
Grant type:	Hazardous & Petroleum
Accomplishment type:	Cleanup Planning
Accomplishment count:	0
Cooperative agreement #:	96678101
Ownership entity:	Not reported
Current owner:	East Baton Rouge Redevelopment Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	09/04/2012 00:00:00
State/tribal program ID:	6290
State/tribal NFA date:	01/20/2015 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	6
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

# Below Poverty:	945
% Below Poverty:	3.5%
# Low Income:	1722
% Low Income:	1.9%
Meidan Income:	2554
# Unemployed:	215
% Unemployed:	15.4%
# Vacant Housing:	340
% Vacant Housing:	9.7%

Recipient name:	Louisiana Department of Environmental Quality
Grant type:	Section 128(a) State/Tribal
Property name:	EBR-RDA GOVERNEMNT STREET SITE
Property #:	830341450, 830341451, 830341452, 830341698
Parcel size:	6
Property Description:	The property is currently vacant and unused. The property had a wholesale hay and feed store developed in the northwest corner of the property in 1908 until 1911. A lumber yard operated on the western portion of the property from 1911 until the 1940s. Baton Rouge Electric Light Plant operated an electrical generation plant from 1916 until the 1940s. Gulf States Utilities Co. operated an electrical substation at hte property from the 1940s until the 1970s. Gulf States Utilities Co. used the property for storage, day to day operations, and business operations from the 1970s until the 1990s. Entergy used the property for financial, business, and paperwork activities, maintenance and repair operations, and storage from the 1990s until 2011. The property has been vacant and unused since the end of 2011.
Latitude:	30.4437314
Longitude:	-91.17287599999997
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	155441
Start date:	09/02/2014 00:00:00
Completed date:	10/23/2014 00:00:00
Acres cleaned up:	6
Cleanup funding:	200000
Cleanup funding source:	US EPA - State & Tribal Section 128(a) Funding
Assessment funding:	4331
Assessment funding source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	EPA
Grant type:	Hazardous & Petroleum
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	96678101
Ownership entity:	Not reported
Current owner:	East Baton Rouge Redevelopment Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	09/04/2012 00:00:00
State/tribal program ID:	6290
State/tribal NFA date:	01/20/2015 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	6
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	945
% Below Poverty:	3.5%
# Low Income:	1722
% Low Income:	1.9%
Meidan Income:	2554
# Unemployed:	215
% Unemployed:	15.4%
# Vacant Housing:	340
% Vacant Housing:	9.7%

Recipient name:	Baton Rouge-Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	EBR-RDA GOVERNEMNT STREET SITE
Property #:	830341450, 830341451, 830341452, 830341698
Parcel size:	6
Property Description:	The property is currently vacant and unused. The property had a wholesale hay and feed store developed in the northwest corner of the property in 1908 until 1911. A lumber yard operated on the western portion of the property from 1911 until the 1940s. Baton Rouge Electric Light Plant operated an electrical generation plant from 1916 until the 1940s. Gulf States Utilities Co. operated an electrical substation at hte property from the 1940s until the 1970s. Gulf States Utilities Co. used the property for storage, day to day operations, and business operations from the 1970s until the 1990s. Entergy used the property for financial, business, and paperwork

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

activities, maintenance and repair operations, and storage from the 1990s until 2011. The property has been vacant and unused since the end of 2011.

Latitude:	30.4437314
Longitude:	-91.17287599999997
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	155441
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	6275
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous & Petroleum
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	00F18601
Ownership entity:	Not reported
Current owner:	East Baton Rouge Redevelopment Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	09/04/2012 00:00:00
State/tribal program ID:	6290
State/tribal NFA date:	01/20/2015 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	6
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	945
% Below Poverty:	3.5%
# Low Income:	1722
% Low Income:	1.9%
Meidan Income:	2554
# Unemployed:	215
% Unemployed:	15.4%
# Vacant Housing:	340
% Vacant Housing:	9.7%
Recipient name:	Baton Rouge-Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	EBR-RDA GOVERNEMNT STREET SITE
Property #:	830341450, 830341451, 830341452, 830341698
Parcel size:	6
Property Description:	The property is currently vacant and unused. The property had a wholesale hay and feed store developed in the northwest corner of the property in 1908 until 1911. A lumber yard operated on the western portion of the property from 1911 until the 1940s. Baton Rouge Electric Light Plant operated an electrical generation plant from 1916 until the 1940s. Gulf States Utilities Co. operated an electrical substation at hte property from the 1940s until the 1970s. Gulf States Utilities Co. used the property for storage, day to day operations, and business operations from the 1970s until the 1990s. Entergy used the property for financial, business, and paperwork activities, maintenance and repair operations, and storage from the 1990s until 2011. The property has been vacant and unused since the end of 2011.
Latitude:	30.4437314
Longitude:	-91.17287599999997
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	155441
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	76377
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous & Petroleum
Accomplishment type:	Phase II Environmental Assessment

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Accomplishment count:	0
Cooperative agreement #:	00F18601
Ownership entity:	Not reported
Current owner:	East Baton Rouge Redevelopment Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	09/04/2012 00:00:00
State/tribal program ID:	6290
State/tribal NFA date:	01/20/2015 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Y
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	6
Future use greenspace acreage:	Not reported

EBR-RDA GOVERNEMNT STREET SITE (Continued) **1018273128**

Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Y
Media affected indoor air:	Y
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	945
% Below Poverty:	3.5%
# Low Income:	1722
% Low Income:	1.9%
Meidan Income:	2554
# Unemployed:	215
% Unemployed:	15.4%
# Vacant Housing:	340
% Vacant Housing:	9.7%

4 ENTERGY CORPORATION
1509 GOVERNMENT
BATON ROUGE, LA 70802

RCRA-CESQG
FINDS
ECHO

1000227426
LAD981584832

RCRA-CESQG:

Date form received by agency:	08/11/1986
Facility name:	ENTERGY CORPORATION
Facility address:	1509 GOVERNMENT BATON ROUGE, LA 70802
EPA ID:	LAD981584832
Mailing address:	ESSEN LN BATON ROUGE, LA 70809
Contact:	FERNANDO CALLE
Contact address:	ESSEN LN BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 763-5055
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	GULF STATES UTILITY
Owner/operator address:	PO BOX 2951 BEAUMONT, TX 77704
Owner/operator country:	Not reported
Owner/operator telephone:	(409) 838-7893
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

ENTERGY CORPORATION (Continued) **1000227426**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D018
. Waste name: BENZENE

. Waste code: D019
. Waste name: CARBON TETRACHLORIDE

. Waste code: D021
. Waste name: CHLOROBENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF

ENTERGY CORPORATION (Continued) **1000227426**

ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Facility Has Received Notices of Violations:

Regulation violated:	Not reported
Area of violation:	Generators - General
Date violation determined:	05/13/1987
Date achieved compliance:	08/20/1987
Violation lead agency:	State
Enforcement action:	FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date:	07/30/1987
Enf. disposition status:	Not reported
Enf. disp. status date:	Not reported
Enforcement lead agency:	State
Proposed penalty amount:	Not reported

ENTERGY CORPORATION (Continued) **1000227426**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 08/20/1987
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/13/1987
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 08/20/1987
Evaluation lead agency: State

FINDS:

Registry ID: 110009578386

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110054627043

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000227426
Registry ID: 110009578386
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009578386

---

4 **1509 GOVERNMENT ST PROJECT** **LA HIST LUST** **S106033777**
1509 GOVERNMENT **LA SPILLS** **N/A**
BATON ROUGE, LA 70802 **LA VCP**
LA ASBESTOS
LA REM

HIST LUST:
Facility ID: 17-004624
Facility Parish: EAST BATON ROUGE
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: 20-30 GAL
Quantity 2: Not reported

1509 GOVERNMENT ST PROJECT (Continued) **S106033777**

Date Confirmed:	09/28/1993	
Date Confirmed 2:	Not reported	
Incident Number:	93-2-0242	
Incident Date:	09/28/1993	
Type of Incident:		UST LEAK
Type of Incident No2:		Not reported
Reported By:	JOHN KNIPPA	
Reported By 2:	Not reported	
Owner ID:	00122200	
Owner Name:	G. S. U./ENVIRONMENTAL AFFAIRS	
Owner Address:	P.O. BOX 2951	
Owner City,St,Zip:	BEAUMONT, TX 77704	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		Not reported
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		Not reported
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		Not reported
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ LETTER DATED 28 OCT 93 APPROVING IN PLACE CLOSURE OF THEDISPENSING LINE BY FLUSHING REMAINING PRODUCT AND CAPPINGEACH END. DISPENSER TAKEN OUT OF SERVICE.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-004624	
Facility Parish:	EAST BATON ROUGE	
Substance Name:	Not reported	
Substance Name 2:	Not reported	
Quantity:	Not reported	
Quantity 2:	Not reported	
Date Confirmed:	Not reported	
Date Confirmed 2:	Not reported	
Incident Number:	93-2-0242	
Incident Date:	09/28/1993	
Type of Incident:		Not reported
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	

1509 GOVERNMENT ST PROJECT (Continued) **S106033777**

Owner ID:	00122200
Owner Name:	G. S. U./ENVIRONMENTAL AFFAIRS
Owner Address:	P.O. BOX 2951
Owner City,St,Zip:	BEAUMONT, TX 77704
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ LETTER DATED 28 OCT 93 APPROVING IN PLACE CLOSURE OF THEDISPENSING LINE BY FLUSHING REMAINING PRODUCT AND CAPPINGEACH END. DISPENSER TAKEN OUT OF SERVICE.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

SPILLS:

Region Code:	Not reported
Date Rec:	07/07/2008
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	106957
Incident Date:	07/05/2008
Incident Status:	**Open**
Media Desc:	Water
Location Description:	Entergy Corp 1509 Government St Baton Rouge
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c08-2285 Closed, unused Entergy Corp building contains a toxic mix in the basement--concerned about material leaking into ground water...jd
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported

1509 GOVERNMENT ST PROJECT (Continued) **S106033777**

Quantity: Not reported
Other Substance Desc: Not reported

VCP:

DEQ AI #:	6290
Date Closed:	09/12/2013
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	6
Applicant name:	East Baton Rouge Redevelopment Authority
DEQ Contact:	Todd Thibodeaux
Date of Applicantion:	09/04/2012
Remedial Investigaton/Action Phase:	Action Phase - Partial
Status:	Withdrew
Unrestricted Use:	Not reported
Investigation Approval Date:	Not reported
Use Restrictions/Institutional Controls A:	Not reported
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.17277800
Longitude:	30.44388900

ASBESTOS:

Asbestos Disposal Facility Id:	RAL-010
Site Location:	site wide
Issue Date:	07/10/2013
Expire Date:	10/08/2013
Qty Rec By Disposal Facility (CY):	10.00
AI#:	6290
Contractor AI Id:	99313
Alternate AI Id:	36801
Amount:	5
Unit:	CUBIC YARDS
Scheduled Start:	07/10/2013
Scheduled End:	07/12/2013
Asbestos Contractors:	Air Environmental Services Inc
Transporter Name:	Air Environmental Services Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	25491
SW Disposal Facility Address:	Hwy 190
SW Disposal Facility City:	Livonia
SW Disposal Facility State:	LA
SW Disposal Facility Zip:	70755-
Parish:	EAST BATON ROUGE
Deq Copy Received:	True
Days Elapsed Since Issuance:	274
Days To Expiration:	EXPIRED
Type Of Notification:	REVISED
Type Of Operation:	EMERGENCY-RENO
Ordered By:	Not reported

1509 GOVERNMENT ST PROJECT (Continued) **S106033777**

Ordered Date:	Not reported
# Of Floors:	1
Age In Years:	30
Present Use:	warehouse
Prior Use:	warehouse
Mailing Address Line 1:	11862 Cloverland Ct
Mailing Address City/State/Zip:	Baton Rouge, LA 70809-
Transporter AI Id:	99313
Transporter Id:	T-033-10995
Transporter Address:	Asbestos Training Organization
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Statewide, LA 70000-
Total ADVFs Issued:	29781
Total Emergency ADVFs Issued:	4658
Total Emergency ADVF Revenue Generated:	$1,658,118.00
ADVF #:	ADVF-0028757
Total Non-Emergency ADVFs Issued:	25123
Total Non-Emergency ADVF Revenue Generated	$1,658,118.00
Total ADVF Revenue Generated:	$2,119,260.00
Comments:	RACM volume changed to 10 CY

Asbestos Disposal Facility Id:	Not reported
Site Location:	bldgs 1, 2, 3, 7
Issue Date:	08/27/2014
Expire Date:	11/25/2014
Qty Rec By Disposal Facility (CY):	0.00
AI#:	6290
Contractor AI Id:	Not reported
Alternate AI Id:	Not reported
Amount:	75
Unit:	Not reported
Scheduled Start:	09/01/2014
Scheduled End:	12/31/2014
Asbestos Contractors:	Air Environmental Services Inc
Transporter Name:	Gator Environmental & Rentals Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	Not reported
SW Disposal Facility Address:	Not reported
SW Disposal Facility City:	Not reported
SW Disposal Facility State:	Not reported
SW Disposal Facility Zip:	Not reported
Parish:	Not reported
Deq Copy Received:	Not reported
Days Elapsed Since Issuance:	Not reported
Days To Expiration:	Not reported
Type Of Notification:	Not reported
Type Of Operation:	Not reported
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	Not reported
Age In Years:	Not reported
Present Use:	Not reported
Prior Use:	Not reported
Mailing Address Line 1:	Not reported
Mailing Address City/State/Zip:	Not reported
Transporter AI Id:	Not reported
Transporter Id:	Not reported

1509 GOVERNMENT ST PROJECT (Continued) **S106033777**

Transporter Address:	Not reported
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Not reported
Total ADVFs Issued:	Not reported
Total Emergency ADVFs Issued:	Not reported
Total Emergency ADVF Revenue Generated:	Not reported
ADVF #:	ADVF-0031972
Total Non-Emergency ADVFs Issued:	Not reported
Total Non-Emergency ADVF Revenue Generated:	Not reported
Total ADVF Revenue Generated:	Not reported
Comments:	Not reported

Asbestos Disposal Facility Id:	Not reported
Site Location:	bldgs 1, 2, 3, 7
Issue Date:	08/27/2014
Expire Date:	11/25/2014
Qty Rec By Disposal Facility (CY):	18.00
AI#:	6290
Contractor AI Id:	Not reported
Alternate AI Id:	Not reported
Amount:	75
Unit:	Not reported
Scheduled Start:	09/01/2014
Scheduled End:	12/31/2014
Asbestos Contractors:	Air Environmental Services Inc
Transporter Name:	Gator Environmental & Rentals Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	Not reported
SW Disposal Facility Address:	Not reported
SW Disposal Facility City:	Not reported
SW Disposal Facility State:	Not reported
SW Disposal Facility Zip:	Not reported
Parish:	Not reported
Deq Copy Received:	Not reported
Days Elapsed Since Issuance:	Not reported
Days To Expiration:	Not reported
Type Of Notification:	Not reported
Type Of Operation:	Not reported
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	Not reported
Age In Years:	Not reported
Present Use:	Not reported
Prior Use:	Not reported
Mailing Address Line 1:	Not reported
Mailing Address City/State/Zip:	Not reported
Transporter AI Id:	Not reported
Transporter Id:	Not reported
Transporter Address:	Not reported
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Not reported
Total ADVFs Issued:	Not reported
Total Emergency ADVFs Issued:	Not reported
Total Emergency ADVF Revenue Generated:	Not reported
ADVF #:	ADVF-0031971
Total Non-Emergency ADVFs Issued:	Not reported
Total Non-Emergency ADVF Revenue Generated:	Not reported

1509 GOVERNMENT ST PROJECT (Continued) **S106033777**

Total ADVF Revenue Generated:	Not reported
Comments:	Not reported
Asbestos Disposal Facility Id:	Not reported
Site Location:	bldgs 1, 2, 3, 7
Issue Date:	08/27/2014
Expire Date:	11/25/2014
Qty Rec By Disposal Facility (CY):	30.00
AI#:	6290
Contractor AI Id:	Not reported
Alternate AI Id:	Not reported
Amount:	75
Unit:	Not reported
Scheduled Start:	09/01/2014
Scheduled End:	12/31/2014
Asbestos Contractors:	Air Environmental Services Inc
Transporter Name:	Gator Environmental & Rentals Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	Not reported
SW Disposal Facility Address:	Not reported
SW Disposal Facility City:	Not reported
SW Disposal Facility State:	Not reported
SW Disposal Facility Zip:	Not reported
Parish:	Not reported
Deq Copy Received:	Not reported
Days Elapsed Since Issuance:	Not reported
Days To Expiration:	Not reported
Type Of Notification:	Not reported
Type Of Operation:	Not reported
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	Not reported
Age In Years:	Not reported
Present Use:	Not reported
Prior Use:	Not reported
Mailing Address Line 1:	Not reported
Mailing Address City/State/Zip:	Not reported
Transporter AI Id:	Not reported
Transporter Id:	Not reported
Transporter Address:	Not reported
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Not reported
Total ADVFs Issued:	Not reported
Total Emergency ADVFs Issued:	Not reported
Total Emergency ADVF Revenue Generated:	Not reported
ADVF #:	ADVF-0031970
Total Non-Emergency ADVFs Issued:	Not reported
Total Non-Emergency ADVF Revenue Generated:	Not reported
Total ADVF Revenue Generated:	Not reported
Comments:	Not reported

REM:

AI Num:	6290
Evaluated And Closed:	11/15/2013
Program:	Solid Waste
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 9105753

4 **WILLIS WM H C DCLO CLNR** **EDR Hist Cleaner** **1013787482**
302 13TH ST S **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1936	WILLIS WM H C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

4 **GLAZERS CO** **LA UST** **U003923293**
340 S 14TH ST **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	67846
Subject Item ID:	1
UST Tank Num:	1984
Tank Status:	**Closed**
Install Date:	05/12/1963
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	1985
Tank Status:	**Closed**
Install Date:	05/12/1963
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported

GLAZERS CO (Continued) **U003923293**

MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	53842
Tank Status:	**Closed**
Install Date:	05/01/1963
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

4 E HAYES TRUCKING INC — **RCRA NonGen / NLR** — **1000864226**
225 EDDIE ROBINSON DR — **FINDS** — **LA0000080531**
BATON ROUGE, LA 70802 — **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	12/17/1993
Facility name:	E HAYES TRUCKING INC
Facility address:	225 EDDIE ROBINSON DR BATON ROUGE, LA 70802
EPA ID:	LA0000080531
Mailing address:	EDDIE ROBINSON DR BATON ROUGE, LA 70802
Contact:	EMMITT HAYES-JR
Contact address:	225 EDDIE ROBINSON DR BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 344-7388
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	EMMIT HAYES JR
Owner/operator address:	225 EDDIE DR BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 344-7388
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110003258572

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

E HAYES TRUCKING INC (Continued) **1000864226**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000864226
Registry ID:	110003258572
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003258572

---

4 **MANUEL RADIO & T V REPAIR** **EDR Hist Auto** **1013773061**
1202 AMERICA ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1975	MANUEL RADIO & T V REPAIR	REPAIR SHOPS
1980	MANUEL RADIO & T V REPAIR	REPAIR SHOPS

---

4 **KEMP LUKE C DCLO CLNR** **EDR Hist Cleaner** **1013783493**
172 12TH ST S **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1940	KEMP LUKE C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

4 **LA DOA LPAA** **RCRA NonGen / NLR** **1000189694**
125 S 14TH ST **FINDS** **LAD981585813**
BATON ROUGE, LA 70802 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	09/10/1986
Facility name:	LA DOA LPAA
Facility address:	125 S 14TH ST BATON ROUGE, LA 70802
EPA ID:	LAD981585813
Mailing address:	PO BOX 94095 BATON ROUGE, LA 70804
Contact:	JESSE WALLACE
Contact address:	PO BOX 94095 BATON ROUGE, LA 70804
Contact country:	US
Contact telephone:	(225) 342-6864
Contact email:	Not reported
EPA Region:	06
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator

LA DOA LPAA (Continued) **1000189694**

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: STATE OF LOUISIANA
Owner/operator address: UNKNOWN
UNKNOWN, LA 00000
Owner/operator country: Not reported
Owner/operator telephone: (000) 000-0000
Legal status: State
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F004
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: CRESOLS, CRESYLIC ACID, AND NITROBENZENE; AND THE STILL BOTTOMS FROM THE RECOVERY OF THESE SOLVENTS; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND

LA DOA LPAA (Continued) **1000189694**

F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 07/09/1993
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003294970

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000189694
Registry ID: 110003294970
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003294970

---

4 CONOCO WAREHOUSE FACILITY **LA HIST LUST U001898409**
115 S 14TH ST **LA UST N/A**
BATON ROUGE, LA 70802

HIST LUST:
Facility ID: 17-014522
Facility Parish: EAST BATON ROUGE
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 12/15/1993
Date Confirmed 2: Not reported
Incident Number: 93-2-0310
Incident Date: 12/13/1993
Type of Incident: UNKNOWN
Type of Incident No2: Not reported
Reported By: DAVID MARSHAL/CK ASSOC.
Reported By 2: Not reported
Owner ID: 00613900
Owner Name: CONSOLIDATED COMPANIES, INC.
Owner Address: P O BOX 6096
Owner City,St,Zip: METAIRIE, LA 70009
Assessment Pending Info: No

CONOCO WAREHOUSE FACILITY (Continued) **U001898409**

Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CK ASSOCIATES INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: SITE IS:WAREHOUSE115 NORTH 14TH STREETBATON ROUGE, LA.

LA HIST LUST ASSESMENT:
Comments: FREE PHASE FOUND IN GROUND WATER AT ABOVE FACILITY DURINGA REAL ESTATE ENVIRONMENTAL SITE ASSESSMENT. ASSESSMENTREQUIRED. SEE DEQ INSPECTION REPORT(S) DATED 15-DEC-93 AND20-APR-94.

LA HIST LUST CORRECTIVE ACTION:
Comments: CLOSURE STATUS GRANTED FOR ONE 6000 GALLON GASOLINE UST ATTHIS SITE BY 5-27-94 LETTER.

Facility ID:	17-014522
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	93-2-0310
Incident Date:	12/13/1993
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00613900
Owner Name:	CONSOLIDATED COMPANIES, INC.
Owner Address:	P O BOX 6096
Owner City,St,Zip:	METAIRIE, LA 70009
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CK ASSOCIATES INC.
Assess Date Add Info Due:	Not reported

CONOCO WAREHOUSE FACILITY (Continued) **U001898409**

Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: SITE IS:WAREHOUSE115 NORTH 14TH STREETBATON ROUGE, LA.

LA HIST LUST ASSESMENT:
Comments: FREE PHASE FOUND IN GROUND WATER AT ABOVE FACILITY DURINGA REAL ESTATE ENVIRONMENTAL SITE ASSESSMENT. ASSESSMENTREQUIRED. SEE DEQ INSPECTION REPORT(S) DATED 15-DEC-93 AND20-APR-94.

LA HIST LUST CORRECTIVE ACTION:
Comments: CLOSURE STATUS GRANTED FOR ONE 6000 GALLON GASOLINE UST ATTHIS SITE BY 5-27-94 LETTER.

UST:

Master Agency Id:	77420
Subject Item ID:	1
UST Tank Num:	41809
Tank Status:	**Removed**
Install Date:	01/01/1950
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported

CONOCO WAREHOUSE FACILITY (Continued) **U001898409**

Made Of Concrete: Not reported
Liner Covering Excavation Hole: Not reported
Other Material: Not reported
Pipe Method Description: Not reported

---

4 **TAYLOR WESLEY GARAGE** **EDR Hist Auto** **1013770603**
135 12TH ST S **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	TAYLOR WESLEY GARAGE	AUTOMOBILE REPAIRING

---

4 **MORGAN AUTO SERVICE MARINE** **EDR Hist Auto** **1013764057**
1112 NORTH BLVD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	MORGAN AUTO SERVICE MARINE	GASOLINE STATIONS

---

4 **MACS BODY SHOP** **RCRA-CESQG** **1004710392**
1244 N BLVD **FINDS** **LAD985190537**
BATON ROUGE, LA 70802 **ECHO**

RCRA-CESQG:

Date form received by agency:	01/09/1991
Facility name:	MACS BODY SHOP
Facility address:	1244 N BLVD BATON ROUGE, LA 70802
EPA ID:	LAD985190537
Mailing address:	N BLVD BATON ROUGE, LA 70802
Contact:	DON PETTY
Contact address:	1244 N BLVD BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 343-4512
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

MACS BODY SHOP (Continued) **1004710392**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	DON PETTY
Owner/operator address:	12334 BUCKINGHAM AVE BATON ROUGE, LA 70815
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 275-2648
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110003321218

MACS BODY SHOP (Continued) **1004710392**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004710392
Registry ID:	110003321218
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003321218

---

4 **ECONOMY CAR CARE CNTR** **RCRA NonGen / NLR** **1000318402**
1350 NORTH BLVD **LAD982305575**
BATON ROUGE, LA 70802

RCRA NonGen / NLR:

Date form received by agency:	06/23/1987
Facility name:	ECONOMY CAR CARE CNTR
Facility address:	1350 NORTH BLVD BATON ROUGE, LA 70802
EPA ID:	LAD982305575
Mailing address:	NORTH BLVD BATON ROUGE, LA 70802
Contact:	LANCE BROWNER
Contact address:	1350 NORTH BLVD BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 344-1123
Contact email:	Not reported
EPA Region:	06
Land type:	Facility is not located on Indian land. Additional information is not known.
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	LANCE BROWN
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

ECONOMY CAR CARE CNTR (Continued) **1000318402**

Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

Violation Status:	No violations found

Evaluation Action Summary:

Evaluation date:	08/13/1993
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

---

4 **BATON ROUGE CITY OF - PARISH OF EAST BATON ROUGE** **LA UST** **U004179407**
1350 NORTH BLVD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	8353
Subject Item ID:	1
UST Tank Num:	55323
Tank Status:	**Removed**
Install Date:	01/01/1946
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported

BATON ROUGE CITY OF - PARISH OF EAST BATON ROUGE (Continued) **U004179407**

Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55324
Tank Status:	**Removed**
Install Date:	01/01/1946
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55325
Tank Status:	**Removed**
Install Date:	01/01/1946
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

BATON ROUGE CITY OF - PARISH OF EAST BATON ROUGE (Continued) **U004179407**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55531
Tank Status:	**Removed**
Install Date:	01/01/1946
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55532
Tank Status:	**Removed**
Install Date:	01/01/1946
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

BATON ROUGE CITY OF - PARISH OF EAST BATON ROUGE (Continued) **U004179407**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55533
Tank Status:	**Removed**
Install Date:	01/01/1946
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

4 **PETIGO COMPETITION CENTER SPEED SHOP** **EDR Hist Auto** **1013758082**
1038 NORTH BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1970	PETIGO COMPETITION CENTER SPEED	AUTOMOBILE REPAIRING

---

4 **NORTH BLVD IMPROVEMENTS** **LA AUL** **S107520625**
TENTH ST TO 19TH ST **LA VCP** **N/A**
BATON ROUGE, LA 70802 **LA REM**

AUL:

Facility ID:	86103
Type:	Not reported
Incident Number:	Not reported
Agency Interest Id:	Not reported
PPM Project Number:	Not reported
Parish:	East Baton Rouge
Comments:	VRP
Custom Tank Desc:	Conveyance Notice Required

VCP:

DEQ AI #:	86103
Date Closed:	12/15/2005
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	1
Applicant name:	City of Baton Rouge, EBRP, Dept. of Public Works
DEQ Contact:	John Halk
Date of Applicantion:	09/02/2004
Remedial Investigaton/Action Phase:	Action Phase
Status:	NFA/COC
Unrestricted Use:	No
Investigation Approval Date:	Not reported
Use Restrictions/Institutional Controls A:	A
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	F
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	I
Latitude:	-91.17416700
Longitude:	30.44750000

DEQ AI #:	86103
Date Closed:	12/15/2005
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	1
Applicant name:	City of Baton Rouge, EBRP, Dept. of Public Works
DEQ Contact:	John Halk
Date of Applicantion:	11/13/2001
Remedial Investigaton/Action Phase:	Remedial Investigaton
Status:	NFA/COC
Unrestricted Use:	No

NORTH BLVD IMPROVEMENTS (Continued) **S107520625**

Investigation Approval Date:	07/13/2004
Use Restrictions/Institutional Controls A:	A
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	F
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	I
Latitude:	-91.17416700
Longitude:	30.44750000

REM:

AI Num:	86103
Evaluated And Closed:	12/15/2005
Program:	VRP
EAC Type:	Granted VRP Completion Certificate
Comments:	EDMS ID 5233082.

AI Num:	86103
Evaluated And Closed:	12/15/2005
Program:	VRP
EAC Type:	Approve CA NFA w/ BOD
Comments:	EDMS ID 5233082.

---

4 **HAYS SERVICE** **EDR Hist Auto** **1013772627**
1057 NORTH BLVD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1940	NORTH BOULEVARD GULF SERVICE FI	GASOLINE AND OIL SERVICE STATIONS
1945	HAYS SERVICE	GASOLINE AND OIL SERVICE STATIONS

---

4 **MID CONTINENT OIL AND GAS ASSOCIATION GAS SERV STA** **EDR Hist Auto** **1013763888**
801 NORTH BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
2000	MID CONTINENT OIL AND GAS ASSOC	GASOLINE STATIONS

4 **CITY OF BATON ROUGE - PARISH OF EAST BATON ROUGE** **LA UST** **U004222163**
1101 NORTH BLVD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	115848
Subject Item ID:	1
UST Tank Num:	55828
Tank Status:	**Removed**
Install Date:	07/01/2040
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	55829
Tank Status:	**Removed**
Install Date:	07/01/2040
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

CITY OF BATON ROUGE - PARISH OF EAST BATON ROUGE (Continued) **U004222163**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55906
Tank Status:	**Removed**
Install Date:	01/01/2040
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

4 **CAPITOL CITY AUTO CO FILL STA** **EDR Hist Auto** **1013756433**
1111 NORTH BLVD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1931	CAPITOL CITY AUTO CO FILL STA	GASOLINE AND OIL SERVICE STATIONS
1940	MORGAN AUTO SERVICE FILLING	AUTOMOBILE REPAIRING
1940	MORGAN AUTO SERVICE FILLING	GASOLINE AND OIL SERVICE STATIONS
1945	MORGAN AUTO SERVICE FILLING STA	AUTOMOBILE REPAIRING
1945	MORGAN AUTO SERVICE FILLING STA	GASOLINE AND OIL SERVICE STATIONS
1950	MORGAN AUTO SERVICE AUTO	GASOLINE STATIONS
1955	KENNARDS ESSO STA	GASOLINE SERVICE STATIONS

CAPITOL CITY AUTO CO FILL STA (Continued) **1013756433**

1960 CORNER ESSO SERV GASOLINE STATIONS

---

4 LA DEPT OF REVENUE LA SALLE **RCRA-SQG** **1004715070**
617 N THIRD ST **FINDS** **LAR000046995**
BATON ROUGE, LA 70802 **ECHO**

RCRA-SQG:

Date form received by agency:	06/03/2014
Facility name:	LA DEPT OF REVENUE LA SALLE
Facility address:	617 N THIRD ST BATON ROUGE, LA 70802
EPA ID:	LAR000046995
Mailing address:	PO BOX 66987 BATON ROUGE, LA 70896
Contact:	PATRICIA GOUDEAU
Contact address:	PO BOX 66987 BATON ROUGE, LA 70896
Contact country:	US
Contact telephone:	(225) 219-2344
Contact email:	Not reported
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	STATE OF LOUISIANA
Owner/operator address:	617 N THIRD ST BATON ROUGE, LA 70802
Owner/operator country:	US
Owner/operator telephone:	(225) 925-4286
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	06/03/2014
Owner/Op end date:	Not reported

Owner/operator name:	STATE OF LOUISIANA
Owner/operator address:	617 N THIRD ST BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 925-4286
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

LA DEPT OF REVENUE LA SALLE (Continued) **1004715070**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 10/26/2001
Site name: LA DEPT OF REVENUE LA SALLE
Classification: Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110012249192

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004715070
Registry ID: 110012249192
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012249192

---

4 **EXPRESSWAY ESSO SERVICENTER** **EDR Hist Auto** **1013754245**
120 10TH ST N **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1966	EXPRESSWAY ESSO SERVICENTER	GASOLINE STATIONS
1970	EXPRESSWAY ESSO SERVICENTER	GASOLINE STATIONS
1980	WALDOS REPAIR AUTO REPAIR	AUTOMOBILE REPAIRING

4 DIXON BROS QUICK STOP — **EDR Hist Auto** — **1020299045**
120 N 10TH ST — **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1986	DIXON BROS QUICK STOP	General Automotive Repair Shops
1987	DIXON BROS QUICK STOP	General Automotive Repair Shops

---

4 SIMPSONS SVC CTR INC — **RCRA-SQG** — **1000349884**
1225 NORTH BLVD — **LAD981605132**
BATON ROUGE, LA 70802

RCRA-SQG:

Date form received by agency:	11/30/2001
Facility name:	SIMPSONS SVC CTR INC
Facility address:	1225 NORTH BLVD BATON ROUGE, LA 70802
EPA ID:	LAD981605132
Mailing address:	NORTH BLVD BATON ROUGE, LA 70802
Contact:	CHET SIMPSON
Contact address:	1225 NORTH BLVD BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 344-9586
Contact email:	Not reported
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	SIMPSONS SVC CTR INC
Owner/operator address:	1225 NORTH ST BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 344-9586
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

SIMPSONS SVC CTR INC (Continued) **1000349884**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Historical Generators:
Date form received by agency: 09/17/1986
Site name: SIMPSONS SVC CTR INC
Classification: Small Quantity Generator

Violation Status: No violations found

---

4 **SIMPSONS SERVICE CENTER INC** **EDR Hist Auto** **1013764541**
1225 NORTH BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1986	SIMPSONS SERVICE CENTER INC	Gasoline Service Stations
1987	SIMPSONS SERVICE CENTER INC	Gasoline Service Stations
1988	SIMPSONS SERVICE CENTER INC	Gasoline Service Stations
1989	SIMPSONS SERVICE CENTER INC	Gasoline Service Stations, NEC
1990	SIMPSONS SERVICE CENTER INC SER	GASOLINE STATIONS
1990	SIMPSONS SERVICE CENTER INC SER	AUTOMOBILE REPAIRING
1990	SIMPSONS SERVICE CENTER INC	Gasoline Service Stations, NEC
1991	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1992	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1993	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1994	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1995	SIMPSONS SERVICE CENTER INC	GASOLINE STATIONS
1995	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1996	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1997	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1998	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
1999	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
2000	SIMPSONS SERVICE CENTER GENL AU	AUTOMOBILE REPAIRING & SERVICE

SIMPSONS SERVICE CENTER INC (Continued) **1013764541**

2000	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops
2001	SIMPSONS SERVICE CENTER INC	General Automotive Repair Shops

---

4 HCI MAINTENANCE **LA UST** **U003923365**
1225 NORTH BLVD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	6866
Subject Item ID:	1
UST Tank Num:	13534
Tank Status:	**Active**
Install Date:	05/06/1985
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	13535
Tank Status:	**Temp Out of Service**
Install Date:	05/06/1985
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

HCI MAINTENANCE (Continued) **U003923365**

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	13536
Tank Status:	**Temp Out of Service**
Install Date:	05/06/1985
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	13537
Tank Status:	**Active**
Install Date:	05/06/1985
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported

HCI MAINTENANCE (Continued) **U003923365**

Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	13538
Tank Status:	**Deferred**
Install Date:	05/06/1985
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

4 **PEERLESS CLEANERS & DYERS INC** **EDR Hist Cleaner** **1020060631**
1225-29 N BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1969	PEERLESS CLEANERS & DYERS INC	Drycleaning Plants, Except Rugs
1970	PEERLESS CLEANERS & DYERS INC	Drycleaning Plants, Except Rugs
1971	PEERLESS CLEANERS & DYERS INC	Drycleaning Plants, Except Rugs
1972	PEERLESS CLEANERS & DYERS INC	Drycleaning Plants, Except Rugs
1973	PEERLESS CLEANERS & DYERS INC	Drycleaning Plants, Except Rugs

---

4 **DOWNTOWN SPEED WASH COIFI OPR** **EDR Hist Cleaner** **1013782412**
1050 CONVENTION ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1960	1050 52 RUSSELL SPEED WASH	LAUNDRIES-SELF SERVE
1966	RUSSELL SPEED WASH	LAUNDRIES-SELF SERVE
1970	DOWNTOWN SPEED WASH COIFI OPR	LAUNDRIES-SELF SERVE
1975	DOWNTOWN SPEED WASH COIN OPR	LAUNDRIES-SELF SERVE

---

4 **US POSTAL SERVICE - MAIN OFFICE CARRIER ANNEX** **LA UST** **U003923712**
717 CONVENTION ST **N/A**
BATON ROUGE, LA 70801

UST:

Master Agency Id:	69815
Subject Item ID:	1
UST Tank Num:	25783
Tank Status:	**Removed**
Install Date:	12/21/1978
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

US POSTAL SERVICE - MAIN OFFICE CARRIER ANNEX (Continued) **U003923712**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

4 **DOYLES AUTO REPAIRING** **EDR Hist Auto** **1013756835**
1118 CONVENTION ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1940	DOYLES AUTO REPAIRING	AUTOMOBILE REPAIRING

---

4 **T AND T SERVICES** **EDR Hist Auto** **1020587547**
1142 CONVENTION ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
2007	T AND T SERVICES	General Automotive Repair Shops
2008	T AND T SERVICES	General Automotive Repair Shops

---

4 **US POSTAL SERVICE - MAIN OFFICE CARRIER ANNEX** **LA UST** **U003926100**
210 SEVENTH ST **N/A**
BATON ROUGE, LA 70821

UST:

Master Agency Id:	78073
Subject Item ID:	1
UST Tank Num:	43745
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported

US POSTAL SERVICE - MAIN OFFICE CARRIER ANNEX (Continued) **U003926100**

Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

4 **USPS VEHICLE MAINTENANCE FACILITY** **RCRA-CESQG** **1009398869**
899 CONVENTION ST **LAR000060020**
BATON ROUGE, LA 70802

RCRA-CESQG:

Date form received by agency:	04/21/2006
Facility name:	USPS VEHICLE MAINTENANCE FACILITY
Facility address:	899 CONVENTION ST BATON ROUGE, LA 70802
EPA ID:	LAR000060020
Mailing address:	CONVENTION ST BATON ROUGE, LA 70802
Contact:	MANUEL A LOPEZ
Contact address:	CONVENTION ST BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 381-0388
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Operator
Owner/Op start date:	04/21/2006
Owner/Op end date:	Not reported
Owner/operator name:	US POSTAL SERVICE
Owner/operator address:	Not reported

USPS VEHICLE MAINTENANCE FACILITY (Continued) **1009398869**

	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Owner
Owner/Op start date:	04/21/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

---

4 **SANCHEZ EUPHEMIA MRS** **EDR Hist Cleaner** **1013782169**
1109 CONVENTION ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1931	SANCHEZ EUPHEMIA MRS	CLOTHES PRESSERS AND CLEANERS

---

4 **SICARDS CLEANERS & DYERS CLNR CLNRS** **EDR Hist Cleaner** **1013785196**
1105 CONVENTION ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1936	ACOSTA CLEANERS	CLOTHES PRESSERS AND CLEANERS
1940	SICARDS CLEANERS DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1945	SICARDS CLEANERS & DYERS CLNR C	DRY CLEANERS
1945	SICARDS CLEANERS & DYERS CLNR C	CLOTHES PRESSERS AND CLEANERS

4 QUIK PRINT
638 FLORIDA ST
BATON ROUGE, LA 70802

RCRA-CESQG
FINDS
ECHO

1004707675
LA0001018597

RCRA-CESQG:

Date form received by agency:	01/30/1995
Facility name:	QUIK PRINT
Facility address:	638 FLORIDA ST BATON ROUGE, LA 70802
EPA ID:	LA0001018597
Mailing address:	FLORIDA ST BATON ROUGE, LA 70802
Contact:	JIM EAVES
Contact address:	638 FLORIDA ST BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 344-3343
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	QUIK PRINT
Owner/operator address:	638 FLORIDA ST BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 344-3343
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

QUIK PRINT (Continued) **1004707675**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003265243

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707675
Registry ID: 110003265243
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003265243

---

4 USPS BATON ROUGE VMF **RCRA-CESQG** **1004513704**
750 FLORIDA ST **FINDS** **LA2180000067**
BATON ROUGE, LA 70821 **LA NPDES**
ECHO
LA ASBESTOS

RCRA-CESQG:
Date form received by agency: 05/13/2003
Facility name: USPS BATON ROUGE VMF
Facility address: 750 FLORIDA ST
BATON ROUGE, LA 70821
EPA ID: LA2180000067
Mailing address: FLORIDA ST
BATON ROUGE, LA 70821
Contact: DENIS YOUNG
Contact address: FLORIDA ST
BATON ROUGE, LA 70821
Contact country: US
Contact telephone: (225) 381-0388
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

USPS BATON ROUGE VMF (Continued) **1004513704**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	USPS BATON ROUGE VMF
Owner/operator address:	FLORIDA ST BATON ROUGE, LA 70821
Owner/operator country:	US
Owner/operator telephone:	(225) 381-0388
Legal status:	Federal
Owner/Operator Type:	Owner
Owner/Op start date:	09/24/1986
Owner/Op end date:	Not reported

Owner/operator name:	USPS BATON ROUGE VMF
Owner/operator address:	FLORIDA BLVD BATON ROUGE, LA 70821
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Operator
Owner/Op start date:	09/24/1986
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/24/1986
Site name:	US POST SVC BATON ROUGE
Classification:	Conditionally Exempt Small Quantity Generator

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

USPS BATON ROUGE VMF (Continued) **1004513704**

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110006368000

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NPDES:

Facility Id: 9001
Facility Phone: Not reported
Issued Date: 07/16/2001
Title Description: Fiscal Migration: LAR05M817
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20000002

Facility Id: 9001
Facility Phone: Not reported
Issued Date: 07/23/2014
Title Description: MSGP Gen Permit
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20140001

Facility Id: 9001
Facility Phone: Not reported
Issued Date: 09/06/2016
Title Description: MSGP Renewed Coverage
Permit Type Description: Not reported
Program: Water
Activity Number: GEN20160001

Facility Id: 9001
Facility Phone: Not reported

USPS BATON ROUGE VMF (Continued) **1004513704**

Issued Date:	06/02/2000
Title Description:	LAR05B352 Permit
Permit Type Description:	Gen-LAR05-Multi-Sector
Program:	Water
Activity Number:	GEN20000001

ECHO:

Envid:	1004513704
Registry ID:	110006368000
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110006368000

ASBESTOS:

Asbestos Disposal Facility Id:	Not reported
Site Location:	Not reported
Issue Date:	10/06/2009
Expire Date:	01/04/2010
Qty Rec By Disposal Facility (CY):	2
AI#:	9001
Contractor AI Id:	Not reported
Alternate AI Id:	Not reported
Amount:	1
Unit:	Not reported
Scheduled Start:	10/17/2009
Scheduled End:	10/26/2009
Asbestos Contractors:	Insulation Technologies Inc
Transporter Name:	Insulation Technologies Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	Not reported
SW Disposal Facility Address:	Not reported
SW Disposal Facility City:	Not reported
SW Disposal Facility State:	Not reported
SW Disposal Facility Zip:	Not reported
Parish:	Not reported
Deq Copy Received:	False
Days Elapsed Since Issuance:	Not reported
Days To Expiration:	Not reported
Type Of Notification:	Not reported
Type Of Operation:	Not reported
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	Not reported
Age In Years:	Not reported
Present Use:	Not reported
Prior Use:	Not reported
Mailing Address Line 1:	Not reported
Mailing Address City/State/Zip:	Not reported
Transporter AI Id:	Not reported
Transporter Id:	Not reported
Transporter Address:	Not reported
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Not reported
Total ADVFs Issued:	Not reported
Total Emergency ADVFs Issued:	Not reported
Total Emergency ADVF Revenue Generated:	Not reported
ADVF #:	13879
Total Non-Emergency ADVFs Issued:	Not reported

USPS BATON ROUGE VMF (Continued) **1004513704**

Total Non-Emergency ADVF Revenue Generated: Not reported
Total ADVF Revenue Generated: Not reported
Comments: Not reported

---

4 **US POSTAL SERVICE - DOWNTOWN STATION** **LA UST** **U004222719**
750 FLORIDA ST **N/A**
BATON ROUGE, LA 70801

UST:

Master Agency Id:	9001
Subject Item ID:	1
UST Tank Num:	31624
Tank Status:	**Removed**
Install Date:	02/13/1969
Total Capacity:	5000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	31625
Tank Status:	**Removed**
Install Date:	02/13/1969
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported

US POSTAL SERVICE - DOWNTOWN STATION (Continued) **U004222719**

MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Y
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	31626
Tank Status:	**Removed**
Install Date:	02/13/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35535
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	5000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported

US POSTAL SERVICE - DOWNTOWN STATION (Continued) **U004222719**

Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	51079
Tank Status:	**Removed**
Install Date:	02/01/1992
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

US POSTAL SERVICE - DOWNTOWN STATION (Continued) **U004222719**

UST Tank Num:	51080
Tank Status:	**Removed**
Install Date:	02/01/1992
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	51081
Tank Status:	**Removed**
Install Date:	01/01/1992
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

US POSTAL SERVICE - DOWNTOWN STATION (Continued) **U004222719**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

4 **SIMPSON'S SERVICE CENTER** **LA UST** **U003926812**
1334 FLORIDA BLVD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	86511
Subject Item ID:	2
UST Tank Num:	54372
Tank Status:	**Active**
Install Date:	01/01/2000
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	54373
Tank Status:	**Active**
Install Date:	01/01/2000
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

SIMPSON'S SERVICE CENTER (Continued) **U003926812**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	54374
Tank Status:	**Active**
Install Date:	01/01/2000
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

4 **GREYHOUND LINES INC**
1253 FLORIDA BLVD
BATON ROUGE, LA 70802

LA HIST LUST
LA UST
LA SPILLS
LA NPDES

U001894554
N/A

HIST LUST:

Facility ID:	17-004566	
Facility Parish:	EAST BATON ROUGE	
Substance Name:	UNKNOWN	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	09/20/1991	
Date Confirmed 2:	Not reported	
Incident Number:	91-2-0319	
Incident Date:	09/20/1991	
Type of Incident:		UST LEAK
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00120500	
Owner Name:	GREYHOUND LINES INC.	
Owner Address:	1253 FLORIDA STREET	
Owner City,St,Zip:	BATON ROUGE, LA 70802	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		Not reported
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		Not reported
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		09/17/1991
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ'S MICHAEL P. OBSERVED THE REMOVAL OF UST ON 17 SEP 91.PRODUCT LINE LEAKING INTO TANK BED. AUMILLER'S AT SITE

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-004566
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported

GREYHOUND LINES INC (Continued) **U001894554**

Quantity:	Not reported	
Quantity 2:	Not reported	
Date Confirmed:	Not reported	
Date Confirmed 2:	Not reported	
Incident Number:	91-2-0319	
Incident Date:	09/20/1991	
Type of Incident:		Not reported
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00120500	
Owner Name:	GREYHOUND LINES INC.	
Owner Address:	1253 FLORIDA STREET	
Owner City,St,Zip:	BATON ROUGE, LA 70802	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		Not reported
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		Not reported
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		09/17/1991
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ'S MICHAEL P. OBSERVED THE REMOVAL OF UST ON 17 SEP 91.PRODUCT LINE LEAKING INTO TANK BED. AUMILLER'S AT SITE

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-004566	
Facility Parish:	EAST BATON ROUGE	
Substance Name:	GASOLINE	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	09/17/1991	
Date Confirmed 2:	Not reported	
Incident Number:	91-2-0411	
Incident Date:	09/17/1991	
Type of Incident:		PIPING LEAK
Type of Incident No2:		Not reported

GREYHOUND LINES INC (Continued) **U001894554**

Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00120500
Owner Name: GREYHOUND LINES INC.
Owner Address: 1253 FLORIDA STREET
Owner City,St,Zip: BATON ROUGE, LA 70802
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: ECT, Enviromental Consulting & Tech.Inc.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: (1) 12000 GALLON DIESEL UST WAS REMOVED ON/ABOUT 9/11/91 AND A NEW12,000 GALLON DIESEL UST WAS INSTALLED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-004566
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-2-0411
Incident Date: 09/17/1991
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00120500
Owner Name: GREYHOUND LINES INC.
Owner Address: 1253 FLORIDA STREET
Owner City,St,Zip: BATON ROUGE, LA 70802
Assessment Pending Info: No
Assessment Request Date: Not reported

GREYHOUND LINES INC (Continued) **U001894554**

Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ECT, Enviromental Consulting & Tech.Inc.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: (1) 12000 GALLON DIESEL UST WAS REMOVED ON/ABOUT 9/11/91 AND A NEW12,000 GALLON DIESEL UST WAS INSTALLED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:

Master Agency Id:	41665
Subject Item ID:	1
UST Tank Num:	12780
Tank Status:	**Closed**
Install Date:	04/28/1974
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported

GREYHOUND LINES INC (Continued) **U001894554**

Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39090
Tank Status:	**Active**
Install Date:	08/25/1991
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

SPILLS:

Region Code:	Not reported
Date Rec:	11/22/2008
Date Initiated:	Not reported
aiid:	83561
Incident Id:	111006
Incident Date:	11/22/2008
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Greyhound Bus Lines 1253 Florida Blvd Baton Rouge
Incident Source Name:	East Baton Rouge Parish
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s08-4588 Greyhound Bus Lines--driver was filling tank and walked

GREYHOUND LINES INC (Continued) **U001894554**

away-discovered nozzle on ground still running...jd Greyhound Bus Lines--Driver filling tank; walked away found nozzle on ground still running...jd

Incident Type Desc: Not reported
Comments: Not reported
Parameter: Not reported
Quantity: Not reported
Other Substance Desc: Not reported

NPDES:

Facility Id: 41665
Facility Phone: 2253830990
Issued Date: 06/03/2011
Title Description: MSG Renewed Coverage
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20110001

Facility Id: 41665
Facility Phone: Not reported
Issued Date: 05/23/2006
Title Description: LAR05M062 Reauthorization
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20060001

Facility Id: 41665
Facility Phone: 2253830990
Issued Date: 09/06/2016
Title Description: MSGP Renewed Coverage
Permit Type Description: Not reported
Program: Water
Activity Number: GEN20160001

Facility Id: 41665
Facility Phone: Not reported
Issued Date: 05/21/2001
Title Description: Fiscal Migration: LAR05M062
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN19960001

---

4 **DEVIL'S LAKE** **SEMS** **1000482391**
HWY 61 **ICIS** **LAD985202464**
BATON ROUGE, LA 70821

SEMS:

Site ID: 604431
EPA ID: LAD985202464
Federal Facility: N
NPL: Site is Part of NPL Site
Non NPL Status: Not reported

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID: 0604431
EPA ID: LAD985202464
Facility County: EAST BATON ROUGE

DEVIL'S LAKE (Continued) **1000482391**

Short Name:	DEVIL'S LAKE
Congressional District:	06
IFMS ID:	064E
SMSA Number:	0760
USGC Hydro Unit:	08070201
Federal Facility:	Not a Federal Facility
DMNSN Number:	0.00000
Site Orphan Flag:	N
RCRA ID:	Not reported
USGS Quadrangle:	Not reported
Site Init By Prog:	Not reported
NFRAP Flag:	Not reported
Parent ID:	0600652
RST Code:	Not reported
EPA Region:	06
Classification:	Not reported
Site Settings Code:	Not reported
NPL Status:	Site is Part of NPL Site
DMNSN Unit Code:	Not reported
RBRAC Code:	Not reported
RResp Fed Agency Code:	Not reported
Non NPL Status:	Not reported
Non NPL Status Date:	/ /
Site Fips Code:	22033
CC Concurrence Date:	/ /
CC Concurrence FY:	Not reported
Alias EPA ID:	Not reported
Site FUDS Flag:	Not reported

CERCLIS Site Alias Name(s):

Alias ID:	101
Alias Name:	DEVIL'S SWAMP LAKE
Alias Address:	HWY 61 BATON ROUGE, LA 70821
Alias Comments:	Not reported
Site Description:	See Devils Swamp-Ewell Property. ERS exclusion made in consultation with LDEQ 12/03.

CERCLIS Assessment History:

Action Code:	001
Action:	DISCOVERY
Date Started:	/ /
Date Completed:	08/01/91
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	EPA Fund-Financed
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

Action Code:	001
Action:	SITE INSPECTION
Date Started:	05/13/92
Date Completed:	05/13/92
Priority Level:	Higher priority for further assessment

DEVIL'S LAKE (Continued) **1000482391**

Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: PRELIMINARY ASSESSMENT
Date Started: 05/13/92
Date Completed: 05/13/92
Priority Level: Higher priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: EXPANDED SITE INSPECTION
Date Started: 10/29/93
Date Completed: 10/29/93
Priority Level: Recommended for HRS Scoring
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: NATIONAL PRIORITIES LIST RESPONSIBLE PARTY SEARCH
Date Started: 09/11/95
Date Completed: 07/03/96
Priority Level: Search Complete, Viable PRPs
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Primary
Urgency Indicator: Not reported
Action Anomaly: Not reported

ICIS:
Enforcement Action ID: 06-2010-2875
FRS ID: 110012799659
Action Name: Devil's Swamp
Facility Name: DEVIL'S LAKE
Facility Address: HWY 61
BATON ROUGE, LA 70821
Enforcement Action Type: CERCLA 104E5A AO For Access And/Or Info
Facility County: EAST BATON ROUGE
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 104E5A
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: +30.561944

DEVIL'S LAKE (Continued) **1000482391**

Longitude in Decimal Degrees: -91.220556
Permit Type Desc: Not reported
Program System Acronym: 2200001659
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 06-2010-2875
FRS ID: 110012799659
Action Name: Devil's Swamp
Facility Name: DEVIL'S LAKE
Facility Address: HWY 61
BATON ROUGE, LA 70821
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: EAST BATON ROUGE
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 106
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: Not reported
Longitude in Decimal Degrees: Not reported
Permit Type Desc: Not reported
Program System Acronym: LAD985202464
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 06-2010-2875
FRS ID: 110012799659
Action Name: Devil's Swamp
Facility Name: DEVIL'S LAKE
Facility Address: HWY 61
BATON ROUGE, LA 70821
Enforcement Action Type: CERCLA 106 AO For Resp Action/Imm Haz
Facility County: EAST BATON ROUGE
Program System Acronym: ICIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 106
Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: +30.561944
Longitude in Decimal Degrees: -91.220556
Permit Type Desc: Not reported
Program System Acronym: 2200001659
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Enforcement Action ID: 06-2010-2875
FRS ID: 110012799659
Action Name: Devil's Swamp
Facility Name: DEVIL'S LAKE
Facility Address: HWY 61
BATON ROUGE, LA 70821
Enforcement Action Type: CERCLA 104E5A AO For Access And/Or Info
Facility County: EAST BATON ROUGE
Program System Acronym: CERCLIS
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: 104E5A

DEVIL'S LAKE (Continued) **1000482391**

Facility SIC Code: Not reported
Federal Facility ID: Not reported
Latitude in Decimal Degrees: Not reported
Longitude in Decimal Degrees: Not reported
Permit Type Desc: Not reported
Program System Acronym: LAD985202464
Facility NAICS Code: Not reported
Tribal Land Code: Not reported

Facility Name: DEVIL'S LAKE
Address: HWY 61
Tribal Indicator: N
Fed Facility: Not reported
NAIC Code: Not reported
SIC Code: Not reported

Facility Name: DEVIL'S LAKE
Address: HWY 61
Tribal Indicator: N
Fed Facility: Not reported
NAIC Code: Not reported
SIC Code: Not reported

---

4 **BATON ROUGE GAS WORKS** **LA SHWS** **S112659436**
LAUREL ST & N 12TH ST **N/A**
BATON ROUGE, LA 70818

SHWS:
Facility ID: 9911
Facility Status: Confirmed

---

4 **BATON ROUGE FIRE DEPT** **RCRA-CESQG** **1004713029**
1100 LAUREL ST **FINDS** **LAR000005157**
BATON ROUGE, LA 70802 **ECHO**

RCRA-CESQG:
Date form received by agency: 06/14/1995
Facility name: BATON ROUGE FIRE DEPT
Facility address: 1100 LAUREL ST
BATON ROUGE, LA 70802
EPA ID: LAR000005157
Mailing address: LAUREL ST
BATON ROUGE, LA 70802
Contact: ED SMITH
Contact address: 1100 LAUREL ST
BATON ROUGE, LA 70802
Contact country: US
Contact telephone: (225) 389-4612
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar

BATON ROUGE FIRE DEPT (Continued) **1004713029**

month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CITY OF BATON ROUGE
Owner/operator address:	1100 LAUREL BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 389-4600
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110003348949

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and

BATON ROUGE FIRE DEPT (Continued) **1004713029**

corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004713029
Registry ID:	110003348949
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003348949

---

4 BR 131 O'BRIEN HOUSE **US BROWNFIELDS** **1016356310**
1217 LAUREL ST. **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge-Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 131 O'BRIEN HOUSE
Property #:	830341866, 830341867
Parcel size:	.24
Property Description:	The site was used by the Baton Rouge Gas Works in the late 1800s. Since 1971 it has been used as O'Brien House- a residential halfway house for recovering adult alcoholics and drug addicts.
Latitude:	30.4506986
Longitude:	-91.1774865
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	114241
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	1937
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	300000
Redev. funding source:	Private/Other Funding
Redev. funding entity name:	Not reported
Redevelopment start date:	10/31/2011 00:00:00
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Cleanup Planning
Accomplishment count:	0
Cooperative agreement #:	00F18701
Ownership entity:	Private
Current owner:	O'Brien House
Did owner change:	N
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported

BR 131 O'BRIEN HOUSE (Continued) **1016356310**

IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	5
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	.24
Future use greenspace acreage:	.24
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported

BR 131 O'BRIEN HOUSE (Continued) **1016356310**

nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	01/10/2013 00:00:00
# Below Poverty:	844
% Below Poverty:	2.5%
# Low Income:	1397
% Low Income:	1.5%
Meidan Income:	3961
# Unemployed:	142
% Unemployed:	14.7%
# Vacant Housing:	247
% Vacant Housing:	8.5%
Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 131 O'BRIEN HOUSE
Property #:	830341866, 830341867
Parcel size:	.24
Property Description:	The site was used by the Baton Rouge Gas Works in the late 1800s. Since 1971 it has been used as O'Brien House- a residential halfway house for recovering adult alcoholics and drug addicts.
Latitude:	30.4506986
Longitude:	-91.1774865
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	North American Datum of 1983
ACRES property ID:	114241
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported

BR 131 O'BRIEN HOUSE (Continued) **1016356310**

Cleanup funding source:	Not reported
Assessment funding:	18600
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Supplemental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Private
Current owner:	O'Brien House
Did owner change:	N
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y

BR 131 O'BRIEN HOUSE (Continued) **1016356310**

Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	.24
Future use greenspace acreage:	.24
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	844
% Below Poverty:	2.5%
# Low Income:	1397
% Low Income:	1.5%
Meidan Income:	3961
# Unemployed:	142
% Unemployed:	14.7%

BR 131 O'BRIEN HOUSE (Continued) **1016356310**

Vacant Housing: 247
% Vacant Housing: 8.5%

FINDS:

Registry ID: 110042111791

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

4 BATON ROUGE GAS WORKS **EDR MGP** **1008408920**
LAUREL STREET **N/A**
BATON ROUGE, LA 70802

Manufactured Gas Plants:
Alternate Name:BATON ROUGE ELECTRIC CO. No additional information available

---

4 FIFTH STREET MAIN GULF **LA HIST LUST** **S106033848**
501 MAIN ST **N/A**
BATON ROUGE, LA 70802

HIST LUST:

Facility ID:	17-006367
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	05/06/1992
Date Confirmed 2:	Not reported
Incident Number:	92-2-0140
Incident Date:	05/06/1992
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00191400
Owner Name:	MCMAHON, R. RUSSELL
Owner Address:	1645 PERKINS RD.
Owner City,St,Zip:	BATON ROUGE, LA 70808
Assessment Pending Info:	No
Assessment Request Date:	07/01/1992
Assessment Plan Due Date:	09/20/1992
Assessment Plan Received Date:	09/24/1992
Assessment Approved Date:	11/06/1992
Assessment Contractor:	CK ASSOCIATES INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported

FIFTH STREET MAIN GULF (Continued) **S106033848**

Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/15/1992
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: REC'D LETTER FROM OWNER DATED 9/23/92 THAT SOIL SAMPLES WERE TAKENAND WAITING ON RESULTS. USTS HAVE BEEN REMOVED AND SITE IS TO BECONVERTED INTO A PARKING LOT. ANALYTICAL RESULTS CAME BACK SLIGHTLYELEVATED. NO FURTHER ACTION REQUIRED.

LA HIST LUST ASSESMENT:
Comments: .

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-006367
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	92-2-0140
Incident Date:	05/06/1992
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00191400
Owner Name:	MCMAHON, R. RUSSELL
Owner Address:	1645 PERKINS RD.
Owner City,St,Zip:	BATON ROUGE, LA 70808
Assessment Pending Info:	No
Assessment Request Date:	07/01/1992
Assessment Plan Due Date:	09/20/1992
Assessment Plan Received Date:	09/24/1992
Assessment Approved Date:	11/06/1992
Assessment Contractor:	CK ASSOCIATES INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/15/1992

FIFTH STREET MAIN GULF (Continued) **S106033848**

Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: REC'D LETTER FROM OWNER DATED 9/23/92 THAT SOIL SAMPLES WERE TAKENAND WAITING ON RESULTS. USTS HAVE BEEN REMOVED AND SITE IS TO BECONVERTED INTO A PARKING LOT. ANALYTICAL RESULTS CAME BACK SLIGHTLYELEVATED. NO FURTHER ACTION REQUIRED.

LA HIST LUST ASSESMENT:
Comments: .

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

---

4 **BR 161 SPANISH TOWN SITE 'A'** **US BROWNFIELDS** **1014476341**
1104 MAIN ST. BETWEEN NORTH AND MAIN ON CANAL ST. **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 161 SPANISH TOWN SITE 'A'
Property #:	830340785-830340791
Parcel size:	.44
Property Description:	The site consists of 7 undeveloped, vacant lots near electrical substations and surrounded by an area with light commercial uses. Signs of historical use evident at the time of the Phase I ESA included concrete slab remnants, retaining walls and driveways. Two billboards are located on the northern portion of the site. Mr. Joseph Atiyah was the property owner at the time the Phase I ESA was conducted.
Latitude:	30.452744
Longitude:	-91.1792374
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	114461
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	4740
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous

BR 161 SPANISH TOWN SITE 'A' (Continued) **1014476341**

Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Private
Current owner:	Donnie Jarreau Companies
Did owner change:	Y
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	.44
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

BR 161 SPANISH TOWN SITE 'A' (Continued) **1014476341**

Future use greenspace acreage:	Not reported
Future use residential acreage:	.44
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Y
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	855
% Below Poverty:	2.4%
# Low Income:	1409
% Low Income:	1.5%
Meidan Income:	4495
# Unemployed:	131
% Unemployed:	16.0%
# Vacant Housing:	243
% Vacant Housing:	8.6%

4 **BOB DEAN ENTERPRISES** **LA REM** **S118246523**
1034 MAIN ST **N/A**
BATON ROUGE, LA 70802

REM:

AI Num:	120463
Evaluated And Closed:	Not reported
Program:	Solid Waste
EAC Type:	Not reported
Comments:	Not reported

---

4 **MAIN STREET USA, INC.** **US BROWNFIELDS FINDS** **1016348852**
1201 MAIN STREET **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Main Street USA, Inc.
Grant type:	Cleanup
Property name:	MAIN STREET USA, INC.
Property #:	Not reported
Parcel size:	1
Property Description:	Buildling was used as a car dealership, then became an auto parts warehouse. The building was abandoned in 1985 until redevelopment through the Brownfields Program.
Latitude:	30.451844
Longitude:	-91.177133
HCM label:	Not reported
Map scale:	1:24000
Point of reference:	Not reported
Datum:	North American Datum of 1983
ACRES property ID:	38864
Start date:	08/01/2005 00:00:00
Completed date:	11/10/2005 00:00:00
Acres cleaned up:	1
Cleanup funding:	178000
Cleanup funding source:	US EPA - Brownfields Cleanup Cooperative Agreement
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	2700000
Redev. funding source:	Private/Other Funding
Redev. funding entity name:	Angle Systems, LLC
Redevelopment start date:	11/15/2005 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	EPA
Grant type:	N/A
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	97699301
Ownership entity:	Private
Current owner:	Not reported
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported

MAIN STREET USA, INC. (Continued) **1016348852**

IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Y
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Y
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	20
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	1
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	U
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported

MAIN STREET USA, INC. (Continued) **1016348852**

Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	811
% Below Poverty:	2.4%
# Low Income:	1337
% Low Income:	1.5%
Meidan Income:	4302
# Unemployed:	130
% Unemployed:	15.0%
# Vacant Housing:	240
% Vacant Housing:	8.1%

Recipient name:	Main Street USA, Inc.
Grant type:	Cleanup
Property name:	MAIN STREET USA, INC.
Property #:	Not reported
Parcel size:	1
Property Description:	Buildling was used as a car dealership, then became an auto parts warehouse. The building was abandoned in 1985 until redevelopment through the Brownfields Program.
Latitude:	30.451844
Longitude:	-91.177133
HCM label:	Not reported
Map scale:	1:24000
Point of reference:	Not reported
Datum:	North American Datum of 1983
ACRES property ID:	38864
Start date:	08/01/2005 00:00:00
Completed date:	11/10/2005 00:00:00
Acres cleaned up:	1
Cleanup funding:	51000
Cleanup funding source:	Private/Other Funding
Assessment funding:	Not reported
Assessment funding source:	Not reported

MAIN STREET USA, INC. (Continued) **1016348852**

Redevelopment funding:	2700000
Redev. funding source:	Private/Other Funding
Redev. funding entity name:	Angle Systems, LLC
Redevelopment start date:	11/15/2005 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Main Street USA
Grant type:	N/A
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	97699301
Ownership entity:	Private
Current owner:	Not reported
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Y
Other cleaned up:	Not reported
Other metals found:	Y
Other metals cleaned:	Y
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Y
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported

MAIN STREET USA, INC. (Continued) **1016348852**

VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	20
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	1
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	1
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	U
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	811
% Below Poverty:	2.4%
# Low Income:	1337
% Low Income:	1.5%
Meidan Income:	4302
# Unemployed:	130
% Unemployed:	15.0%
# Vacant Housing:	240
% Vacant Housing:	8.1%

MAIN STREET USA, INC. (Continued) **1016348852**

FINDS:

Registry ID: 110038750401

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

5 AMERICAN CATALYST SERVICES INC **RCRA NonGen / NLR** **1000360098**
4545 SCALLAN RD **FINDS** **LAD039180740**
PORT ALLEN, LA 70767 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	06/03/2010
Facility name:	AMERICAN CATALYST SERVICES INC
Facility address:	4545 SCALLAN RD PORT ALLEN, LA 70767
EPA ID:	LAD039180740
Mailing address:	PO BOX 772 PORT ALLEN, LA 70767
Contact:	HEBERT MELVIN
Contact address:	PO BOX 772 PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 383-6049
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNKNOWN
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	UNKNOWN
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	US
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/03/2010
Owner/Op end date:	Not reported

AMERICAN CATALYST SERVICES INC (Continued) **1000360098**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Universal Waste Summary:

Waste type:	Batteries
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
Waste type:	Lamps
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
Waste type:	Pesticides
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
Waste type:	Thermostats
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported

Historical Generators:

Date form received by agency:	04/06/1984
Site name:	AMERICAN CATALYST SERVICES INC
Classification:	Not a generator, verified
Violation Status:	No violations found

FINDS:

Registry ID: 110003272734

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

AMERICAN CATALYST SERVICES INC (Continued) **1000360098**

ECHO:
Envid: 1000360098
Registry ID: 110003272734
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003272734

---

6 **HUDSON RESIDENCE** **LA REM** **S116492280**
310 CONVENTION ST **N/A**
BATON ROUGE, LA 70801

REM:
AI Num: 190708
Evaluated And Closed: 07/03/2014
Program: Solid Waste
EAC Type: No Further Interest
Comments: EDMS ID 9368169.

---

6 **PARKING GARAGE** **LA HIST LUST** **S106034272**
220 CONVENTION ST **N/A**
BATON ROUGE, LA 70804

HIST LUST:
Facility ID: 17-015464
Facility Parish: EAST BATON ROUGE
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 12/07/1995
Date Confirmed 2: Not reported
Incident Number: 95-2-0148
Incident Date: 12/07/1995
Type of Incident: UNKNOWN
Type of Incident No2: Not reported
Reported By: MIKE DUCOTE
Reported By 2: Not reported
Owner ID: 00729200
Owner Name: STATE OF LA,DOA,FAC PLAN & CONT.
Owner Address: P. O. BOX 94095
Owner City,St,Zip: BATON ROUGE, LA 70804-9095
Assessment Pending Info: No
Assessment Request Date: 01/18/1996
Assessment Plan Due Date: 04/08/1996
Assessment Plan Received Date: 05/03/1996
Assessment Approved Date: Not reported
Assessment Contractor: SSCI (LA)
Assess Date Add Info Due: 07/01/1996
Assess Date Add Info Recd: 12/16/1996
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 05/02/1997
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported

PARKING GARAGE (Continued) **S106034272**

Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: 6 USTS (GASOLINE) WERE REMOVED AT THE ABOVE SITE. THERE IS A DRINKINGWATER WELL ACROSS THE STREET IN LAFAYETTE PARK. ELEVATED BTEX ANDTPH-G LEVELS REPORTED. REC'D INITIAL ABATEMENT REPORT 3/12/96. REC'DSITE ASSESSMENT PROPOSAL ON 5/3/96. DEQ RECORD OF COMMUNICATIONS MEMO5/29/96: REQUEST CONSULTANT TO GET INFORMATION ON WATER WELL INLAFAYETTE PARK.

LA HIST LUST CORRECTIVE ACTION:
Comments: REC'D SITE ASSESS. PROPOSAL ON 12-16-96. REC'D ADDITIONAL SITEASSESS. ON 1-6-97. DEQ APPROVED ADDITIONAL SITE ASSESSMENT INSTALLATINOF 2 SOIL BORINGS. DEQ INSPECT. 3-18-97 TO OBSERVE SOIL BORINGSDEQ APPROVES NO FURTHER ASSESSMENT AND/OR REMEDIATION ON5/2/97.

Facility ID: 17-015464
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 95-2-0148
Incident Date: 12/07/1995
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00729200
Owner Name: STATE OF LA,DOA,FAC PLAN & CONT.
Owner Address: P. O. BOX 94095
Owner City,St,Zip: BATON ROUGE, LA 70804-9095
Assessment Pending Info: No
Assessment Request Date: 01/18/1996
Assessment Plan Due Date: 04/08/1996
Assessment Plan Received Date: 05/03/1996
Assessment Approved Date: Not reported
Assessment Contractor: SSCI (LA)
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 05/02/1997
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported

PARKING GARAGE (Continued) **S106034272**

Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: 6 USTS (GASOLINE) WERE REMOVED AT THE ABOVE SITE. THERE IS A DRINKINGWATER WELL ACROSS THE STREET IN LAFAYETTE PARK. ELEVATED BTEX ANDTPH-G LEVELS REPORTED. REC'D INITIAL ABATEMENT REPORT 3/12/96. REC'DSITE ASSESSMENT PROPOSAL ON 5/3/96. DEQ RECORD OF COMMUNICATIONS MEMO5/29/96: REQUEST CONSULTANT TO GET INFORMATION ON WATER WELL INLAFAYETTE PARK.

LA HIST LUST CORRECTIVE ACTION:
Comments: REC'D SITE ASSESS. PROPOSAL ON 12-16-96. REC'D ADDITIONAL SITEASSESS. ON 1-6-97. DEQ APPROVED ADDITIONAL SITE ASSESSMENT INSTALLATINOF 2 SOIL BORINGS. DEQ INSPECT. 3-18-97 TO OBSERVE SOIL BORINGSDEQ APPROVES NO FURTHER ASSESSMENT AND/OR REMEDIATION ON5/2/97.

---

6 **MAPP PROPERTIES SITE** **LA REM** **S112658985**
350 THIRD ST **N/A**
BATON ROUGE, LA 70821

REM:
AI Num: 47367
Evaluated And Closed: 10/03/2006
Program: UST
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 3004303

---

7 **CHEVRON FOOD MART** **LA HIST LUST** **U001892901**
704 S ALEXANDER ST **LA UST** **N/A**
PORT ALLEN, LA 70767

HIST LUST:
Facility ID: 61-013538
Facility Parish: WEST BATON ROUGE
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 11/19/1991
Date Confirmed 2: Not reported
Incident Number: 91-2-0380
Incident Date: 11/18/1991
Type of Incident: PIPING LEAK
Type of Incident No2: Not reported
Reported By: HAL GILDER
Reported By 2: Not reported
Owner ID: 00022200
Owner Name: BATON ROUGE OIL CO (MORELLA CO)
Owner Address: 10319 OLD HAMMOND - SUITE B-1
Owner City,St,Zip: BATON ROUGE, LA 70816
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported

CHEVRON FOOD MART (Continued) **U001892901**

Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: CHANGING LINES DISCOVERED PRODUCT IN THE LINES AND CONTAMINATED SOILS.SEE INCIDENT NO. 93-2-0051.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	61-013538
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0380
Incident Date:	11/18/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00022200
Owner Name:	BATON ROUGE OIL CO (MORELLA CO)
Owner Address:	10319 OLD HAMMOND - SUITE B-1
Owner City,St,Zip:	BATON ROUGE, LA 70816
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported

CHEVRON FOOD MART (Continued) **U001892901**

Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: CHANGING LINES DISCOVERED PRODUCT IN THE LINES AND CONTAMINATED SOILS.SEE INCIDENT NO. 93-2-0051.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 61-013538
Facility Parish: WEST BATON ROUGE
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 02/25/1993
Date Confirmed 2: Not reported
Incident Number: 93-2-0051
Incident Date: 02/25/1993
Type of Incident: DISPENSER LEAK
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00022200
Owner Name: BATON ROUGE OIL CO (MORELLA CO)
Owner Address: 10319 OLD HAMMOND - SUITE B-1
Owner City,St,Zip: BATON ROUGE, LA 70816
Assessment Pending Info: Yes
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: 04/20/1993
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported

CHEVRON FOOD MART (Continued) **U001892901**

Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: CUSTOMER ACCIDENTLY DROVE OFF WITH DISPENSER NOZZLE IN THE VEHICLESGAS TANK. DEQ LETTER 3-3-93 REQUESTING NOTIFICATION AND INVESTIGATION

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 61-013538
Facility Parish: WEST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 93-2-0051
Incident Date: 02/25/1993
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00022200
Owner Name: BATON ROUGE OIL CO (MORELLA CO)
Owner Address: 10319 OLD HAMMOND - SUITE B-1
Owner City,St,Zip: BATON ROUGE, LA 70816
Assessment Pending Info: Yes
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: CUSTOMER ACCIDENTLY DROVE OFF WITH DISPENSER NOZZLE IN THE VEHICLESGAS TANK. DEQ LETTER 3-3-93 REQUESTING NOTIFICATION AND INVESTIGATION

CHEVRON FOOD MART (Continued) **U001892901**

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:

Master Agency Id:	76572
Subject Item ID:	1
UST Tank Num:	39149
Tank Status:	**Active**
Install Date:	01/01/1975
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	39150
Tank Status:	**Active**
Install Date:	01/01/1975
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported

CHEVRON FOOD MART (Continued) **U001892901**

Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39151
Tank Status:	**Active**
Install Date:	01/01/1975
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

7 **CIRCLE K #9733** **LA HIST LUST** **S103490390**
650 S ALEXANDER AVE **LA SPILLS** **N/A**
PORT ALLEN, LA 70767 **LA NPDES**

HIST LUST:

Facility ID:	61-011327
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	07/22/1994

CIRCLE K #9733 (Continued) **S103490390**

Date Confirmed 2:	Not reported
Incident Number:	94-2-0113
Incident Date:	07/22/1994
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	TOM EWING/G&E ENGINEERING
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	No
Assessment Request Date:	08/23/1994
Assessment Plan Due Date:	11/13/1994
Assessment Plan Received Date:	09/16/1994
Assessment Approved Date:	12/13/1994
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: G&E ENGINEERING DISCOVERED BTEX LEVELS OF 6.0 PPM TO 5.8 PPM IN THEGROUNDWATER IN 4 OF THE 7 BORINGS DRILLED ON SITE. SITE ASSESSMENTAPPROVED 12/13/94. REC'D REPORT OF ENVIRONMENTAL ASSESSMENT ACTIVITISON 4/22/95. ADDITIOONAL ASSESSMENT APPROVED 6/7/95. REC'D INITIALSUBSURFACE INVESTIGATION ON 11/22/95. QTLY REPORTS SUBMITTED.

LA HIST LUST CORRECTIVE ACTION:
Comments: QTLY REPORTS SUBMITTED. DEQ REQUEST ADDITIONAL ASSESSMENT ON 11/26/96REC'D SECOND ADDITIONAL ASSESSMENT REPORT ON 9/9/98. DEQ LETTER10/14/98 APPROVED 9/98 ASSESSMENT REPORT.

Facility ID:	61-011327
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	94-2-0113
Incident Date:	07/22/1994

CIRCLE K #9733 (Continued) **S103490390**

Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	No
Assessment Request Date:	08/23/1994
Assessment Plan Due Date:	11/13/1994
Assessment Plan Received Date:	09/16/1994
Assessment Approved Date:	12/13/1994
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: G&E ENGINEERING DISCOVERED BTEX LEVELS OF 6.0 PPM TO 5.8 PPM IN THEGROUNDWATER IN 4 OF THE 7 BORINGS DRILLED ON SITE. SITE ASSESSMENTAPPROVED 12/13/94. REC'D REPORT OF ENVIRONMENTAL ASSESSMENT ACTIVITISON 4/22/95. ADDITIOONAL ASSESSMENT APPROVED 6/7/95. REC'D INITIALSUBSURFACE INVESTIGATION ON 11/22/95. QTLY REPORTS SUBMITTED.

LA HIST LUST CORRECTIVE ACTION:
Comments: QTLY REPORTS SUBMITTED. DEQ REQUEST ADDITIONAL ASSESSMENT ON 11/26/96REC'D SECOND ADDITIONAL ASSESSMENT REPORT ON 9/9/98. DEQ LETTER10/14/98 APPROVED 9/98 ASSESSMENT REPORT.

SPILLS:

Region Code:	CR
Date Rec:	02/06/2012
Date Initiated:	02/08/2012
aiid:	66396
Incident Id:	137023
Incident Date:	02/06/2012
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Circle K Store 9733 650 S Alexander Ave Port Allen
Incident Source Name:	Circle K #9733
Reporter Name:	Not reported

CIRCLE K #9733 (Continued) **S103490390**

Mailing Address 1: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Incident Desc: TTT PASSED
Incident Type Desc: UST, Release Detection Failure
Comments: 2/7/12 - Emailed Circle K for TTT results 2/14/12 - TTT performed
2/20/12 - TTT results recieved (PASSING)
Parameter: 0
Quantity: 0 0
Other Substance Desc: 0

NPDES:
Facility Id: 66396
Facility Phone: 8139106830
Issued Date: 06/12/2009
Title Description: Permit
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20090001

Facility Id: 66396
Facility Phone: 8139106830
Issued Date: 01/23/2007
Title Description: LAG750582 Permit
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20060001

---

7 **CIRCLE K #2709733** **LA REM** **S118246617**
650 S ALEXANDER AVE **N/A**
PORT ALLEN, LA 70767

REM:
AI Num: 66396
Evaluated And Closed: Not reported
Program: UST
EAC Type: Not reported
Comments: Not reported

AI Num: 66396
Evaluated And Closed: 08/14/2015
Program: UST
EAC Type: Closure
Comments: EDMS ID 9911912

7 CIRCLE K #2709733 — **LA LUST** — **U003986985**
650 S ALEXANDER AVE — **LA UST** — **N/A**
PORT ALLEN, LA 70767 — **LA NPDES**

LUST:

Facility ID:	66396
Comments:	UST

UST:

Master Agency Id:	66396
Subject Item ID:	2
UST Tank Num:	30091
Tank Status:	**Removed**
Install Date:	03/26/1971
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	30092
Tank Status:	**Removed**
Install Date:	03/26/1970
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

CIRCLE K #2709733 (Continued) **U003986985**

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	30093
Tank Status:	**Removed**
Install Date:	03/26/1970
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	39274
Tank Status:	**Removed**
Install Date:	01/01/1986
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes

CIRCLE K #2709733 (Continued) **U003986985**

Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39275
Tank Status:	**Removed**
Install Date:	01/01/1986
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39276

CIRCLE K #2709733 (Continued) **U003986985**

Tank Status:	**Removed**
Install Date:	01/01/1986
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39277
Tank Status:	**Removed**
Install Date:	01/01/1986
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported

CIRCLE K #2709733 (Continued) **U003986985**

Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	71110
Tank Status:	**Active**
Install Date:	07/16/2015
Total Capacity:	20000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	71111
Tank Status:	**Active**
Install Date:	07/16/2015
Total Capacity:	20000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

CIRCLE K #2709733 (Continued) **U003986985**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NPDES:

Facility Id:	66396
Facility Phone:	8139106830
Issued Date:	08/28/1998
Title Description:	Fiscal Migration: LAG750103
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN19940001

Facility Id:	66396
Facility Phone:	8139106830
Issued Date:	05/07/2004
Title Description:	LAG750103 Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20040001

Facility Id:	66396
Facility Phone:	2253837721
Issued Date:	07/22/2014
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20140001

---

7 **EXXON STATION 52061** **LA HIST LUST** **S106033766**
520 S. ALEXANDER DR. / I-10 **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-004062
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	12-13 GAL
Quantity 2:	Not reported
Date Confirmed:	09/10/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0180
Incident Date:	09/09/1990
Type of Incident:	DISPENSER LEAK
Type of Incident No2:	Not reported
Reported By:	DON SIMPSON
Reported By 2:	Not reported
Owner ID:	00109200

EXXON STATION 52061 (Continued) **S106033766**

Owner Name: EXXON MOBIL COMPANY, U.S.A.
Owner Address: P. O. BOX 4386
Owner City,St,Zip: HOUSTON,, TX 77210-4386
Assessment Pending Info: No
Assessment Request Date: 09/13/1990
Assessment Plan Due Date: 12/03/1990
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 10/23/1990
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DRESSER COUPLING IN DISPENCER CREATED A SURFACE SPILL.REPAIRS WERE MADE AND THE PRODUCT WAS RETURNED TO SERVICE. NO CAPNEEDED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 61-004062
Facility Parish: WEST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 90-2-0180
Incident Date: 09/09/1990
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00109200
Owner Name: EXXON MOBIL COMPANY, U.S.A.
Owner Address: P. O. BOX 4386
Owner City,St,Zip: HOUSTON,, TX 77210-4386
Assessment Pending Info: No
Assessment Request Date: 09/13/1990
Assessment Plan Due Date: 12/03/1990
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported

EXXON STATION 52061 (Continued) **S106033766**

Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	10/23/1990
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DRESSER COUPLING IN DISPENCER CREATED A SURFACE SPILL.REPAIRS WERE MADE AND THE PRODUCT WAS RETURNED TO SERVICE. NO CAPNEEDED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	61-004062
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	08/22/1994
Date Confirmed 2:	Not reported
Incident Number:	94-2-0131
Incident Date:	08/22/1994
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	BARRY HEBERT/ G&E ENGINEERING
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	10/21/1994
Assessment Plan Due Date:	01/11/1994
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	09/11/1996
Corrective Plan Received Date:	09/11/1996

EXXON STATION 52061 (Continued) **S106033766**

Corrective Plan Approved Date:	12/20/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: DEQ APPROVED WELL POINT RECOVERY & TREATMENT SYSTEM ON 12/20/96.REC'D REVISED COST ESTIMATE FOR INSTALL. OF THE WELLPOINT RECOVERYAND TREATMENT SYSTEM ON 1/22/98. NEW EST: $191,834. WAS: $177,260.REC'D REVISED COST EST: $316,334 ON 5/13/98.

LA HIST LUST ASSESMENT:

Comments: THE PLUS UNLEADED GASOLINE PRODUCT LINE FAILED TIGHTNESS TEST.INVENTORY RECORDS INDICATED A PRODUCT LOST. ASSESSMENT REQUIRED.REC'D INITIAL SUBSURFACE INVESTIGATION REPORT ON 7/5/95. DEQ APPROVEDSUBSURFACE INVESTIGATION TO INSTALL 10 SOIL BORINGS W/ GEOPROBE.

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 11-8-95 CONT. CURRENT SAMPLING PROGRAM. DEQ INSPECTION11/6/95 TO WITNESS THE INSTALLATION OF 10 GEOPROBE SOIL BORING. DEQLETTER 2/16/96 CONTINUE QTLY MONITORING. QTLY REPORTS SUBMITTED.REC'D ADDITIONAL SUBSURFACE INVESTIGATION REPORT ON 5/20/96. DEQAPPROVED SITE ASSESSMENT & REQUEST A CAP ON 7/11/96. QTLY REPORTSSUBMITTED.

Facility ID:	61-004062
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	94-2-0131
Incident Date:	08/22/1994
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	10/21/1994
Assessment Plan Due Date:	01/11/1994
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	09/11/1996

EXXON STATION 52061 (Continued) **S106033766**

Corrective Plan Received Date:	09/11/1996
Corrective Plan Approved Date:	12/20/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: DEQ APPROVED WELL POINT RECOVERY & TREATMENT SYSTEM ON 12/20/96.REC'D REVISED COST ESTIMATE FOR INSTALL. OF THE WELLPOINT RECOVERYAND TREATMENT SYSTEM ON 1/22/98. NEW EST: $191,834. WAS: $177,260.REC'D REVISED COST EST: $316,334 ON 5/13/98.

LA HIST LUST ASSESMENT:

Comments: THE PLUS UNLEADED GASOLINE PRODUCT LINE FAILED TIGHTNESS TEST.INVENTORY RECORDS INDICATED A PRODUCT LOST. ASSESSMENT REQUIRED.REC'D INITIAL SUBSURFACE INVESTIGATION REPORT ON 7/5/95. DEQ APPROVEDSUBSURFACE INVESTIGATION TO INSTALL 10 SOIL BORINGS W/ GEOPROBE.

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 11-8-95 CONT. CURRENT SAMPLING PROGRAM. DEQ INSPECTION11/6/95 TO WITNESS THE INSTALLATION OF 10 GEOPROBE SOIL BORING. DEQLETTER 2/16/96 CONTINUE QTLY MONITORING. QTLY REPORTS SUBMITTED.REC'D ADDITIONAL SUBSURFACE INVESTIGATION REPORT ON 5/20/96. DEQAPPROVED SITE ASSESSMENT & REQUEST A CAP ON 7/11/96. QTLY REPORTSSUBMITTED.

---

7 **EXXON CO USA #52061** **LA UST** **U003986738**
520 S ALEXANDER AVE **LA NPDES** **N/A**
PORT ALLEN, LA 70767 **LA REM**

UST:

Master Agency Id:	13392
Subject Item ID:	1
UST Tank Num:	11303
Tank Status:	**Removed**
Install Date:	04/12/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported

EXXON CO USA #52061 (Continued) **U003986738**

A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	11304
Tank Status:	**Removed**
Install Date:	04/12/1981
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	11305
Tank Status:	**Removed**
Install Date:	04/12/1981
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported

EXXON CO USA #52061 (Continued) **U003986738**

MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	11306
Tank Status:	**Removed**
Install Date:	04/12/1981
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55059
Tank Status:	**Removed**
Install Date:	01/01/1970
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported

EXXON CO USA #52061 (Continued) **U003986738**

Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55060
Tank Status:	**Removed**
Install Date:	01/01/1970
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

EXXON CO USA #52061 (Continued) **U003986738**

UST Tank Num:	55061
Tank Status:	**Removed**
Install Date:	01/01/1970
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55062
Tank Status:	**Removed**
Install Date:	01/01/1970
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

EXXON CO USA #52061 (Continued) **U003986738**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

NPDES:

Facility Id:	13392
Facility Phone:	Not reported
Issued Date:	09/30/1998
Title Description:	LAG830053 Permit
Permit Type Description:	Gen-LAG83-Petroleum UST Rem
Program:	Water
Activity Number:	GEN20010001

REM:

AI Num:	13392
Evaluated And Closed:	11/19/2007
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 5970777.

---

8 **SPAIN STREET AT 19TH STREET** **US BROWNFIELDS** **1016350988**
SPAIN STREET AT 19TH STREET **FINDS** **N/A**
BATON ROUGE, LA 70806

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	SPAIN STREET AT 19TH STREET
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.444759
Longitude:	-91.168553
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14535
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	09/30/2003 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401

SPAIN STREET AT 19TH STREET (Continued) **1016350988**

Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Not reported
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported

SPAIN STREET AT 19TH STREET (Continued) **1016350988**

Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	836
% Below Poverty:	4.7%
# Low Income:	1708
% Low Income:	2.3%
Meidan Income:	2940
# Unemployed:	220
% Unemployed:	17.7%
# Vacant Housing:	280
% Vacant Housing:	13.9%

FINDS:

Registry ID: 110039529971

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

SPAIN STREET AT 19TH STREET (Continued) **1016350988**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

8 **LOTS 8 & 9 SQUARE 6 FUQUA & LEMON TOWN** **US BROWNFIELDS** **1016345272**
216 SOUTH 19TH STREET **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	LOTS 8 & 9 SQUARE 6 FUQUA & LEMON TOWN
Property #:	830341853 & 830341584
Parcel size:	.21
Property Description:	auto repair, bookstore
Latitude:	30.446472
Longitude:	-91.169372
HCM label:	Interpolation-Map
Map scale:	1:2400
Point of reference:	Entrance Point of a Facility or Station
Datum:	Not reported
ACRES property ID:	15137
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	1000
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	97646001
Ownership entity:	Private
Current owner:	Dr. S. J. Cefalu
Did owner change:	N
Cleanup required:	Unknown
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y

LOTS 8 & 9 SQUARE 6 FUQUA & LEMON TOWN (Continued) **1016345272**

Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Y
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Y
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Y
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	PCP
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported

LOTS 8 & 9 SQUARE 6 FUQUA & LEMON TOWN (Continued) **1016345272**

Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	767
% Below Poverty:	4.3%
# Low Income:	1585
% Low Income:	2.1%
Meidan Income:	2248
# Unemployed:	221
% Unemployed:	14.9%
# Vacant Housing:	249
% Vacant Housing:	13.2%

FINDS:

Registry ID: 110038693045

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

9 **OHM CORPORATION PORT ALLEN** **RCRA NonGen / NLR** **1000296608**
1090 CINCLARE DR **FINDS** **LAD982550816**
PORT ALLEN, LA 70767 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	03/21/1991
Facility name:	OHM CORPORATION PORT ALLEN
Facility address:	1090 CINCLARE DR PORT ALLEN, LA 70767
EPA ID:	LAD982550816
Mailing address:	CINCLARE DR PORT ALLEN, LA 70767
Contact:	CHARLES BEARDEN
Contact address:	1090 CINCLARE DR PORT ALLEN, LA 70767
Contact country:	US

OHM CORPORATION PORT ALLEN (Continued) **1000296608**

Contact telephone: (225) 389-9596
Contact email: Not reported
EPA Region: 06
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: OHM CORPORATION
Owner/operator address: 1090 CINCLAIR DR
PORT ALLEN, LA 70767
Owner/operator country: Not reported
Owner/operator telephone: (225) 389-9596
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110003310373

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000296608
Registry ID: 110003310373
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003310373

9 AIRGAS SPECIALTY GASES PORT ALLEN **RCRA-LQG** **1000176735**
1075 CINCLARE DRIVE **LAD094178050**
PORT ALLEN, LA 70767

RCRA-LQG:

Date form received by agency:	05/19/2016
Facility name:	AIRGAS SPECIALTY GASES PORT ALLEN
Facility address:	1075 CINCLARE DRIVE PORT ALLEN, LA 70767
EPA ID:	LAD094178050
Mailing address:	CINCLARE DRIVE PORT ALLEN, LA 70767
Contact:	RAUL MOLIERI
Contact address:	CINCLARE DRIVE PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 388-0900
Contact email:	RAUL.MOLIERI@AIRGAS.COM
EPA Region:	06
Land type:	Private
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	AIRGAS SPECIALTY GASES INC
Owner/operator address:	CINCLARE DRIVE PORT ALLEN, LA 70767
Owner/operator country:	US
Owner/operator telephone:	(225) 388-0900
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/01/2003
Owner/Op end date:	Not reported
Owner/operator name:	AIRGAS SPECIALTY GASES INC
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/01/2003
Owner/Op end date:	Not reported
Owner/operator name:	BOC GASES
Owner/operator address:	1075 CINCLARE DR PORT ALLEN, LA 70767
Owner/operator country:	Not reported

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

Owner/operator telephone: (225) 388-0900
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AIRCO INDUSTRIAL GASES
Owner/operator address: 575 MOUNTAIN AVENUE
UNKNOWN, NJ 00000
Owner/operator country: Not reported
Owner/operator telephone: (201) 464-8100
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: AIR CO INC-BOC
Owner/operator address: 1075 CINCLARE DR
PORT ALLEN, LA 70767
Owner/operator country: Not reported
Owner/operator telephone: (225) 388-0900
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

. Waste code: D008
. Waste name: LEAD

. Waste code: D011
. Waste name: SILVER

. Waste code: D021
. Waste name: CHLOROBENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D028
. Waste name: 1,2-DICHLOROETHANE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P003
. Waste name: 2-PROPENAL (OR) ACROLEIN

. Waste code: P022
. Waste name: CARBON DISULFIDE

. Waste code: P028
. Waste name: BENZENE, (CHLOROMETHYL)- (OR) BENZYL CHLORIDE

. Waste code: P056
. Waste name: FLUORINE

. Waste code: P096
. Waste name: HYDROGEN PHOSPHIDE (OR) PHOSPHINE

. Waste code: U001
. Waste name: ACETALDEHYDE (I) (OR) ETHANAL (I)

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U003
. Waste name: ACETONITRILE (I,T)

. Waste code: U009
. Waste name: 2-PROPENENITRILE (OR) ACRYLONITRILE

. Waste code: U031
. Waste name: 1-BUTANOL (I) (OR) N-BUTYL ALCOHOL (I)

. Waste code: U037
. Waste name: BENZENE, CHLORO- (OR) CHLOROBENZENE

. Waste code: U041
. Waste name: EPICHLOROHYDRIN (OR) OXIRANE, (CHLOROMETHYL)-

. Waste code: U055
. Waste name: BENZENE, (1-METHYLETHYL)- (I) (OR) CUMENE (I)

. Waste code: U056
. Waste name: BENZENE, HEXAHYDRO- (I) (OR) CYCLOHEXANE (I)

. Waste code: U057
. Waste name: CYCLOHEXANONE (I)

. Waste code: U070
. Waste name: BENZENE, 1,2-DICHLORO- (OR) O-DICHLOROBENZENE

. Waste code: U079
. Waste name: 1,2-DICHLOROETHYLENE (OR) ETHENE, 1,2-DICHLORO-,(E)-

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U124
. Waste name: FURAN (I) (OR) FURFURAN (I)

. Waste code: U135
. Waste name: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

. Waste code: U138
. Waste name: METHANE, IODO- (OR) METHYL IODIDE

. Waste code: U140
. Waste name: 1-PROPANOL, 2-METHYL- (I,T) (OR) ISOBUTYL ALCOHOL (I,T)

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U161
. Waste name: 4-METHYL-2-PENTANONE (I) (OR) METHYL ISOBUTYL KETONE (I) (OR) PENTANOL, 4-METHYL-

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

. Waste code: U171
. Waste name: 2-NITROPROPANE (I,T) (OR) PROPANE, 2-NITRO- (I,T)

. Waste code: U184
. Waste name: ETHANE, PENTACHLORO- (OR) PENTACHLOROETHANE

. Waste code: U208
. Waste name: 1,1,1,2-TETRACHLOROETHANE (OR) ETHANE, 1,1,1,2-TETRACHLORO-

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U211
. Waste name: CARBON TETRACHLORIDE (OR) METHANE, TETRACHLORO-

. Waste code: U213
. Waste name: FURAN, TETRAHYDRO-(I) (OR) TETRAHYDROFURAN (I)

. Waste code: U225
. Waste name: BROMOFORM (OR) METHANE, TRIBROMO-

. Waste code: U227
. Waste name: 1,1,2-TRICHLOROETHANE (OR) ETHANE, 1,1,2-TRICHLORO-

. Waste code: U228
. Waste name: ETHENE, TRICHLORO- (OR) TRICHLOROETHYLENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Historical Generators:
Date form received by agency: 02/16/2011
Site name: AIRGAS SPECIALTY GASES
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P076
. Waste name: NITRIC OXIDE (OR) NITROGEN OXIDE NO

. Waste code: U135
. Waste name: HYDROGEN SULFIDE (OR) HYDROGEN SULFIDE H2S

. Waste code: U153
. Waste name: METHANETHIOL (I,T) (OR) THIOMETHANOL (I,T)

Date form received by agency: 04/22/2010
Site name: AIRGAS SPECIALTY GASES
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U077
. Waste name: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

Date form received by agency: 10/12/2009
Site name: AIRGAS SPECIALTY GASES
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: U019
. Waste name: BENZENE (I,T)

. Waste code: U077
. Waste name: ETHANE, 1,2-DICHLORO- (OR) ETHYLENE DICHLORIDE

. Waste code: U220
. Waste name: BENZENE, METHYL- (OR) TOLUENE

. Waste code: U239
. Waste name: BENZENE, DIMETHYL- (I,T) (OR) XYLENE (I)

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

Date form received by agency: 04/09/2008
Site name: AIRGAS SPECIALTY GASES
Classification: Small Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Date form received by agency: 04/09/2008
Site name: AIRGAS SPECIALTY GASES
Classification: Small Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: P033
. Waste name: CYANOGEN CHLORIDE (OR) CYANOGEN CHLORIDE (CN)CL

Date form received by agency: 03/19/1991
Site name: BOC GASES MEMBER OF BOC GROUP
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P033
. Waste name: CYANOGEN CHLORIDE (OR) CYANOGEN CHLORIDE (CN)CL

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 10/06/2009
Date achieved compliance: 11/16/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/29/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 11/16/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 10/06/2009

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

Date achieved compliance: 11/16/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 10/29/2009
Enf. disposition status: Action Satisfied (Case Closed)
Enf. disp. status date: 11/16/2009
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1119
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 05/20/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1105
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 10/31/2003
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1117
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 05/20/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/04/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 01/19/1987
Date achieved compliance: 06/19/1987

AIRGAS SPECIALTY GASES PORT ALLEN (Continued) **1000176735**

Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/12/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 10/06/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 11/16/2009
Evaluation lead agency: State

Evaluation date: 10/06/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/16/2009
Evaluation lead agency: State

Evaluation date: 09/18/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 11/02/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 05/20/2000
Evaluation lead agency: State

Evaluation date: 11/02/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/31/2003
Evaluation lead agency: State

Evaluation date: 08/13/1987
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - General
Date achieved compliance: 06/19/1987
Evaluation lead agency: State

Evaluation date: 01/19/1987
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Generators - General
Date achieved compliance: 06/19/1987
Evaluation lead agency: State

9 AIRCO INDUSTRIAL GASES — **NY MANIFEST** — **S119069504**
1075 CINCLARE DR — **N/A**
PORT ALLEN, LA 70767

NY MANIFEST:

Country:	USA
EPA ID:	LAD094178050
Facility Status:	Not reported
Location Address 1:	1075 CINCLARE AVE
Code:	BP
Location Address 2:	Not reported
Total Tanks:	Not reported
Location City:	PORT ALLEN
Location State:	LA
Location Zip:	70767
Location Zip 4:	Not reported

NY MANIFEST:

EPAID:	LAD094178050
Mailing Name:	AIRCO INDUSTRIAL GASES
Mailing Contact:	JEFF GIAUQUE
Mailing Address 1:	1075 CINCLARE AVE
Mailing Address 2:	Not reported
Mailing City:	PORT ALEN
Mailing State:	LA
Mailing Zip:	70767
Mailing Zip 4:	Not reported
Mailing Country:	USA
Mailing Phone:	5083880400

NY MANIFEST:

Document ID:	NYB5440401
Manifest Status:	C
seq:	Not reported
Year:	1995
Trans1 State ID:	10210PNY
Trans2 State ID:	Not reported
Generator Ship Date:	01/17/1995
Trans1 Recv Date:	01/17/1995
Trans2 Recv Date:	/ /
TSD Site Recv Date:	01/26/1995
Part A Recv Date:	01/26/1995
Part B Recv Date:	02/07/1995
Generator EPA ID:	LAD094178050
Trans1 EPA ID:	NYD980769947
Trans2 EPA ID:	Not reported
TSDF ID 1:	NYD000632372
TSDF ID 2:	Not reported
Manifest Tracking Number:	Not reported
Import Indicator:	Not reported
Export Indicator:	Not reported
Discr Quantity Indicator:	Not reported
Discr Type Indicator:	Not reported
Discr Residue Indicator:	Not reported
Discr Partial Reject Indicator:	Not reported
Discr Full Reject Indicator:	Not reported
Manifest Ref Number:	Not reported
Alt Facility RCRA ID:	Not reported
Alt Facility Sign Date:	Not reported

AIRCO INDUSTRIAL GASES (Continued) **S119069504**

MGMT Method Type Code:	Not reported
Waste Code:	P033 - CYANOGEN CHLORIDE
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Waste Code:	Not reported
Quantity:	00045
Units:	P - Pounds
Number of Containers:	001
Container Type:	CY - Cylinders
Handling Method:	T Chemical, physical, or biological treatment.
Specific Gravity:	100

---

9 **THE MARTIN BROWER CO** **LA UST** **U001898369**
1585 COMMERCIAL DR **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	42412
Subject Item ID:	1
UST Tank Num:	40537
Tank Status:	**Removed**
Install Date:	05/01/1984
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	40538
Tank Status:	**Removed**
Install Date:	06/01/1987

THE MARTIN BROWER CO (Continued) **U001898369**

Total Capacity:	4500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

9 **ROLLINS LEASING CORP 503B** **RCRA NonGen / NLR** **1004714701**
1585 COMMERCIAL DR **FINDS** **LAR000037515**
PORT ALLEN, LA 70767 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	12/30/2003
Facility name:	ROLLINS LEASING CORP 503B
Facility address:	1585 COMMERCIAL DR PORT ALLEN, LA 70767
EPA ID:	LAR000037515
Mailing address:	PO BOX 1791 WILMINGTON, DE 19899
Contact:	RALPH GRANT
Contact address:	PO BOX 1791 WILMINGTON, DE 19899
Contact country:	US
Contact telephone:	(302) 426-2899
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ROLLINS LEASING CORP
Owner/operator address:	PO BOX 1791 WILMINGTON, DE 19899
Owner/operator country:	Not reported
Owner/operator telephone:	(302) 426-2899

ROLLINS LEASING CORP 503B (Continued) **1004714701**

Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Historical Generators:
Date form received by agency: 12/05/2001
Site name: ROLLINS LEASING CORP 503B
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Date form received by agency: 02/18/2000
Site name: ROLLINS LEASING CORP 503B
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/27/2004
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported

ROLLINS LEASING CORP 503B (Continued) **1004714701**

Evaluation lead agency: State

FINDS:

Registry ID: 110003366269

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004714701
Registry ID: 110003366269
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003366269

---

9 CAJUN VALVE SERVICES LLC **RCRA-SQG** **1014923695**
1605 COMMERCIAL DR **LAR000074781**
PORT ALLEN, LA 70767

RCRA-SQG:
Date form received by agency: 02/06/2014
Facility name: CAJUN VALVE SERVICES LLC
Facility address: 1605 COMMERCIAL DR
PORT ALLEN, LA 70767
EPA ID: LAR000074781
Mailing address: COMMERCIAL DR
PORT ALLEN, LA 70767
Contact: ROBERT V HASSELBECK
Contact address: COMMERCIAL DR
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 706-6000
Contact email: Not reported
EPA Region: 06
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: TFT
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner

CAJUN VALVE SERVICES LLC (Continued) **1014923695**

Owner/Op start date: 10/31/2000
Owner/Op end date: Not reported

Owner/operator name: CAJUN VALVE SERVICES
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/31/2000
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

Historical Generators:
Date form received by agency: 12/12/2011
Site name: CAJUN VALVE SERVICES LLC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

Violation Status: No violations found

9 MCCARTY CORP — **LA HIST LUST** — **U001898264**
1405 COMMERCIAL DR — **LA UST** — **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-013766	
Facility Parish:	WEST BATON ROUGE	
Substance Name:	UNKNOWN	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	07/17/1992	
Date Confirmed 2:	Not reported	
Incident Number:	92-2-0162	
Incident Date:	07/17/1992	
Type of Incident:		UST LEAK
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00586100	
Owner Name:	MCCARTY CORPORATION	
Owner Address:	1405 COMMERCIAL DRIVE	
Owner City,St,Zip:	PORT ALLEN, LA 70767	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		Not reported
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		Not reported
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		12/29/1998
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:

Comments: DEQ INSPECTION 7/17/92 WAS MADE DUE TO THE REMOVAL OF ONE 2000 GLUST. THE TANK WAS WASHED AND DEGASED. NATIONAL WASTE OIL WAS ONSITE DRAININGTHE RESUIDUALS OUT OF THE UST. THE TANK HAD PERFORATIONSWHICH POSSIBLY CAUSED THE RELEASE. THE TANK HAD BEEN OUT OF OPERATIONFOR APPROX. 7 YEARS. THE CONTAMINATED SOILS WERE PLACED ONVISQUEEN TO AERATE. DEQ LETTER 2/10/93 REQUEST A SKETCH OF THE SITEDEPICTING UST AND SAMPLING LOCATIONS BEFORE FURTHER PROCESSING CLOSUREREQUEST.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

MCCARTY CORP (Continued) **U001898264**

Facility ID:	61-013766	
Facility Parish:	WEST BATON ROUGE	
Substance Name:	Not reported	
Substance Name 2:	Not reported	
Quantity:	Not reported	
Quantity 2:	Not reported	
Date Confirmed:	Not reported	
Date Confirmed 2:	Not reported	
Incident Number:	92-2-0162	
Incident Date:	07/17/1992	
Type of Incident:		Not reported
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00586100	
Owner Name:	MCCARTY CORPORATION	
Owner Address:	1405 COMMERCIAL DRIVE	
Owner City,St,Zip:	PORT ALLEN, LA 70767	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		Not reported
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		Not reported
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		12/29/1998
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:

Comments: DEQ INSPECTION 7/17/92 WAS MADE DUE TO THE REMOVAL OF ONE 2000 GLUST. THE TANK WAS WASHED AND DEGASED. NATIONAL WASTE OIL WAS ONSITE DRAININGTHE RESUIDUALS OUT OF THE UST. THE TANK HAD PERFORATIONSWHICH POSSIBLY CAUSED THE RELEASE. THE TANK HAD BEEN OUT OF OPERATIONFOR APPROX. 7 YEARS. THE CONTAMINATED SOILS WERE PLACED ONVISQUEEN TO AERATE. DEQ LETTER 2/10/93 REQUEST A SKETCH OF THE SITEDEPICTING UST AND SAMPLING LOCATIONS BEFORE FURTHER PROCESSING CLOSUREREQUEST.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

UST:

Master Agency Id: 76794

MCCARTY CORP (Continued) **U001898264**

Subject Item ID:	1
UST Tank Num:	39902
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

9 **LUNDIN ROOFING CO INC** **RCRA-CESQG** **1004714838**
1301 COMMERCIAL DR **FINDS** **LAR000041632**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:

Date form received by agency:	06/12/2000
Facility name:	LUNDIN ROOFING CO INC
Facility address:	1301 COMMERCIAL DR PORT ALLEN, LA 707673227
EPA ID:	LAR000041632
Mailing address:	COMMERCIAL DR PORT ALLEN, LA 707673227
Contact:	ED LUNDIN
Contact address:	1301 COMMERCIAL DR PORT ALLEN, LA 707673227
Contact country:	US
Contact telephone:	(225) 343-7663
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

LUNDIN ROOFING CO INC (Continued) **1004714838**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	LUNDIN ROOFING CO INC
Owner/operator address:	1301 COMMERCIAL DR PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 343-7663
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

LUNDIN ROOFING CO INC (Continued) **1004714838**

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110003367650

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004714838
Registry ID: 110003367650
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003367650

---

9 SOUTHWEST STAINLESS LP ,HG 9060 **RCRA-CESQG** **1010318523**
1510 COMMERCIAL DR **LAR000063420**
PORT ALLEN, LA 70767

RCRA-CESQG:
Date form received by agency: 07/31/2008
Facility name: SOUTHWEST STAINLESS LP ,HG 9060
Facility address: 1510 COMMERCIAL DR
PORT ALLEN, LA 70767
EPA ID: LAR000063420
Mailing address: CUMBERLAND BLVD, STE 1700
ATLANTA, GA 30339
Contact: MARK LAUBACH
Contact address: CUMBERLAND BLVD, STE 1700
ATLANTA, GA 30339
Contact country: US
Contact telephone: (407) 822-2822
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

SOUTHWEST STAINLESS LP ,HG 9060 (Continued) **1010318523**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SOUTHWEST STAINLESS LP
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	08/31/2007
Owner/Op end date:	Not reported

Owner/operator name:	SOUTHWEST STAINLESS LP
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	08/31/2007
Owner/Op end date:	Not reported

Owner/operator name:	HOME DEPOT USA INC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/30/2006
Owner/Op end date:	Not reported

Owner/operator name:	HOME DEPOT USA INC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/30/2006
Owner/Op end date:	Not reported

Owner/operator name:	SOUTHWEST STAINLESS
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner

SOUTHWEST STAINLESS LP ,HG 9060 (Continued) **1010318523**

Owner/Op start date: 05/01/2006
Owner/Op end date: Not reported

Owner/operator name: SOUTHWEST STAINLESS
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/01/2006
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Historical Generators:
Date form received by agency: 10/01/2007
Site name: SOUTHWEST STAINLESS LP ,HG 9060
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

SOUTHWEST STAINLESS LP ,HG 9060 (Continued) **1010318523**

. Waste code: D009
. Waste name: MERCURY

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Date form received by agency: 11/17/2006
Site name: HUGHES SUPPLY #HDHG 9060
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

---

9 **MALLINCKRODT MANF LLC** **RCRA-CESQG** **1004714431**
1060 ALLENDALE DR **FINDS** **LAR000032318**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:
Date form received by agency: 03/03/2016
Facility name: MALLINCKRODT MANF LLC
Facility address: 1060 ALLENDALE DR
PORT ALLEN, LA 70767
EPA ID: LAR000032318
Mailing address: ALLENDALE DR
PORT ALLEN, LA 70767
Contact: ANDEANA PRUITT
Contact address: ALLENDALE DR
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 376-4414
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely

MALLINCKRODT MANF LLC (Continued) **1004714431**

hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MALLINCKRODT MANF
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/19/2016
Owner/Op end date:	Not reported

Owner/operator name:	MALLINCKRODT MANF
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/19/2016
Owner/Op end date:	Not reported

Owner/operator name:	JOE D AGNOSTINO
Owner/operator address:	6055 ROCKSIDE WOODS BLVD
	INDEPENDENCE, OH 44131
Owner/operator country:	Not reported
Owner/operator telephone:	(216) 642-6695
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

MALLINCKRODT MANF LLC (Continued) **1004714431**

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

Historical Generators:
Date form received by agency: 09/30/1998
Site name: INO THERAPEUTICS
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D003
. Waste name: REACTIVE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110003363351

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004714431
Registry ID: 110003363351
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003363351

---

9 **BOWMAN TRANSPORTATION CO INC** **RCRA NonGen / NLR** **1000295424**
770 ALLENDALE DR **FINDS** **LAD125787085**
PORT ALLEN, LA 70767 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 10/24/1986
Facility name: BOWMAN TRANSPORTATION CO INC
Facility address: 770 ALLENDALE DR
PORT ALLEN, LA 70767
EPA ID: LAD125787085
Mailing address: ALLENDALE DR

BOWMAN TRANSPORTATION CO INC (Continued) **1000295424**

PORT ALLEN, LA 70767
Contact: WM ROBERTSON
Contact address: 770 ALLENDALE DR
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 344-4713
Contact email: Not reported
EPA Region: 06
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: BOWMAN TRANSP INC
Owner/operator address: UNKNOWN
UNKNOWN, LA 00000
Owner/operator country: Not reported
Owner/operator telephone: (000) 000-0000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE,

BOWMAN TRANSPORTATION CO INC (Continued) **1000295424**

ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110003284115

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1000295424
Registry ID: 110003284115
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003284115

9 BOWMAN TRANSPORTATION INC — **LA HIST LUST** — **S106033542**
770 ALLENDALE DR — **LA SPILLS** — **N/A**
PORT ALLEN, LA 70764

HIST LUST:

Facility ID:	61-000945
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	12/07/1989
Date Confirmed 2:	Not reported
Incident Number:	89-2-0070
Incident Date:	12/07/1989
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	CAROL MCGRIFF/BOWMAN
Reported By 2:	Not reported
Owner ID:	00039400
Owner Name:	BOWMAN TRANSPORTATION INC
Owner Address:	P.O.BOX 17744
Owner City,St,Zip:	ATLANTA, GA 30316
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	WESTINGHOUSE ENVRNTL& GEOTECH SRVCS INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	07/31/1991
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ LETTER 12/12/93 REQUEST QTLY REPORTS AND DENIES REQUEST OFTERMINATION OF REMEDIATION BY CONSULTATNT. DIESEL SEEPED INTO CANAL.3 USTS WERE CLOSED AND REMOVED 6/24/91. WESTINGHOUSE NO LONGER ISCONSULTANT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	61-000945
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported

BOWMAN TRANSPORTATION INC (Continued) **S106033542**

Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	89-2-0070
Incident Date:	12/07/1989
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00039400
Owner Name:	BOWMAN TRANSPORTATION INC
Owner Address:	P.O.BOX 17744
Owner City,St,Zip:	ATLANTA, GA 30316
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	WESTINGHOUSE ENVRNTL& GEOTECH SRVCS INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	07/31/1991
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ LETTER 12/12/93 REQUEST QTLY REPORTS AND DENIES REQUEST OFTERMINATION OF REMEDIATION BY CONSULTATNT. DIESEL SEEPED INTO CANAL.3 USTS WERE CLOSED AND REMOVED 6/24/91. WESTINGHOUSE NO LONGER ISCONSULTANT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

SPILLS:

Region Code:	CR
Date Rec:	01/14/2010
Date Initiated:	01/14/2010
aiid:	168715
Incident Id:	120774
Incident Date:	01/14/2010
Incident Status:	**Open**
Media Desc:	Water/Soil
Location Description:	Werner Enterprises 770 Allendale Dr Port Allen

BOWMAN TRANSPORTATION INC (Continued) **S106033542**

Incident Source Name:	Werner Enterprises Inc - Drop Yard
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Release/Spill, Highway Transport
Comments:	Werner Enterprises Inc. January 14, 2010 Tempo# 120774 On January 14, 2010 at approximately 1230 hours, Louisiana Department of Environmental Quality Emergency Responder (LDEQ-ER) Bryan Riche responded to 770 Allendale Drive in Port Allen concerning a diesel fuel spill. According to Mr. Gary Weiss of American Compliance Technologies, a Werner Enterprises Inc. tractor-trailer was parked in the drop yard when an employee noticed a leak from the left side saddle tank. Approximately forty gallons of diesel fuel impacted the concrete pavement and entered a nearby catch basin. Oil Mop responded to cleanup the spilled diesel. Free phase liquid diesel fuel was removed and booms will be placed in two catch basins and at the outfall for further removal. No road closures, fires or injuries were reported as a result of this incident. Further action by LDEQ-ER pending results of investigation. BPR.
Parameter:	Diesel
Quantity:	0 0
Other Substance Desc:	0

---

9 **CONSOLIDATED FREIGHTWAYS** **LA UST** **U003921825**
770 ALLENDALE DR **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	18131
Subject Item ID:	1
UST Tank Num:	3204
Tank Status:	**Removed**
Install Date:	04/09/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported

CONSOLIDATED FREIGHTWAYS (Continued) **U003921825**

Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	3205
Tank Status:	**Removed**
Install Date:	04/09/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	3206
Tank Status:	**Removed**
Install Date:	04/09/1980
Total Capacity:	5000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported

CONSOLIDATED FREIGHTWAYS (Continued) **U003921825**

Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

10 **GUARANTY INCOME LIFE** **LA UST** **U001965595**
2373 S WESTPORT **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	77754
Subject Item ID:	1
UST Tank Num:	42685
Tank Status:	**Closed**
Install Date:	01/01/1982
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

10 **LA SCRAP METAL RECYCLING FACILITY - THE LEMOINE CO** **LA NPDES** **S111085423**
S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

NPDES:

Facility Id:	175591
Facility Phone:	2253033710x2224
Issued Date:	05/11/2011
Title Description:	Gen Const. Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20110001

---

10 **LOUISIANA SCRAP METAL** **LA SPILLS** **S108629983**
HWY 190 AND LA 1 **N/A**
PORT ALLEN, LA

SPILLS:

Region Code:	Not reported
Date Rec:	03/22/2007
Date Initiated:	Not reported
aiid:	34031
Incident Id:	94804
Incident Date:	03/22/2007
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Louisiana Scrap Metal Hwy 190 and LA 1 Port Allen
Incident Source Name:	Louisiana Scrap Metal Recycling
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c07-0915 When it rains mud is all over the highway causing hazardous conditions, scrap metal is above containment wall....jd
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

10 **LOUISIANA SCRAP METAL RECYCLING** **LA NPDES** **S111768535**
2527 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

NPDES:

Facility Id:	180689
Facility Phone:	Not reported
Issued Date:	09/06/2016
Title Description:	MSGP Renewed Coverage
Permit Type Description:	Not reported
Program:	Water
Activity Number:	GEN20160001

Facility Id:	180689
Facility Phone:	Not reported
Issued Date:	03/23/2012
Title Description:	Gen MSGP Permit

LOUISIANA SCRAP METAL RECYCLING (Continued) **S111768535**

Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20120001

---

10 **LOUISIANA SCRAP METAL RECYCLING FACILITY** **FINDS** **1015887083**
2527 S. WESTPORT DR. **ECHO** **N/A**
PORT ALLEN, LA 70767

FINDS:

Registry ID: 110045504398

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1015887083
Registry ID: 110045504398
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110045504398

---

11 **TSD REMEDIAL SERVICES 1780 COMMERCIAL** **TX Ind. Haz Waste** **S106523233**
1780 COMMERCIAL DR **N/A**
PORT ALLEN, LA 70767

Ind. Haz Waste:
Registration Number: 41331
Registration Initial Notification Date: 01/12/1989
Registration Last Amendment Date: 07/26/2001
EPA Identification: LAD982559585
Primary NAICS Code: 484121
Status Change Date: 19890112
Land Type: Not reported
Description of Facility Site Location: Not reported
Site Primary Standard Industrial Code: Not reported
Site Primary SIC Description: Not reported
Registration is Generator of Waste: No
Registration is Receivers of Waste: No
Registration is Transporter of Waste: Yes
Registration is Transfer Facility: No
Facility is STEERS Reporter: No
Reqired to Submit Annual Waste Summary: No
Facility Involved In Recycling: No
Revcr Has Monthly Reporting Requirement: 0
Mexican Facility: Not reported
Type of Generator: Not reported

TSD REMEDIAL SERVICES 1780 COMMERCIAL (Continued) **S106523233**

TNRCC Region:	Not reported
Company Name:	TSD REMEDIAL SERVICES CORPORATION
Contact Name:	LYNETTE HART
Contact Telephone Number:	504-3440034
Mailing Address:	1780 COMMERCIAL DR
Mailing Address2:	Not reported
Mailing City,St,Zip:	PORT ALLEN, LA 707676103
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	17722
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20040109
Ind. waste permit Number:	Not reported
Mun waste permit Number:	Not reported
Non Notifier:	No

Business Records Not Found for this RegNo/Year:

Owner:

Owner Mailing Address:	1780 COMMERCIAL DR
Owner Mailing Address2:	Not reported
Owner Mailing Address3:	Not reported
Owner City,St,Zip:	PORT ALLEN, LA 70767 6103
Owner Country:	UNITED STA
Owner Phone Number:	1-504-3440034
Owner Fax Number:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Corporation
Owner Tax Id:	Not reported
Owner Bankruptcy Code:	Not reported

Operator:

Operator Last Name:	TSD REMEDIAL SERVICES CORP
Operator First Name:	Not reported
Operator Name:	TSD REMEDIAL SERVICES CORP
Operator Mailing Address:	1780 COMMERCIAL DR
Operator Mailing Address 2:	Not reported
Operator Mailing City,St,Zip:	PORT ALLEN, LA 70767 6103
Operator Country:	UNITED STA
Operator Phone:	1-504-3440034
Operator Fax:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax Id:	Not reported
Operator Bankruptcy Code:	Not reported

Contact:

Contact Name:	LYNETTE HART
Contact Title:	ENV MGR
Contact Role:	PRICONT
Contact Address:	1780 COMMERCIAL DR
Contact Address2:	Not reported
Conact City,St,Zip:	PORT ALLEN, LA 70767 6103
Contact Phone:	1-504-3440034
Contact Fax:	Not reported
Contact Email:	Not reported

TSD REMEDIAL SERVICES 1780 COMMERCIAL (Continued) **S106523233**

Contact:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	1780 COMMERCIAL DR
Contact Address2:	Not reported
Conact City,St,Zip:	PORT ALLEN, LA 70767 6103
Contact Phone:	1-504-3440034
Contact Fax:	Not reported
Contact Email:	Not reported

Contact:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1780 COMMERCIAL DR
Contact Address2:	Not reported
Conact City,St,Zip:	PORT ALLEN, LA 70767 6103
Contact Phone:	1-504-3440034
Contact Fax:	Not reported
Contact Email:	Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:

Receiver Type:	Not reported
Transporter for hire:	1
Transport own waste:	0
Eq 01, if transport waste type = 1:	Not reported
Eq 02, if transport waste type = 2:	Not reported
Eq 03, if transport waste type = 3:	Not reported
Eq 04, if transport waste type = H:	04
Target TCEQ unique facid for discarded(merged) facility:	Not reported

Waste Records Not Found for this RegNo/Year:

---

11 TSD REMEDIAL SVC CORP **RCRA NonGen / NLR** **1000129727**
1780 COMMERCIAL DR **FINDS** **LAD982559585**
PORT ALLEN, LA 70767 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	04/13/2010
Facility name:	TSD REMEDIAL SVC CORP
Facility address:	1780 COMMERCIAL DR PORT ALLEN, LA 70767
EPA ID:	LAD982559585
Mailing address:	PO BOX 348 PORT ALLEN, LA 70767
Contact:	RAYMON WHITE
Contact address:	PO BOX 348 PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 344-0034
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

TSD REMEDIAL SVC CORP (Continued) **1000129727**

Owner/Operator Summary:

Owner/operator name:	JTS MANAGEMENT CORP
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	JTS MANAGEMENT CORP
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	US
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	04/13/2010
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Universal Waste Summary:

Waste type:	Batteries
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported

Waste type:	Lamps
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported

Waste type:	Pesticides
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported

Waste type:	Thermostats
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported

TSD REMEDIAL SVC CORP (Continued) **1000129727**

Historical Generators:
Date form received by agency: 11/02/1988
Site name: TSD REMEDIAL SVC CORP
Classification: Not a generator, verified

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/13/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003311416

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000129727
Registry ID: 110003311416
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003311416

---

12 GROENDYKE TRANSPORT INC **RCRA NonGen / NLR** **1000426371**
2723 S WESTPORT DR **FINDS** **LAD108187279**
PORT ALLEN, LA 70767 **US AIRS**
ECHO

RCRA NonGen / NLR:
Date form received by agency: 03/05/2013
Facility name: GROENDYKE TRANSPORT, INC.
Facility address: 2723 SOUTH WESTPORT DRIVE
PORT ALLEN, LA 70767
EPA ID: LAD108187279
Mailing address: SOUTH WESTPORT DRIVE
PORT ALLEN, LA 70767
Contact: PAT WOODS
Contact address: SOUTH WESTPORT DRIVE
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 338-1191
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	GROENDYKE TRANSPORT, INC.
Owner/operator address:	2510 ROCK ISLAND BLVD ENID, OK 73701
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	11/01/1989
Owner/Op end date:	Not reported

Owner/operator name:	GROENDYKE TRANSPORT, INC.
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	11/01/1989
Owner/Op end date:	Not reported

Owner/operator name:	FRED HUGHES
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/19/2000
Owner/Op end date:	Not reported

Owner/operator name:	GROENDYKE TRANSPORT, INC.
Owner/operator address:	ROCK ISLAND BLVD ENID, OK 73701
Owner/operator country:	Not reported
Owner/operator telephone:	(580) 234-4663
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/19/2000
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Historical Generators:
Date form received by agency: 08/13/2012
Site name: GROENDYKE TRANSPORT, INC.
Classification: Large Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 02/29/2012
Site name: GROENDYKE TRANSPORT, INC.
Classification: Large Quantity Generator

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 04/16/2010
Site name: GROENDYKE TRANSPORT, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Date form received by agency: 10/21/2009
Site name: GROENDYKE TRANSPORT
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Date form received by agency: 02/27/2008
Site name: GROENDYKE TRANSPORT
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

GROENDYKE TRANSPORT INC (Continued) **1000426371**

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 02/23/2006
Site name: GROENDYKE TRANSPORT, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 02/13/2006
Site name: GROENDYKE TRANSPORT, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Date form received by agency: 02/20/2004
Site name: GROENDYKE TRANSPORT, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

GROENDYKE TRANSPORT INC (Continued) **1000426371**

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Date form received by agency: 02/28/2002
Site name: GROENDYKE TRANSPORT INC.
Classification: Large Quantity Generator

Date form received by agency: 01/24/2000
Site name: GROENDYKE TRANSPORTS, INC.
Classification: Large Quantity Generator

Date form received by agency: 01/14/1998
Site name: GROENDYKE TRANSPORT
Classification: Large Quantity Generator

Date form received by agency: 03/22/1991
Site name: GROENDYKE TRANSPORT INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Biennial Reports:

Last Biennial Reporting Year: 2013

Annual Waste Handled:
Waste code: D039
Waste name: TETRACHLOROETHYLENE
Amount (Lbs): 25164

Waste code: D040
Waste name: TRICHLOROETHYLENE
Amount (Lbs): 87830.7

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - Manifest
Date violation determined: 08/17/2012
Date achieved compliance: 03/22/2013
Violation lead agency: EPA
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 03/11/2013
Enf. disposition status: Action Satisfied (Case Closed)

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Enf. disp. status date: 03/22/2013
Enforcement lead agency: EPA
Proposed penalty amount: Not reported
Final penalty amount: 30000
Paid penalty amount: 30000

Regulation violated: Not reported
Area of violation: Generators - Pre-transport
Date violation determined: 06/30/2009
Date achieved compliance: 12/16/2009
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/30/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Universal Waste - Small Quantity Handlers
Date violation determined: 06/30/2009
Date achieved compliance: 12/16/2009
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/30/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: State Statute or Regulation
Date violation determined: 06/30/2009
Date achieved compliance: 12/16/2009
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 09/30/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1103.B.1
Area of violation: Generators - General
Date violation determined: 02/01/2006
Date achieved compliance: 03/16/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1109.E.1.a.ii
Area of violation: Generators - General
Date violation determined: 02/01/2006
Date achieved compliance: 03/16/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1119.A
Area of violation: Generators - Records/Reporting
Date violation determined: 02/01/2006
Date achieved compliance: 03/16/2006
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 03/16/2006
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1905.H
Area of violation: Generators - Pre-transport
Date violation determined: 04/18/1996
Date achieved compliance: 08/30/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1111.A.1
Area of violation: Generators - Manifest
Date violation determined: 02/21/1996
Date achieved compliance: 02/28/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2245.H
Area of violation: LDR - General
Date violation determined: 02/21/1996
Date achieved compliance: 02/28/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1117
Area of violation: Generators - General
Date violation determined: 02/21/1996
Date achieved compliance: 08/30/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1119
Area of violation: Generators - General
Date violation determined: 02/21/1996
Date achieved compliance: 08/30/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1105.B
Area of violation: Generators - General
Date violation determined: 02/21/1996
Date achieved compliance: 02/28/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1109.E
Area of violation: Generators - General
Date violation determined: 02/21/1996
Date achieved compliance: 08/30/1996
Violation lead agency: State
Enforcement action: INITIAL 3008(A) COMPLIANCE
Enforcement action date: 05/09/1996
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 03/05/2013
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/27/2013
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 08/17/2012
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Generators - Manifest
Date achieved compliance: 03/22/2013
Evaluation lead agency: EPA

Evaluation date: 06/30/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 12/16/2009
Evaluation lead agency: State

Evaluation date: 06/30/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Universal Waste - Small Quantity Handlers
Date achieved compliance: 12/16/2009
Evaluation lead agency: State

Evaluation date: 06/30/2009
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: State Statute or Regulation
Date achieved compliance: 12/16/2009
Evaluation lead agency: State

Evaluation date: 02/01/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Date achieved compliance: 03/16/2006
Evaluation lead agency: State

Evaluation date: 02/01/2006
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Records/Reporting
Date achieved compliance: 03/16/2006
Evaluation lead agency: State

Evaluation date: 08/30/1996
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - Manifest
Date achieved compliance: 02/28/1996
Evaluation lead agency: State

Evaluation date: 08/30/1996
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/30/1996
Evaluation lead agency: State

Evaluation date: 08/30/1996
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: LDR - General
Date achieved compliance: 02/28/1996
Evaluation lead agency: State

Evaluation date: 08/30/1996
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - General
Date achieved compliance: 08/30/1996
Evaluation lead agency: State

Evaluation date: 08/30/1996
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - General
Date achieved compliance: 02/28/1996
Evaluation lead agency: State

Evaluation date: 02/21/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: LDR - General
Date achieved compliance: 02/28/1996
Evaluation lead agency: State

Evaluation date: 02/21/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/30/1996
Evaluation lead agency: State

Evaluation date: 02/21/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 02/28/1996
Evaluation lead agency: State

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Evaluation date: 02/21/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 08/30/1996
Evaluation lead agency: State

Evaluation date: 02/21/1996
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Manifest
Date achieved compliance: 02/28/1996
Evaluation lead agency: State

FINDS:

Registry ID: 110000899868

Environmental Interest/Information System
AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

Louisiana Tools for Environmental Management and Protection Organizations (LA-TEMPO) is an Integrated Management System.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

HAZARDOUS WASTE BIENNIAL REPORTER

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

US AIRS MINOR:
Envid: 1000426371
Region Code: 06
Programmatic ID: AIR LA0000002212100050
Facility Registry ID: 110000899868
D and B Number: Not reported
Primary SIC Code: 4742
NAICS Code: 484121
Default Air Classification Code: MIN
Facility Type of Ownership Code: POF

GROENDYKE TRANSPORT INC (Continued) **1000426371**

Air CMS Category Code: Not reported
HPV Status: Not reported

ECHO:
Envid: 1000426371
Registry ID: 110000899868
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110000899868

---

12 **CAJUN KENWORTH INC** **EDR Hist Auto** **1021127738**
2723 S WEST PORT DR **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1987	CAJUN KENWORTH INC	New And Used Car Dealers

---

13 **UNITED PARCEL SERVICE INC (UPS)** **LA REM** **S118246607**
1111 COMMERCIAL DR **N/A**
PORT ALLEN, LA 70767

REM:
AI Num: 43711
Evaluated And Closed: 10/05/2001
Program: UST
EAC Type: No Further Interest
Comments: EDMS ID 7551025. No release occurred

---

13 **UNITED PARCEL SERVICE INC (UPS)** **LA UST** **U003922764**
1111 COMMERCIAL DR **LA NPDES** **N/A**
PORT ALLEN, LA 70767

UST:
Master Agency Id: 43711
Subject Item ID: 2

UST Tank Num: 28725
Tank Status: **Active**
Install Date: 03/31/1985
Total Capacity: 10000
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Yes
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported

UNITED PARCEL SERVICE INC (UPS) (Continued) **U003922764**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	28726
Tank Status:	**Removed**
Install Date:	03/31/1984
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

NPDES:

Facility Id:	43711
Facility Phone:	Not reported
Issued Date:	06/19/2001
Title Description:	Fiscal Migration: LAR05M565
Permit Type Description:	Gen-LAR05-Multi-Sector
Program:	Water
Activity Number:	GEN19980001

13 UNITED PARCEL SVC — **RCRA-CESQG, FINDS, ECHO** — **1000399156, LAD981521750**
1111 COMERICAL DR
PORT ALLEN, LA 70767

RCRA-CESQG:

Date form received by agency:	07/18/1986
Facility name:	UNITED PARCEL SVC
Facility address:	1111 COMERICAL DR PORT ALLEN, LA 70767
EPA ID:	LAD981521750
Mailing address:	MORRISON RD NEW ORLEANS, LA 70126
Contact:	SID JACKSON
Contact address:	MORRISON RD NEW ORLEANS, LA 70126
Contact country:	US
Contact telephone:	(504) 244-4718
Contact email:	Not reported
EPA Region:	06
Land type:	Other land type
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNITED PARCEL SERVICE
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

UNITED PARCEL SVC (Continued) **1000399156**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/01/1987
Date achieved compliance: 09/14/1988
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 11/12/1987
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/14/1988
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 10/01/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/14/1988
Evaluation lead agency: State

FINDS:

Registry ID: 110003293560

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

UNITED PARCEL SVC (Continued) **1000399156**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000399156
Registry ID:	110003293560
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003293560

---

13 UNITED PARCEL SERVICE INC (UPS) **LA HIST LUST** **S106034038**
1111 COMMERCIAL DR **LA NPDES** **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-010798	
Facility Parish:	WEST BATON ROUGE	
Substance Name:	UNKNOWN	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	09/19/1991	
Date Confirmed 2:	Not reported	
Incident Number:	91-2-0316	
Incident Date:	09/19/1991	
Type of Incident:		UST LEAK
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00373600	
Owner Name:	UNITED PARCEL SERVICE	
Owner Address:	151 BROOK HOLLOW ROAD	
Owner City,St,Zip:	HARAHAN, LA 70123	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		Not reported
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		HUGHES ENVIROMENTAL CONSULTANT
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		Not reported
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:

Comments: DEQ INSPECTION 5/21/94 TO OBSERVE USTS REMOVAL. CLOSURE OF USTS WEREGRANTED ON 9/25/91.

UNITED PARCEL SERVICE INC (UPS) (Continued) **S106034038**

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	61-010798
Facility Parish:	WEST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0316
Incident Date:	09/19/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00373600
Owner Name:	UNITED PARCEL SERVICE
Owner Address:	151 BROOK HOLLOW ROAD
Owner City,St,Zip:	HARAHAN, LA 70123
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	HUGHES ENVIROMENTAL CONSULTANT
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: DEQ INSPECTION 5/21/94 TO OBSERVE USTS REMOVAL. CLOSURE OF USTS WEREGRANTED ON 9/25/91.

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

NPDES:

UNITED PARCEL SERVICE INC (UPS) (Continued) **S106034038**

Facility Id: 43711
Facility Phone: Not reported
Issued Date: 05/24/2006
Title Description: LAR05M565 Reauthorization
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20060001

Facility Id: 43711
Facility Phone: Not reported
Issued Date: 06/03/2011
Title Description: MSGP Renewed Coverage
Permit Type Description: Gen-LAR05-Multi-Sector
Program: Water
Activity Number: GEN20110001

Facility Id: 43711
Facility Phone: Not reported
Issued Date: 09/06/2016
Title Description: MSGP Renewed Coverage
Permit Type Description: Not reported
Program: Water
Activity Number: GEN20160001

---

14 **BATTERY CLINIC THE** **EDR Hist Auto** **1022221230**
970 GOVERNMENT ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1987	BATTERY CLINIC THE	Auto And Home Supply Stores
1988	BATTERY CLINIC THE	Auto And Home Supply Stores

---

14 **BATTERY CLINIC** **LA SWRCY** **S105571224**
970 GOVERNMENT STREET **N/A**
BATON ROUGE, LA 70802

LA SWRCY:
Mailing Address: Not reported
Parish: East Baton Rouge
Contact: Mark Newstrom
Contact Phone: 225-381-9295
Contact Fax: 225-381-7255
Contact Email: Not reported
Material Accepted: Lead

Mailing Address: Not reported
Parish: East Baton Rouge
Contact: Mark Newstrom
Contact Phone: 225-381-9295
Contact Fax: 225-381-7255
Contact Email: Not reported
Material Accepted: Aluminum

Mailing Address: Not reported

BATTERY CLINIC (Continued) **S105571224**

Parish:	East Baton Rouge
Contact:	Mark Newstrom
Contact Phone:	225-381-9295
Contact Fax:	225-381-7255
Contact Email:	Not reported
Material Accepted:	Batteries

Mailing Address:	Not reported
Parish:	East Baton Rouge
Contact:	Mark Newstrom
Contact Phone:	225-381-9295
Contact Fax:	225-381-7255
Contact Email:	Not reported
Material Accepted:	Copper

---

14 **DONS AUTO CLINIC** **EDR Hist Auto** **1013770531**
800 GOVERNMENT ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1971	DONS AUTO CLINIC	General Automotive Repair Shops
1972	DONS AUTO CLINIC	General Automotive Repair Shops
1975	SIDS AUTO SERVICE	AUTOMOBILE REPAIRING

---

14 **STEWARTS SHELL SERV** **EDR Hist Auto** **1013772652**
962 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1940	HOCHENEDEL FRED G JR FILLING	GASOLINE AND OIL SERVICE STATIONS
1945	HERBERTS SERVICE STATION FILLIN	GASOLINE AND OIL SERVICE STATIONS
1950	SIMMINONS BROS SERV STA	GASOLINE STATIONS
1955	STEWARTS SHELL SERV	GASOLINE SERVICE STATIONS
1960	PHILS SHELL SERV	GASOLINE STATIONS

---

14 **PEL-STATE OIL COMPANY INC** **EDR Hist Auto** **1021548357**
521 EAST BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1969	EAST BLVD SHELL SERVICE	Gasoline Service Stations
1970	EAST BLVD SHELL SERVICE	Gasoline Service Stations
1972	PEL STATE OIL CO INC	Gasoline Service Stations
1973	PEL STATE OIL CO INC	Gasoline Service Stations
1974	PEL STATE OIL CO INC	Gasoline Service Stations
1975	PEL-STATE OIL COMPANY INC	Gasoline Service Stations
1977	PEL-STATE OIL COMPANY INC	Gasoline Service Stations
1978	PEL-STATE OIL COMPANY INC	Gasoline Service Stations
1979	PEL-STATE OIL COMPANY INC	Gasoline Service Stations

14 **HANEY AUTOMOTIVE INCORPORATED** **EDR Hist Auto** **1020881905**
918 GOVERNMENT ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
2008	HANEY AUTOMOTIVE INCORPORATED	Auto And Home Supply Stores, NEC
2009	HANEY AUTOMOTIVE INCORPORATED	Auto And Home Supply Stores, NEC
2010	HANEY AUTOMOTIVE INCORPORATED	Auto And Home Supply Stores, NEC
2011	HANEY AUTOMOTIVE INCORPORATED	Auto And Home Supply Stores, NEC
2012	HANEY AUTOMOTIVE INCORPORATED	Auto And Home Supply Stores, NEC

---

14 **CENTRAL ESSO SERV** **EDR Hist Auto** **1013762747**
959 GOVERNMENT ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1945	HAMILTON SERVICE STATION FILLIN	GASOLINE AND OIL SERVICE STATIONS
1955	CENTRAL ESSO SERV	GASOLINE SERVICE STATIONS
1960	CENTRAL ESSO SERV	GASOLINE STATIONS

---

14 **1075 GOVERNMENT ST** **LA SPILLS** **S117440001**
1075 GOVERNMENT ST **LA REM** **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	11/25/2014
Date Initiated:	Not reported
aiid:	194644
Incident Id:	160268
Incident Date:	11/25/2014
Incident Status:	**Open**
Media Desc:	Soil
Location Description:	1075 Government StBaton Rouge
Incident Source Name:	1075 Government St
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s1452747Benzene discovered to be above RECAP screening standards. Sample exceeded hold time at lab. WL
Incident Type Desc:	Release/Spill, Miscellaneous
Comments:	Not reported
Parameter:	Benzene
Quantity:	0 mg/l
Other Substance Desc:	Not reported

REM:

AI Num:	194644
Evaluated And Closed:	04/30/2015
Program:	Solid Waste
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 9738775

14 **CENTRAL ESSO SERVICENTER** **EDR Hist Auto** **1013765768**
403 EAST BLVD **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1966	CENTRAL ESSO SERVICENTER	GASOLINE STATIONS
1969	CENTRAL ESSO STATION	Gasoline Service Stations
1970	CENTRAL ESSO SERVICENTER	GASOLINE STATIONS
1970	CENTRAL ESSO STATION	Gasoline Service Stations
1971	CENTRAL ESSO STATION	Gasoline Service Stations
1972	CENTRAL ESSO STATION	Gasoline Service Stations
1973	CENTRAL ESSO STATION	Gasoline Service Stations
1974	CENTRAL ESSO STATION	Gasoline Service Stations
1975	CENTRAL EXXON SERVICENTER	GASOLINE STATIONS
1975	CENTRAL ESSO STATION	Gasoline Service Stations

---

14 **CLOSED STATION** **LA UST** **U002038921**
403 FAST BLVD **N/A**
BATON ROUGE, LA 70800

UST:

Master Agency Id:	78088
Subject Item ID:	1
UST Tank Num:	43795
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	43796
Tank Status:	**Removed**

CLOSED STATION (Continued) **U002038921**

Install Date:	01/01/1980
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	44740
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported

CLOSED STATION (Continued) **U002038921**

Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	44741
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	44742
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported

CLOSED STATION (Continued) **U002038921**

Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	44743
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

15 **LA SPILLS** **S116691310**
N/A

1785 S WESTPORT DR
PORT ALLEN, LA 70767

SPILLS:

Region Code:	Not reported
Date Rec:	05/08/2014
Date Initiated:	Not reported
aiid:	6264
Incident Id:	155839
Incident Date:	05/08/2014
Incident Status:	**Closed**
Media Desc:	Soil/Air
Location Description:	1785 S. Westport DrivePort Allen
Incident Source Name:	Lhoist North America of Missouri Inc - Port Allen Terminal

(Continued) **S116691310**

Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c14-42772Lime Dust drifted from facility property onto complainants business property covering and damaging vehicles CML
Incident Type Desc:	Complaint, Dust/Particulates/Sandblasting
Comments:	Refer to INS20140001 for details of complaint and resulting Partial Compliance Evalution.
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

15 **LA SPILLS** **S117044246**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

SPILLS:

Region Code:	Not reported
Date Rec:	09/02/2014
Date Initiated:	Not reported
aiid:	6264
Incident Id:	158453
Incident Date:	09/02/2014
Incident Status:	**Closed**
Media Desc:	Soil/Air
Location Description:	next to 1891 WestportPort Allen
Incident Source Name:	Lhoist North America of Missouri Inc - Port Allen Terminal
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c14-48507lime dust releasing from facility impacting neighboring businesses vehicles CML
Incident Type Desc:	Complaint, Dust/Particulates/Sandblasting
Comments:	Refer to INS20140001 for details of complaint and resulting Partial Compliance Evalution
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **LA UST** **U003922947**
1785 S WESTPORT DR **LA SPILLS** **N/A**
PORT ALLEN, LA 70767 **LA NPDES**

UST:

Master Agency Id:	6264
Subject Item ID:	1
UST Tank Num:	27941
Tank Status:	**Closed**
Install Date:	05/07/1984
Total Capacity:	500
Number Of Compartments:	1

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **U003922947**

Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

SPILLS:

Region Code:	Not reported
Date Rec:	06/06/2014
Date Initiated:	Not reported
aiid:	6264
Incident Id:	156579
Incident Date:	06/05/2014
Incident Status:	**Closed**
Media Desc:	Soil/Air
Location Description:	1785 S. Westport Dr.Port Allen
Incident Source Name:	Lhoist North America of Missouri Inc - Port Allen Terminal
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c14-44252lime dust releasing from facility impacting neighboring businesses vehicles CML
Incident Type Desc:	Complaint, Dust/Particulates/Sandblasting
Comments:	Refer to INS20140001 for details of complaint and resulting Partial Compliance Evalution.
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

Region Code:	Not reported
Date Rec:	05/05/2003
Date Initiated:	Not reported
aiid:	6264
Incident Id:	60927
Incident Date:	05/05/2003

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **U003922947**

Incident Status:	**Closed**
Media Desc:	Air
Location Description:	Chemical Lime 1785 S Westport Dr Port Allen
Incident Source Name:	Chemical Lime Co of Missouri Inc
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c03-1373 Company is blowing lime all over the place - car is covered in lime. jt
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

NPDES:

Facility Id:	6264
Facility Phone:	2253873051
Issued Date:	05/07/2004
Title Description:	LAG110132 Reauthorization
Permit Type Description:	Gen-LAG11-Concrete/Asphalt
Program:	Water
Activity Number:	GEN20040001

Facility Id:	6264
Facility Phone:	2253873051
Issued Date:	05/27/2009
Title Description:	Permit Reauthorization
Permit Type Description:	Gen-LAG11-Concrete/Asphalt
Program:	Water
Activity Number:	GEN20090001

Facility Id:	6264
Facility Phone:	2253873051
Issued Date:	08/11/2014
Title Description:	LAG11 Renewed Coverage
Permit Type Description:	Gen-LAG11-Concrete/Asphalt
Program:	Water
Activity Number:	GEN20140001

Facility Id:	6264
Facility Phone:	2253873051
Issued Date:	06/06/2002
Title Description:	LAG110132 Permit
Permit Type Description:	Gen-LAG11-Concrete/Asphalt
Program:	Water
Activity Number:	GEN20020001

Map ID Direction Distance Distance (ft.)	Site	Database(s)	EDR ID Number EPA ID Number
15	**CHEMICAL LIME CO - PORT ALLEN TERMINAL** **1785 S. WESTPORT DRIVE** **PORT ALLEN, LA 70767**	**TSCA**	**1014198218** **N/A**

Click this hyperlink while viewing on your computer to access additional TSCA detail in the EDR Site Report.

15	**PORTA BATCH LIME SRY** **1785 SOUTH WESTPORT DRIVE** **PORT ALLEN, LA 70767**	**FINDS** **ECHO**	**1016098257** **N/A**

FINDS:

Registry ID: 110009578368

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid: 1016098257
Registry ID: 110009578368
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009578368

15 **CHEMICAL LIME** **LA SPILLS** **S110103300**
1785 SOUTH WESTPORT **N/A**
PORT ALLEN, LA

SPILLS:

Region Code:	Not reported
Date Rec:	09/18/2001
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	45846
Incident Date:	09/18/2001
Incident Status:	**Closed**
Media Desc:	Air
Location Description:	Chemical Lime 1785 South Westport
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c01-2861 Lime all over his car and blowing in the air. Second complaint. esg
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	lime

---

15 **ERNS** **2001558150**
1785 SOUTH WESTPORT DR **N/A**
PORT ALLAN, LA 70767

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

15 **LA SPILLS** **S108592955**
1785 SOUTH WESTPORT DR **N/A**
PORT ALLEN, LA

SPILLS:

Region Code:	Not reported
Date Rec:	10/31/2005
Date Initiated:	Not reported
aiid:	6264
Incident Id:	83533
Incident Date:	10/31/2005
Incident Status:	**Closed**
Media Desc:	Air
Location Description:	1785 South Westport Dr.
Incident Source Name:	Chemical Lime Co of Missouri Inc
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c05-3328 Release of a large quanity of dust into the air.

(Continued) **S108592955**

Incident Type Desc: Not reported
Comments: Not reported
Parameter: Not reported
Quantity: Not reported
Other Substance Desc: Not reported

---

15 **CHEMICAL LIME CO - PORT ALLEN TERMINAL** **TSCA** **1014198219**
1785 S. WESTPORT DRIVE. **N/A**
PORT ALLEN, LA 70767

Click this hyperlink while viewing on your computer to access additional TSCA detail in the EDR Site Report.

---

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **RCRA-CESQG** **1004514470**
1785 S WESTPORT DR **ICIS** **LAD981584576**
PORT ALLEN, LA 70767 **FINDS**
ECHO
US AIRS

RCRA-CESQG:
Date form received by agency: 08/11/1986
Facility name: FALCO LIME INC
Facility address: 1785 S WESTPORT DR
PORT ALLEN, LA 70767
EPA ID: LAD981584576
Mailing address: S WESTPORT DR
PORT ALLEN, LA 70767
Contact: ALTON MCCAFFREY
Contact address: S WESTPORT DR
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 387-3051
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: FALCO LIME INC
Owner/operator address: HARBOR PROJECT

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **1004514470**

VICKSBURG, MS 39180
Owner/operator country: Not reported
Owner/operator telephone: (601) 636-0932
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

ICIS:
Enforcement Action ID: LA000A0000221210004100011
FRS ID: 110009578368
Action Name: LHOIST NORTH AMERICA OF MISSOURI INC - P 221210004100011
Facility Name: LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL
Facility Address: 1785 S WESTPORT DR
PORT ALLEN, LA 70767
Enforcement Action Type: Administrative Order
Facility County: WEST BATON ROUGE
Program System Acronym: AIR
Enforcement Action Forum Desc: Administrative - Formal
EA Type Code: SCAAAO
Facility SIC Code: 3274
Federal Facility ID: Not reported
Latitude in Decimal Degrees: 30.0000553
Longitude in Decimal Degrees: 91.0001373
Permit Type Desc: Not reported
Program System Acronym: LA0000002212100041
Facility NAICS Code: 327410
Tribal Land Code: Not reported

Enforcement Action ID: LA000A0000221210004100007
FRS ID: 110009578368
Action Name: LHOIST NORTH AMERICA OF MISSOURI INC - P 221210004100007
Facility Name: LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL
Facility Address: 1785 S WESTPORT DR
PORT ALLEN, LA 70767

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **1004514470**

Enforcement Action Type:	Administrative Order
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	SCAAAO
Facility SIC Code:	3274
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001373
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100041
Facility NAICS Code:	327410
Tribal Land Code:	Not reported

Enforcement Action ID:	LA000A0000221210004100005
FRS ID:	110009578368
Action Name:	LHOIST NORTH AMERICA OF MISSOURI INC - P 221210004100005
Facility Name:	LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL
Facility Address:	1785 S WESTPORT DR PORT ALLEN, LA 70767
Enforcement Action Type:	Notice of Violation
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	3274
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001373
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100041
Facility NAICS Code:	327410
Tribal Land Code:	Not reported

Enforcement Action ID:	LA000A0000221210004100002
FRS ID:	110009578368
Action Name:	LHOIST NORTH AMERICA OF MISSOURI INC - P 221210004100002
Facility Name:	LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL
Facility Address:	1785 S WESTPORT DR PORT ALLEN, LA 70767
Enforcement Action Type:	Notice of Violation
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	3274
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001373
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100041
Facility NAICS Code:	327410
Tribal Land Code:	Not reported

Enforcement Action ID:	LA000A0000221210004100001
FRS ID:	110009578368
Action Name:	LHOIST NORTH AMERICA OF MISSOURI INC - P 221210004100001

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **1004514470**

Facility Name:	LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL
Facility Address:	1785 S WESTPORT DR PORT ALLEN, LA 70767
Enforcement Action Type:	Notice of Violation
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	3274
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001373
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100041
Facility NAICS Code:	327410
Tribal Land Code:	Not reported

Enforcement Action ID:	06-2003-A038
FRS ID:	110009578368
Action Name:	LHOIST NORTH AMERICA OF MISSOURI INC - P 221210004100009
Facility Name:	LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL
Facility Address:	1785 S WESTPORT DR PORT ALLEN, LA 70767
Enforcement Action Type:	CAA 113D1 Action For Penalty
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	113D1
Facility SIC Code:	3274
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001373
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100041
Facility NAICS Code:	327410
Tribal Land Code:	Not reported

FINDS:

Registry ID: 110012673516

Environmental Interest/Information System
TSCA SUBMITTER

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **1004514470**

ECHO:

Envid:	1004514470
Registry ID:	110012673516
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110012673516

US AIRS MINOR:

Envid:	1004514470
Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
D and B Number:	Not reported
Primary SIC Code:	3274
NAICS Code:	327410
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1989-02-06 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1989-02-13 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2001-12-12 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100041

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **1004514470**

Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2002-04-24 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2004-02-09 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2002-08-29 00:00:00
Activity Status Date:	2002-08-29 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Final Order Issued

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2003-09-17 00:00:00
Activity Status Date:	2003-09-17 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Formal
Activity Status:	Final Order Issued

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1986-08-06 00:00:00
Activity Status Date:	1986-08-06 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **1004514470**

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1988-07-22 00:00:00
Activity Status Date:	1988-07-22 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

Region Code:	06
Programmatic ID:	AIR LA0000002212100041
Facility Registry ID:	110009578368
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1993-05-03 00:00:00
Activity Status Date:	1993-05-03 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

---

15 **ERNS** **98437038**
1785 SOUTH WESTPORT **N/A**
PORT ALLEN, LA

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **LA AIRS** **S116597914**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

AIRS:

Permit Number:	3120-00041-03
Permit Type Desc:	Minor Source/Small Source Mod
AI No#:	6264
Activity No#:	PER20030001
Region Code:	Capital
Latitude:	30.441389
Longitude:	-91.223056
Title Desc:	PER/3120-00041/03 Port Allen
Mailing Address:	3700 Hulen St
Mailing Address2:	Not reported
Mailing City/State/Zip:	Fort Worth, TX 76107
Issue Date:	11/30/2003
Expiration Date:	02/21/2007
Effective End Date:	02/21/2007
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	3120-00041-03

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **LA AIRS** **S116597913**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

AIRS:

Permit Number:	3120-00041-02
Permit Type Desc:	State permit (unspecified)
AI No#:	6264
Activity No#:	PER20000007
Region Code:	Capital
Latitude:	30.441389
Longitude:	-91.223056
Title Desc:	PORT ALLEN TERMINAL
Mailing Address:	3700 Hulen St
Mailing Address2:	Not reported
Mailing City/State/Zip:	Fort Worth, TX 76107
Issue Date:	11/29/2000
Expiration Date:	11/30/2003
Effective End Date:	11/30/2003
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	3120-00041-02

---

15 **LA SPILLS** **S117043195**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

SPILLS:

Region Code:	Not reported
Date Rec:	06/17/2014
Date Initiated:	Not reported
aiid:	6264
Incident Id:	156894
Incident Date:	06/16/2014
Incident Status:	**Closed**
Media Desc:	Soil/Air
Location Description:	next to 1981 Westport Dr.Port Allen
Incident Source Name:	Lhoist North America of Missouri Inc - Port Allen Terminal
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c14-44890Lime Dust drifted from facility property onto complainants business property covering and damaging vehicles CML
Incident Type Desc:	Complaint, Dust/Particulates/Sandblasting
Comments:	Refer to INS20140001 for details of complaint and resulting Partial Compliance Evalution.
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **LA AIRS** **S116597915**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

AIRS:

Permit Number:	3120-00041-04
Permit Type Desc:	Minor Source/Small Source Mod
AI No#:	6264
Activity No#:	PER20070001
Region Code:	Capital
Latitude:	30.441389
Longitude:	-91.223056
Title Desc:	Entire Facility
Mailing Address:	3700 Hulen St
Mailing Address2:	Not reported
Mailing City/State/Zip:	Fort Worth, TX 76107
Issue Date:	02/21/2007
Expiration Date:	03/30/2009
Effective End Date:	03/30/2009
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	3120-00041-04

---

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **LA AIRS** **S116597917**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

AIRS:

Permit Number:	3120-00041-06
Permit Type Desc:	Minor Source/Small Source Admin Amendmt
AI No#:	6264
Activity No#:	PER20140003
Region Code:	Capital
Latitude:	30.441389
Longitude:	-91.223056
Title Desc:	Permit - Entire Facility
Mailing Address:	3700 Hulen St
Mailing Address2:	Not reported
Mailing City/State/Zip:	Fort Worth, TX 76107
Issue Date:	05/27/2014
Expiration Date:	05/07/2024
Effective End Date:	05/07/2024
Effective Flag:	Y
Extended Flag:	Y
EDR Link ID:	3120-00041-06

Permit Number:	3120-00041-06
Permit Type Desc:	Minor Source/Small Source Mod
AI No#:	6264
Activity No#:	PER20140001
Region Code:	Capital
Latitude:	30.441389
Longitude:	-91.223056
Title Desc:	Permit - Entire Facility
Mailing Address:	3700 Hulen St
Mailing Address2:	Not reported
Mailing City/State/Zip:	Fort Worth, TX 76107
Issue Date:	05/07/2014
Expiration Date:	05/27/2014
Effective End Date:	05/27/2014

LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN TERMINAL (Continued) **S116597917**

Effective Flag: N
Extended Flag: N
EDR Link ID: 3120-00041-06

---

15 **LA SPILLS** **S117370553**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

SPILLS:

Region Code:	Not reported
Date Rec:	10/01/2014
Date Initiated:	Not reported
aiid:	6264
Incident Id:	159230
Incident Date:	10/01/2014
Incident Status:	**Open**
Media Desc:	Soil/Air
Location Description:	West Port RoadPort Allen
Incident Source Name:	Lhoist North America of Missouri Inc - Port Allen Terminal
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c14-50321Lime dust on complainants truck from facility CML
Incident Type Desc:	Complaint, Dust/Particulates/Sandblasting
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

15 **LHOIST NORTH AMERICA OF MISSOURI INC - PORT ALLEN** **LA AIRS** **S116597916**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

AIRS:

Permit Number:	3120-00041-05
Permit Type Desc:	Minor Source/Small Source Mod
AI No#:	6264
Activity No#:	PER20090001
Region Code:	Capital
Latitude:	30.441389
Longitude:	-91.223056
Title Desc:	Entire Facility
Mailing Address:	3700 Hulen St
Mailing Address2:	Not reported
Mailing City/State/Zip:	Fort Worth, TX 76107
Issue Date:	03/30/2009
Expiration Date:	05/07/2014
Effective End Date:	05/07/2014
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	3120-00041-05

15 **CHEMICAL LIME CO OF MISSOURI INC** **FINDS** **1010726865**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

FINDS:

Registry ID: 110033668546

Environmental Interest/Information System
Louisiana Tools for Environmental Management and Protection Organizations (LA-TEMPO) is an Integrated Management System.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

15 **ERNS** **2002608046**
1785 SOUTH WESTPORT DR **N/A**
PORT ALLEN, LA 70767

Click this hyperlink while viewing on your computer to access additional ERNS detail in the EDR Site Report.

---

15 **LA SPILLS** **S116691479**
1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

SPILLS:

Region Code:	Not reported
Date Rec:	05/21/2014
Date Initiated:	Not reported
aiid:	6264
Incident Id:	156101
Incident Date:	05/21/2014
Incident Status:	**Closed**
Media Desc:	Air
Location Description:	Next door to 1981 West Port Dr.Port Allen
Incident Source Name:	Lhoist North America of Missouri Inc - Port Allen Terminal
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c14-43319responsible party dumping lime, causing dust to migrate throughout the area CML
Incident Type Desc:	Complaint, Dust/Particulates/Sandblasting
Comments:	Refer to INS20140001 for details of complaint and resulting Partial Compliance Evalution.
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

15 **PORTA-BATCH SLURRY #728** **LA AIRS** **S113395351**
STATEWIDE - 1785 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

AIRS:

Permit Number:	7777-00409-00
Permit Type Desc:	State permit (unspecified)
AI No#:	103737
Activity No#:	PER20000001
Region Code:	Capital
Latitude:	Not reported
Longitude:	Not reported
Title Desc:	PORTA-BATCH SLRY 728
Mailing Address:	Not reported
Mailing Address2:	Not reported
Mailing City/State/Zip:	LA
Issue Date:	12/18/2000
Expiration Date:	Not reported
Effective End Date:	01/26/2001
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	7777-00409-00

---

15 **PORTA-BATCH SLURRY #727** **LA AIRS** **S113395350**
STATEWIDE - 1785 S WESTPORT DR **N/A**
PORTABLE SOURCE, LA 70767

AIRS:

Permit Number:	7777-00408-00
Permit Type Desc:	State permit (unspecified)
AI No#:	103736
Activity No#:	PER20000001
Region Code:	Multiple
Latitude:	Not reported
Longitude:	Not reported
Title Desc:	PORTA-BATCH SLRY 727
Mailing Address:	Not reported
Mailing Address2:	Not reported
Mailing City/State/Zip:	LA
Issue Date:	12/18/2000
Expiration Date:	Not reported
Effective End Date:	01/26/2001
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	7777-00408-00

---

15 **CHEMICAL LINE** **LA SPILLS** **S108592954**
1785 S. WESTPORT DRIVE **N/A**
PORT ALLEN, LA

SPILLS:

Region Code:	Not reported
Date Rec:	09/04/2001
Date Initiated:	Not reported
aiid:	6264
Incident Id:	45487
Incident Date:	08/30/2001
Incident Status:	**Closed**

CHEMICAL LINE (Continued) **S108592954**

Media Desc:	Air
Location Description:	Chemical Line 1785 S. Westport Drive
Incident Source Name:	Chemical Lime Co - Port Allen Terminal
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c01-2709 Line released in air. Damage to vehicle. esg
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

15 **NUGENT STEEL & SUPPLY CO INC** **RCRA-CESQG** **1004714558**
1800 S WESTPORT DR **FINDS** **LAR000035048**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:

Date form received by agency:	10/18/1999
Facility name:	NUGENT STEEL & SUPPLY CO INC
Facility address:	1800 S WESTPORT DR PORT ALLEN, LA 70767
EPA ID:	LAR000035048
Mailing address:	PO BOX 730 PORT ALLEN, LA 707670730
Contact:	JIM NUGENT
Contact address:	PO BOX 730 PORT ALLEN, LA 707670730
Contact country:	US
Contact telephone:	(225) 387-0987
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	JIM NUGENT
Owner/operator address:	PO BOX 730 PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 387-0987
Legal status:	Private

NUGENT STEEL & SUPPLY CO INC (Continued) **1004714558**

Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

FINDS:

Registry ID: 110003364804

NUGENT STEEL & SUPPLY CO INC (Continued) **1004714558**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004714558
Registry ID:	110003364804
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003364804

---

15 **BP HOLLY COLEMAN** **EDR Hist Auto** **1021585328**
1981 S WESTPORT DR **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
2010	BP HOLLY COLEMAN	Gasoline Service Stations, NEC
2011	BP HOLLY COLEMAN	Gasoline Service Stations, NEC
2012	BP HOLLY COLEMAN	Gasoline Service Stations, NEC
2013	BP HOLLY COLEMAN	Gasoline Service Stations, NEC
2014	BP HOLLY COLEMAN	Gasoline Service Stations, NEC

---

15 **GRAHAM PACKAGING CO** **RCRA-CESQG** **1005416290**
1981B S WESTPORT DR **LAD985193580**
PORT ALLEN, LA 70767

RCRA-CESQG:

Date form received by agency:	02/25/1991
Facility name:	GRAHAM PACKAGING CO
Facility address:	1981B S WESTPORT DR PORT ALLEN, LA 70767
EPA ID:	LAD985193580
Mailing address:	S WESTPORT DR PORT ALLEN, LA 70767
Contact:	CHRISTINA JOHNSON
Contact address:	1981B S WESTPORT DR PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 344-6860
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

GRAHAM PACKAGING CO (Continued) **1005416290**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	GRAHAM PACKAGING CO
Owner/operator address:	1110 E PRINCESS ST YORK, PA 17405
Owner/operator country:	Not reported
Owner/operator telephone:	(717) 849-8500
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

Violation Status: No violations found

---

15 **BP LUBRICANTS USA INC** **RCRA-SQG** **1000420010**
1981 S WESTPORT DR **TRIS** **70767CSTRL1981S**
PORT ALLEN, LA 70767 **ICIS**
FINDS
US AIRS
ECHO

RCRA-SQG:

Date form received by agency:	08/11/2015
Facility name:	BP LUBRICANTS USA, INC.
Facility address:	1981 S WESTPORT DR PORT ALLEN, LA 70767
EPA ID:	LAD028507127
Mailing address:	S WESTPORT DR PORT ALLEN, LA 70767
Contact:	HOLLY M COLEMAN

BP LUBRICANTS USA INC (Continued) **1000420010**

Contact address:	S WESTPORT DR PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 382-8526
Contact email:	HOLLY.COLEMAN@BP.COM
EPA Region:	06
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	BP LUBRICANTS USA, INC.
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/01/2004
Owner/Op end date:	Not reported

Owner/operator name:	BP LUBRICANTS USA, INC.
Owner/operator address:	1981 SOUTH WESTPORT DRIVE PORT ALLEN, LA 70767
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	12/01/2004
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002

BP LUBRICANTS USA INC (Continued) **1000420010**

. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 02/27/2009
Site name: BP LUBRICANTS USA, INC.
Classification: Small Quantity Generator

BP LUBRICANTS USA INC (Continued) **1000420010**

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 10/21/2008
Site name: BP LUBRICANTS USA, INC.
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/13/2006
Site name: BP LUBRICANTS USA, INC.
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/10/2006
Site name: BP LUBRICANTS USA INC
Classification: Small Quantity Generator

BP LUBRICANTS USA INC (Continued) **1000420010**

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 03/02/2005
Site name: BP LUBRICANTS USA INC
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 12/01/2004
Site name: BP LUBRICANTS USA INC
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT

BP LUBRICANTS USA INC (Continued) **1000420010**

MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/03/2004
Site name: CASTROL NORTH AMERICA
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 01/14/2004
Site name: CASTROL NORTH AMERICA
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F003
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Date form received by agency: 02/28/2002
Site name: CASTROL NORTH AMERICA
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Date form received by agency: 01/12/2001

BP LUBRICANTS USA INC (Continued) **1000420010**

Site name: CASTROL NORTH AMERICA
Classification: Large Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

Date form received by agency: 02/04/2000
Site name: CASTROL CONSUMER NORTH AMERICA
Classification: Large Quantity Generator

Date form received by agency: 03/19/1991
Site name: CASTROL NORTH AMERICA
Classification: Large Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - LAC33V1105B
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 11/04/1993
Violation lead agency: State
Enforcement action: VERBAL INFORMAL
Enforcement action date: 11/02/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1109E4
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 11/03/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/27/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2111A
Area of violation: Generators - Pre-transport
Date violation determined: 11/02/1993
Date achieved compliance: 11/10/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/27/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported

BP LUBRICANTS USA INC (Continued) **1000420010**

Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2111A
Area of violation: Generators - Pre-transport
Date violation determined: 11/02/1993
Date achieved compliance: 11/10/1993
Violation lead agency: State
Enforcement action: VERBAL INFORMAL
Enforcement action date: 11/02/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1105B
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 11/04/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/27/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2109A
Area of violation: Generators - Pre-transport
Date violation determined: 11/02/1993
Date achieved compliance: 11/08/1993
Violation lead agency: State
Enforcement action: VERBAL INFORMAL
Enforcement action date: 11/02/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1109E4
Area of violation: Generators - General
Date violation determined: 11/02/1993
Date achieved compliance: 11/03/1993
Violation lead agency: State
Enforcement action: VERBAL INFORMAL
Enforcement action date: 11/02/1993
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported

BP LUBRICANTS USA INC (Continued) **1000420010**

Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2109A
Area of violation: Generators - Pre-transport
Date violation determined: 11/02/1993
Date achieved compliance: 11/08/1993
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/27/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 03/31/1988
Date achieved compliance: 08/25/1988
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/23/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 09/30/1997
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 02/04/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - General
Date achieved compliance: 11/03/1993
Evaluation lead agency: State

Evaluation date: 02/04/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/10/1993
Evaluation lead agency: State

Evaluation date: 02/04/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/08/1993
Evaluation lead agency: State

Evaluation date: 02/04/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION

BP LUBRICANTS USA INC (Continued) **1000420010**

Area of violation: Generators - General
Date achieved compliance: 11/04/1993
Evaluation lead agency: State

Evaluation date: 11/02/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/04/1993
Evaluation lead agency: State

Evaluation date: 11/02/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/08/1993
Evaluation lead agency: State

Evaluation date: 11/02/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 11/03/1993
Evaluation lead agency: State

Evaluation date: 11/02/1993
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 11/10/1993
Evaluation lead agency: State

Evaluation date: 07/03/1990
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 05/02/1989
Evaluation: NON-FINANCIAL RECORD REVIEW
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: EPA

Evaluation date: 08/25/1988
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - General
Date achieved compliance: 08/25/1988
Evaluation lead agency: State

Evaluation date: 03/31/1988
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/25/1988
Evaluation lead agency: State

TRIS:

Click this hyperlink while viewing on your computer to access
1 additional US_TRIS: record(s) in the EDR Site Report.

ICIS:

BP LUBRICANTS USA INC (Continued) **1000420010**

Enforcement Action ID:	LA000A0000221210004300015
FRS ID:	110000449836
Action Name:	BP LUBRICANTS USA INC - PORT ALLEN FACIL 221210004300015
Facility Name:	BP LUBRICANTS USA INC - PORT ALLEN FACILITY
Facility Address:	1981 S WESTPORT ST PORT ALLEN, LA 70767
Enforcement Action Type:	Notice of Violation
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	2992
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001907
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100043
Facility NAICS Code:	324191
Tribal Land Code:	Not reported

Enforcement Action ID:	LA000A0000221210004300003
FRS ID:	110000449836
Action Name:	BP LUBRICANTS USA INC - PORT ALLEN FACIL 221210004300003
Facility Name:	BP LUBRICANTS USA INC - PORT ALLEN FACILITY
Facility Address:	1981 S WESTPORT ST PORT ALLEN, LA 70767
Enforcement Action Type:	Notice of Violation
Facility County:	WEST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	2992
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.0000553
Longitude in Decimal Degrees:	91.0001907
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002212100043
Facility NAICS Code:	324191
Tribal Land Code:	Not reported

FINDS:

Registry ID: 110003322645

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

BP LUBRICANTS USA INC (Continued) **1000420010**

US AIRS MINOR:

Envid:	1000420010
Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
D and B Number:	Not reported
Primary SIC Code:	2992
NAICS Code:	324191
Default Air Classification Code:	MIN
Facility Type of Ownership Code:	POF
Air CMS Category Code:	Not reported
HPV Status:	Not reported

US AIRS MINOR:

Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1996-09-20 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1997-08-07 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1998-08-04 00:00:00
Activity Status Date:	Not reported
Activity Group:	Compliance Monitoring
Activity Type:	Inspection/Evaluation
Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	New Source Performance Standards
Activity Date:	1999-09-15 00:00:00

BP LUBRICANTS USA INC (Continued) **1000420010**

Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2000-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2002-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: New Source Performance Standards
Activity Date: 2004-11-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1986-03-18 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR

BP LUBRICANTS USA INC (Continued) **1000420010**

Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1988-05-17 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1993-02-22 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1996-09-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1997-08-07 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1998-08-04 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06

BP LUBRICANTS USA INC (Continued) **1000420010**

Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 1999-09-15 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2000-06-28 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2002-10-31 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2004-11-12 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation
Activity Status: Not reported

Region Code: 06
Programmatic ID: AIR LA0000002212100043
Facility Registry ID: 110000449836
Air Operating Status Code: OPR
Default Air Classification Code: MIN
Air Program: State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date: 2008-10-20 00:00:00
Activity Status Date: Not reported
Activity Group: Compliance Monitoring
Activity Type: Inspection/Evaluation

BP LUBRICANTS USA INC (Continued) **1000420010**

Activity Status:	Not reported

Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	1992-07-13 00:00:00
Activity Status Date:	1992-07-13 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

Region Code:	06
Programmatic ID:	AIR LA0000002212100043
Facility Registry ID:	110000449836
Air Operating Status Code:	OPR
Default Air Classification Code:	MIN
Air Program:	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Activity Date:	2008-11-04 00:00:00
Activity Status Date:	2008-11-04 00:00:00
Activity Group:	Enforcement Action
Activity Type:	Administrative - Informal
Activity Status:	Achieved

ECHO:

Envid:	1000420010
Registry ID:	110003322645
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003322645

---

15 **GRAHAM PACKAGING** **LA SPILLS** **S109961870**
NEAR 1981 SOUTH WESTPORT DR **N/A**
PORT ALLEN, LA

SPILLS:

Region Code:	Not reported
Date Rec:	06/23/2009
Date Initiated:	Not reported
aiid:	1648
Incident Id:	115906
Incident Date:	06/21/2009
Incident Status:	**Closed**
Media Desc:	Air
Location Description:	Graham Packaging near 1981 South Westport Dr Port Allen
Incident Source Name:	BP Lubricants USA Inc - Port Allen Facility
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	0
Quantity:	0 0

GRAHAM PACKAGING (Continued) **S109961870**

Other Substance Desc: 0

---

16 WESTPORT TEXACO **LA HIST LUST** **U001893778**
841 LOBDELL SOUTH EXT **LA UST** **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-002612
Facility Parish:	WEST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	03/13/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0072
Incident Date:	03/13/1990
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	ROSS WILLIAMS/ DEQ EMER. RESP.
Reported By 2:	Not reported
Owner ID:	00078900
Owner Name:	D & S DISTRIBUTORS, INC
Owner Address:	P. O. BOX 307
Owner City,St,Zip:	PLAQUEMINE, LA 70764
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: Not reported

LA HIST LUST ASSESMENT:

Comments: GASOLINE ODORS SMELLED IN MANHOLE. SHEEN ON WATER IN DITCHES. TANKTESTED. LEAK IN FILTER AND IN PRODUCT LINE. FILTER REPLACED. LINE TOBE UPGRADED. DEQ INSPECT. 3/19/90 RESPONSE TO REPORT OF GASOLINEODORS IN DRAINAGE MAN WAY. DEQ INSPECT. 11/21/91 TO OBSERVE AERATIONACTIVITIES OF CONTAMINATED SOILS AFTER PIPING LINE REPLACEMENT.

LA HIST LUST CORRECTIVE ACTION:

WESTPORT TEXACO (Continued) **U001893778**

Comments: Not reported

Facility ID: 61-002612
Facility Parish: WEST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 90-2-0072
Incident Date: 03/13/1990
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00078900
Owner Name: D & S DISTRIBUTORS, INC
Owner Address: P. O. BOX 307
Owner City,St,Zip: PLAQUEMINE, LA 70764
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: GASOLINE ODORS SMELLED IN MANHOLE. SHEEN ON WATER IN DITCHES. TANKTESTED. LEAK IN FILTER AND IN PRODUCT LINE. FILTER REPLACED. LINE TOBE UPGRADED. DEQ INSPECT. 3/19/90 RESPONSE TO REPORT OF GASOLINEODORS IN DRAINAGE MAN WAY. DEQ INSPECT. 11/21/91 TO OBSERVE AERATIONACTIVITIES OF CONTAMINATED SOILS AFTER PIPING LINE REPLACEMENT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:
Master Agency Id: 74791

WESTPORT TEXACO (Continued) **U001893778**

Subject Item ID:	1
UST Tank Num:	7363
Tank Status:	**Removed**
Install Date:	05/07/1976
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	7364
Tank Status:	**Removed**
Install Date:	05/07/1976
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported

WESTPORT TEXACO (Continued) **U001893778**

Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

16 **WESTPORT TEXACO** **EDR Hist Auto** **1020328334**
841 LOBDELL EXT S **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
1994	WESTPORT TEXACO	Gasoline Service Stations
1995	WESTPORT TEXACO	Gasoline Service Stations
1996	WESTPORT TEXACO	Gasoline Service Stations
1997	WESTPORT TEXACO	Gasoline Service Stations

---

16 **LOVE'S TRAVEL STOP 240** **RCRA-SQG** **1018275332**
751 LOBDELL EXT S **FINDS** **LAR000090688**
PORT ALLEN, LA 70767 **ECHO**

RCRA-SQG:

Date form received by agency:	05/09/2016
Facility name:	LOVE'S TRAVEL STOP 240
Facility address:	751 LOBDELL EXT S PORT ALLEN, LA 70767
EPA ID:	LAR000090688
Mailing address:	PO BOX 26210 OKLAHOMA CITY, OK 73126
Contact:	CHRIS WELDON
Contact address:	PO BOX 26210 OKLAHOMA CITY, OK 73126
Contact country:	US
Contact telephone:	(405) 302-6673
Contact email:	Not reported
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	LOVES TRAVEL STOP
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	09/21/1999
Owner/Op end date:	Not reported

LOVE'S TRAVEL STOP 240 (Continued) **1018275332**

Owner/operator name: LOVES TRAVEL STOP
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/21/1999
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110069285133

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018275332
Registry ID: 110069285133

LOVE'S TRAVEL STOP 240 (Continued) **1018275332**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110069285133

---

16 **LOVES TRVL STOPS CNTRY STORES** **EDR Hist Auto** **1021443735**
751 LOBDELL EXT S **N/A**
PORT ALLEN, LA 70767

EDR Hist Auto

Year:	Name:	Type:
2003	LOVES TRVL STOPS CNTRY STORES	Gasoline Service Stations, NEC
2004	LOVES TRVL STOPS CNTRY STORES	Gasoline Service Stations, NEC
2005	LOVES TRVL STOPS CNTRY STORES	Gasoline Service Stations, NEC
2006	LOVES TRVL STOPS CNTRY STORES	Gasoline Service Stations, NEC
2007	LOVES TRVL STOPS CNTRY STORES	Gasoline Service Stations, NEC
2008	LOVES TRAVEL STOPS	Gasoline Service Stations, NEC

---

17 **NICHOLSON DRIVE SHOPPING CENTER - LDEQ** **US BROWNFIELDS** **1014476364**
1600 BLOCK, NICHOLSON DRIVE **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	R6 Brownfields TBA (previously Superfund TBA)
Grant type:	TBA
Property name:	NICHOLSON DRIVE SHOPPING CENTER - LDEQ
Property #:	Not reported
Parcel size:	2
Property Description:	City Directories indicate four businesses operating at the site in the past. 1580 Nicholson Drive was listed as a supermarket in 1966 and 1971, Savco Drugs in 1985 and 1990, and a lounge/bar in 1996 and 2002. 1601 Nicholson Drive was a TG&Y store in 1966 and 1971, Flea market in 1985, and Bingo Hall in 1990 and 1996. 1626 Nicholson Drive was a Dry Cleaner in 1966 and vacant in subsequent listings reviewed. 1628 Nicholson Drive was a barbershop in 1966 and vacant in subsequent listings reviewed (PPF - Nicholson Drive Shopping Center, 7/19/06).
Latitude:	30.432694
Longitude:	-91.187972
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Not reported
Datum:	World Geodetic System of 1984
ACRES property ID:	37561
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	4193
Assessment funding source:	US EPA - TBA Funding
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	State Brownfields Assessment Grant
Cleanup funding entity:	Not reported
Grant type:	N/A

NICHOLSON DRIVE SHOPPING CENTER - LDEQ (Continued) **1014476364**

Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	n/a
Ownership entity:	Private
Current owner:	Nicholson-Wampold, LLC
Did owner change:	N
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Y
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported

NICHOLSON DRIVE SHOPPING CENTER - LDEQ (Continued) **1014476364**

Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	658
% Below Poverty:	2.7%
# Low Income:	1179
% Low Income:	1.5%
Meidan Income:	1735
# Unemployed:	141
% Unemployed:	12.7%
# Vacant Housing:	145
% Vacant Housing:	12.4%

17 GILMAR MARINE SERVICES INC — **LA SHWS** — **S105201029**
1500 RIVER RD — **LA REM** — **N/A**
BATON ROUGE, LA 70821

SHWS:

Facility ID:	8003
Facility Status:	Potential*

REM:

AI Num:	8003
Evaluated And Closed:	Not reported
Program:	Potential*
EAC Type:	Not reported
Comments:	Not reported

---

17 COTERIE BUILDERS INC — **LA UST** — **U003750692**
1429 - 1435 NICHOLSON DR — **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	86420
Subject Item ID:	1
UST Tank Num:	54384
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	54385
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	3000

COTERIE BUILDERS INC (Continued) **U003750692**

Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	54386
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported

COTERIE BUILDERS INC (Continued) **U003750692**

Pipe Method Description: Not reported

---

17 **GILMAR MARINE SERVICES** **SEMS-ARCHIVE** **1012043006**
1500 RIVER ROADS, **LAN000606799**
BATON ROUGE, LA 70809

SEMS-ARCHIVE:

Site ID:	606799
EPA ID:	LAN000606799
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

---

17 **EBR CITY PARISH PROPERTY** **RCRA-LQG** **1012210881**
600 OKLAHOMA ST **LAR000070193**
BATON ROUGE, LA 70802

RCRA-LQG:

Date form received by agency:	02/05/2010
Facility name:	EBR CITY PARISH PROPERTY
Facility address:	600 OKLAHOMA ST BATON ROUGE, LA 70802
EPA ID:	LAR000070193
Mailing address:	PO BOX 1471 BATON ROUGE, LA 70821
Contact:	DALE E CAMPAU
Contact address:	PO BOX 1471 BATON ROUGE, LA 70821
Contact country:	US
Contact telephone:	(225) 389-5456
Contact email:	Not reported
EPA Region:	06
Classification:	Large Quantity Generator
Description:	Handler: generates 1,000 kg or more of hazardous waste during any calendar month; or generates more than 1 kg of acutely hazardous waste during any calendar month; or generates more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generates 1 kg or less of acutely hazardous waste during any calendar month, and accumulates more than 1 kg of acutely hazardous waste at any time; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates more than 100 kg of that material at any time

Owner/Operator Summary:

Owner/operator name:	EBR PARISH
Owner/operator address:	Not reported Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1970
Owner/Op end date:	Not reported

EBR CITY PARISH PROPERTY (Continued) **1012210881**

Owner/operator name:	EBR PARISH
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1970
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

---

17 **BR 169 OSBR DUANE & GLACIER STREET LOTS** **US BROWNFIELDS** **1016356309**
1349 DUANE STREET **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 169 OSBR DUANE & GLACIER STREET LOTS
Property #:	840351652-840351654, 840351663-840351666, 840351674, 840353980
Parcel size:	.7
Property Description:	Subject property consists of 9 lots between Duane and Glacier Streets. Homes are present on 3 of the nine lots and the remaining lots are vacant. Multiple past owners for the properties.
Latitude:	30.435771
Longitude:	-91.186247
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	114223
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported

BR 169 OSBR DUANE & GLACIER STREET LOTS (Continued) **1016356309**

Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	15000
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Government
Current owner:	Housing Authority of East Baton Rouge Parish
Did owner change:	Y
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported

BR 169 OSBR DUANE & GLACIER STREET LOTS (Continued) **1016356309**

Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	.7
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	.7
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Y
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	731
% Below Poverty:	3.0%
# Low Income:	1364
% Low Income:	1.6%
Meidan Income:	1162
# Unemployed:	168

BR 169 OSBR DUANE & GLACIER STREET LOTS (Continued) **1016356309**

% Unemployed:	12.9%
# Vacant Housing:	157
% Vacant Housing:	13.8%

FINDS:

Registry ID: 110042111782

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 **BR 166 OSBR TURKISH BATHS 208 OKLAHOMA ST** **US BROWNFIELDS** **1016356308**
208 OKLAHOMA ST. **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	BR 166 OSBR TURKISH BATHS 208 OKLAHOMA ST
Property #:	840351660
Parcel size:	.19
Property Description:	The subject property houses one commercial building which was previously used as a Turkish Bath house and gymnasium, surrounded by residential and vacant properties. Previous owner was Edgar Barrie Properties.
Latitude:	30.4349924
Longitude:	-91.1856083
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	World Geodetic System of 1984
ACRES property ID:	114222
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	6258
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Hazardous
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	96637101
Ownership entity:	Private
Current owner:	OSBR Land, LLC

BR 166 OSBR TURKISH BATHS 208 OKLAHOMA ST (Continued) **1016356308**

Did owner change:	Y
Cleanup required:	No
Video available:	No
Photo available:	No
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Y
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	.19
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	.19
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported

BR 166 OSBR TURKISH BATHS 208 OKLAHOMA ST (Continued) **1016356308**

Superfund Fed. landowner flag:	Y
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	757
% Below Poverty:	3.0%
# Low Income:	1434
% Low Income:	1.6%
Meidan Income:	1447
# Unemployed:	177
% Unemployed:	12.8%
# Vacant Housing:	171
% Vacant Housing:	13.3%

FINDS:

Registry ID: 110042111773

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

17 FRANKLIN PRESS INC
1391 HIGHLAND RD
BATON ROUGE, LA 70802

RCRA-SQG
FINDS
LA UST
ECHO

1004707743
LAD008180226

RCRA-SQG:

Date form received by agency:	04/13/2015
Facility name:	FRANKLIN PRESS INC
Facility address:	1391 HIGHLAND RD BATON ROUGE, LA 70802
EPA ID:	LAD008180226
Mailing address:	HIGHLAND RD BATON ROUGE, LA 70802
Contact:	CRAIG C CHUMNEY
Contact address:	HIGHLAND RD BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 288-7711
Contact email:	Not reported
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	FRANKLIN PRESS INC
Owner/operator address:	UNKNOWN UNKNOWN, 00000
Owner/operator country:	US
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/31/1950
Owner/Op end date:	Not reported

Owner/operator name:	FRANKLIN PRESS INC
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No

FRANKLIN PRESS INC (Continued) **1004707743**

Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:
Date form received by agency: 03/10/1987
Site name: FRANKLIN PRESS INC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110001252206

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UST:
Master Agency Id: 10136
Subject Item ID: 1

UST Tank Num: 11156
Tank Status: Closed
Install Date: 06/06/1980
Total Capacity: 2500
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Yes
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported

FRANKLIN PRESS INC (Continued) **1004707743**

Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

ECHO:

Envid:	1004707743
Registry ID:	110001252206
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001252206

---

17 **HIGHLAND TERRACE AMOCO** **LA UST** **U004222316**
1375 HIGHLAND RD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	20637
Subject Item ID:	1
UST Tank Num:	14803
Tank Status:	**Removed**
Install Date:	04/29/1985
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

HIGHLAND TERRACE AMOCO (Continued) **U004222316**

UST Tank Num:	14804
Tank Status:	**Removed**
Install Date:	04/29/1985
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	14805
Tank Status:	**Removed**
Install Date:	04/29/1985
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

HIGHLAND TERRACE AMOCO (Continued) **U004222316**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	14806
Tank Status:	**Removed**
Install Date:	04/29/1985
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

17 **PERSONAL TOUCH CAR WASH AND USED TIRE** **US BROWNFIELDS** **1014722356**
1320 HIGHLAND ROAD **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Old South Baton Rouge
Grant type:	Cleanup
Property name:	PERSONAL TOUCH CAR WASH AND USED TIRE
Property #:	E. Baton RougeParish, Suburb Magnolia, Lots 1-7, B Square 279
Parcel size:	1.44
Property Description:	History of automotive repair, car wash, tire repair
Latitude:	30.436033
Longitude:	-91.185347
HCM label:	Address Matching-Block Face
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	50221
Start date:	09/01/2009 00:00:00
Completed date:	10/30/2009 00:00:00

PERSONAL TOUCH CAR WASH AND USED TIRE (Continued) **1014722356**

Acres cleaned up:	Not reported
Cleanup funding:	200000
Cleanup funding source:	US EPA - Brownfields Cleanup Cooperative Agreement
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	06/01/2010 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	EPA
Grant type:	Petroleum
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	96687201
Ownership entity:	Private
Current owner:	OSBR, LLC
Did owner change:	N
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	06/16/2008 00:00:00
State/tribal program ID:	20655
State/tribal NFA date:	09/28/2010 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported

PERSONAL TOUCH CAR WASH AND USED TIRE (Continued) **1014722356**

Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	1.44
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	1.44
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	818
% Below Poverty:	3.0%
# Low Income:	1533
% Low Income:	1.6%
Meidan Income:	1573

PERSONAL TOUCH CAR WASH AND USED TIRE (Continued) **1014722356**

# Unemployed:	193
% Unemployed:	12.6%
# Vacant Housing:	186
% Vacant Housing:	13.0%

Recipient name:	Louisiana Department of Environmental Quality
Grant type:	Section 128(a) State/Tribal
Property name:	PERSONAL TOUCH CAR WASH AND USED TIRE
Property #:	E. Baton RougeParish, Suburb Magnolia, Lots 1-7, B Square 279
Parcel size:	1.44
Property Description:	History of automotive repair, car wash, tire repair
Latitude:	30.436033
Longitude:	-91.185347
HCM label:	Address Matching-Block Face
Map scale:	Not reported
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	50221
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	41518
Assessment funding source:	US EPA - State & Tribal Section 128(a) Funding
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	Petroleum
Accomplishment type:	Supplemental Assessment
Accomplishment count:	1
Cooperative agreement #:	97654001
Ownership entity:	Private
Current owner:	OSBR, LLC
Did owner change:	N
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	No
State/tribal program date:	06/16/2008 00:00:00
State/tribal program ID:	20655
State/tribal NFA date:	09/28/2010 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported

PERSONAL TOUCH CAR WASH AND USED TIRE (Continued) **1014722356**

Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	1.44
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	1.44
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported

PERSONAL TOUCH CAR WASH AND USED TIRE (Continued) **1014722356**

No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	818
% Below Poverty:	3.0%
# Low Income:	1533
% Low Income:	1.6%
Meidan Income:	1573
# Unemployed:	193
% Unemployed:	12.6%
# Vacant Housing:	186
% Vacant Housing:	13.0%

---

17 **OSBR LAND LLC - SOUTHERN ENVIRONMENTAL MANAGEMENT** **LA UST** **U004222516**
1320 HIGHLAND RD **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	20655
Subject Item ID:	1
UST Tank Num:	35923
Tank Status:	**Removed**
Install Date:	07/26/1969
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

OSBR LAND LLC - SOUTHERN ENVIRONMENTAL MANAGEMENT & SPECIALT (Continued) **U004222516**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35924
Tank Status:	**Removed**
Install Date:	07/26/1969
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35925
Tank Status:	**Removed**
Install Date:	07/26/1969
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

OSBR LAND LLC - SOUTHERN ENVIRONMENTAL MANAGEMENT & SPECIALT (Continued) **U004222516**

Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35926
Tank Status:	**Removed**
Install Date:	07/26/1969
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

17 **HIGHLAND GULF INC.** **LA HIST LUST** **U000219977**
1320 HIGHLAND RD **LA VCP** **N/A**
BATON ROUGE, LA 70802 **LA NPDES**
LA REM

HIST LUST:

Facility ID:	17-012599
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	08/02/1989

HIGHLAND GULF INC. (Continued) **U000219977**

Date Confirmed 2:	Not reported
Incident Number:	89-2-0026
Incident Date:	07/24/1989
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00467400
Owner Name:	FULLER, RAYMOND T.
Owner Address:	9635 SOUTHLAWN DRIVE
Owner City,St,Zip:	BATON ROUGE, LA 70810
Assessment Pending Info:	Yes
Assessment Request Date:	07/27/1989
Assessment Plan Due Date:	10/17/1989
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	04/02/1991
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: GASOLINE VAPORS ENCOUNTERED IN NE CORNER OF SITE WHILE EXCAVATING FORA NEW SIGN. FREE PHASE DOUND IN SEWER LINE. DEQ CONTRACTED IT CORP.TO PERFORM EMERGENCY CLEAN UP.

LA HIST LUST CORRECTIVE ACTION:
Comments: GRAVEL TRENCH SYSTEM INSTALLED. AIR STRIPPER USED TO TREAT RECOVERDCONTAMINATED GROUNDWATER. REC'D OCTOBER 1990 REMEDIATL REPORT.USTS ARE SCHEDULED FOR REMOVAL.

Facility ID:	17-012599
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	89-2-0026
Incident Date:	07/24/1989
Type of Incident:	Not reported
Type of Incident No2:	Not reported

HIGHLAND GULF INC. (Continued) **U000219977**

Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00467400
Owner Name: FULLER, RAYMOND T.
Owner Address: 9635 SOUTHLAWN DRIVE
Owner City,St,Zip: BATON ROUGE, LA 70810
Assessment Pending Info: Yes
Assessment Request Date: 07/27/1989
Assessment Plan Due Date: 10/17/1989
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: 04/02/1991
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: GASOLINE VAPORS ENCOUNTERED IN NE CORNER OF SITE WHILE EXCAVATING FORA NEW SIGN. FREE PHASE DOUND IN SEWER LINE. DEQ CONTRACTED IT CORP.TO PERFORM EMERGENCY CLEAN UP.

LA HIST LUST CORRECTIVE ACTION:
Comments: GRAVEL TRENCH SYSTEM INSTALLED. AIR STRIPPER USED TO TREAT RECOVERDCONTAMINATED GROUNDWATER. REC'D OCTOBER 1990 REMEDIATL REPORT.USTS ARE SCHEDULED FOR REMOVAL.

VCP:
DEQ AI #: 20655
Date Closed: 09/28/2010
Site Also Known As: Not reported
Facility Parish: East Baton Rouge
Acres: 1
Applicant name: OSBR Land LLC
DEQ Contact: Duane Wilson
Date of Applicantion: 05/08/2009
Remedial Investigaton/Action Phase: Action Phase - Partial
Status: NFA/COC
Unrestricted Use: Yes
Investigation Approval Date: Not reported
Use Restrictions/Institutional Controls A: Not reported
Use Restrictions/Institutional Controls B: Not reported
Use Restrictions/Institutional Controls C: Not reported

HIGHLAND GULF INC. (Continued) **U000219977**

Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.18505600
Longitude:	30.43591700

DEQ AI #:	20655
Date Closed:	09/28/2010
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	1
Applicant name:	OSBR Land LLC
DEQ Contact:	Duane Wilson
Date of Applicantion:	05/08/2008
Remedial Investigaton/Action Phase:	Remedial Investigaton
Status:	NFA/COC
Unrestricted Use:	Yes
Investigation Approval Date:	03/06/2009
Use Restrictions/Institutional Controls A:	Not reported
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.18505600
Longitude:	30.43591700

NPDES:

Facility Id:	20655
Facility Phone:	Not reported
Issued Date:	11/04/2009
Title Description:	Permit
Permit Type Description:	Gen-LAG30-UST Dewatering
Program:	Water
Activity Number:	GEN20090001

REM:

AI Num:	20655
Evaluated And Closed:	09/28/2010
Program:	VRP
EAC Type:	Granted VRP Completion Certificate
Comments:	EDMS ID 7677520.

AI Num:	20655
Evaluated And Closed:	09/28/2010
Program:	VRP
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 7677520

17 **PIPES JAS M C O** **EDR Hist Auto** **1013767226**
452 TERRACE ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	PIPES JAS M C O	AUTOMOBILE REPAIRING
1955	PIPES JAS M AUTO REPR	AUTOMOBILE REPAIRING

---

17 **DAVIS LIONEL ESSO SERVICE STN** **EDR Hist Auto** **1013762256**
1254 HIGHLAND **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1955	AUMILLERS ESSO SERV	GASOLINE SERVICE STATIONS
1960	DAVIS LIONEL ESSO SERVICENTER	GASOLINE STATIONS
1969	DAVIS LIONEL ESSO SERVICE STN	Gasoline Service Stations
1970	DAVIS LIONEL ESSO SERVICE STN	Gasoline Service Stations

---

17 **BATON ROUGE MUNICIPAL DOCK - LDEQ** **US BROWNFIELDS FINDS** **1012109047**
1100 - 1300 RIVER ROAD **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	R6 Brownfields TBA (previously Superfund TBA)
Grant type:	TBA
Property name:	BATON ROUGE MUNICIPAL DOCK - LDEQ
Property #:	Not reported
Parcel size:	15.26
Property Description:	The site was occupied by Capital City Oil Mill until around 1923. The dock was constructed in the 1920s and was used as a port until around 1960. A storm water pump station is located near the center of the property. The pump station is used for drainage of stormwater from downtown Baton Rouge into the Mississippi River. The docks have been vacant since the 1960s. The dock structure is still in place (PPF - Baton Rouge Municipal Dock, 7/19/06).
Latitude:	30.436731
Longitude:	-91.190806
HCM label:	Address Matching-House Number
Map scale:	Not reported
Point of reference:	Not reported
Datum:	World Geodetic System of 1984
ACRES property ID:	37542
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	4411
Assessment funding source:	US EPA - TBA Funding
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	State Brownfields Assessment Grant

BATON ROUGE MUNICIPAL DOCK - LDEQ (Continued) **1012109047**

Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	n/a
Ownership entity:	Government
Current owner:	City of Baton Rouge
Did owner change:	N
Cleanup required:	Unknown
Video available:	No
Photo available:	Yes
Institutional controls required:	U
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Not reported
Lead contaminant found:	Y
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported

BATON ROUGE MUNICIPAL DOCK - LDEQ (Continued) **1012109047**

Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	381
% Below Poverty:	2.6%
# Low Income:	635
% Low Income:	1.6%
Meidan Income:	6855
# Unemployed:	96
% Unemployed:	10.4%
# Vacant Housing:	66
% Vacant Housing:	15.2%

FINDS:

Registry ID: 110038750205

Environmental Interest/Information System

BATON ROUGE MUNICIPAL DOCK - LDEQ (Continued) **1012109047**

US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 **VAUGHN MARSHALL AUTO REPR** **EDR Hist Auto** **1013764704**
1200 HIGHLAND RD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1945	VAUGHN MARSHALL AUTO REPR	AUTOMOBILE REPAIRING

---

17 **CLEARWATER FLUIDS RECYCLING INC.** **SEMS** **1000893493**
1001 SOUTH FIRST ST. **LIENS 2** **LA0000383075**
BATON ROUGE, LA 70801 **PRP**

SEMS:

Site ID:	604867
EPA ID:	LA0000383075
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0604867
EPA ID:	LA0000383075
Facility County:	EAST BATON ROUGE
Short Name:	CLEARWATER FLUIDS RECYCLI
Congressional District:	08
IFMS ID:	06AC
SMSA Number:	0760
USGC Hydro Unit:	08070201
Federal Facility:	Not a Federal Facility
DMNSN Number:	0.00000
Site Orphan Flag:	Y
RCRA ID:	Not reported
USGS Quadrangle:	Not reported
Site Init By Prog:	Not reported
NFRAP Flag:	Not reported
Parent ID:	Not reported
RST Code:	Not reported
EPA Region:	06
Classification:	Not reported
Site Settings Code:	Not reported
NPL Status:	Not on the NPL
DMNSN Unit Code:	Not reported
RBRAC Code:	Not reported
RResp Fed Agency Code:	Not reported
Non NPL Status:	NFRAP-Site does not qualify for the NPL based on existing information
Non NPL Status Date:	04/05/02
Site Fips Code:	22033

CLEARWATER FLUIDS RECYCLING INC. (Continued) **1000893493**

CC Concurrence Date: / /
CC Concurrence FY: Not reported
Alias EPA ID: Not reported
Site FUDS Flag: Not reported

CERCLIS Site Contact Name(s):

Contact ID: 6000055.00000
Contact Name: CRAIG CARROLL
Contact Tel: (214) 665-2220
Contact Title: On-Scene Coordinator (OSC)
Contact Email: Not reported

Contact ID: 6270175.00000
Contact Name: Philip Ofosu
Contact Tel: (214) 665-3178
Contact Title: Site Assessment Manager (SAM)
Contact Email: Not reported

Alias Comments: Not reported
Site Description: 14 LARGE TANKS WITH HAZ. WASTE. TANKS LEAKING

CERCLIS Assessment History:

Action Code: 001
Action: DISCOVERY
Date Started: / /
Date Completed: 06/27/94
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: State, Fund Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: LIEN ON POTENTIALLY RESPONSIBLE PARTY PROPERTY
Date Started: / /
Date Completed: 09/21/94
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: REMOVAL
Date Started: 07/11/94
Date Completed: 08/30/95
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Emergency
Action Anomaly: Not reported

CLEARWATER FLUIDS RECYCLING INC. (Continued) **1000893493**

Action Code:	001
Action:	NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH
Date Started:	07/11/94
Date Completed:	09/30/95
Priority Level:	No PRPs Identified
Operable Unit:	SITEWIDE
Primary Responsibility:	Federal Enforcement
Planning Status:	Primary
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

Action Code:	002
Action:	NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH
Date Started:	07/15/97
Date Completed:	04/17/98
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	Federal Enforcement
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

Action Code:	001
Action:	ISSUE REQUEST LETTERS (104E)
Date Started:	/ /
Date Completed:	04/17/98
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	Federal Enforcement
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

Action Code:	001
Action:	Notice Letters Issued
Date Started:	/ /
Date Completed:	04/17/98
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	Federal Enforcement
Planning Status:	Not reported
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

Action Code:	001
Action:	REMOVAL NEGOTIATIONS
Date Started:	/ /
Date Completed:	04/17/98
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	Federal Enforcement
Planning Status:	Not reported
Urgency Indicator:	Not reported

CLEARWATER FLUIDS RECYCLING INC. (Continued) **1000893493**

Action Anomaly: Not reported

Action Code: 002
Action: REMOVAL
Date Started: 04/07/98
Date Completed: 02/05/99
Priority Level: Stabilized
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Approved
Urgency Indicator: Time Critical
Action Anomaly: Not reported

Action Code: 002
Action: ISSUE REQUEST LETTERS (104E)
Date Started: / /
Date Completed: 01/30/01
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: COMBINED PRELIMINARY ASSESSMENT/SITE INSPECTION
Date Started: / /
Date Completed: 04/06/01
Priority Level: Higher priority for further assessment
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: EXPANDED SITE INSPECTION
Date Started: / /
Date Completed: 04/05/02
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information
Operable Unit: SITEWIDE
Primary Responsibility: EPA Fund-Financed
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 001
Action: COST RECOVERY NEGOTIATIONS
Date Started: 08/01/00
Date Completed: 03/13/03
Priority Level: Not reported
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported

CLEARWATER FLUIDS RECYCLING INC. (Continued) **1000893493**

Urgency Indicator: Not reported
Action Anomaly: Not reported

Action Code: 003
Action: NON-NATIONAL PRIORITIES LIST POTENTIALLY RESPONSIBLE PARTY SEARCH
Date Started: 10/17/00
Date Completed: 03/13/03
Priority Level: Viable PRPs - Cannot Do Work
Operable Unit: SITEWIDE
Primary Responsibility: Federal Enforcement
Planning Status: Not reported
Urgency Indicator: Not reported
Action Anomaly: Not reported

LIENS 2:

Facility name: CLEARWATER FLUIDS RECYCLING INC.
Facility address: 1001 SOUTH FIRST ST.
BATON ROUGE, LA 70801
EPA ID: LA0000383075
Effective date: Not reported
Lien: LP001
Party name: Not reported
Reg: 06
Release date: Not reported
Start date: Not reported
Complete date: 09/21/1994

Facility name: CLEARWATER FLUIDS RECYCLING INC.
Facility address: 1001 SOUTH FIRST STREET
BATON ROUGE, LA
EPA ID: LA0000383075
Effective date: Not reported
Lien: LP002
Party name: MCCRARY, EDWARD W.
Reg: 06
Release date: Not reported
Start date: 07/11/2000
Complete date: Not reported

PRP:

PRP name: HENRIETTA MCCRARY
MCCRARY, EDWARD W.

---

17 **PORTER DAVID B MECH** **EDR Hist Auto** **1013776234**
501 JULIA ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Auto

Year:	Name:	Type:
1975	PORTER DAVID B MECH	AUTOMOBILE REPAIRING

17 LA VOTECH JAMES M FRAZIER CNTR — **RCRA-SQG** — **1000262914**
555 JULIA ST — **FINDS** — **LAD982289365**
BATON ROUGE, LA 70802 — **ECHO**

RCRA-SQG:

Date form received by agency:	08/24/1987
Facility name:	LA VOTECH JAMES M FRAZIER CNTR
Facility address:	555 JULIA ST BATON ROUGE, LA 70802
EPA ID:	LAD982289365
Mailing address:	JULIA ST BATON ROUGE, LA 70802
Contact:	JOSEPH WRIGHT
Contact address:	555 JULIA ST BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 342-6828
Contact email:	Not reported
EPA Region:	06
Land type:	Other land type
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	JAMES M FRAZIER SR VO
Owner/operator address:	555 JULIA ST BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

LA VOTECH JAMES M FRAZIER CNTR (Continued) **1000262914**

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/02/2011
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003307644

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000262914
Registry ID: 110003307644
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003307644

---

17 **CAPONES AUTOMOTIVE SERV** **EDR Hist Auto** **1013756458**
510 MYRTLE ST **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1950	MARGOT BRAKE & SPRING	AUTOMOBILE REPAIRING
1955	CAPONES AUTOMOTIVE SERV	AUTOMOBILE REPAIRING

---

17 **JOHNNYS WASHETTE** **EDR Hist Cleaner** **1013780727**
633 MYRTLE ST **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1966	JOHNNYS WASHETTE	LAUNDRIES-SELF SERVE

17 **CHEVRON USA BATON ROUGE PLANT** **LA DEL SHWS** **S117324513**
1059 BRICKYARD LN **N/A**
BATON ROUGE, LA 70802

DEL SHWS:

Program:	Confirmed
EAC Type:	Approve Completion NFA w/ BOD
AI #:	1429
Evaluated And Closed:	10/15/2015
Comments:	EDMS ID 9965846

---

17 **CHEVRON USA BATON ROUGE PLANT** **LA REM** **S117324437**
1059 BRICKYARD LN **N/A**
BATON ROUGE, LA 70802

REM:

AI Num:	1429
Evaluated And Closed:	10/15/2015
Program:	Confirmed
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 9965846

---

17 **CHEM RAIL TRANSPORTING TRANSFER SITE** **RCRA NonGen / NLR** **1000864373**
1001 BRICKYARD LN **FINDS** **LAD985227222**
BATON ROUGE, LA 70802 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	05/27/1993
Facility name:	CHEM RAIL TRANSPORTING TRANSFER SITE
Facility address:	1001 BRICKYARD LN BATON ROUGE, LA 70802
EPA ID:	LAD985227222
Mailing address:	CHOCTAW BATON ROUGE, LA 70816
Contact:	KENNY WEBER
Contact address:	12649 CHOCTAW BATON ROUGE, LA 70816
Contact country:	US
Contact telephone:	(225) 273-4555
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	CHEM RAIL TRANSPORT
Owner/operator address:	12692 SHAWNEE MISSION PKWY SHAWNEE, KS 66216
Owner/operator country:	Not reported
Owner/operator telephone:	(913) 631-5912
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

CHEM RAIL TRANSPORTING TRANSFER SITE (Continued) **1000864373**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: Yes
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Violation Status: No violations found

FINDS:

Registry ID: 110003344355

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000864373
Registry ID: 110003344355
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003344355

---

17 DIVISION OF ADMIN STATE PRINTING **RCRA-CESQG** **1005416456**
950 BRICKYARD LN **FINDS** **LAR000048785**
BATON ROUGE, LA 70802 **ECHO**

RCRA-CESQG:
Date form received by agency: 09/02/2015
Facility name: DIVISION OF ADMIN STATE PRINTING
Facility address: 950 BRICKYARD LN
BATON ROUGE, LA 70802
EPA ID: LAR000048785
Mailing address: PO BOX 94095
BATON ROUGE, LA 70804
Contact: KENNY FLOYD
Contact address: PO BOX 94095
BATON ROUGE, LA 70804
Contact country: US
Contact telephone: (225) 219-9570
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator

DIVISION OF ADMIN STATE PRINTING (Continued) **1005416456**

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	STATE OF LOUISIANA
Owner/operator address:	950 BRICKYARD LN BATON ROUGE, LA 70802
Owner/operator country:	US
Owner/operator telephone:	(225) 219-9570
Legal status:	State
Owner/Operator Type:	Operator
Owner/Op start date:	09/02/2015
Owner/Op end date:	Not reported

Owner/operator name:	STATE OF LOUISIANA
Owner/operator address:	950 BRICKYARD LN BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 219-9570
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

DIVISION OF ADMIN STATE PRINTING (Continued) **1005416456**

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Historical Generators:
Date form received by agency: 03/19/2002
Site name: DIVISION OF ADMIN STATE PRINTING
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110012218108

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1005416456
Registry ID: 110012218108
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110012218108

---

17 **RIDLEY JOE TAILOR & CLEANERS** **EDR Hist Cleaner** **1013784556**
1005 HIGHLAND RD **N/A**
BATON ROUGE, LA 70802

EDR Hist Cleaner

Year:	Name:	Type:
1970	RIDLEY JOE TAILOR & CLEANERS	CLEANERS AND DYERS

17 **LA SPILLS** **S108601459**
N/A

746 HIGHLAND PLANTATION RD., 754 PLANTATION RIDGE LANE
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	07/24/2004
Date Initiated:	Not reported
aiid:	25205
Incident Id:	72309
Incident Date:	07/24/2004
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	746 Highland Plantation Rd., 754 Plantation Ridge Lane Baton Rouge
Incident Source Name:	Department of Public Works
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c04-2219 Sewage overflow...ongoing problem. col
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

17 **RIDLEY JOS C DCLO CLNR** **EDR Hist Cleaner** **1013784557**
1005 ST FERDINAND ST **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1931	RIDLEY JOS C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS
1936	RIDLEY JOS C DCLO CLNR	CLOTHES PRESSERS AND CLEANERS

---

17 **HERBS TEXACO SERVICE STATION** **EDR Hist Auto** **1020329489**
605 S ALEXANDER ST **N/A**
BATON ROUGE, LA 70806

EDR Hist Auto

Year:	Name:	Type:
1973	HERBS TEXACO SERVICE STATION	Gasoline Service Stations
1974	HERBS TEXACO SERVICE STATION	Gasoline Service Stations
1975	HERBS TEXACO SERVICE STATION	Gasoline Service Stations

17 **COMPUTERS FOR LA KIDS C/O CORPORATE RECYCLING COUN** **LA SWRCY** **S106449671**
800 ST. PHILLIP STREET **N/A**
BATON ROUGE, LA 70802

LA SWRCY:

Mailing Address:	Not reported
Parish:	East Baton Rouge
Contact:	Not reported
Contact Phone:	225-379-3577
Contact Fax:	Not reported
Contact Email:	Not reported
Material Accepted:	Electronics

Mailing Address:	Not reported
Parish:	East Baton Rouge
Contact:	Jay Thomas
Contact Phone:	225-379-3579
Contact Fax:	Not reported
Contact Email:	Not reported
Material Accepted:	Electronics

Mailing Address:	Not reported
Parish:	East Baton Rouge
Contact:	Jay Thomas
Contact Phone:	225-379-3577
Contact Fax:	Not reported
Contact Email:	Not reported
Material Accepted:	Computers

Mailing Address:	Not reported
Parish:	East Baton Rouge
Contact:	Not reported
Contact Phone:	225-379-3578
Contact Fax:	Not reported
Contact Email:	Not reported
Material Accepted:	Printers

---

17 **VBC BUILDING** **LA UST** **U000879784**
800 ST PHILLIPS ST **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	68619
Subject Item ID:	1
UST Tank Num:	38066
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

VBC BUILDING (Continued) **U000879784**

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	38067
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

17 BATON ROUGE POLICE DEPT PHOTO LAB — **RCRA-CESQG, FINDS, ECHO** — **1004712103 / LAD985220110**
704 MAYFLOWER RM 205
BATON ROUGE, LA 70802

RCRA-CESQG:

Date form received by agency:	09/04/2013
Facility name:	BATON ROUGE POLICE DEPT PHOTO LAB
Facility address:	704 MAYFLOWER RM 205 BATON ROUGE, LA 70802
EPA ID:	LAD985220110
Mailing address:	MAYFLOWER RM 205 BATON ROUGE, LA 70802
Contact:	CD GIGLIO
Contact address:	MAYFLOWER RM 205 BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 389-3896
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BATON ROUGE POLICE
Owner/operator address:	704 MAYFLOWER BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 389-3896
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	BATON ROUGE POLICE
Owner/operator address:	704 MAYFLOWER BATON ROUGE, LA 70802
Owner/operator country:	US
Owner/operator telephone:	(225) 389-3896
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

BATON ROUGE POLICE DEPT PHOTO LAB (Continued) **1004712103**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 08/14/1992
Site name: BATON ROUGE POLICE DEPT PHOTO LAB
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003339370

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004712103
Registry ID: 110003339370
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003339370

17 GULF SERVICE STATION FILLING — **EDR Hist Auto** — **1013774659**
701 ST FERDINAND ST — **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1940	GULF SERVICE STATION FILLING	GASOLINE AND OIL SERVICE STATIONS
1945	DUNCANS GULF SERVICE	GASOLINE AND OIL SERVICE STATIONS
1950	BONGYS THREE POINT GULF SERV	GASOLINE STATIONS
1955	THREE POINT GULF SERV	GASOLINE SERVICE STATIONS

---

17 LUNAR GRAPHICS INC — **RCRA-CESQG** — **1004710895**
655 ST FERDINAND — **FINDS** — **LAD985199256**
BATON ROUGE, LA 70802 — **ECHO**

RCRA-CESQG:

Date form received by agency:	02/14/2000
Facility name:	LUNAR GRAPHICS INC
Facility address:	655 ST FERDINAND BATON ROUGE, LA 70802
EPA ID:	LAD985199256
Mailing address:	ST FERDINAND BATON ROUGE, LA 70802
Contact:	CONNIE BLANCHARD
Contact address:	655 ST FERDINAND BATON ROUGE, LA 70802
Contact country:	US
Contact telephone:	(225) 383-7652
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	EDNA ST JULEIN
Owner/operator address:	655 ST FERDINAND BATON ROUGE, LA 70802
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 383-7652
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

LUNAR GRAPHICS INC (Continued) **1004710895**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003326829

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004710895
Registry ID:	110003326829
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003326829

---

17 **RICHARDS PRINTING** **RCRA-CESQG** **1004706921**
603 ST CHARLES ST **FINDS** **LA0000009811**
BATON ROUGE, LA 70802 **ECHO**

RCRA-CESQG:

Date form received by agency:	09/17/1993
Facility name:	RICHARDS PRINTING
Facility address:	603 ST CHARLES ST BATON ROUGE, LA 70802
EPA ID:	LA0000009811
Mailing address:	ST CHARLES ST BATON ROUGE, LA 70802
Contact:	RICHARD KATER
Contact address:	603 ST CHARLES ST

RICHARDS PRINTING (Continued) **1004706921**

BATON ROUGE, LA 70802
Contact country: US
Contact telephone: (225) 383-1376
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: RICHARDS PRINTING
Owner/operator address: 603 ST CHARLES ST
BATON ROUGE, LA 70802
Owner/operator country: Not reported
Owner/operator telephone: (225) 383-1376
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003257341

RICHARDS PRINTING (Continued) **1004706921**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004706921
Registry ID:	110003257341
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003257341

---

17 **BATON ROUGE CHECK CASHING #3** **LA HIST LUST** **U001898193**
602 ST CHARLES **LA UST** **N/A**
BATON ROUGE, LA 70802

HIST LUST:

Facility ID:	17-013648
Facility Parish:	EAST BATON ROUGE
Substance Name:	UNKNOWN
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	06/25/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0208
Incident Date:	06/25/1991
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00573900
Owner Name:	ARMSTRONG PAULSEN G.
Owner Address:	9777 HIGHLAND RD
Owner City,St,Zip:	BATON ROUGE, LA 70810
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CK ASSOCIATES INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/02/1999
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported

BATON ROUGE CHECK CASHING #3 (Continued) **U001898193**

Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ GRANTED CLOUSRE OF (1) 500 GL USED OIL UST, (2) 2000 GL GASOLINEUST, (1) 1000 GL GASOLINE UST AND (1) 3000 GL GASOLINE UST ON 2/18/95DEQ LETTER 9/2/99: REVIEW OF FILES INDICATE NO FURTHER REMEDIATION ISWARRANTED FOR THIS INCIDENT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-013648
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-2-0208
Incident Date: 06/25/1991
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00573900
Owner Name: ARMSTRONG PAULSEN G.
Owner Address: 9777 HIGHLAND RD
Owner City,St,Zip: BATON ROUGE, LA 70810
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: CK ASSOCIATES INC.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 09/02/1999
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

BATON ROUGE CHECK CASHING #3 (Continued) **U001898193**

Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DEQ GRANTED CLOUSRE OF (1) 500 GL USED OIL UST, (2) 2000 GL GASOLINEUST, (1) 1000 GL GASOLINE UST AND (1) 3000 GL GASOLINE UST ON 2/18/95DEQ LETTER 9/2/99: REVIEW OF FILES INDICATE NO FURTHER REMEDIATION ISWARRANTED FOR THIS INCIDENT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:

Master Agency Id:	76669
Subject Item ID:	1
UST Tank Num:	39513
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	39514
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

BATON ROUGE CHECK CASHING #3 (Continued) **U001898193**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	39515
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	39516
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	1000
Number Of Compartments:	1

BATON ROUGE CHECK CASHING #3 (Continued) **U001898193**

Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

17 **CATFISH TOWN** **LA UST** **U003299535**
100 FRANCE ST **N/A**
BATON ROUGE, LA 70802

UST:

Master Agency Id:	79575
Subject Item ID:	1
UST Tank Num:	51730
Tank Status:	**Removed**
Install Date:	01/01/1990
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported

CATFISH TOWN (Continued) **U003299535**

Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

17 ILLINOIS CTRL GULF RR CO **RCRA NonGen / NLR** **1000258214**
111 FRANCIS ST **FINDS** **LAD053785382**
BATON ROUGE, LA 70821 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	08/18/1980
Facility name:	ILLINOIS CTRL GULF RR CO
Facility address:	111 FRANCIS ST BATON ROUGE, LA 70821
EPA ID:	LAD053785382
Mailing address:	N MICHIGAN AVE CHICAGO, IL 60601
Contact:	GARY COKER
Contact address:	233 N MICHIGAN AVE CHICAGO, IL 60601
Contact country:	US
Contact telephone:	(312) 565-1600
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ILLINOIS CENTRAL GULF RAILROAD COMPANY
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

ILLINOIS CTRL GULF RR CO (Continued) **1000258214**

Violation Status: No violations found

FINDS:

Registry ID: 110003274803

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000258214
Registry ID: 110003274803
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003274803

---

17 **CHEVRON FOOD MART #2** **LA UST** **U003925568**
510 ST FERDINAND ST **N/A**
BATON ROUGE, LA 70802

UST:
Master Agency Id: 76172
Subject Item ID: 2

UST Tank Num: 1789
Tank Status: **Removed**
Install Date: 01/01/1980
Total Capacity: 2000
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Yes
Gasohol: Not reported
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported
Steel Tank Covered With Asphalt: Yes
Cathodically Protected: Not reported
Epoxy Coated Tank: Not reported
A Composite Of Different Materials: Not reported
Fiberglass Or Plastic: Not reported
Interior Line With Some Material: Not reported
Double Wall As Opposed To Single Wall: Not reported
Outside Lined w/ Polyethylen Jacket: Not reported
Made Of Concrete: Not reported

CHEVRON FOOD MART #2 (Continued) **U003925568**

Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	1790
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	1791
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported

CHEVRON FOOD MART #2 (Continued) **U003925568**

Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	1792
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	40212
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported

CHEVRON FOOD MART #2 (Continued) **U003925568**

MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	40213
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	40214
Tank Status:	**Active**
Install Date:	07/01/1992
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported

CHEVRON FOOD MART #2 (Continued) **U003925568**

Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

17 **CATFISH TOWN CHEVRON** **LA HIST LUST** **S106034411**
510 SAINT FERDINAND ST **N/A**
BATON ROUGE, LA 70821

HIST LUST:

Facility ID:	17-000729
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	40-100 GAL
Quantity 2:	Not reported
Date Confirmed:	09/21/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0195
Incident Date:	09/21/1990
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	ROSS WILLIAMS/ DEQ EMER. RESP.
Reported By 2:	Not reported
Owner ID:	00022200
Owner Name:	BATON ROUGE OIL CO (MORELLA CO)
Owner Address:	10319 OLD HAMMOND - SUITE B-1
Owner City,St,Zip:	BATON ROUGE, LA 70816
Assessment Pending Info:	Yes
Assessment Request Date:	09/27/1990
Assessment Plan Due Date:	12/17/1990
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ENVIRONMENTAL CONSULTING & TECHNOLOGY
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported

CATFISH TOWN CHEVRON (Continued) **S106034411**

Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	06/27/1994
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: MR WILLIAMS HEARD FROM BR FIRE DEPT THAT THERE WAS A SPILL.GAS WAS COMING OUT OF FILL PORT WHEN GAS WAS BEING DELIVEREDA VAPOR LOCK HAPPENED AND PUSHED GAS BACK OUT OF FILL PORTWHEN HOSE WAS REMOVED. VAPOR RECOVERY. THIS IS THE 3RD TIME THISHAPPENED THIS YEAR. THIS YEAR. REC'D UST REMOVAL AND CLOSURE REPORT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-000729
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	90-2-0195
Incident Date:	09/21/1990
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00022200
Owner Name:	BATON ROUGE OIL CO (MORELLA CO)
Owner Address:	10319 OLD HAMMOND - SUITE B-1
Owner City,St,Zip:	BATON ROUGE, LA 70816
Assessment Pending Info:	Yes
Assessment Request Date:	09/27/1990
Assessment Plan Due Date:	12/17/1990
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ENVIRONMENTAL CONSULTING & TECHNOLOGY
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	06/27/1994
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported

CATFISH TOWN CHEVRON (Continued) **S106034411**

Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: MR WILLIAMS HEARD FROM BR FIRE DEPT THAT THERE WAS A SPILL.GAS WAS COMING OUT OF FILL PORT WHEN GAS WAS BEING DELIVEREDA VAPOR LOCK HAPPENED AND PUSHED GAS BACK OUT OF FILL PORTWHEN HOSE WAS REMOVED. VAPOR RECOVERY. THIS IS THE 3RD TIME THISHAPPENED THIS YEAR. THIS YEAR. REC'D UST REMOVAL AND CLOSURE REPORT.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

---

17 **CAPITAL PARK CDC BR107** **US BROWNFIELDS** **1016350986**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	CAPITAL PARK CDC BR107
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14533
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	No
Video available:	Not reported

CAPITAL PARK CDC BR107 (Continued) **1016350986**

Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

CAPITAL PARK CDC BR107 (Continued) **1016350986**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039529953

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

17 **5321 GREENWELL SPRINGS RD, BR108**
500 ST LOUIS ST
BATON ROUGE, LA 70802

US BROWNFIELDS FINDS | **1016350987** / **N/A**

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	5321 GREENWELL SPRINGS RD, BR108
Property #:	Not reported
Parcel size:	3
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14534
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Not reported
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported

5321 GREENWELL SPRINGS RD, BR108 (Continued) **1016350987**

Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported

5321 GREENWELL SPRINGS RD, BR108 (Continued) **1016350987**

Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039529962

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 DEFRANCES MARBLE **US BROWNFIELDS** **1016350977**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	DEFRANCES MARBLE
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14525
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported

DEFRANCES MARBLE (Continued) **1016350977**

Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	12/31/2002 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported

DEFRANCES MARBLE (Continued) **1016350977**

Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96

DEFRANCES MARBLE (Continued) **1016350977**

% Unemployed: 9.8%
# Vacant Housing: 63
% Vacant Housing: 14.9%

FINDS:

Registry ID: 110039529855

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 HUE'S SEAFOOD **US BROWNFIELDS 1016352321**
500 ST LOUIS ST **FINDS N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	HUE'S SEAFOOD
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14524
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	12/31/2002 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported

HUE'S SEAFOOD (Continued) **1016352321**

Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

HUE'S SEAFOOD (Continued) **1016352321**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039549753

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

17 BROUSSARD PAINT
500 ST LOUIS ST
BATON ROUGE, LA 70802

US BROWNFIELDS FINDS

1016350982
N/A

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	BROUSSARD PAINT
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14528
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	03/31/2003 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported

BROUSSARD PAINT (Continued) **1016350982**

Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported

BROUSSARD PAINT (Continued) **1016350982**

Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039529917

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 **CAPITAL PARK CDC BR104** **US BROWNFIELDS** **1016350985**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	CAPITAL PARK CDC BR104
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14531
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported

CAPITAL PARK CDC BR104 (Continued) **1016350985**

Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	09/30/2003 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	No
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported

CAPITAL PARK CDC BR104 (Continued) **1016350985**

Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96

CAPITAL PARK CDC BR104 (Continued) **1016350985**

% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039529944

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 NOLAN LOUIS **US BROWNFIELDS** **1016350980**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	NOLAN LOUIS
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14526
Start date:	06/30/2004 00:00:00
Completed date:	06/30/2004 00:00:00
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	12/31/2002 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported

NOLAN LOUIS (Continued) **1016350980**

Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

NOLAN LOUIS (Continued) **1016350980**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039529882

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

17 **DOC, INC.** **US BROWNFIELDS** **1016350984**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	DOC, INC.
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14530
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	03/31/2003 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Not reported
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported

DOC, INC. (Continued) **1016350984**

Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported

DOC, INC. (Continued) **1016350984**

Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039529935

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 **VACANT BS/1/36-7** **US BROWNFIELDS** **1016352320**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	VACANT BS/1/36-7
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14523
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported

VACANT BS/1/36-7 (Continued) **1016352320**

Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	12/31/2002 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported

VACANT BS/1/36-7 (Continued) **1016352320**

Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96

VACANT BS/1/36-7 (Continued) **1016352320**

% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039549744

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

17 MAC'S BODY SHOP **US BROWNFIELDS** **1016352319**
500 ST LOUIS ST **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	MAC'S BODY SHOP
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14522
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	12/31/2002 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported

MAC'S BODY SHOP (Continued) **1016352319**

Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported

MAC'S BODY SHOP (Continued) **1016352319**

Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039549735

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

17 C AND T CONTRACTORS — **US BROWNFIELDS FINDS** — **1016352318 / N/A**
500 ST LOUIS ST
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge, City of
Grant type:	Assessment
Property name:	C AND T CONTRACTORS
Property #:	Not reported
Parcel size:	Not reported
Property Description:	Not reported
Latitude:	30.44342
Longitude:	-91.186874
HCM label:	Not reported
Map scale:	Not reported
Point of reference:	Not reported
Datum:	Not reported
ACRES property ID:	14521
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	12/31/2002 00:00:00
Assessment funding entity:	Not reported
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	98661401
Ownership entity:	Not reported
Current owner:	Not reported
Did owner change:	Not reported
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	Not reported
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported

C AND T CONTRACTORS (Continued) **1016352318**

Groundwater affected:	Not reported
Groundwater cleaned:	Not reported
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Not reported
PAHs cleaned up:	Not reported
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Not reported
Petro products cleaned:	Not reported
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Not reported
Soil cleaned up:	Not reported
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	0
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported

C AND T CONTRACTORS (Continued) **1016352318**

Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	369
% Below Poverty:	2.5%
# Low Income:	594
% Low Income:	1.6%
Meidan Income:	1788
# Unemployed:	96
% Unemployed:	9.8%
# Vacant Housing:	63
% Vacant Housing:	14.9%

FINDS:

Registry ID: 110039549726

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

18 **IT CORPORATION OF LOUISIANA** **TX Ind. Haz Waste** **S104852231**
1150 LE BLANC RD **N/A**
PORT ALLEN, LA 70767

Ind. Haz Waste:

Registration Number:	40979
Registration Initial Notification Date:	10/31/1986
Registration Last Amendment Date:	09/16/2002
EPA Identification:	LAD981589773
Primary NAICS Code:	484121
Status Change Date:	19861031
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Site Primary SIC Description:	Not reported
Registration is Generator of Waste:	No
Registration is Receivers of Waste:	No
Registration is Transporter of Waste:	Yes
Registration is Transfer Facility:	No
Facility is STEERS Reporter:	No
Reqired to Submit Annual Waste Summary:	No

IT CORPORATION OF LOUISIANA (Continued) **S104852231**

Facility Involved In Recycling:	No
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator:	Not reported
TNRCC Region:	Not reported
Company Name:	IT CORPORATION
Contact Name:	GENE LOVETT
Contact Telephone Number:	504-9285100
Mailing Address:	1150 LE BLANC RD
Mailing Address2:	Not reported
Mailing City,St,Zip:	PORT ALLEN, LA 707673248
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	17380
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20020924
Ind. waste permit Number:	Not reported
Mun waste permit Number:	Not reported
Non Notifier:	No
Business Desc:	9-16-02 Return mail, not able to find anything in white pages or RCRA that wouldhelp. Inactivated SWR sc

Owner:

Owner Mailing Address:	1150 LEBLANC RD
Owner Mailing Address2:	Not reported
Owner Mailing Address3:	Not reported
Owner City,St,Zip:	PORT ALLEN, LA 70767 3248
Owner Country:	UNITED STA
Owner Phone Number:	1-504-9285100
Owner Fax Number:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax Id:	19412590531
Owner Bankruptcy Code:	Not reported

Operator:

Operator Last Name:	IT CORPORATION
Operator First Name:	Not reported
Operator Name:	IT CORPORATION
Operator Mailing Address:	1150 LEBLANC RD
Operator Mailing Address 2:	Not reported
Operator Mailing City,St,Zip:	PORT ALLEN, LA 70767 3248
Operator Country:	UNITED STA
Operator Phone:	1-504-9285100
Operator Fax:	Not reported
Operator Email:	Not reported
Operator Business Type:	Unknown
Operator Tax Id:	19412590531
Operator Bankruptcy Code:	Not reported

Contact:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OPRCON
Contact Address:	1150 LEBLANC RD
Contact Address2:	Not reported
Conact City,St,Zip:	PORT ALLEN, LA 70767 3248

IT CORPORATION OF LOUISIANA (Continued) **S104852231**

Contact Phone: 1-504-9285100
Contact Fax: Not reported
Contact Email: Not reported

Contact:
Contact Name: Not reported
Contact Title: Not reported
Contact Role: OWNCON
Contact Address: 1150 LEBLANC RD
Contact Address2: Not reported
Conact City,St,Zip: PORT ALLEN, LA 70767 3248
Contact Phone: 1-504-9285100
Contact Fax: Not reported
Contact Email: Not reported

Contact:
Contact Name: GENE LOVETT
Contact Title: ENVIRONMENTAL MANAGER
Contact Role: PRICONT
Contact Address: 1150 LEBLANC RD
Contact Address2: Not reported
Conact City,St,Zip: PORT ALLEN, LA 70767 3248
Contact Phone: 1-504-9285100
Contact Fax: Not reported
Contact Email: Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:
Receiver Type: Not reported
Transporter for hire: 1
Transport own waste: 0
Eq 01, if transport waste type = 1: Not reported
Eq 02, if transport waste type = 2: Not reported
Eq 03, if transport waste type = 3: Not reported
Eq 04, if transport waste type = H: 04
Target TCEQ unique facid for discarded(merged) facility: Not reported

Waste Records Not Found for this RegNo/Year:

---

18 **IT CORP** **RCRA NonGen / NLR** **1000180405**
1150 LEBLANC RD **FINDS** **LAD981589773**
PORT ALLEN, LA 70767 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 09/04/1986
Facility name: IT CORP
Facility address: 1150 LEBLANC RD
PORT ALLEN, LA 707673200
EPA ID: LAD981589773
Mailing address: LEBLANC
PORT ALLEN, LA 707673200
Contact: MICHAEL OUBRE
Contact address: 1150 LEBLANC
PORT ALLEN, LA 707673200
Contact country: US
Contact telephone: (225) 343-7622
Contact email: Not reported
EPA Region: 06
Land type: Private

IT CORP (Continued) **1000180405**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: IT CORPORATION
Owner/operator address: 0000000000
MONROEVILLE, PA 15146
Owner/operator country: Not reported
Owner/operator telephone: (412) 372-7701
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D009
. Waste name: MERCURY

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 10/21/1988
Date achieved compliance: 02/27/1995
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 11/28/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

IT CORP (Continued) **1000180405**

Evaluation Action Summary:

Evaluation date:	10/11/1999
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

Evaluation date:	02/27/1995
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

Evaluation date:	10/21/1988
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Generators - General
Date achieved compliance:	02/27/1995
Evaluation lead agency:	State

FINDS:

Registry ID: 110003297147

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000180405
Registry ID:	110003297147
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003297147

---

18 **UNION PACIFIC RAILROAD - PORT ALLEN YARD** **LA HIST LUST** **U001493740**
1300 LEBLANC RD **LA UST** **N/A**
PORT ALLEN, LA 70767

HIST LUST:

Facility ID:	61-014155
Facility Parish:	WEST BATON ROUGE
Substance Name:	UNKNOWN
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	12/01/1989
Date Confirmed 2:	Not reported
Incident Number:	89-2-0121
Incident Date:	Not reported
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported

UNION PACIFIC RAILROAD - PORT ALLEN YARD (Continued) **U001493740**

Reported By: UNKNOWN
Reported By 2: Not reported
Owner ID: 00301500
Owner Name: UNION PACIFIC RAILROAD
Owner Address: 1416 DODGE ST, RM 930
Owner City,St,Zip: OMAHA, NE 68179
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SITE IS MOTOR CONVOY, INC. 1300 LEBLANC RD. PORT ALLEN, LA.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 61-014155
Facility Parish: WEST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 89-2-0121
Incident Date: Not reported
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00301500
Owner Name: UNION PACIFIC RAILROAD
Owner Address: 1416 DODGE ST, RM 930
Owner City,St,Zip: OMAHA, NE 68179
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported

UNION PACIFIC RAILROAD - PORT ALLEN YARD (Continued) **U001493740**

Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SITE IS MOTOR CONVOY, INC. 1300 LEBLANC RD. PORT ALLEN, LA.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:

Master Agency Id:	68541
Subject Item ID:	1
UST Tank Num:	41145
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

UNION PACIFIC RAILROAD - PORT ALLEN YARD (Continued) **U001493740**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	41146
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	43888
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	1680
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

UNION PACIFIC RAILROAD - PORT ALLEN YARD (Continued) **U001493740**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Gravity Feed

---

18 COMPLETE AUTO TRANSIT INC **RCRA-CESQG** **1004712241**
1300 LEBLANC RD STE B **FINDS** **LAD985222348**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:

Date form received by agency:	10/14/1992
Facility name:	COMPLETE AUTO TRANSIT INC
Facility address:	1300 LEBLANC RD STE B PORT ALLEN, LA 70767
EPA ID:	LAD985222348
Mailing address:	LEBLANC RD STE B PORT ALLEN, LA 70767
Contact:	DANIEL WRIGHT
Contact address:	1300 LEBLANC RD STE B PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 344-3100
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	COMPLETE AUTO TRANS
Owner/operator address:	1300 LEBLANC RD STE B PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 344-3100
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported

COMPLETE AUTO TRANSIT INC (Continued) **1004712241**

Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110009582380

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004712241
Registry ID:	110009582380
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009582380

18 ALLIED SYSTEMS LTD — **RCRA-CESQG, FINDS, ECHO** — **1004711379, LAD985207067**
1300 LEBLANC RD
PORT ALLEN, LA 70767

RCRA-CESQG:

Date form received by agency:	09/10/1991
Facility name:	ALLIED SYSTEMS LTD
Facility address:	1300 LEBLANC RD PORT ALLEN, LA 70767
EPA ID:	LAD985207067
Mailing address:	PO BOX 439 PORT ALLEN, LA 70767
Contact:	THOMAS BOURGEOIS
Contact address:	PO BOX 439 PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 383-7113
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALLIED SYSTEMS LTD
Owner/operator address:	1300 LEBLANC RD PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 383-7113
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

ALLIED SYSTEMS LTD (Continued) **1004711379**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110003332064

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004711379
Registry ID: 110003332064
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003332064

---

19 INTERNATIONAL PIPING SYS **RCRA-CESQG** **1000216904**
1700 S WESTPORT DR **FINDS** **LAD065066300**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:
Date form received by agency: 04/03/2001
Facility name: INTERNATIONAL PIPING SYS
Facility address: 1700 S WESTPORT DR
PORT ALLEN, LA 70767
EPA ID: LAD065066300
Mailing address: PO BOX 868
PORT ALLEN, LA 70767
Contact: GEORGE BANTA
Contact address: PO BOX 868
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 376-4114
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar

INTERNATIONAL PIPING SYS (Continued) **1000216904**

month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	TURNER INDUSTRIES LTD
Owner/operator address:	8687 UNITED PLAZA BLVD BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 922-5050
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Historical Generators:

Date form received by agency:	03/16/2001
Site name:	INTERNATIONAL PIPING SYS
Classification:	Small Quantity Generator

Date form received by agency:	03/25/1988
Site name:	INTERNATIONAL PIPING SYS
Classification:	Small Quantity Generator

Facility Has Received Notices of Violations:

Regulation violated:	SR - LAC33V2109.A
Area of violation:	Generators - Pre-transport

INTERNATIONAL PIPING SYS (Continued) **1000216904**

Date violation determined: 03/02/2001
Date achieved compliance: 03/14/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1119
Area of violation: Generators - General
Date violation determined: 03/02/2001
Date achieved compliance: 03/14/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1105.B
Area of violation: Generators - General
Date violation determined: 03/02/2001
Date achieved compliance: 03/14/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/06/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2109C
Area of violation: Generators - Records/Reporting
Date violation determined: 03/02/1994
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/24/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2111A;1109E1d
Area of violation: Generators - Pre-transport
Date violation determined: 03/02/1994

INTERNATIONAL PIPING SYS (Continued) **1000216904**

Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/24/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1111B1e
Area of violation: Generators - Records/Reporting
Date violation determined: 03/02/1994
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/24/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V2107B
Area of violation: Generators - Pre-transport
Date violation determined: 03/02/1994
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/24/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1105B
Area of violation: Generators - Records/Reporting
Date violation determined: 03/02/1994
Date achieved compliance: 09/08/1994
Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/24/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: SR - LAC33V1119
Area of violation: Generators - General
Date violation determined: 03/02/1994
Date achieved compliance: 09/08/1994

INTERNATIONAL PIPING SYS (Continued) **1000216904**

Violation lead agency: State
Enforcement action: FINAL 3008(A) COMPLIANCE ORDER
Enforcement action date: 05/24/1994
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:

Evaluation date: 03/02/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 03/14/2001
Evaluation lead agency: State

Evaluation date: 03/02/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 03/14/2001
Evaluation lead agency: State

Evaluation date: 09/08/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - General
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 09/08/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - Pre-transport
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 09/08/1994
Evaluation: COMPLIANCE SCHEDULE EVALUATION
Area of violation: Generators - Records/Reporting
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 03/02/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Pre-transport
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 03/02/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - Records/Reporting
Date achieved compliance: 09/08/1994
Evaluation lead agency: State

Evaluation date: 03/02/1994
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 09/08/1994

INTERNATIONAL PIPING SYS (Continued) **1000216904**

Evaluation lead agency: State

Evaluation date: 04/26/1990
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003276589

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000216904
Registry ID: 110003276589
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003276589

---

20 SOUTHERN RECYCLING LLC **RCRA-CESQG** **1010564362**
1367 MAHAFFEY RD **FINDS** **LAR000065631**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:
Date form received by agency: 03/10/2009
Facility name: SOUTHERN RECYCLING LLC
Facility address: 1367 MAHAFFEY RD
PORT ALLEN, LA 70767
EPA ID: LAR000065631
Mailing address: PO BOX 53630
BATON ROUGE, LA 70892
Contact: TONY SCHULTZ
Contact address: PO BOX 53630
BATON ROUGE, LA 70892
Contact country: US
Contact telephone: (504) 942-0394
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting

SOUTHERN RECYCLING LLC (Continued) **1010564362**

from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SOUTHERN RECYCLING
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/10/2009
Owner/Op end date:	Not reported
Owner/operator name:	SSX LC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/1980
Owner/Op end date:	Not reported
Owner/operator name:	SOUTHERN RECYCLING
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/10/2009
Owner/Op end date:	Not reported
Owner/operator name:	SSX LC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/01/1980
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

SOUTHERN RECYCLING LLC (Continued) **1010564362**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:
Date form received by agency: 12/18/2008
Site name: SOUTHERN RECYCLING LLC
Classification: Not a generator, verified

Date form received by agency: 10/11/2007
Site name: SSX LC
Classification: Not a generator, verified

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Universal Waste - Large Quantity Handlers
Date violation determined: 04/15/2009
Date achieved compliance: 04/15/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/09/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Regulation violated: Not reported
Area of violation: Used Oil - Generators
Date violation determined: 04/15/2009
Date achieved compliance: 07/09/2009
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 07/09/2009
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

SOUTHERN RECYCLING LLC (Continued) **1010564362**

Evaluation Action Summary:

Evaluation date:	04/15/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Used Oil - Generators
Date achieved compliance:	07/09/2009
Evaluation lead agency:	State

Evaluation date:	04/15/2009
Evaluation:	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation:	Universal Waste - Large Quantity Handlers
Date achieved compliance:	04/15/2009
Evaluation lead agency:	State

FINDS:

Registry ID: 110007227526

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR EMISSIONS CLASSIFICATION UNKNOWN

Louisiana Tools for Environmental Management and Protection Organizations (LA-TEMPO) is an Integrated Management System.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1010564362
Registry ID:	110007227526
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110007227526

---

20 **SOUTHERN RECYCLING LLC - PORT ALLEN** **LA UST** **U003921807**
1367 MAHAFFEY RD **LA SPILLS** **N/A**
PORT ALLEN, LA 70767 **LA NPDES**
LA AIRS

UST:

Master Agency Id:	17683
Subject Item ID:	1
UST Tank Num:	29772
Tank Status:	**Removed**
Install Date:	05/20/1978
Total Capacity:	4000

SOUTHERN RECYCLING LLC - PORT ALLEN (Continued) **U003921807**

Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	29773
Tank Status:	**Removed**
Install Date:	05/20/1978
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported

SOUTHERN RECYCLING LLC - PORT ALLEN (Continued) **U003921807**

Pipe Method Description: Not reported

SPILLS:

Region Code:	Not reported
Date Rec:	07/22/2004
Date Initiated:	Not reported
aiid:	83605
Incident Id:	72252
Incident Date:	07/22/2004
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	Southern Scrap 1367 Mahaffey Rd
Incident Source Name:	West Baton Rouge Parish
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c04-2202 when it rains on the intercoastal canal, oil comes from Southern Scrap's scrap pile on the loading dock and goes into the water - tj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

NPDES:

Facility Id:	17683
Facility Phone:	2253554453
Issued Date:	08/03/2011
Title Description:	Permit
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20110001

Facility Id:	17683
Facility Phone:	2253554453
Issued Date:	07/12/2001
Title Description:	Fiscal Migration: LAR05M605
Permit Type Description:	Gen-LAR05-Multi-Sector
Program:	Water
Activity Number:	GEN19990001

Facility Id:	17683
Facility Phone:	2253554453
Issued Date:	03/28/2016
Title Description:	LAG48 Renewal
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20150001

Facility Id:	17683
Facility Phone:	2253554453
Issued Date:	03/28/2003
Title Description:	LAG480217 Permit

SOUTHERN RECYCLING LLC - PORT ALLEN (Continued) **U003921807**

Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN19980001

Facility Id: 17683
Facility Phone: 2253554453
Issued Date: 01/27/2012
Title Description: Permit
Permit Type Description: Gen-LAG48-Light Commercial
Program: Water
Activity Number: GEN20110002

AIRS:
Permit Number: 3120-00010-00
Permit Type Desc: State permit (unspecified)
AI No#: 17683
Activity No#: PER19870001
Region Code: Capital
Latitude: 30.436667
Longitude: -91.215833
Title Desc: PORT ALLEN,WBR PARIS
Mailing Address: PO Box 53630
Mailing Address2: Not reported
Mailing City/State/Zip: Baton Rouge, LA 708923630
Issue Date: 07/28/1987
Expiration Date: 09/30/2006
Effective End Date: 12/06/2016
Effective Flag: Y
Extended Flag: Y
EDR Link ID: 3120-00010-00

---

20 **BRAND SCAFFOLE SVCS INC** **RCRA-CESQG** **1004712333**
946 MAHAFFEY RD **FINDS** **LAD985223601**
PORT ALLEN, LA 70767 **ECHO**

RCRA-CESQG:
Date form received by agency: 12/17/1992
Facility name: BRAND SCAFFOLE SVCS INC
Facility address: 946 MAHAFFEY RD
PORT ALLEN, LA 70767
EPA ID: LAD985223601
Mailing address: PO BOX 350
PORT ALLEN, LA 70767
Contact: STEVE HAVARD
Contact address: PO BOX 350
PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 344-7825
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

BRAND SCAFFOLE SVCS INC (Continued) **1004712333**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BRAND SCAFFOLD SVC
Owner/operator address:	946 MAHAFFEY RD PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 344-7825
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110003341688

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

BRAND SCAFFOLE SVCS INC (Continued) **1004712333**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004712333
Registry ID:	110003341688
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003341688

---

21 COMMUNITY COFFEE INC **RCRA-CESQG** **1004514226**
1833 HWY 1 S **LAD125787564**
PORT ALLEN, LA 70767

RCRA-CESQG:

Date form received by agency:	03/16/1994
Facility name:	COMMUNITY COFFEE INC
Facility address:	1833 HWY 1 S PORT ALLEN, LA 70767
EPA ID:	LAD125787564
Mailing address:	LA HWY 1 S PORT ALLEN, LA 70767
Contact:	TONY DUSENBERRY
Contact address:	1833 LA HWY 1 S PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 387-5828
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	COMMUNITY COFFEE INC
Owner/operator address:	1833 LA HWY 1 S PORT ALLEN, LA 70767
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 387-5828
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

COMMUNITY COFFEE INC (Continued) **1004514226**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

---

21 **COMMUNITY COFFEE CO LLC - PORT ALLEN PLANT** **LA UST** **U003926964**
1833 HWY 1 S **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	9503
Subject Item ID:	1
UST Tank Num:	3666
Tank Status:	**Closed**
Install Date:	05/01/1971
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported

COMMUNITY COFFEE CO LLC - PORT ALLEN PLANT (Continued) **U003926964**

New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	3667
Tank Status:	**Closed**
Install Date:	05/01/1971
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

21 ANCO SHEET METAL **RCRA NonGen / NLR** **1000887795**
950 MAHAFFEY RD BLDG 4 **LA0000239368**
PORT ALLEN, LA 70767

RCRA NonGen / NLR:

Date form received by agency:	02/01/2001
Facility name:	ANCO SHEET METAL
Facility address:	950 MAHAFFEY RD BLDG 4 PORT ALLEN, LA 70767
EPA ID:	LA0000239368
Mailing address:	PO BOX 83780 BATON ROUGE, LA 70884
Contact:	RICHARD TRISLER
Contact address:	PO BOX 83780 BATON ROUGE, LA 70884
Contact country:	US
Contact telephone:	(225) 756-7674
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	ANCO INSULATIONS
Owner/operator address:	PO BOX 83780 BATON ROUGE, LA 70884
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 752-2000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: F003

ANCO SHEET METAL (Continued) **1000887795**

. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NONHALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS, AND A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F005
. Waste name: THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NONHALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: P041
. Waste name: DIETHYL-P-NITROPHENYL PHOSPHATE (OR) PHOSPHORIC ACID, DIETHYL 4-NITROPHENYL ESTER

Historical Generators:
Date form received by agency: 03/03/1994
Site name: ANCO SHEET METAL
Classification: Large Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/01/2001
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 01/31/2001
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

---

21 **DISTRIBUTION INTERNATIONAL** **RCRA-CESQG** **1010415421**
950 MAHAFFEY RD **LAD985215581**
PORT ALLEN, LA 70767

RCRA-CESQG:
Date form received by agency: 02/18/1992
Facility name: DISTRIBUTION INTERNATIONAL
Facility address: 950 MAHAFFEY RD
PORT ALLEN, LA 70767
EPA ID: LAD985215581
Mailing address: PO BOX 930
PORT ALLEN, LA 70767
Contact: RH PRICE
Contact address: PO BOX 930

DISTRIBUTION INTERNATIONAL (Continued) **1010415421**

PORT ALLEN, LA 70767
Contact country: US
Contact telephone: (225) 343-9250
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: ANCO METAL FABRICATORS
Owner/operator address: 950 MAHAFFEY
PORT ALLEN, LA 70767
Owner/operator country: Not reported
Owner/operator telephone: (225) 343-9250
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

21 **DISTRIBUTION INTERNATIONAL** **LA UST** **U000879684**
950 MAHAFFEY RD **LA NPDES** **N/A**
PORT ALLEN, LA 70767

UST:

Master Agency Id:	52309
Subject Item ID:	1
UST Tank Num:	37460
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	37461
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	5000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

DISTRIBUTION INTERNATIONAL (Continued) **U000879684**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

NPDES:

Facility Id:	39166
Facility Phone:	225-387-2871
Issued Date:	05/19/2011
Title Description:	Permit
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20110001

Facility Id:	52309
Facility Phone:	2253439250
Issued Date:	02/29/2008
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20080001

Facility Id:	52309
Facility Phone:	2253439250
Issued Date:	06/03/2011
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAR05-Multi-Sector
Program:	Water
Activity Number:	GEN20110001

Facility Id:	52309
Facility Phone:	2253439250
Issued Date:	06/30/2002
Title Description:	LA0102351 Permit
Permit Type Description:	Indiv-Minor Industrial
Program:	Water
Activity Number:	PER19980003

Facility Id:	52309
Facility Phone:	2253439250
Issued Date:	02/10/2014
Title Description:	Renewal
Permit Type Description:	Gen-LAG53-Sanitary Class I
Program:	Water
Activity Number:	GEN20120001

Facility Id:	39166
Facility Phone:	225-387-2871
Issued Date:	03/28/2016
Title Description:	LAG48 renewal

DISTRIBUTION INTERNATIONAL (Continued) **U000879684**

Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20150001
Facility Id:	52309
Facility Phone:	2253439250
Issued Date:	09/06/2016
Title Description:	MSGP Renewed Coverage
Permit Type Description:	Not reported
Program:	Water
Activity Number:	GEN20160001

---

22 **HOPE VI** **LA VCP** **S109151998**
1705 HIGHLAND RD **LA NPDES** **N/A**
BATON ROUGE, LA 70802 **LA REM**

VCP:

DEQ AI #:	93917
Date Closed:	04/02/2009
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	1
Applicant name:	Richard Murray
DEQ Contact:	Rashaunda Johnson
Date of Applicantion:	10/31/2007
Remedial Investigaton/Action Phase:	Action Phase - Partial
Status:	COC
Unrestricted Use:	Yes
Investigation Approval Date:	Not reported
Use Restrictions/Institutional Controls A:	Not reported
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.18305600
Longitude:	30.43222200
DEQ AI #:	93917
Date Closed:	04/02/2009
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	1
Applicant name:	Richard Murray
DEQ Contact:	Rashaunda Johnson
Date of Applicantion:	12/07/2005
Remedial Investigaton/Action Phase:	Remedial Investigaton - Partial
Status:	COC
Unrestricted Use:	Yes
Investigation Approval Date:	08/21/2006
Use Restrictions/Institutional Controls A:	Not reported
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported

HOPE VI (Continued) **S109151998**

Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.18305600
Longitude:	30.43222200

NPDES:

Facility Id:	93917
Facility Phone:	2259531345
Issued Date:	03/24/2010
Title Description:	Permit Reauthorization
Permit Type Description:	Gen-LAG30-UST Dewatering
Program:	Water
Activity Number:	GEN20100001

Facility Id:	93917
Facility Phone:	2259531345
Issued Date:	06/19/2008
Title Description:	Permit LAG300016
Permit Type Description:	Gen-LAG30-UST Dewatering
Program:	Water
Activity Number:	GEN20080001

REM:

AI Num:	93917
Evaluated And Closed:	04/02/2009
Program:	VRP
EAC Type:	Granted VRP Completion Certificate
Comments:	EDMS ID 6353265.

---

22 **LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV** **US BROWNFIELDS** **1016345273**
1705 HIGHLAND ROAD **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV
Property #:	0840352473- 0840352478, 0840354017
Parcel size:	.57
Property Description:	Car wash & detail shop, tire center, service station, recycling facilities.
Latitude:	30.434117
Longitude:	-91.183481
HCM label:	Address Matching-House Number
Map scale:	1:24,000
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	15138
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	2200
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement

LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV (Continued) **1016345273**

Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase I Environmental Assessment
Accomplishment count:	1
Cooperative agreement #:	97646001
Ownership entity:	Private
Current owner:	East Baton Rouge Parish Housing Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Y
Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Y
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Y
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Y
Surface water cleaned:	Not reported
VOCs found:	Not reported

LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV (Continued) **1016345273**

VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	1076
% Below Poverty:	2.9%
# Low Income:	2025
% Low Income:	1.5%
Meidan Income:	2666
# Unemployed:	249
% Unemployed:	12.4%
# Vacant Housing:	289
% Vacant Housing:	10.7%

LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV (Continued) **1016345273**

Recipient name:	Baton Rouge and Parish of East Baton Rouge, City of
Grant type:	Assessment
Property name:	LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV
Property #:	0840352473- 0840352478, 0840354017
Parcel size:	.57
Property Description:	Car wash & detail shop, tire center, service station, recycling facilities.
Latitude:	30.434117
Longitude:	-91.183481
HCM label:	Address Matching-House Number
Map scale:	1:24,000
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	15138
Start date:	Not reported
Completed date:	Not reported
Acres cleaned up:	Not reported
Cleanup funding:	Not reported
Cleanup funding source:	Not reported
Assessment funding:	24316
Assessment funding source:	US EPA - Brownfields Assessment Cooperative Agreement
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	EPA
Cleanup funding entity:	Not reported
Grant type:	N/A
Accomplishment type:	Phase II Environmental Assessment
Accomplishment count:	0
Cooperative agreement #:	97646001
Ownership entity:	Private
Current owner:	East Baton Rouge Parish Housing Authority
Did owner change:	Y
Cleanup required:	Yes
Video available:	No
Photo available:	Yes
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Unknown
State/tribal program date:	Not reported
State/tribal program ID:	Not reported
State/tribal NFA date:	Not reported
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Y
Asbestos cleaned:	Y
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Y

LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV (Continued) **1016345273**

Lead contaminant found:	Y
Lead cleaned up:	Y
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Not reported
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Not reported
Other contams found description:	Not reported
PAHs found:	Y
PAHs cleaned up:	Y
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Y
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y
Soil cleaned up:	Y
Surface water cleaned:	Not reported
VOCs found:	Not reported
VOCs cleaned:	Not reported
Cleanup other description:	Not reported
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	N
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported

LOTS 14-19, C & 21 OF SECTION 1 JOHNSTOWN SUBDIV (Continued) **1016345273**

Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	1076
% Below Poverty:	2.9%
# Low Income:	2025
% Low Income:	1.5%
Meidan Income:	2666
# Unemployed:	249
% Unemployed:	12.4%
# Vacant Housing:	289
% Vacant Housing:	10.7%

FINDS:

Registry ID: 110038693054

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

22 **1705 HIGHLAND ROAD** **US BROWNFIELDS** **1016350311**
1705 HIGHLAND ROAD **FINDS** **N/A**
BATON ROUGE, LA 70802

US BROWNFIELDS:

Recipient name:	East Baton Rouge Parish Housing Authority
Grant type:	Cleanup
Property name:	1705 HIGHLAND ROAD
Property #:	840352476, 840352475, 840352477
Parcel size:	.5
Property Description:	Auto maintenance shop, tire shop, vehicle detailing shop, and retail gasoline facility
Latitude:	30.434117
Longitude:	-91.183481
HCM label:	Interpolation-Map
Map scale:	1:25,000
Point of reference:	Entrance Point of a Facility or Station
Datum:	World Geodetic System of 1984
ACRES property ID:	20261
Start date:	01/30/2009 00:00:00
Completed date:	04/02/2009 00:00:00
Acres cleaned up:	.5
Cleanup funding:	197996

1705 HIGHLAND ROAD (Continued) **1016350311**

Cleanup funding source:	US EPA - Brownfields Cleanup Cooperative Agreement
Assessment funding:	Not reported
Assessment funding source:	Not reported
Redevelopment funding:	Not reported
Redev. funding source:	Not reported
Redev. funding entity name:	Not reported
Redevelopment start date:	Not reported
Assessment funding entity:	Not reported
Cleanup funding entity:	EPA
Grant type:	Petroleum
Accomplishment type:	Not reported
Accomplishment count:	0
Cooperative agreement #:	96600401
Ownership entity:	Government
Current owner:	East Baton Rouge Parish Housing Authority
Did owner change:	N
Cleanup required:	Yes
Video available:	Not reported
Photo available:	Not reported
Institutional controls required:	N
IC Category proprietary controls:	Not reported
IC cat. info. devices:	Not reported
IC cat. gov. controls:	Not reported
IC cat. enforcement permit tools:	Not reported
IC in place date:	Not reported
IC in place:	Not reported
State/tribal program date:	09/01/2008 00:00:00
State/tribal program ID:	AI 93917
State/tribal NFA date:	04/02/2009 00:00:00
Air contaminated:	Not reported
Air cleaned:	Not reported
Asbestos found:	Not reported
Asbestos cleaned:	Not reported
Controled substance found:	Not reported
Controled substance cleaned:	Not reported
Drinking water affected:	Not reported
Drinking water cleaned:	Not reported
Groundwater affected:	Y
Groundwater cleaned:	Y
Lead contaminant found:	Not reported
Lead cleaned up:	Not reported
No media affected:	Not reported
Unknown media affected:	Not reported
Other cleaned up:	Y
Other metals found:	Not reported
Other metals cleaned:	Not reported
Other contaminants found:	Y
Other contams found description:	TPH, PCE
PAHs found:	Y
PAHs cleaned up:	Y
PCBs found:	Not reported
PCBs cleaned up:	Not reported
Petro products found:	Y
Petro products cleaned:	Y
Sediments found:	Not reported
Sediments cleaned:	Not reported
Soil affected:	Y

1705 HIGHLAND ROAD (Continued) **1016350311**

Soil cleaned up:	Y
Surface water cleaned:	Not reported
VOCs found:	Y
VOCs cleaned:	Y
Cleanup other description:	Antifreeze
Num. of cleanup and re-dev. jobs:	Not reported
Past use greenspace acreage:	Not reported
Past use residential acreage:	Not reported
Past use commercial acreage:	Not reported
Past use industrial acreage:	Not reported
Future use greenspace acreage:	Not reported
Future use residential acreage:	Not reported
Future use commercial acreage:	Not reported
Future use industrial acreage:	Not reported
Greenspace acreage and type:	Not reported
Superfund Fed. landowner flag:	Not reported
Arsenic cleaned up:	Not reported
Cadmium cleaned up:	Not reported
Chromium cleaned up:	Not reported
Copper cleaned up:	Not reported
Iron cleaned up:	Not reported
mercury cleaned up:	Not reported
nickel cleaned up:	Not reported
No clean up:	Not reported
Pesticides cleaned up:	Not reported
Selenium cleaned up:	Not reported
SVOCs cleaned up:	Not reported
Unknown clean up:	Not reported
Arsenic contaminant found:	Not reported
Cadmium contaminant found:	Not reported
Chromium contaminant found:	Not reported
Copper contaminant found:	Not reported
Iron contaminant found:	Not reported
Mercury contaminant found:	Not reported
Nickel contaminant found:	Not reported
No contaminant found:	Not reported
Pesticides contaminant found:	Not reported
Selenium contaminant found:	Not reported
SVOCs contaminant found:	Not reported
Unknown contaminant found:	Not reported
Future Use: Multistory	Not reported
Media affected Bluiding Material:	Not reported
Media affected indoor air:	Not reported
Building material media cleaned up:	Not reported
Indoor air media cleaned up:	Not reported
Unknown media cleaned up:	Not reported
Past Use: Multistory	Not reported
Highlights:	Not reported
IC Data Address:	Not reported
Redev Completition Date:	Not reported
# Below Poverty:	1076
% Below Poverty:	2.9%
# Low Income:	2025
% Low Income:	1.5%
Meidan Income:	2666
# Unemployed:	249
% Unemployed:	12.4%

1705 HIGHLAND ROAD (Continued) **1016350311**

Vacant Housing: 289
% Vacant Housing: 10.7%

FINDS:

Registry ID: 110039062493

Environmental Interest/Information System
US EPA Assessment, Cleanup and Redevelopment Exchange System (ACRES) is an federal online database for Brownfields Grantees to electronically submit data directly to EPA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

23 VALLEY PARK SCHOOL **SEMS-ARCHIVE** **1003875566**
4510 BAWELL ST. **LAD985170273**
BATON ROUGE, LA 70808

SEMS-ARCHIVE:
Site ID: 604069
EPA ID: LAD985170273
Federal Facility: N
NPL: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

Following information was gathered from the prior CERCLIS update completed in 10/2013:
Site ID: 0604069
Federal Facility: Not a Federal Facility
NPL Status: Not on the NPL
Non NPL Status: NFRAP-Site does not qualify for the NPL based on existing information

CERCLIS-NFRAP Site Contact Details:
Contact Sequence ID: 6428642.00000
Person ID: 6270175.00000

CERCLIS-NFRAP Site Alias Name(s):
Alias Name: VALLEY PARK SCHOOL
Alias Address: Not reported
EAST BATON ROUGE, LA

CERCLIS-NFRAP Assessment History:
Action: PRELIMINARY ASSESSMENT
Date Started: / /
Date Completed: 02/01/90
Priority Level: Low priority for further assessment

Action: DISCOVERY
Date Started: / /
Date Completed: 01/01/90
Priority Level: Not reported

Action: ARCHIVE SITE
Date Started: / /
Date Completed: 01/09/95

VALLEY PARK SCHOOL (Continued) **1003875566**

Priority Level: Not reported

Action: SITE INSPECTION
Date Started: 09/09/92
Date Completed: 09/09/92
Priority Level: NFRAP-Site does not qualify for the NPL based on existing information

---

23 VALLEY PARK SCHOOL **LA SPILLS** **S108598611**
4510 BAWELL ST **LA REM** **N/A**
BATON ROUGE, LA 70808

SPILLS:

Region Code:	Not reported
Date Rec:	03/30/2007
Date Initiated:	Not reported
aiid:	9151
Incident Id:	95016
Incident Date:	03/30/2007
Incident Status:	**Closed**
Media Desc:	Water/Soil/Air
Location Description:	Valley Park Alternative School 4510 Bawell St. Baton Rouge
Incident Source Name:	Valley Park School
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c07-1024 School built over ofl City Dump. A number of patches have been made to school floors. Eruption in cafeteria recently cause unknown...jd
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

REM:

AI Num:	9151
Evaluated And Closed:	12/20/2011
Program:	Solid Waste
EAC Type:	No Further Interest
Comments:	EDMS ID 8229311

AI Num:	9151
Evaluated And Closed:	11/19/2012
Program:	Solid Waste
EAC Type:	No Further Interest
Comments:	EDMS ID 8988959

24 **B-QUIK #3** **LA UST** **U003876292**
4105 PERKINS RD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	89658
Subject Item ID:	2
UST Tank Num:	54805
Tank Status:	**Active**
Install Date:	09/28/2000
Total Capacity:	20000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	54806
Tank Status:	**Active**
Install Date:	09/28/2000
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

B-QUIK #3 (Continued) **U003876292**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	54807
Tank Status:	**Active**
Install Date:	09/28/2000
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

24 **GORDON & SANDIFER AUTOMOTIVE** **RCRA-CESQG** **1004707822**
3825 PERKINS RD **FINDS** **LAD034179630**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	03/19/1987
Facility name:	GORDON & SANDIFER AUTOMOTIVE
Facility address:	3825 PERKINS RD BATON ROUGE, LA 70808
EPA ID:	LAD034179630
Mailing address:	PERKINS RD BATON ROUGE, LA 70808
Contact:	WINSTON LAPRARIE
Contact address:	3825 PERKINS RD

GORDON & SANDIFER AUTOMOTIVE (Continued) **1004707822**

BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 343-3427
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: GORDON & SANDIFER AUTOMOTIVE
Owner/operator address: 3825 PERKINS RD
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 343-3427
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

GORDON & SANDIFER AUTOMOTIVE (Continued) **1004707822**

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 05/03/2000
Evaluation: COMPLIANCE ASSISTANCE VISIT
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003270228

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707822
Registry ID: 110003270228
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003270228

---

24 **ROBERTS ESSO SERVICE STATION** **EDR Hist Auto** **1021240832**
3725 PERKINS RD **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1969	ROBERTS ESSO SERVICE STATION	Gasoline Service Stations
1970	ROBERTS ESSO SERVICE STATION	Gasoline Service Stations

24 BRIDGES PEST CONTROL — **RCRA NonGen / NLR** — **1000188892**
2169 MYRTLEDALE AVE — **FINDS** — **LAD008180754**
BATON ROUGE, LA 70808 — **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	08/13/1980
Facility name:	BRIDGES PEST CONTROL
Facility address:	2169 MYRTLEDALE AVE BATON ROUGE, LA 70808
EPA ID:	LAD008180754
Mailing address:	P.O.BOX 1121 BATON ROUGE, LA 70821
Contact:	LS BRIDGES
Contact address:	P.O.BOX 1121 BATON ROUGE, LA 70821
Contact country:	US
Contact telephone:	(225) 383-7330
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	L.S. BRIDGES
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P059
. Waste name: 4,7-METHANO-1H-INDENE, 1,4,5,6,7,8,8-HEPTACHLORO-3A,4,7,7A-TETRAHYDRO- (OR) HEPTACHLOR

BRIDGES PEST CONTROL (Continued) **1000188892**

Violation Status: No violations found

FINDS:

Registry ID: 110003268277

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000188892
Registry ID: 110003268277
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003268277

---

24 CVS PHARMACY **RCRA-SQG** **1012210849**
3651 PERKINS RD **LAR000060517**
BATON ROUGE, LA 70808

RCRA-SQG:
Date form received by agency: 01/28/2010
Facility name: CVS PHARMACY
Facility address: 3651 PERKINS RD
BATON ROUGE, LA 70808
EPA ID: LAR000060517
Mailing address: CVS DR
WOONSOCKET, RI 02895
Contact: KATIE A COLLINS
Contact address: CVS DR
WOONSOCKET, RI 02895
Contact country: US
Contact telephone: (401) 770-6873
Contact email: Not reported
EPA Region: 06
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: CVS #5312
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator

CVS PHARMACY (Continued) **1012210849**

Owner/Op start date: 08/31/2004
Owner/Op end date: Not reported

Owner/operator name: R G CLAITOR REALTY
Owner/operator address: Not reported
Not reported
Owner/operator country: Not reported
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/31/2004
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

CVS PHARMACY (Continued) **1012210849**

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U248
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Historical Generators:
Date form received by agency: 01/07/2010
Site name: CVS PHARMACY
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

CVS PHARMACY (Continued) **1012210849**

. Waste code: U248
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYL-BUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS OF 0.3% OR LESS

Violation Status: No violations found

---

24 **DRY CLEANERS CLEANERS** **EDR Hist Cleaner** **1013778930**
3627 PERKINS RD **N/A**
BATON ROUGE, LA 70808

EDR Hist Cleaner

Year:	Name:	Type:
2007	DRY CLEANERS CLEANERS	CLEANERS
2008	DRY CLEANERS	Laundry And Drycleaner Agents

---

24 **DRY CLEANERS** **LA DRYCLEANERS** **S107870433**
3627 PERKINS ROAD **N/A**
BATON ROUGE, LA

DRYCLEANERS:
Facility ID: Not reported
Owner: NUMA MORVANT, JR.
Owner Telephone: 225-923-2869
Store Telephone: 225-
Mailing Address: 8381 TOM DRIVE
Mailing City,St,Zip: BATON ROUGE 70815
Contact: Not reported

---

24 **CITY PARISH DEPT OF PUB WKS** **RCRA-CESQG** **1004707357**
3075 VALLEY **FINDS** **LA0000593210**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 07/18/1994
Facility name: CITY PARISH DEPT OF PUB WKS
Facility address: 3075 VALLEY
BATON ROUGE, LA 70808
EPA ID: LA0000593210
Mailing address: VALLEY
BATON ROUGE, LA 70808
Contact: KIM LAWRENCE
Contact address: 2931 VALLEY
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 389-3250
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any

CITY PARISH DEPT OF PUB WKS (Continued) **1004707357**

land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CITY OF BATON ROUGE
Owner/operator address:	3075 VALLEY BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 389-3250
Legal status:	County
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040

CITY PARISH DEPT OF PUB WKS (Continued) **1004707357**

. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110003262059

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707357
Registry ID: 110003262059
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003262059

---

24 BATON ROUGE CITY OF - SOUTH MAINTENANCE LOT **LA UST** **U004156427**
3075 VALLEY ST **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	69686
Subject Item ID:	2
UST Tank Num:	29571
Tank Status:	**Active**
Install Date:	01/27/1986
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

BATON ROUGE CITY OF - SOUTH MAINTENANCE LOT (Continued) **U004156427**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Yes
Pipe Method Description:	Pressure

UST Tank Num:	29572
Tank Status:	**Active**
Install Date:	01/27/1986
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	29573
Tank Status:	**Active**
Install Date:	01/27/1986
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

BATON ROUGE CITY OF - SOUTH MAINTENANCE LOT (Continued) **U004156427**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	29574
Tank Status:	**Closed**
Install Date:	01/27/1986
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Y
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

24 **RCS CONTRACTORS INC - PERKINS RD & STANFORD AVE PR** **LA NPDES** **S110297267**
PERKINS RD & STANFORD AVE **N/A**
BATON ROUGE, LA 70000

NPDES:

Facility Id:	168452
Facility Phone:	Not reported
Issued Date:	03/01/2010
Title Description:	Gen Const. Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20090001

24 EXXON CO USA #5-1052
3191 S ACADIAN HWY
BATON ROUGE, LA 70808

LA AUL **U003986867**
LA UST **N/A**
LA REM

AUL:

Facility ID:	22413
Type:	Not reported
Incident Number:	Not reported
Agency Interest Id:	Not reported
PPM Project Number:	Not reported
Parish:	East Baton Rouge
Comments:	UST
Custom Tank Desc:	Conveyance Notice Required

UST:

Master Agency Id:	22413
Subject Item ID:	1
UST Tank Num:	12007
Tank Status:	**Closed**
Install Date:	04/12/1970
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	12008
Tank Status:	**Removed**
Install Date:	04/12/1970
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported

EXXON CO USA #5-1052 (Continued) **U003986867**

Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	12009
Tank Status:	**Removed**
Install Date:	04/12/1970
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	12010
Tank Status:	**Removed**

EXXON CO USA #5-1052 (Continued) **U003986867**

Install Date:	04/12/1970
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	39271
Tank Status:	**Removed**
Install Date:	10/01/1991
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported

EXXON CO USA #5-1052 (Continued) **U003986867**

Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39272
Tank Status:	**Removed**
Install Date:	10/01/1991
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	39273
Tank Status:	**Removed**
Install Date:	10/01/1991
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported

EXXON CO USA #5-1052 (Continued) **U003986867**

Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

REM:

AI Num:	22413
Evaluated And Closed:	10/28/2014
Program:	UST
EAC Type:	No Further Interest
Comments:	EDMS ID 9527976. No release occurred.

AI Num:	22413
Evaluated And Closed:	03/12/2015
Program:	UST
EAC Type:	No Further Interest
Comments:	EDMS ID 9696417. No release occurred.

AI Num:	22413
Evaluated And Closed:	09/27/2005
Program:	UST
EAC Type:	Approve Investigation NFA w/ BOD
Comments:	EDMS ID 2924445.

---

24 **EXXON CO USA #51052** **LA RGA LUST** **S115491451**
3191 S ACADIAN HWY **N/A**
BATON ROUGE, LA

RGA LUST:

2003	EXXON CO USA #51052	3191 S ACADIAN HWY
2002	EXXON CO USA #51052	3191 S ACADIAN HWY

---

24 **LA SPILLS** **S108596436**
3191 S. ACADIAN THRUWAY **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	06/17/2002
Date Initiated:	Not reported
aiid:	22413
Incident Id:	52798
Incident Date:	05/09/2001
Incident Status:	**Open**
Media Desc:	Not reported
Location Description:	3191 S. Acadian Thruway, Baton Rouge, LA
Incident Source Name:	Exxon Co USA #51052
Reporter Name:	Not reported

(Continued) **S108596436**

Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	Concentrations of benzene, ethylbenzene TPH-GRO and aesenic in soil and benzene, ethylbenzene, TPH-GRO total lead and chromium in groundwater exceed RECAP industrial screening standards. Samples were taken during a divestment investigation and UST closure.
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Gasoline
Quantity:	Not reported
Other Substance Desc:	Not reported

---

24 **STANFORD EXXON STORE #5-1052** **LA HIST LUST** **S106033747**
3191 S ACADIAN THRUWAY **N/A**
BATON ROUGE, LA 70808

HIST LUST:

Facility ID:	17-004226
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	12/24/1992
Date Confirmed 2:	Not reported
Incident Number:	91-2-0004
Incident Date:	12/24/1990
Type of Incident:	DISPENSER LEAK
Type of Incident No2:	Not reported
Reported By:	DON SIMPSON/EXXON
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	09/20/1991
Assessment Approved Date:	Not reported
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported

STANFORD EXXON STORE #5-1052 (Continued) **S106033747**

Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SMALL LEAK UNDER DISPENSER LEAKING ON GROUND. THREE USTS REMOVED.SEE INCIDNET NO. 91-2-0181

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-004226
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-2-0004
Incident Date: 12/24/1990
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00109200
Owner Name: EXXON MOBIL COMPANY, U.S.A.
Owner Address: P. O. BOX 4386
Owner City,St,Zip: HOUSTON,, TX 77210-4386
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: 09/20/1991
Assessment Approved Date: Not reported
Assessment Contractor: IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: Not reported
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SMALL LEAK UNDER DISPENSER LEAKING ON GROUND. THREE USTS REMOVED.SEE INCIDNET NO. 91-2-0181

STANFORD EXXON STORE #5-1052 (Continued) **S106033747**

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-004226
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	12/24/1990
Date Confirmed 2:	Not reported
Incident Number:	91-2-0181
Incident Date:	12/24/1990
Type of Incident:	DISPENSER LEAK
Type of Incident No2:	Not reported
Reported By:	DON SIMPSON
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	06/25/1991
Assessment Plan Due Date:	08/28/1991
Assessment Plan Received Date:	09/20/1991
Assessment Approved Date:	10/28/1991
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	09/20/1991
Corrective Plan Approved Date:	10/28/1991
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: UST REMOVED ON OR ABOUT 10/28/91. CONSULTANT REQUEST TERMINATION OFREMEDIATION ON 2/27/95.

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-004226
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported

STANFORD EXXON STORE #5-1052 (Continued) **S106033747**

Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0181
Incident Date:	12/24/1990
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	06/25/1991
Assessment Plan Due Date:	08/28/1991
Assessment Plan Received Date:	09/20/1991
Assessment Approved Date:	10/28/1991
Assessment Contractor:	IT INTERNATIONAL TECHNOLOGY CORPORATION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	09/20/1991
Corrective Plan Approved Date:	10/28/1991
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: UST REMOVED ON OR ABOUT 10/28/91. CONSULTANT REQUEST TERMINATION OFREMEDIATION ON 2/27/95.

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

---

24 **EXXON CO USA 51052** **RCRA-SQG** **1000622664**
3191 S ACADIAN HWY **FINDS** **LAD985199793**
BATON ROUGE, LA 70808 **ECHO**

RCRA-SQG:

Date form received by agency:	03/12/1991
Facility name:	EXXON CO USA 51052
Facility address:	3191 S ACADIAN HWY BATON ROUGE, LA 70808
EPA ID:	LAD985199793
Mailing address:	PO BOX 4415 HOUSTON, TX 77210

EXXON CO USA 51052 (Continued) **1000622664**

Contact: ALDA S POOL
Contact address: PO BOX 4415
HOUSTON, TX 77210
Contact country: US
Contact telephone: (713) 656-7709
Contact email: Not reported
EPA Region: 06
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: EXXON CO USA
Owner/operator address: PO BOX 4415
HOUSTON, TX 77210
Owner/operator country: Not reported
Owner/operator telephone: (713) 656-7761
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110003327098

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

EXXON CO USA 51052 (Continued) **1000622664**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000622664
Registry ID:	110003327098
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003327098

---

24 **STANFORD EXXON MCFEARIN E** **EDR Hist Auto** **1013776773**
3191 S ACADIAN THRUWAY **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1972	STANFORD ESSO	Gasoline Service Stations
1973	STANFORD EXXON	Gasoline Service Stations
1974	STANFORD EXXON	Gasoline Service Stations
1975	STANFORD EXXON	GASOLINE STATIONS
1975	STANFORD EXXON	Gasoline Service Stations
1976	STANFORD EXXON	Gasoline Service Stations
1977	STANFORD EXXON	Gasoline Service Stations
1980	STANFORD SELF SERV EXXON	GASOLINE STATIONS
1986	EXXON INC	Gasoline Service Stations
1987	EXXON INC	Gasoline Service Stations
1988	EXXON CORPORATION	Gasoline Service Stations
1989	EXXON CORPORATION	Gasoline Service Stations, NEC
1990	STANFORD SELF SERVICE EXXON	GASOLINE STATIONS
1990	EXXON CORPORATION	Gasoline Service Stations, NEC
1991	EXXON CORPORATION	Gasoline Service Stations, NEC
1992	EXXON CORPORATION	Gasoline Service Stations, NEC
1993	EXXON CORPORATION	Gasoline Service Stations, NEC
1995	STANFORD EXXON	GASOLINE STATIONS
1996	STANFORD EXXON MCFEARIN E	Gasoline Service Stations
1997	STANFORD EXXON MCFEARIN E	Gasoline Service Stations

---

24 **EXXON CO USA #5-1052** **LA RGA LUST** **S115491446**
3191 S ACADIAN HWY **N/A**
BATON ROUGE, LA

RGA LUST:

2005	EXXON CO USA #5-1052	3191 S ACADIAN HWY
2004	EXXON CO USA #5-1052	3191 S ACADIAN HWY

24 ACADIAN INTERSTATE MOBIL
3192 S ACADIAN
BATON ROUGE, LA 70808

RCRA NonGen / NLR
FINDS
LA UST
ECHO

1004713346
LAR000010926

RCRA NonGen / NLR:

Date form received by agency:	06/02/2010
Facility name:	ACADIAN INTERSTATE MOBIL
Facility address:	3192 S ACADIAN BATON ROUGE, LA 70808
EPA ID:	LAR000010926
Mailing address:	S ACADIAN BATON ROUGE, LA 70808
Contact:	DARREL BACON
Contact address:	3192 S ACADIAN BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 381-9002
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DARREL BACON
Owner/operator address:	3192 S ACADIAN BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 381-9002
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	DARREL BACON
Owner/operator address:	3192 S ACADIAN BATON ROUGE, LA 70808
Owner/operator country:	US
Owner/operator telephone:	(225) 381-9002
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

ACADIAN INTERSTATE MOBIL (Continued) **1004713346**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Historical Generators:
Date form received by agency: 02/01/1996
Site name: ACADIAN INTERSTATE MOBIL
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

ACADIAN INTERSTATE MOBIL (Continued) **1004713346**

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/02/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003352229

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UST:
Master Agency Id: 15665
Subject Item ID: 1

UST Tank Num: 17853
Tank Status: Removed
Install Date: 08/05/1975
Total Capacity: 4000
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Not reported
Gasohol: Yes
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported

ACADIAN INTERSTATE MOBIL (Continued) **1004713346**

Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	17854
Tank Status:	**Removed**
Install Date:	08/05/1970
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	17855
Tank Status:	**Removed**
Install Date:	08/05/1970
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported

ACADIAN INTERSTATE MOBIL (Continued) **1004713346**

Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	17856
Tank Status:	**Removed**
Install Date:	08/05/1970
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

ECHO:

Envid:	1004713346
Registry ID:	110003352229

ACADIAN INTERSTATE MOBIL (Continued) **1004713346**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003352229

---

24 **GIVENS SOUTHSIDE MOBIL SERVICE CENTER** **EDR Hist Auto** **1013771139**
3192 S ACADIAN TRWY **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1976	GIVENS SOUTHSIDE MOBIL SV CTR	Gasoline Service Stations
1977	GIVENS STHSD MBL SRV	Gasoline Service Stations
1978	GIVENS STHSD MBL SRV	Gasoline Service Stations
1979	GIVENS STHSD MBL SRV	Gasoline Service Stations
1979	GIVENS STHSD MBL SRV	Gasoline Service Stations
1980	GIVENS SOUTHSIDE MOBIL SERVICE	GASOLINE STATIONS
1983	ACADIAN INTERSTATE MOBIL	Gasoline Service Stations
1985	ACADIAN INTERSTATE MOBIL	Gasoline Service Stations
1986	ACADIAN INTERSTATE MOBIL	Gasoline Service Stations
1987	BACON ENTERPRISES INC	Gasoline Service Stations
1988	BACON ENTERPRISES INC	Gasoline Service Stations
1989	BACON ENTERPRISES INC	Gasoline Service Stations, NEC
1990	ACADIAN INTERSTATE MOBIL GAS	GASOLINE STATIONS
1990	BACON ENTERPRISES INC	Gasoline Service Stations, NEC
1995	ACADIAN INTERSTATE MOBIL GAS	GASOLINE STATIONS
2000	ACADIAN MOBIL GAS SERV STA	GASOLINE STATIONS
2001	ACADIAN MOBIL	Gasoline Service Stations
2002	ACADIAN MOBIL	Gasoline Service Stations
2003	ACADIAN MOBIL	Gasoline Service Stations
2004	ACADIAN MOBIL	Gasoline Service Stations
2005	ACADIAN MOBIL	Gasoline Service Stations
2006	ACADIAN MOBIL	Gasoline Service Stations
2007	ACADIAN MOBIL	Gasoline Service Stations
2008	ACADIAN MOBIL	Gasoline Service Stations

---

24 **ACADIAN INTERSTATE MOBIL** **LA SPILLS** **S110658406**
3192 S ACADIAN **LA REM** **N/A**
BATON ROUGE, LA 70808

SPILLS:

Region Code:	CR
Date Rec:	09/16/2010
Date Initiated:	Not reported
aiid:	15665
Incident Id:	126454
Incident Date:	09/16/2010
Incident Status:	**Referred to Remediation**
Media Desc:	Soil
Location Description:	Iberia Bank 3192 S. Acadian Thruway Baton Rouge
Incident Source Name:	Acadian Interstate Mobil
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	UST Rem, Unknown

ACADIAN INTERSTATE MOBIL (Continued) **S110658406**

Comments: 0
Parameter: 0
Quantity: 0 0
Other Substance Desc: 0

REM:
AI Num: 15665
Evaluated And Closed: 09/30/2011
Program: Solid Waste
EAC Type: No Further Interest
Comments: EDMS ID 8141055.

---

24 **CIRCLE K #9717** **LA UST** **U003987090**
3375 PERKINS RD **LA SPILLS** **N/A**
BATON ROUGE, LA 70808 **LA NPDES**
LA REM

UST:
Master Agency Id: 70017
Subject Item ID: 2

UST Tank Num: 30408
Tank Status: **Active**
Install Date: 04/01/1991
Total Capacity: 12000
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Not reported
Gasohol: Yes
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported
Unknown: Not reported
Other Sub: Not reported
Steel Tank Covered With Asphalt: Not reported
Cathodically Protected: Not reported
Epoxy Coated Tank: Not reported
A Composite Of Different Materials: Not reported
Fiberglass Or Plastic: Y
Interior Line With Some Material: Not reported
Double Wall As Opposed To Single Wall: Yes
Outside Lined w/ Polyethylen Jacket: Not reported
Made Of Concrete: Not reported
Liner Covering Excavation Hole: Not reported
Other Material: Not reported
Pipe Method Description: Pressure

UST Tank Num: 30409
Tank Status: **Active**
Install Date: 04/01/1991
Total Capacity: 10000

CIRCLE K #9717 (Continued) **U003987090**

Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	30410
Tank Status:	**Active**
Install Date:	04/01/1991
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported

CIRCLE K #9717 (Continued) **U003987090**

Pipe Method Description:	Pressure

UST Tank Num:	30411
Tank Status:	**Active**
Install Date:	04/01/1991
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

SPILLS:

Region Code:	Not reported
Date Rec:	09/25/2008
Date Initiated:	Not reported
aiid:	70017
Incident Id:	109562
Incident Date:	09/24/2008
Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	Former Shell #101221 3375 Perkins Rd Baton Rouge
Incident Source Name:	Circle K #2709717
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s08-3924 UST - soil & gw samples collected during site investigation showed suspected petroleum fuel hydrocarbons above RECAP...cj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

CIRCLE K #9717 (Continued) **U003987090**

Region Code:	Not reported
Date Rec:	05/17/2004
Date Initiated:	Not reported
aiid:	70017
Incident Id:	70392
Incident Date:	05/15/2004
Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	Motiva Enterprises LLC 3375 Perkins Rd
Incident Source Name:	Motiva Enterprises LLC - Shell #101221
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s04-1918 due to heavy rain water from motor fuel tank pit seeped onto surface at site - tj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	dissolved gasoline

Region Code:	Not reported
Date Rec:	03/07/2006
Date Initiated:	Not reported
aiid:	70017
Incident Id:	86293
Incident Date:	03/07/2006
Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	3375 Perkins Rd Baton Rouge
Incident Source Name:	Shell #101221
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s06-0680 Petroleum hydrocarbons were found in the soil above RECAP. CMD
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

NPDES:

Facility Id:	70017
Facility Phone:	8139106830
Issued Date:	01/23/2007
Title Description:	LAG750573 Permit
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20060001

Facility Id:	70017
Facility Phone:	8139106830

CIRCLE K #9717 (Continued) **U003987090**

Issued Date: 05/07/2004
Title Description: LAG750118 Reauthorization
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20040001

Facility Id: 70017
Facility Phone: 8139106830
Issued Date: 08/28/1998
Title Description: Fiscal Migration: LAG750118
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN19940001

Facility Id: 70017
Facility Phone: 8139106830
Issued Date: 06/12/2009
Title Description: Permit
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20090001

Facility Id: 70017
Facility Phone: 8139106830
Issued Date: 07/25/2014
Title Description: Renewed Coverage
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20140001

REM:
AI Num: 70017
Evaluated And Closed: 08/21/2009
Program: UST
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 6534754.

AI Num: 70017
Evaluated And Closed: 10/11/2006
Program: UST
EAC Type: No Further Interest
Comments: EDMS ID 3045948. No release occurred

---

24 **STAR ENT** **RCRA NonGen / NLR** **1000622435**
3375 PERKINS RD **FINDS** **LAD985197334**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 06/27/2002
Facility name: STAR ENT
Facility address: 3375 PERKINS RD
BATON ROUGE, LA 70808
EPA ID: LAD985197334
Mailing address: PO BOX 2099
HOUSTON, TX 772522099
Contact: JENA HENRY
Contact address: PO BOX 2099

STAR ENT (Continued) **1000622435**

HOUSTON, TX 772522099
Contact country: US
Contact telephone: (713) 241-0236
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: MOTIVA ENTERPRISES LLC
Owner/operator address: PO BOX 4540
HOUSTON, TX 77210
Owner/operator country: Not reported
Owner/operator telephone: (713) 241-0236
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Historical Generators:
Date form received by agency: 03/21/2000
Site name: STAR ENT
Classification: Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/27/2002
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported

STAR ENT (Continued) **1000622435**

Evaluation lead agency: State

FINDS:

Registry ID: 110003325312

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000622435
Registry ID: 110003325312
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003325312

---

24 **TEXACO SELF SERVICE** **EDR Hist Auto** **1013776204**
3375 PERKINS RD **N/A**
BATON ROUGE, LA 70806

EDR Hist Auto

Year:	Name:	Type:
1971	ARAS TEXACO	Gasoline Service Stations
1972	ARAS TEXACO	Gasoline Service Stations
1973	ARAS TEXACO	Gasoline Service Stations
1974	REEDS TEXACO	Gasoline Service Stations
1975	REEDS TEXACO SERVICE STATION	GASOLINE STATIONS
1975	REEDS TEXACO	Gasoline Service Stations
1976	REEDS TEXACO	Gasoline Service Stations
1977	REEDS TEXACO	Gasoline Service Stations
1978	REEDS TEXACO	Gasoline Service Stations
1979	REEDS TEXACO	Gasoline Service Stations
1980	TEXACO SELF SERV	GASOLINE STATIONS
1980	REEDS TEXACO	Gasoline Service Stations
1982	REEDS TEXACO	Gasoline Service Stations
1983	REEDS TEXACO	Gasoline Service Stations
1986	CRACKER BARREL	Gasoline Service Stations
1987	CRACKER BARREL STORES INC	Grocery Stores
1988	CRACKER BARREL STORES INC	Grocery Stores
1989	CRACKER BARREL STORES INC	Convenience Stores
1990	TEXACO SERVICE STATION & FOOD M	GASOLINE STATIONS
1995	TEXACO SELF SERVICE	GASOLINE STATIONS
1997	STAR ENTERPRISE	Gasoline Service Stations
1998	MOTIVA ENTERPRISES LLC	Gasoline Service Stations
1999	MOTIVA ENTERPRISES LLC	Gasoline Service Stations
2000	MOTIVA ENTERPRISES GAS SERV STA	GASOLINE STATIONS
2000	MOTIVA ENTERPRISES LLC	Gasoline Service Stations
2001	MOTIVA ENTERPRISES LLC	Gasoline Service Stations
2002	MOTIVA ENTERPRISES LLC	Gasoline Service Stations
2003	MOTIVA ENTERPRISES LLC	Gasoline Service Stations

TEXACO SELF SERVICE (Continued) **1013776204**

2004	MOTIVA ENTERPRISES LLC	Gasoline Service Stations
2005	BRADLEY PRISCILLA	Gasoline Service Stations, NEC
2006	BRADLEY PRISCILLA	Gasoline Service Stations, NEC
2007	TORRENCE STACEY	Gasoline Service Stations, NEC
2008	TORRENCE STACEY	Gasoline Service Stations, NEC
2009	TORRENCE STACEY	Gasoline Service Stations, NEC
2010	TORRENCE STACEY	Gasoline Service Stations, NEC

---

24 **ROBERTSON AUTO SERVICE** **EDR Hist Auto** **1021052622**
2575 N ACADIAN THRUWAY **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1978	ROBERTSON AUTO SERVICE	General Automotive Repair Shops
1979	ROBERTSON AUTO SERVICE	General Automotive Repair Shops

---

24 **ROGER A BARIELLE** **LA UST** **U003921931**
3235 PERKINS RD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	20656
Subject Item ID:	1
UST Tank Num:	37548
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

ROGER A BARIELLE (Continued) **U003921931**

UST Tank Num:	37549
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	37550
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

ROGER A BARIELLE (Continued) **U003921931**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	37551
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

24 **ROGER A. BARIELLE** **LA HIST LUST** **S106034152**
3235 PERKINS RD **N/A**
BATON ROUGE, LA 70808

HIST LUST:

Facility ID:	17-013030	
Facility Parish:	EAST BATON ROUGE	
Substance Name:	GASOLINE	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	06/18/1990	
Date Confirmed 2:	Not reported	
Incident Number:	90-2-0140	
Incident Date:	06/18/1990	
Type of Incident:		UST LEAK
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00521800	

ROGER A. BARIELLE (Continued) **S106034152**

Owner Name: BARIELLE, ROGER A.
Owner Address: 3235 PERKINS ROAD
Owner City,St,Zip: BATON ROUGE, LA 70808
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: 10/15/1990
Assessment Approved Date: Not reported
Assessment Contractor: ENVIROMENTAL MATERIALS INC.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: 10/15/1990
Corrective Plan Approved Date: 05/18/1993
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SITE IS STAR VIDEO AND A FORMER SPUR STATION. CONTAMINATIONWAS DISCOVERED WHEN (4) USTS WERE CLOSED AND REMOVED. (2) ADDITIONALBORINGS WERE DONE ON 7/11/91. QTLY REPORTS SUBMITTED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-013030
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 90-2-0140
Incident Date: 06/18/1990
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00521800
Owner Name: BARIELLE, ROGER A.
Owner Address: 3235 PERKINS ROAD
Owner City,St,Zip: BATON ROUGE, LA 70808
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: 10/15/1990

ROGER A. BARIELLE (Continued) **S106034152**

Assessment Approved Date:	Not reported
Assessment Contractor:	ENVIROMENTAL MATERIALS INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	10/15/1990
Corrective Plan Approved Date:	05/18/1993
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SITE IS STAR VIDEO AND A FORMER SPUR STATION. CONTAMINATIONWAS DISCOVERED WHEN (4) USTS WERE CLOSED AND REMOVED. (2) ADDITIONALBORINGS WERE DONE ON 7/11/91. QTLY REPORTS SUBMITTED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

---

24 **HANEYS SPUR SERVICE STATION** **EDR Hist Auto** **1013769619**
3235 PERKINS RD **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1969	HANEYS SPUR SERVICE	Gasoline Service Stations
1970	HANEYS SPUR SERVICE STATION	GASOLINE STATIONS
1970	HANEYS SPUR SERVICE	Gasoline Service Stations
1982	BARIELLE OIL CO INC	Petroleum Products, NEC
1983	BARIELLE OIL CO INC	Petroleum Products, NEC

---

24 **ACADIAN CENTRE** **LA UST** **U003926883**
2431 S ACADIAN THRUWAY **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	89345
Subject Item ID:	1
UST Tank Num:	54832
Tank Status:	**Closed**
Install Date:	01/01/1983
Total Capacity:	150
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported

ACADIAN CENTRE (Continued) **U003926883**

Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

24 **LA SPILLS** **S110101675**
2431 SOUTH ACADIAN BACK PARKING LOT **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	04/05/2001
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	41320
Incident Date:	04/05/2001
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	2431 South Acadian Back Parking Lot
Incident Source Name:	Unknown
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c01-1000 Citizens advised a green substance covers the back parking lot of Union Planters Bank each morning and in the afternoon it seems to dry but the next morning it's liquified again, there is no odor, she says it seems to be seeping through the cracks in the concrete.-jmr
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Unknown

24 ZIPPY'S LLC — **LA HIST LUST** — **S106034224**
3155 PERKINS RD — **LA NPDES** — **N/A**
BATON ROUGE, LA 70808

HIST LUST:

Facility ID:	17-013437
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	10/07/1998
Date Confirmed 2:	Not reported
Incident Number:	98-2-0101
Incident Date:	10/06/1998
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	CARY LILL
Reported By 2:	Not reported
Owner ID:	00624300
Owner Name:	MARABELLA'S 66
Owner Address:	3155 PERKINS ROAD
Owner City,St,Zip:	BATON ROUGE, LA 70808
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	03/01/1999
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: FREE PHASE PRODUCT WAS FOUND IN 2 RDD'S WHILE PERFORMING A PHASE IPROPERTY ASSESSMENT. DEQ INFORMED OPERATOR TO SHUT DOWN SYSTEM ANDCONTACT HOME OIL TO PERFORM TANK AND LINE TEST. FURTHER INFORMATIONWILL BE DETERMINED AFTER RESULTS OF TIGHTNESS TEST ARE KNOWN.REC'D WRITTEN RELEASE NOTIFICATION REPORT ON 10/22/98. REC'D LETTERDATED 2/3/99 FROM OWNER'S ATTORNEY REQUESTING CLOSURE OF THIS INCIDENT

LA HIST LUST ASSESMENT:

Comments: DEQ LETTER 3/1/99 NO FURTHER ASSESSMENT AND/OR REMEDIATION ISWARRANTED AT THIS TIME.

LA HIST LUST CORRECTIVE ACTION:

Comments: FACILITY AKA: LILLS 66.

ZIPPY'S LLC (Continued) **S106034224**

Facility ID:	17-013437
Facility Parish:	EAST BATON ROUGE
Substance Name:	UNKNOWN
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	04/23/1999
Date Confirmed 2:	Not reported
Incident Number:	99-2-0027
Incident Date:	04/23/1999
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00624300
Owner Name:	MARABELLA'S 66
Owner Address:	3155 PERKINS ROAD
Owner City,St,Zip:	BATON ROUGE, LA 70808
Assessment Pending Info:	No
Assessment Request Date:	05/21/1999
Assessment Plan Due Date:	08/11/1999
Assessment Plan Received Date:	10/14/1999
Assessment Approved Date:	Not reported
Assessment Contractor:	COOKE-SMITH ENVIRONMENTAL SERVICES,INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: DEQ LETTER 5/21/1999 REQUEST LIMITED PHASE II ENVIRONMENTAL SITEASSESSMENT. RECEIVED LETTER FROM OWNER'S ATTORNEY THAT COOKE SMITHIS CONSULTANT AND TO DIRECT ALL CORRESPONDENCE TO THE ATTORNEY.RECEIVED INITIAL ABATEMENT REPORT ON 6/16/99. DEQ LETTER 7/27/99APPROVED WORK PLAN FOR MW INSTALLATION.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: Not reported

NPDES:

Facility Id:	20657
Facility Phone:	Not reported
Issued Date:	11/26/2007
Title Description:	LAG830205 Reauthorization

ZIPPY'S LLC (Continued) **S106034224**

Permit Type Description: Gen-LAG83-Petroleum UST Rem
Program: Water
Activity Number: GEN20070001

---

24 **ZIPPY'S LLC** **LA UST** **U003921932**
3155 PERKINS RD **LA NPDES** **N/A**
BATON ROUGE, LA 70808 **LA REM**

UST:

Master Agency Id:	20657
Subject Item ID:	2
UST Tank Num:	38854
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection
UST Tank Num:	38855
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported

ZIPPY'S LLC (Continued) **U003921932**

MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

UST Tank Num:	38856
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

UST Tank Num:	38857
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported

ZIPPY'S LLC (Continued) **U003921932**

Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

NPDES:

Facility Id:	20657
Facility Phone:	Not reported
Issued Date:	12/31/2002
Title Description:	LAG830205 reauthorization
Permit Type Description:	Gen-LAG83-Petroleum UST Rem
Program:	Water
Activity Number:	GEN20020002

Facility Id:	20657
Facility Phone:	Not reported
Issued Date:	10/11/2002
Title Description:	LAG830205 Permit
Permit Type Description:	Gen-LAG83-Petroleum UST Rem
Program:	Water
Activity Number:	GEN20020001

REM:

AI Num:	20657
Evaluated And Closed:	08/06/2004
Program:	UST
EAC Type:	Approve CA NFA w/ BOD
Comments:	EDMS ID 2404916

24 ULLS PHILUPS — **EDR Hist Auto** — **1013763688**
3155 PERKINS RD — **N/A**
BATON ROUGE, LA 70806

EDR Hist Auto

Year:	Name:	Type:
1969	OVERPASS ESSO SERVICE STATION	Gasoline Service Stations
1970	OVERPASS ESSO SERVICE STATION	Gasoline Service Stations
1971	OVERPASS ESSO SERVICE STATION	Gasoline Service Stations
1972	OVERPASS ESSO SERVICE STATION	Gasoline Service Stations
1973	OVERPASS ESSO SERVICE STATION	Gasoline Service Stations
1974	OVERPASS ESSO SERVICE STATION	Gasoline Service Stations
1975	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1976	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1977	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1978	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1979	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1980	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1982	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1983	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1985	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1986	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1987	OVERPASS EXXON SERVICE STATION	Gasoline Service Stations
1987	MARABELLA PHILLIPS 66	Truck Rental And Leasing, Without Drivers
1988	MARABELLA PHILLIPS 66	Gasoline Service Stations
1989	MARABELLA PHILLIPS 66	Gasoline Service Stations
1990	MARABELLAS PHILLIP	SERVICE STATIONS
1990	MARABELLAS PHILLIP	GASOLINE STATIONS
1990	MARABELLA PHILLIPS 66	Gasoline Service Stations
1991	MARABELLA PHILLIPS 66	Gasoline Service Stations
1992	MARABELLA PHILLIPS 66	Gasoline Service Stations
1993	MARABELLA PHILLIPS 66	Gasoline Service Stations
1994	MARABELLA PHILLIPS 66	Gasoline Service Stations
1995	ULLS PHILUPS	GASOLINE STATIONS
1997	LILLS CAR CARE	General Automotive Repair Shops
1998	LILLS CAR CARE	General Automotive Repair Shops
1999	LILLS CAR CARE	General Automotive Repair Shops
2000	LILLS CAR CARE GENL AUTO REPR S	AUTOMOBILE REPAIRING & SERVICE
2000	LILLS CAR CARE	General Automotive Repair Shops

---

24 LILLS CAR CARE — **RCRA NonGen / NLR** — **1004707506**
3155 PERKINS RD — **FINDS** — **LA0000917666**
BATON ROUGE, LA 70808 — **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	03/30/2010
Facility name:	LILLS CAR CARE
Facility address:	3155 PERKINS RD BATON ROUGE, LA 70808
EPA ID:	LA0000917666
Mailing address:	PERKINS RD BATON ROUGE, LA 70808
Contact:	CARY LILL
Contact address:	3155 PERKINS RD BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 383-2122
Contact email:	Not reported
EPA Region:	06

LILLS CAR CARE (Continued) **1004707506**

Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LILLS CAR CARE
Owner/operator address: 3155 PERKINS RD
BATON ROUGE, LA 70808
Owner/operator country: US
Owner/operator telephone: (225) 383-2122
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

Owner/operator name: LILLS CAR CARE
Owner/operator address: 3155 PERKINS RD
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 383-2122
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats

LILLS CAR CARE (Continued) **1004707506**

Accumulated waste on-site: Yes
Generated waste on-site: Not reported

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Historical Generators:
Date form received by agency: 07/25/1994
Site name: LILLS CAR CARE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/30/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported

LILLS CAR CARE (Continued) **1004707506**

Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003263496

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707506
Registry ID: 110003263496
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003263496

---

24 WIFE SAVER LAUND O MAT **EDR Hist Cleaner** **1013780796**
3109 PERKINS RD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1960	WIFE SAVER LAUND O MAT	LAUNDRIES-SELF SERVE
1966	KEANS	CLEANERS AND DYERS
1970	KEANS BR CINS	CLEANERS AND DYERS
1975	KEANS BR CLNS	CLEANERS AND DYERS
1980	KEANS BR CINS	CLEANERS AND DYERS
1986	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1987	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1988	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1989	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1990	KEANS THE CLEANER	CLEANERS AND DYERS
1990	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1991	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1992	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1993	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1994	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
1995	KEANS THE CLEANER	CLEANERS
1995	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2000	KEANS THE CLEANER STORES DRYCTN	CLEANERS
2001	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2002	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2003	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2004	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2005	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2006	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2007	KEANS THE CLEANER CLEANERS	CLEANERS
2007	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2008	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents

WIFE SAVER LAUND O MAT (Continued) **1013780796**

2009	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2010	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2011	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2012	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2013	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents
2014	KEANS LAUNDRY	Garment Pressing And Cleaners' Agents

---

24 **KEANS CLNS & LNDRY BR** **EDR Hist Cleaner** **1013783459**
3103 PERKINS RD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1960	KEANS CLNS & LNDRY BR	LAUNDRIES
1966	WIFE SAVER LANDRO MAT SELF	LAUNDRIES-SELF SERVE

---

24 **KEAN'S THE CLEANER** **LA DRYCLEANERS** **S107446262**
3109 PERKINS RD **LA ASBESTOS** **N/A**
BATON ROUGE, LA 70808 **LA REM**

DRYCLEANERS:

Facility ID:	39372
Owner:	FRANK H KEAN III
Owner Telephone:	Not reported
Store Telephone:	225-383-5553
Mailing Address:	9323 MAMMOTH AVE
Mailing City,St,Zip:	BATON ROUGE 70814
Contact:	Not reported

ASBESTOS:

Asbestos Disposal Facility Id:	Not reported
Site Location:	lobby
Issue Date:	05/09/2014
Expire Date:	08/07/2014
Qty Rec By Disposal Facility (CY):	3.00
AI#:	39372
Contractor AI Id:	Not reported
Alternate AI Id:	Not reported
Amount:	3
Unit:	Not reported
Scheduled Start:	05/20/2014
Scheduled End:	05/27/2014
Asbestos Contractors:	JJE Contracting LLC
Transporter Name:	JJE Contracting LLC
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	Not reported
SW Disposal Facility Address:	Not reported
SW Disposal Facility City:	Not reported
SW Disposal Facility State:	Not reported
SW Disposal Facility Zip:	Not reported
Parish:	Not reported
Deq Copy Received:	Not reported
Days Elapsed Since Issuance:	Not reported
Days To Expiration:	Not reported
Type Of Notification:	Not reported

KEAN'S THE CLEANER (Continued) **S107446262**

Type Of Operation:	Not reported
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	Not reported
Age In Years:	Not reported
Present Use:	Not reported
Prior Use:	Not reported
Mailing Address Line 1:	Not reported
Mailing Address City/State/Zip:	Not reported
Transporter AI Id:	Not reported
Transporter Id:	Not reported
Transporter Address:	Not reported
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Not reported
Total ADVFs Issued:	Not reported
Total Emergency ADVFs Issued:	Not reported
Total Emergency ADVF Revenue Generated:	Not reported
ADVF #:	ADVF-0031134
Total Non-Emergency ADVFs Issued:	Not reported
Total Non-Emergency ADVF Revenue Generated:	Not reported
Total ADVF Revenue Generated:	Not reported
Comments:	Not reported

REM:

AI Num:	39372
Evaluated And Closed:	Not reported
Program:	Solid Waste
EAC Type:	Not reported
Comments:	Not reported

---

24 **LA SPILLS** **S108596407**
N/A

3172 GREENWOOD
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	01/04/2006
Date Initiated:	Not reported
aiid:	4842
Incident Id:	84929
Incident Date:	01/03/2006
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	3172 Greenwood Baton Rouge
Incident Source Name:	East Baton Rouge City Parish - Central WWTP
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s05-0016 Overflow of sewage caused from stoppage in collection line. col
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

24 **LA SPILLS** **S108596395**
N/A

3162 GREENWOOD
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	12/12/2001
Date Initiated:	Not reported
aiid:	4842
Incident Id:	48098
Incident Date:	12/11/2001
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	3162 Greenwood Baton Rouge
Incident Source Name:	East Baton Rouge City Parish - Central WWTP
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s01-5346 sewage overflow - cs
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	sewage

---

24 **CRACKER BARREL #48** **LA SPILLS** **S109152701**
3030 PERKINS RD **LA REM** **N/A**
BATON ROUGE, LA 70808

SPILLS:

Region Code:	Not reported
Date Rec:	12/12/2007
Date Initiated:	Not reported
aiid:	69357
Incident Id:	101634
Incident Date:	12/11/2007
Incident Status:	**Pending Review**
Media Desc:	Air
Location Description:	Cracker Barrel/Texaco station 3030 Perkins Rd, Baton Rouge
Incident Source Name:	Cracker Barrel Stores Inc #48
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c07-4062 UST-Gas pumps do not have covers to prevent gasoline vapor fumes from escaping when filling gas tank...spoke to store mgr ...nothing done...complaintant also had gasoline splash onto hands when gas tank was full..cj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

Region Code:	Not reported
Date Rec:	04/28/2014
Date Initiated:	Not reported

CRACKER BARREL #48 (Continued) **S109152701**

aiid:	69357
Incident Id:	155625
Incident Date:	04/28/2014
Incident Status:	**Referred to USTD for TL Assignment**
Media Desc:	Soil
Location Description:	Cracker Barrel3030 Perkins Rd.Baton Rouge
Incident Source Name:	Cracker Barrel Stores Inc #48
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s14-42292UST - Gasoline seeping from the ground. col
Incident Type Desc:	UST Release, Submersible Turbine Pump / Physical or Mechanical Damage
Comments:	Confirmed Release = 4/28/14On 04/28/2014 @ 04:30am, I was on ER duty and received a call from SPOC. Cracker Barrel Convenience and gas station had gasoline emerging from an underground source. The store was closed and gasoline was seeping from the ground. Baton Rouge police and fire departments were on the scene. Air monitoring was being conducted with the results were nothing detected. I called Cracker Barrel's weekend emergency contact, Mike Butcher, in Lafayette, La. Mr. Butcher had limited information by only knowing there was a leak and that gasoline was on the ground. Mr. Butcher stated that he had called his emergency contact numbers in Baton Rouge and that Gator Environmental had been dispatched and Tank Testers were on the way. Upon arrival at Cracker Barrel, the State Police were onsite, Tank Testers, Baton Rouge Fire Department, Baton Rouge Police Department and Gator Environmental had not arrived. I spoke with the State Police and the Tank Testers supervisor. The amount of gasoline released was unknown. The clerk inside the Cracker Barrel store listed the loss amount as unregistered. The Tank Testers stated that the gas pumps had been activated by a customer which caused the pumps to prime up. The pumps were never de-activated so the pressure caused an o-ring on the pumps to fail causing the release. The release was confined to the manhole entry to the pumps. Tank Testers had dipped out the gasoline and the loss partially filled a 5-gallon bucket. On May 8, 2014, I received an e-mail from Cracker Barrel which was their notification letter. In the letter, it stated that the loss of gasoline from the station was calculated at 250 gallons. On May 15, 2014, I spoke with Larry Pentecost in UST/Remediation. Mr. Pentecost had received the information from SPOC at the same time that I did. UST/Remediation is already working the Cracker Barrel incident. JAK Site visit on 4-29-14. By this time, surface cleanup was completed. LP
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

REM:

AI Num:	69357
Evaluated And Closed:	12/30/2015
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 10033685

24 **AMERICAN GEN INVESTMENTS LLC** **EDR Hist Auto** **1013774826**
3030 PERKINS RD **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1966	HOLDENS FRIENDLY SERVICE	GASOLINE STATIONS
1980	CITGO SERVICE STATION	GASOLINE STATIONS
1980	LOUISIANA PETROLEUM SERV	GASOLINE STATIONS
1988	KAJON FOOD STORE INC	Grocery Stores
1994	CRACKER BARREL STORES INC	Gasoline Service Stations
1995	CRACKER BARREL STORES INC	Gasoline Service Stations
1998	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
1999	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2001	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2004	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2005	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2006	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2007	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2008	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2009	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2010	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2011	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2012	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2013	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC
2014	AMERICAN GEN INVESTMENTS LLC	Gasoline Service Stations, NEC

---

24 **CRACKER BARREL #48** **LA UST** **U003923586**
3030 PERKINS RD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	69357
Subject Item ID:	1
UST Tank Num:	35444
Tank Status:	**Removed**
Install Date:	03/14/1964
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported

CRACKER BARREL #48 (Continued) **U003923586**

Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35445
Tank Status:	**Removed**
Install Date:	03/14/1964
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	35446
Tank Status:	**Removed**
Install Date:	03/14/1964
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported

CRACKER BARREL #48 (Continued) **U003923586**

Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	70371
Tank Status:	**Active**
Install Date:	09/15/2014
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	70372
Tank Status:	**Active**
Install Date:	09/15/2014
Total Capacity:	10000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported

CRACKER BARREL #48 (Continued) **U003923586**

New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

24 **RALPHS TEXACO SERVICE** **EDR Hist Auto** **1013759122**
3063 PERKINS RD **N/A**
BATON ROUGE, LA 70806

EDR Hist Auto

Year:	Name:	Type:
1955	MARTINEZ TEXACO SERV	GASOLINE SERVICE STATIONS
1960	BROWNS TEXACO SERV GAS STA	GASOLINE STATIONS
1966	RALPHS TEXACO SERVICE	GASOLINE STATIONS
1969	ARAS TEXACO	Gasoline Service Stations
1970	ARAS TEXACO SERVICE	GASOLINE STATIONS
1970	ARAS TEXACO	Gasoline Service Stations

---

24 **PERKINS ROAD HARDWARE LLC** **RCRA NonGen / NLR** **1010318535**
3043 PERKINS RD **LAR000063545**
BATON ROUGE, LA 70808

RCRA NonGen / NLR:

Date form received by agency:	12/19/2006
Facility name:	PERKINS ROAD HARDWARE LLC
Facility address:	3043 PERKINS RD BATON ROUGE, LA 70808
EPA ID:	LAR000063545
Mailing address:	PERKINS RD BATON ROUGE, LA 70808
Contact:	JEFF CANADY
Contact address:	Not reported Not reported
Contact country:	US
Contact telephone:	(225) 343-6485
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

PERKINS ROAD HARDWARE LLC (Continued) **1010318535**

Owner/Operator Summary:

Owner/operator name:	JEFF CANADY
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	12/19/2006
Owner/Op end date:	Not reported

Owner/operator name:	JEFF CANADY
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/19/2006
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

---

24 **WHITE STAR AUTOMATIC LNDRY** **EDR Hist Cleaner** **1013782160**
3043 PERKINS RD **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	WHITE STAR AUTOMATIC LNDRY	LAUNDRIES
1955	WHITE STAR AUTOMATIC LNDRY	LAUNDRIES

24 **PERKINS RD HARDWARE EMERGENCY HW** **LA UST** **U003172965**
3043 PERKINS RD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	79088
Subject Item ID:	1
UST Tank Num:	50426
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection
UST Tank Num:	50427
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes

PERKINS RD HARDWARE EMERGENCY HW (Continued) **U003172965**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

UST Tank Num:	50428
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

---

24 **LA SPILLS** **S111929494**

S. EUGENE @ HONEYSUCKLE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	CR
Date Rec:	04/23/2012
Date Initiated:	04/23/2012
aiid:	4842
Incident Id:	139014
Incident Date:	04/19/2012
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	S. Eugene @ Honeysuckle Baton Rouge

(Continued) **S111929494**

Incident Source Name:	East Baton Rouge City Parish - Central WWTP
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Release/Spill, Sewage
Comments:	stoppage in main collection line resulted in release of approx 200 gals sewage from the manhole to the storm drain. stoppage cleared, area deodorized and disinfected. submitted report. md
Parameter:	Sewage
Quantity:	200 gallons
Other Substance Desc:	sewage 200 gals

---

24 **DIXIES MONO WASH LAUNDERETTE** **EDR Hist Cleaner** **1013784182**
2275 CHRISTIAN ST **N/A**
UNIVERSITY GARDENS, LA

EDR Hist Cleaner

Year:	Name:	Type:
1955	DIXIES MONO WASH LAUNDERETTE	LAUNDRIES-SELF SERVE

---

24 **GEORGE'S RESTAURANT** **LA SPILLS** **S110990484**
2943 PERKINS RD (UNDER OVERPASS) **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	CR
Date Rec:	01/07/2011
Date Initiated:	01/14/2011
aiid:	83561
Incident Id:	128520
Incident Date:	01/07/2011
Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	George's Restaurant 2943 Perkins Rd (under overpass) Baton Rouge
Incident Source Name:	East Baton Rouge Parish
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	Closed by site visit 01/14/2011
Incident Type Desc:	Complaint, Sewage
Comments:	I conducted a site visit on 01/14/2011. There was standing water in the street, which appeared to be stormwater. There was no evidence that the water came from George's Restaurant. I did not detect any foul odors in the area. mkm
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0

24 **LA SPILLS** **S108596306**
N/A

3127 GREENWOOD
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	01/23/2002
Date Initiated:	Not reported
aiid:	4842
Incident Id:	48976
Incident Date:	01/17/2002
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	3127 Greenwood
Incident Source Name:	East Baton Rouge City Parish - Central WWTP
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s02-0268 Stoppage in main line, sewer in ditch. col
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Sewage
Quantity:	400 gallons
Other Substance Desc:	Not reported

---

24 **LA SPILLS** **S110101522**
N/A

3047 GREENWOOD
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	03/20/2001
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	40879
Incident Date:	03/14/2001
Incident Status:	**Open**
Media Desc:	Not reported
Location Description:	3047 Greenwood Baton Rouge
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s01-1121 sewage by-pass
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

24 **LA SPILLS** **S110099601**
3047 GREENWOOD **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	09/01/2000
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	36412
Incident Date:	08/31/2000
Incident Status:	**Open**
Media Desc:	Water
Location Description:	3047 Greenwood BR, La
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s00-3494 stoppage in main line - release of 25 gals raw sewage to water. - jmn
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	raw sewage - 25 gals

---

24 **OVERPASS CLEANERS** **EDR Hist Cleaner** **1013787136**
2929 PERKINS RD **N/A**
BATON ROUGE, LA 70806

EDR Hist Cleaner

Year:	Name:	Type:
1969	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1970	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1971	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1972	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1973	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1974	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1975	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1976	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1977	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1978	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1979	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1980	OVERPASS CLEANERS INC	Drycleaning Plants, Except Rugs
1982	OVERPASS CLEANERS INC	Garment Pressing And Cleaners' Agents
1983	OVERPASS CLEANERS INC	Garment Pressing And Cleaners' Agents
1985	OVERPASS CLEANERS INC	Garment Pressing And Cleaners' Agents
1986	OVERPASS CLEANERS INC	Garment Pressing And Cleaners' Agents
1987	OVERPASS CLEANERS INC	Garment Pressing And Cleaners' Agents
1988	OVERPASS CLEANERS INC	Garment Pressing And Cleaners' Agents
1989	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1990	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1991	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1992	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1993	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1994	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1995	OVERPASS CLEANERS	CLEANERS

OVERPASS CLEANERS (Continued) **1013787136**

1995	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1996	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1997	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1998	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
1999	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2000	OVERPASS CLEANERS RETAIL AGT LA	CLEANERS
2000	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2001	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2002	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2003	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2004	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2005	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2006	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2007	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2008	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2009	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2010	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2011	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2012	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2013	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents
2014	OVERPASS CLEANERS INC	Laundry And Drycleaner Agents

---

24 **OVERPASS CLEANERS** **LA DRYCLEANERS** **S107446324**
2929 PERKINS RD **N/A**
BATON ROUGE, LA 70808

DRYCLEANERS:

Facility ID:	39434
Owner:	Ronald Mcintire
Owner Telephone:	Not reported
Store Telephone:	--
Mailing Address:	2929 Perkins Rd
Mailing City,St,Zip:	Baton Rouge, LA 70808
Contact:	Not reported

Facility ID:	39434
Owner:	RONALD MCINTIRE
Owner Telephone:	Not reported
Store Telephone:	225-383-8364
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact:	Not reported

---

24 **CONFEDERATE MOTOR WORKS** **RCRA NonGen / NLR** **1000987689**
2311 CHRISTIAN ST **FINDS** **LA0001014349**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	12/06/1994
Facility name:	CONFEDERATE MOTOR WORKS
Facility address:	2311 CHRISTIAN ST BATON ROUGE, LA 70808
EPA ID:	LA0001014349
Mailing address:	CHRISTIAN ST BATON ROUGE, LA 70808
Contact:	MATT CHAMBERS

CONFEDERATE MOTOR WORKS (Continued) **1000987689**

Contact address: 2311 CHRISTIAN ST
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 383-8663
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CONFEDERATE MOTOR WORKS
Owner/operator address: 2311 CHRISTIAN ST
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 383-8663
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

CONFEDERATE MOTOR WORKS (Continued) **1000987689**

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 12/30/1998
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003264789

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000987689
Registry ID: 110003264789
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003264789

---

24 **EXPERT AUTO SERVICE** **EDR Hist Auto** **1013768988**
2311 CHRISTIAN ST **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1971	EXPERT AUTO SERVICE	General Automotive Repair Shops
1972	EXPERT AUTO SERVICE	General Automotive Repair Shops
1973	EXPERT AUTO SERVICE	General Automotive Repair Shops
1974	EXPERT AUTO SERVICE	General Automotive Repair Shops
1975	EXPERT AUTO SERVICE	AUTOMOBILE REPAIRING
1975	EXPERT AUTO SERVICE	General Automotive Repair Shops
1980	CONNERS AUTO REPAIR	AUTOMOBILE REPAIRING
1989	CONNER AUTO REPAIR	General Automotive Repair Shops
1990	CONNERS AUTO REPAIR	AUTOMOBILE REPAIRING

24 **LANDRYS IMPORT SERVICE REPRS** **EDR Hist Auto** **1013769749**
2890 GREENWOOD DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1970	LANDRYS IMPORT SERVICE REPRS	AUTOMOBILE REPAIRING

---

24 **OVERPASS SERVICE STA** **EDR Hist Auto** **1013767076**
2540 PERKINS RD **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1945	OVERPASS SERVICE STA	GASOLINE AND OIL SERVICE STATIONS

---

25 **SPEEDWAY SUPERAMERICA LLC** **EDR Hist Auto** **1013753699**
2385 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1990	ECOL	GASOLINE STATIONS
1990	EMRO MARKETING COMPANY*	Gasoline Service Stations
1991	EMRO MARKETING COMPANY	Gasoline Service Stations
1992	EMRO MARKETING COMPANY	Gasoline Service Stations
1993	EMRO MARKETING COMPANY	Gasoline Service Stations
1994	EMRO MARKETING COMPANY	Gasoline Service Stations
1995	SPEEDWAY	GASOLINE STATIONS
1995	EMRO MARKETING COMPANY	Gasoline Service Stations
1996	EMRO MARKETING COMPANY	Gasoline Service Stations
1997	EMRO MARKETING COMPANY	Gasoline Service Stations
1998	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations
1999	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations
2000	SPEEDWAY SUPERAMERICA GAS SERV	GASOLINE STATIONS
2000	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations
2001	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations
2002	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations
2003	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2004	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2005	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2006	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2007	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2008	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2009	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2010	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2011	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2012	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2013	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC
2014	SPEEDWAY SUPERAMERICA LLC	Gasoline Service Stations, NEC

25 **AK & CO INVESTMENTS LLC** **LA UST** **U003924847**
2385 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	74019
Subject Item ID:	2
UST Tank Num:	10288
Tank Status:	**Active**
Install Date:	03/30/1979
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	10289
Tank Status:	**Active**
Install Date:	03/30/1979
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

AK & CO INVESTMENTS LLC (Continued) **U003924847**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	10290
Tank Status:	**Active**
Install Date:	03/30/1979
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	10291
Tank Status:	**Active**
Install Date:	03/30/1979
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

AK & CO INVESTMENTS LLC (Continued) **U003924847**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	10292
Tank Status:	**Active**
Install Date:	03/30/1979
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

25 **ECOL SERVICE CENTER** **EDR Hist Auto** **1021243498**
2373 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1986	ECOL SERVICE CENTER	General Automotive Repair Shops
1987	ECOL SERVICE CENTER	General Automotive Repair Shops
1988	ECOL SERVICE CENTER	General Automotive Repair Shops
1989	ECOL SERVICE CENTER	Gasoline Service Stations

---

25 **ECOL SELF SERVICE GAS STA** **EDR Hist Auto** **1013768873**
2375 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1980	ECOL SELF SERVICE GAS STA	GASOLINE STATIONS

---

25 **COLLEGE DRIVE EXXON GAS TA** **EDR Hist Auto** **1013762586**
2372 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1975	COLLEGE DRIVE EXXON GAS TA	GASOLINE STATIONS
1980	COLLEGE DRIVE EXXON GAS STA	GASOLINE STATIONS

---

25 **MIDAS AUTO SYSTEMS EXPERTS** **EDR Hist Auto** **1013760327**
2358 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1987	MIDAS MUFFLER SHOP	Automotive Repair Shops, NEC
1988	MIDAS MUFFLER SHOP	Automotive Repair Shops, NEC
2000	G P R MUFFLER SHOP	AUTOMOBILE REPAIRING & SERVICE
2001	MIDAS AUTO SYSTEMS EXPERTS	General Automotive Repair Shops
2002	MIDAS AUTO SYSTEMS EXPERTS	General Automotive Repair Shops
2003	MIDAS AUTO SYSTEMS EXPERTS	General Automotive Repair Shops
2007	MIDAS AUTO SVC EXPERTS AUTO	AUTOMOBILE REPAIRING & SERVICE

25 MIDAS MUFFLER SHOP — **RCRA-CESQG** — **1004708402**
2358 COLLEGE — **FINDS** — **LAD125624742**
BATON ROUGE, LA 70808 — **ECHO**

RCRA-CESQG:

Date form received by agency:	03/10/1987
Facility name:	MIDAS MUFFLER SHOP
Facility address:	2358 COLLEGE BATON ROUGE, LA 70808
EPA ID:	LAD125624742
Mailing address:	S SHERWOOD FOREST BLVD BATON ROUGE, LA 70816
Contact:	SARA PEPITONE
Contact address:	S SHERWOOD FOREST BLVD BATON ROUGE, LA 70816
Contact country:	US
Contact telephone:	(225) 293-9487
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SARA PEPITONE
Owner/operator address:	10610 FLORIDA BLVD BATON ROUGE, LA 70815
Owner/operator country:	US
Owner/operator telephone:	(225) 272-5921
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported
Owner/operator name:	WILLIAM C PEPITONE
Owner/operator address:	10610 FLORIDA BLVD BATON ROUGE, LA 70815
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 272-5921
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

MIDAS MUFFLER SHOP (Continued) **1004708402**

Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110003284017

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004708402
Registry ID: 110003284017
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003284017

---

25 **RACEWAY SELF SERVICE GAS ETA** **EDR Hist Auto** **1013773395**
2330 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1975	RACEWAY SELF SERVICE GAS ETA	GASOLINE STATIONS
1980	RACETRACK SELF SERV GAS STA	GASOLINE STATIONS

25 **RACETRAC** **LA UST** **U003987169**
2300 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	71938
Subject Item ID:	1
UST Tank Num:	29301
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	29302
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

RACETRAC (Continued) **U003987169**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	29303
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	9500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

25 **RACETRAC** **LA REM** **S112659119**
2300 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

REM:

AI Num:	71938
Evaluated And Closed:	03/01/2012
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 8309888.

26 GROUNDWATER TECHNOLO — **ICIS** — **1004515038**
2314 S ACADIAN THRWY — **FINDS** — **N/A**
BATON ROUGE, LA 70806 — **ECHO**

ICIS:

Enforcement Action ID:	LA000A0000220330012100001
FRS ID:	110001376127
Action Name:	GROUNDWATER TECHNOLO 220330012100001
Facility Name:	GROUNDWATER TECHNOLO
Facility Address:	2314 S ACADIAN THRWY BATON ROUGE, LA 70806
Enforcement Action Type:	Notice of Violation
Facility County:	EAST BATON ROUGE
Program System Acronym:	AIR
Enforcement Action Forum Desc:	Administrative - Informal
EA Type Code:	NOV
Facility SIC Code:	9999
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.426113
Longitude in Decimal Degrees:	-91.150647
Permit Type Desc:	Not reported
Program System Acronym:	LA0000002203300121
Facility NAICS Code:	999999
Tribal Land Code:	Not reported

FINDS:

Registry ID: 110001376127

Environmental Interest/Information System

AFS (Aerometric Information Retrieval System (AIRS) Facility Subsystem) replaces the former Compliance Data System (CDS), the National Emission Data System (NEDS), and the Storage and Retrieval of Aerometric Data (SAROAD). AIRS is the national repository for information concerning airborne pollution in the United States. AFS is used to track emissions and compliance data from industrial plants. AFS data are utilized by states to prepare State Implementation Plans to comply with regulatory programs and by EPA as an input for the estimation of total national emissions. AFS is undergoing a major redesign to support facility operating permits required under Title V of the Clean Air Act.

AIR MINOR

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004515038
Registry ID:	110001376127
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110001376127

26 **CIRCLE K #9730** **LA RGA LUST** **S115491026**
2300 S ACADIAN THWY **N/A**
BATON ROUGE, LA

RGA LUST:

2012	CIRCLE K #9730	2300 S ACADIAN THWY
2011	CIRCLE K #9730	2300 S ACADIAN THWY
2010	CIRCLE K #9730	2300 S ACADIAN THWY

---

26 **CIRCLE K #9730** **LA UST** **U003987157**
2300 S ACADIAN THWY **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	71560
Subject Item ID:	2
UST Tank Num:	22538
Tank Status:	**Active**
Install Date:	04/09/1983
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	22539
Tank Status:	**Active**
Install Date:	04/09/1983
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported

CIRCLE K #9730 (Continued) **U003987157**

Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	22540
Tank Status:	**Active**
Install Date:	05/09/1983
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

26 **PARSONS INC** **EDR Hist Auto** **1021496679**
2300 ACADIAN THRUWAY **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1985	PARSONS INC	Grocery Stores
1986	PARSONS INC	Grocery Stores
1987	PARSONS INC	Grocery Stores
1988	PARSONS INC	Grocery Stores
1989	PARSONS INC	Convenience Stores
1990	PARSONS INC	Convenience Stores

---

26 **SHELL #142059** **LA RGA LUST** **S115492960**
2300 S ACADIAN THWY **N/A**
BATON ROUGE, LA

RGA LUST:

2008	SHELL #142059	2300 S ACADIAN THWY
2006	SHELL #142059	2300 S ACADIAN THWY

---

26 **ACADIAN SHELL SERVICE STATION** **EDR Hist Auto** **1013771140**
2300 S ACADIAN THRWY **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1970	ACADIAN SHELL	GASOLINE STATIONS
1973	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1974	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1975	ACADIAN SHELL	GASOLINE STATIONS
1975	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1976	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1977	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1978	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1979	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1980	ACADIAN SHELL	GASOLINE STATIONS
1980	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1982	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1983	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1985	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1986	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1987	ACADIAN SHELL SERVICE STATION	Gasoline Service Stations
1990	PARSONS TOM INC GAS STA	GASOLINE STATIONS
1991	PARSONS INC	Convenience Stores
1992	PARSONS INC	Convenience Stores
1993	PARSONS INC	Convenience Stores
1994	PARSONS INC	Convenience Stores
1995	PARSON INK ACADIAN SHELL GAS ST	GASOLINE STATIONS
1995	PARSONS INC	Convenience Stores
1996	PARSONS INC	Convenience Stores
1997	PARSONS INC	Convenience Stores
1998	PARSONS INC	Convenience Stores
1999	PARSONS INC	Convenience Stores

ACADIAN SHELL SERVICE STATION (Continued) **1013771140**

2000	PARSONS INC	Convenience Stores
2009	PARSONS INC	Convenience Stores
2010	PARSONS INC	Convenience Stores
2011	PARSONS INC	Convenience Stores
2012	PARSONS INC	Convenience Stores
2013	PARSONS INC	Convenience Stores

---

26 **CIRCLE K #9730** **LA SPILLS** **S108594601**
2300 S ACADIAN THWY **LA REM** **N/A**
BATON ROUGE, LA 70808

SPILLS:

Region Code:	Not reported
Date Rec:	08/14/2008
Date Initiated:	Not reported
aiid:	71560
Incident Id:	108018
Incident Date:	08/13/2008
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Circle K Store #2709730 2300 S Acadian Thrwy Baton Rouge
Incident Source Name:	Circle K #2709729
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s08-3199 UST - regular unleaded tank inconclusive July SIR...cj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

Region Code:	Not reported
Date Rec:	03/10/2006
Date Initiated:	Not reported
aiid:	71560
Incident Id:	86368
Incident Date:	03/10/2006
Incident Status:	**Referred to Enforcement**
Media Desc:	Water/Soil
Location Description:	2300 S Acadian Thruway Baton Rouge
Incident Source Name:	Shell #142059
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s06-0723 Petroleum hydrocarbons were found above RECAP in the soil. CMD
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

CIRCLE K #9730 (Continued) **S108594601**

REM:

AI Num:	71560
Evaluated And Closed:	01/15/2013
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 8682278.

---

26 **CIRCLE K #2709730** **LA RGA LUST** **S115490857**
2300 S ACADIAN THWY **N/A**
BATON ROUGE, LA

RGA LUST:

2009 CIRCLE K #2709730 2300 S ACADIAN THWY

---

26 **CIRCLE K #2709729** **LA RGA LUST** **S115490856**
2300 S ACADIAN THWY **N/A**
BATON ROUGE, LA

RGA LUST:

2007 CIRCLE K #2709729 2300 S ACADIAN THWY

---

26 **RAINBOW MARKETERS INC** **EDR Hist Auto** **1013768133**
2313 S ACADIAN TRWY **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1972	SPEARS JAKE	Gasoline Service Stations
1973	SPEARS JAKE	Gasoline Service Stations
1974	SPEARS JAKE	Gasoline Service Stations
1975	ACADIAN THRUWAY GULF	GASOLINE STATIONS
1975	SPEARS JAKE	Gasoline Service Stations
1976	SPEARS JAKE	Gasoline Service Stations
1980	ACADIAN THRUWAY GULF	GASOLINE STATIONS
1990	ACADIAN CHEVRON INC	SERVICE STATIONS
1990	ACADIAN CHEVRON INC	GASOLINE STATIONS
1995	ACADIAN CHEVRON GAS MA	GASOLINE STATIONS
1997	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
1998	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
1999	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2000	RAINBOW MARKETERS GAS SERV STA	GASOLINE STATIONS
2000	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2001	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2002	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2003	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2004	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2005	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2005	RAINBOW MARKETERS INC	Gasoline Service Stations, NEC
2006	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC

RAINBOW MARKETERS INC (Continued) **1013768133**

2007	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2008	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2009	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2010	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2011	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2012	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2013	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC
2014	CITGO STN & CONVENIENCE STR	Gasoline Service Stations, NEC

---

26 **JET 24 FOOD STORE #42** **ICIS** **1005640875**
2313 ACADIAN THRUWAY & I-10 **FINDS** **N/A**
BATON ROUGE, LA 70808 **LA UST**
ECHO

ICIS:

Enforcement Action ID:	06-2000-0380
FRS ID:	110010658608
Action Name:	JET 24 FOOD STORE #42
Facility Name:	JET 24 FOOD STORE #42
Facility Address:	2313 ACADIAN THRUWAY & I-10 BATON ROUGE, LA 70808
Enforcement Action Type:	RCRA 9006 Field Citation (UST)
Facility County:	EAST BATON ROUGE
Program System Acronym:	ICIS
Enforcement Action Forum Desc:	Administrative - Formal
EA Type Code:	9006FC
Facility SIC Code:	5411
Federal Facility ID:	Not reported
Latitude in Decimal Degrees:	30.42352
Longitude in Decimal Degrees:	-91.14528
Permit Type Desc:	Not reported
Program System Acronym:	12752
Facility NAICS Code:	Not reported
Tribal Land Code:	Not reported

Facility Name:	JET 24 FOOD STORE #42
Address:	2313 ACADIAN THRUWAY & I-10
Tribal Indicator:	N
Fed Facility:	Not reported
NAIC Code:	Not reported
SIC Code:	5411

FINDS:

Registry ID: 110010658608

Environmental Interest/Information System

ICIS (Integrated Compliance Information System) is the Integrated Compliance Information System and provides a database that, when complete, will contain integrated Enforcement and Compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain Enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions. This information is maintained in ICIS by EPA in the Regional offices and it Headquarters. A future release of ICIS will replace the Permit

JET 24 FOOD STORE #42 (Continued) **1005640875**

Compliance System (PCS) which supports the NPDES and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities occurring in the Region that support Compliance and Enforcement programs. These include; Incident Tracking, Compliance Assistance, and Compliance Monitoring.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

UST:

Master Agency Id:	20620
Subject Item ID:	2
UST Tank Num:	37839
Tank Status:	**Removed**
Install Date:	04/01/1990
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	37840
Tank Status:	**Active**
Install Date:	04/01/1990
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported

JET 24 FOOD STORE #42 (Continued) **1005640875**

MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	37841
Tank Status:	**Active**
Install Date:	04/01/1990
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	37842
Tank Status:	**Active**
Install Date:	04/01/1990
Total Capacity:	8000

JET 24 FOOD STORE #42 (Continued) **1005640875**

Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	37843
Tank Status:	**Active**
Install Date:	04/01/1990
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported

JET 24 FOOD STORE #42 (Continued) **1005640875**

Pipe Method Description: Not reported

ECHO:

Envid:	1005640875
Registry ID:	110010658608
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110010658608

---

26 **HIT & RUN FOOD STORES #3** **LA AIRS** **S113393386**
2313 S ACADIAN THRWY **N/A**
BATON ROUGE, LA 70808

AIRS:

Permit Number:	0840-00121-00
Permit Type Desc:	State permit (unspecified)
AI No#:	20620
Activity No#:	PER19880001
Region Code:	Capital
Latitude:	30.426146
Longitude:	-91.150194
Title Desc:	GROUNDWATER TECHNOLO
Mailing Address:	PO Box 61
Mailing Address2:	Not reported
Mailing City/State/Zip:	Youngsville, LA 705920061
Issue Date:	11/10/1988
Expiration Date:	Not reported
Effective End Date:	11/10/1998
Effective Flag:	N
Extended Flag:	N
EDR Link ID:	0840-00121-00

---

26 **NEUROMEDICAL CTR** **RCRA NonGen / NLR** **1000367425**
2237 S ACADIAN STE 400 **FINDS** **LAD982294852**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	02/09/1988
Facility name:	NEUROMEDICAL CTR
Facility address:	2237 S ACADIAN STE 400 BATON ROUGE, LA 70808
EPA ID:	LAD982294852
Mailing address:	S ACADIAN STE 400 BATON ROUGE, LA 70808
Contact:	JAMES LAMBERT
Contact address:	2237 S ACADIAN STE 400 BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 928-5972
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	THE NEUROMEDICAL CTR
Owner/operator address:	UNKNOWN

NEUROMEDICAL CTR (Continued) **1000367425**

UNKNOWN, LA 00000
Owner/operator country: Not reported
Owner/operator telephone: (000) 000-0000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003308625

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000367425
Registry ID: 110003308625
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003308625

26 **LWCC** **LA UST** **U004156226**
2237 S ACADIAN THRUWAY **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	163707
Subject Item ID:	1
UST Tank Num:	57666
Tank Status:	**Removed**
Install Date:	01/01/1984
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

27 **AMERICAN CATALYST SVCS INC** **RCRA NonGen / NLR** **1000360125**
4884 CONSTITUTION SUITE 2F **FINDS** **LAT230013450**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	04/06/1984
Facility name:	AMERICAN CATALYST SVCS INC
Facility address:	4884 CONSTITUTION SUITE 2F BATON ROUGE, LA 70808
EPA ID:	LAT230013450
Mailing address:	PO BOX 772 PORT ALLEN, LA 70767
Contact:	HEBERT MELVIN
Contact address:	PO BOX 772 PORT ALLEN, LA 70767
Contact country:	US
Contact telephone:	(225) 383-6049
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

AMERICAN CATALYST SVCS INC (Continued) **1000360125**

Owner/Operator Summary:

Owner/operator name:	MELVIN HEBERT
Owner/operator address:	4884 CONSTITUTION SUITE 2F BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	Yes
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110003368980

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000360125
Registry ID:	110003368980
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003368980

27 C & R ENVIRONMENTAL SVC INC — **RCRA NonGen / NLR** — **1001127329**
5555 HILTON AVE STE 325 — **FINDS** — **LAR000019398**
BATON ROUGE, LA 70808 — **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	01/24/1997
Facility name:	C & R ENVIRONMENTAL SVC INC
Facility address:	5555 HILTON AVE STE 325 BATON ROUGE, LA 70808
EPA ID:	LAR000019398
Mailing address:	HILTON AVE STE 325 BATON ROUGE, LA 70808
Contact:	BAHRAM CHARKHIAN
Contact address:	5555 HILTON AVE STE 325 BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 925-8297
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JTS MGMT CORP
Owner/operator address:	243 S ACADIAN THRUWAY BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 922-4019
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

FINDS:

Registry ID: 110009583904

C & R ENVIRONMENTAL SVC INC (Continued) **1001127329**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001127329
Registry ID: 110009583904
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009583904

---

27 CHURCHILL ENVIRONMENTAL SVCS INC **RCRA NonGen / NLR** **1000622635**
5420 CORPORATE BLVD STE 305 **FINDS** **LAD985199421**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 03/09/2010
Facility name: CHURCHILL ENVIRONMENTAL SVCS INC
Facility address: 5420 CORPORATE BLVD STE 305
BATON ROUGE, LA 70808
EPA ID: LAD985199421
Mailing address: CORPORATE BLVD STE 305
BATON ROUGE, LA 70808
Contact: RAYMOND WHITE
Contact address: 5420 CORPORATE BLVD STE 305
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 923-1904
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: CHURCHILL ENVIRONMENTAL
Owner/operator address: 5420 CORPORATE BLVD STE 305
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 923-1904
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: CHURCHILL ENVIRONMENTAL
Owner/operator address: 5420 CORPORATE BLVD STE 305
BATON ROUGE, LA 70808
Owner/operator country: US
Owner/operator telephone: (225) 923-1904
Legal status: Private

CHURCHILL ENVIRONMENTAL SVCS INC (Continued) **1000622635**

Owner/Operator Type: Operator
Owner/Op start date: 03/09/2010
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Historical Generators:
Date form received by agency: 06/03/1991
Site name: CHURCHILL ENVIRONMENTAL SVCS INC
Classification: Not a generator, verified

. Waste code: NONE
. Waste name: None

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/09/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

CHURCHILL ENVIRONMENTAL SVCS INC (Continued) **1000622635**

FINDS:

Registry ID: 110003326954

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000622635
Registry ID:	110003326954
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003326954

---

27 **LAMAR BUILDING** **LA UST** **U003133057**
5321 CORPORATE BLVD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	78911
Subject Item ID:	1
UST Tank Num:	46809
Tank Status:	**Removed**
Install Date:	06/01/1986
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported

LAMAR BUILDING (Continued) **U003133057**

Other Material: Not reported
Pipe Method Description: Suction: With Release Detection

---

27 BONE & JOINT CLINIC **RCRA-SQG** **1000195115**
5630 BANKERS AVE **FINDS** **LAD071940191**
BATON ROUGE, LA 70808 **ECHO**

RCRA-SQG:
Date form received by agency: 02/24/1988
Facility name: BONE & JOINT CLINIC
Facility address: 5630 BANKERS AVE
BATON ROUGE, LA 70808
EPA ID: LAD071940191
Mailing address: BANKERS AVE
BATON ROUGE, LA 70808
Contact: STEVE DONAHUE
Contact address: 5630 BANKERS AVE
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 927-0050
Contact email: Not reported
EPA Region: 06
Classification: Small Small Quantity Generator
Description: Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:
Owner/operator name: BONE & JOINT CLINIC INC
Owner/operator address: 5630 BANKERS AVE
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (000) 000-0000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

BONE & JOINT CLINIC (Continued) **1000195115**

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003277882

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000195115
Registry ID: 110003277882
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003277882

---

28 WHITNEY BANK - BOCAGE BRANCH **LA VCP S112658937**
8006 JEFFERSON HWY **LA REM N/A**
BATON ROUGE, LA 70810

VCP:

DEQ AI #:	33815
Date Closed:	01/07/2002
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	4
Applicant name:	Whitney Bank Corporation
DEQ Contact:	Carey Dicharry
Date of Applicantion:	11/28/2000
Remedial Investigaton/Action Phase:	Action Phase
Status:	COC
Unrestricted Use:	No
Investigation Approval Date:	Not reported
Use Restrictions/Institutional Controls A:	A
Use Restrictions/Institutional Controls B:	B
Use Restrictions/Institutional Controls C:	C
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	E
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	I
Latitude:	Not reported
Longitude:	Not reported

REM:
AI Num: 33815

WHITNEY BANK - BOCAGE BRANCH (Continued) **S112658937**

Evaluated And Closed: 01/07/2002
Program: VRP
EAC Type: Granted VRP Completion Certificate
Comments: EDMS ID 1134981.

---

28 GULF OIL CORP. **LA HIST LUST** **S106033567**
7930 JEFFERSON HWY. & OWEN **N/A**
BATON ROUGE, LA 70809

HIST LUST:

Facility ID:	17-001943
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	08/06/1990
Date Confirmed 2:	Not reported
Incident Number:	90-2-0156
Incident Date:	08/03/1990
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	TIM JOHNSON/ CHEVRON
Reported By 2:	Not reported
Owner ID:	00061700
Owner Name:	CHEVRON USA PRODUCTS COMPANY
Owner Address:	2300 WINDY RIDGE PARKWAY #800
Owner City,St,Zip:	ATLANTA, GA 30339
Assessment Pending Info:	Yes
Assessment Request Date:	08/06/1990
Assessment Plan Due Date:	10/26/1990
Assessment Plan Received Date:	09/06/1990
Assessment Approved Date:	01/11/1993
Assessment Contractor:	RUST ENVIRONMENT & INFRASTRUCTURE
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	01/25/1991
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	04/14/1992
Corrective Plan Approved Date:	05/16/1994
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: DEQ APPROVED WORK PLAN TO COLLECT GW SAMPLES ON 9/15/94. RECIEVEDSUMMARY AND RECOMMENDATIONS ON 1/13/95: HIGHEST BTEX LEVELS IN MW-1AND MW-4. DEQ LETTER 3/17/95 CONTINUE QTLY REPORTS. QTLY REPORTSSUBMITTED. REC'D QTLY MONITORING PROPOSAL ON 12/15/98.

LA HIST LUST ASSESMENT:

Comments: SITE IS CHEVRON. PHASE SEPARATED HYDROCARBONS (PSH) IN WELL. SOILBORINGS NEAR

GULF OIL CORP. (Continued) **S106033567**

TANK PAD. SITE TO BE CLOSED AND USTS REMOVED. DEQINSPCET. 6/27 & 28/91. REC'D UST REMOVAL REPORT 8/91. REC'D PHASE IIASSESS. 9/91. QTLY REPORTS SUBMITTED.

LA HIST LUST CORRECTIVE ACTION:

Comments: HALLIBURTON NUS SUBMITTED A PROPOSAL FOR SITE REMEDIATION ON 4/12/92.DEQ LETTER 1/20/94 STILL REVIEWING REMEDIATION PROPOSAL AND TOCONTINUE QTLY MONITORING. REC'D CAP AMENDMENT ON 11/15/93. DEQAPPROVED CAP AMENDMENT ON 5/16/94.

Facility ID:	17-001943
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	90-2-0156
Incident Date:	08/03/1990
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00061700
Owner Name:	CHEVRON USA PRODUCTS COMPANY
Owner Address:	2300 WINDY RIDGE PARKWAY #800
Owner City,St,Zip:	ATLANTA, GA 30339
Assessment Pending Info:	Yes
Assessment Request Date:	08/06/1990
Assessment Plan Due Date:	10/26/1990
Assessment Plan Received Date:	09/06/1990
Assessment Approved Date:	01/11/1993
Assessment Contractor:	RUST ENVIRONMENT & INFRASTRUCTURE
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	04/14/1992
Corrective Plan Approved Date:	05/16/1994
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	PUMP AND TREATMENT
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: DEQ APPROVED WORK PLAN TO COLLECT GW SAMPLES ON 9/15/94. RECIEVEDSUMMARY AND RECOMMENDATIONS ON 1/13/95: HIGHEST BTEX LEVELS IN MW-1AND MW-4. DEQ LETTER 3/17/95 CONTINUE QTLY REPORTS. QTLY REPORTSSUBMITTED. REC'D QTLY MONITORING PROPOSAL ON 12/15/98.

LA HIST LUST ASSESMENT:

Comments: SITE IS CHEVRON. PHASE SEPARATED HYDROCARBONS (PSH) IN WELL. SOILBORINGS NEAR TANK PAD. SITE TO BE CLOSED AND USTS REMOVED. DEQINSPCET. 6/27 & 28/91. REC'D UST REMOVAL REPORT 8/91. REC'D PHASE IIASSESS. 9/91. QTLY REPORTS SUBMITTED.

GULF OIL CORP. (Continued) **S106033567**

LA HIST LUST CORRECTIVE ACTION:
Comments: HALLIBURTON NUS SUBMITTED A PROPOSAL FOR SITE REMEDIATION ON 4/12/92.DEQ LETTER 1/20/94 STILL REVIEWING REMEDIATION PROPOSAL AND TOCONTINUE QTLY MONITORING. REC'D CAP AMENDMENT ON 11/15/93. DEQAPPROVED CAP AMENDMENT ON 5/16/94.

---

29 **2011 MISSISSIPPI RIVER FLOOD** **SEMS-ARCHIVE** **1014915082**
10930 HWY 67 **LAN000607169**
BENTON, LA

SEMS-ARCHIVE:

Site ID:	607169
EPA ID:	LAN000607169
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0607169
Federal Facility:	Not a Federal Facility
NPL Status:	Not on the NPL
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)

---

30 **PREFERRED CARPET CLEANING** **EDR Hist Cleaner** **1018440216**
2603 E LAKESHORE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Cleaner

Year:	Name:	Type:
1983	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1985	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1986	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1987	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1988	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1989	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1990	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1991	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning
1992	PREFERRED CARPET CLEANING	Carpet And Upholstery Cleaning

---

30 **LAKES @ CARRIAGEWOOD** **FINDS** **1009606403**
ESTATES **ECHO** **N/A**
BATON ROUGE, LA 70809

FINDS:

Registry ID: 110030760120

Environmental Interest/Information System
US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting

LAKES @ CARRIAGEWOOD (Continued) **1009606403**

requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1009606403
Registry ID:	110030760120
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110030760120

---

31 **AM MART II** **LA HIST LUST** **U001898073**
2400 HIGHLAND **LA UST** **N/A**
BATON ROUGE, LA 70819

HIST LUST:

Facility ID:	17-010249
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	01/17/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0064
Incident Date:	01/17/1991
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00553100
Owner Name:	AMERICAN GROCERIES, INC.
Owner Address:	3764 PLANK ROAD
Owner City,St,Zip:	BATON ROUGE, LA 70807
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

AM MART II (Continued) **U001898073**

LA HIST LUST INCIDENT:
Comments: WATER FOUND IN SUPER UNLEADED UST. DEQ REQUESTED TIGHTNESS TEST.

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-010249
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0064
Incident Date:	01/17/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00553100
Owner Name:	AMERICAN GROCERIES, INC.
Owner Address:	3764 PLANK ROAD
Owner City,St,Zip:	BATON ROUGE, LA 70807
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: WATER FOUND IN SUPER UNLEADED UST. DEQ REQUESTED TIGHTNESS TEST.

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

AM MART II (Continued) **U001898073**

UST:

Master Agency Id:	76343
Subject Item ID:	1
UST Tank Num:	27383
Tank Status:	**Removed**
Install Date:	02/20/1981
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Yes
Pipe Method Description:	Not reported
UST Tank Num:	27384
Tank Status:	**Removed**
Install Date:	02/20/1981
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported

AM MART II (Continued) **U001898073**

A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Yes
Pipe Method Description:	Not reported

UST Tank Num:	27385
Tank Status:	**Removed**
Install Date:	02/20/1981
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Yes
Pipe Method Description:	Not reported

---

32 **SUPERB CLEANERS** **LA DRYCLEANERS** **S107446290**
2626 BALIS DR **N/A**
BATON ROUGE, LA 70808

DRYCLEANERS:

Facility ID:	39529
Owner:	Walker Thomas
Owner Telephone:	Not reported
Store Telephone:	--
Mailing Address:	2626 Balis Dr
Mailing City,St,Zip:	Baton Rouge, LA 70808
Contact:	Not reported

Facility ID:	39529
Owner:	WALKER THOMAS
Owner Telephone:	Not reported

SUPERB CLEANERS (Continued) **S107446290**

Store Telephone: 225-926-5624
Mailing Address: Not reported
Mailing City,St,Zip: Not reported
Contact: Not reported

---

32 **SUPERB CLEANERS** **EDR Hist Cleaner** **1013780992**
2626 BALIS DR **N/A**
BATON ROUGE, LA

EDR Hist Cleaner

Year:	Name:	Type:
1950	SUPERB CLEANERS	CLEANERS AND DYERS
1955	SUPERB CLEANERS	CLEANERS AND DYERS
1960	SUPERB CINS	CLEANERS AND DYERS
1966	SUPERB CLEANERS	CLEANERS AND DYERS
1970	SUPERB CLEANERS	CLEANERS AND DYERS
1972	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1974	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1975	SUPERB CLEANERS	CLEANERS AND DYERS
1976	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1977	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1978	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1979	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1980	SUPERB CLEANERS	CLEANERS AND DYERS
1980	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1982	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1983	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1985	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1986	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1987	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1988	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1989	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1990	SUPERB DRY CLEANERS	CLEANERS AND DYERS
1990	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1991	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1992	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1993	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1994	SUPERB CLEANERS	Drycleaning Plants, Except Rugs
1995	SUPERB DRY CLEANERS	CLEANERS
1995	SUPERB CLEANERS INC	Drycleaning Plants, Except Rugs
1996	SUPERB CLEANERS INC	Drycleaning Plants, Except Rugs
1997	SUPERB CLEANERS INC	Drycleaning Plants, Except Rugs
1998	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
1999	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2000	SUPERB DRYCLEANERS & LAUNDRY DR	CLEANERS
2000	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2001	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2002	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2003	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2004	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2005	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2006	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2007	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2008	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs
2009	SUPERB DRYCLEANERS & LAUNDRY	Drycleaning Plants, Except Rugs

33 MCKINLEY HIGH SCHOOL MERCURY SPILL — **SEMS** — **1014915090**
800 E. MCKINLEY STREET — **LAN000607178**
BATON ROUGE, LA 70802

SEMS:

Site ID:	607178
EPA ID:	LAN000607178
Federal Facility:	N
NPL:	Not on the NPL
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)

Following information was gathered from the prior CERCLIS update completed in 10/2013:

Site ID:	0607178
EPA ID:	LAN000607178
Facility County:	EAST BATON ROUGE
Short Name:	MCKINLEY HIGH SCHOOL MERC
Congressional District:	Not reported
IFMS ID:	A6BV
SMSA Number:	Not reported
USGC Hydro Unit:	Not reported
Federal Facility:	Not a Federal Facility
DMNSN Number:	0.00000
Site Orphan Flag:	Not reported
RCRA ID:	Not reported
USGS Quadrangle:	Not reported
Site Init By Prog:	O
NFRAP Flag:	Not reported
Parent ID:	Not reported
RST Code:	Not reported
EPA Region:	06
Classification:	Not reported
Site Settings Code:	Not reported
NPL Status:	Not on the NPL
DMNSN Unit Code:	Not reported
RBRAC Code:	Not reported
RResp Fed Agency Code:	Not reported
Non NPL Status:	Removal Only Site (No Site Assessment Work Needed)
Non NPL Status Date:	08/10/11
Site Fips Code:	22033
CC Concurrence Date:	/ /
CC Concurrence FY:	Not reported
Alias EPA ID:	Not reported
Site FUDS Flag:	Not reported

CERCLIS Site Contact Name(s):

Contact ID:	13000810.00000
Contact Name:	Mark Hayes
Contact Tel:	(214) 665-2705
Contact Title:	On-Scene Coordinator (OSC)
Contact Email:	hayes.mark@epa.gov

Alias Comments:	Not reported
Site Description:	Not reported

CERCLIS Assessment History:

Action Code:	001
Action:	REMOVAL
Date Started:	08/09/11

MCKINLEY HIGH SCHOOL MERCURY SPILL (Continued) **1014915090**

Date Completed:	08/12/11
Priority Level:	Not reported
Operable Unit:	SITEWIDE
Primary Responsibility:	EPA Fund-Financed
Planning Status:	Approved
Urgency Indicator:	Not reported
Action Anomaly:	Not reported

---

34 **EXXON STATION 53838** **LA HIST LUST** **S106033743**
4527 PERKINS RD **LA SPILLS** **N/A**
BATON ROUGE, LA 70803

HIST LUST:

Facility ID:	17-004220
Facility Parish:	EAST BATON ROUGE
Substance Name:	WASTE OIL
Substance Name 2:	Not reported
Quantity:	50 GAL.
Quantity 2:	Not reported
Date Confirmed:	06/28/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0223
Incident Date:	06/27/1991
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	DON SIMPSON
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	02/12/1991
Assessment Approved Date:	07/16/1991
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: WASTE OIL LINE REMOVED DUE TO UST LEAK. LINE WAS REPAIRED.

EXXON STATION 53838 (Continued) **S106033743**

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-004220
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0223
Incident Date:	06/27/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	02/12/1991
Assessment Approved Date:	07/16/1991
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: WASTE OIL LINE REMOVED DUE TO UST LEAK. LINE WAS REPAIRED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

SPILLS:

Region Code:	Not reported
Date Rec:	04/23/2001
Date Initiated:	Not reported
aiid:	Not reported

EXXON STATION 53838 (Continued) **S106033743**

Incident Id:	41763
Incident Date:	04/20/2001
Incident Status:	**Open**
Media Desc:	Soil
Location Description:	Exxon Mobil 4527 Perkins Rd, Baton Rouge
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s01-1536 While performing an assessment of soil and ground water concentration, the above exceedances were discovered. las.
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Soil Concentrations and Ground Water Concentrations

Region Code:	CR
Date Rec:	03/23/2011
Date Initiated:	05/10/2011
aiid:	15667
Incident Id:	131458
Incident Date:	03/23/2011
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	ExxonMobil #5-3838 4527 Perkins Rd. Baton Rouge
Incident Source Name:	ExxonMobil Corp - RAS #53838
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	Confirmed Release 05/10/2011, REM Unknown. Phase II results above RECAP SS for Gas, Oil & Diesel. Will close out using MO-1 & established LRS after all wells P&A'd. 10/21/11 - Incident closed using MO-1 and established LRS, all wells P&Ad. luc
Incident Type Desc:	UST Rem, Unknown
Comments:	Confirmed Release 05/10/2011, REM Unknown. Phase II results above RECAP SS for Gas, Oil & Diesel. Will close out using MO-1 & established LRS after all wells P&A'd. 10/21/11 - Incident closed using MO-1 and established LRS, all wells P&Ad. luc
Parameter:	0
Quantity:	0 0
Other Substance Desc:	Diesel

Region Code:	CR
Date Rec:	03/23/2011
Date Initiated:	05/10/2011
aiid:	15667
Incident Id:	131461
Incident Date:	03/23/2011
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	ExxonMobil #5-3838 4527 Perkins Rd. Baton Rouge
Incident Source Name:	ExxonMobil Corp - RAS #53838

EXXON STATION 53838 (Continued) **S106033743**

Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	Confirmed Release 05/10/2011, REM Unknown. Phase II results above RECAP SS for Gas, Oil & Diesel. Will close out using MO-1 & established LRS after all wells P&A'd. 10/21/11 - Incident closed using MO-1 and established LRS, all wells P&Ad. luc
Incident Type Desc:	UST Rem, Unknown
Comments:	Confirmed Release 05/10/2011, REM Unknown. Phase II results above RECAP SS for Gas, Oil & Diesel. Will close out using MO-1 & established LRS after all wells P&A'd. 10/21/11 - Incident closed using MO-1 and established LRS, all wells P&Ad. luc
Parameter:	0
Quantity:	0 0
Other Substance Desc:	Used Oil

---

34 **CIRCLE K #7655** **LA UST** **U003986809**
4527 PERKINS RD **LA NPDES** **N/A**
BATON ROUGE, LA 70808 **LA REM**

UST:

Master Agency Id:	15667
Subject Item ID:	2
UST Tank Num:	11977
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

CIRCLE K #7655 (Continued) **U003986809**

UST Tank Num:	11978
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	11979
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

CIRCLE K #7655 (Continued) **U003986809**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	11980
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	11981
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

CIRCLE K #7655 (Continued) **U003986809**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	55200
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55257
Tank Status:	**Active**
Install Date:	08/01/2001
Total Capacity:	20000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported

CIRCLE K #7655 (Continued) **U003986809**

MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	55258
Tank Status:	**Active**
Install Date:	08/01/2001
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	55259
Tank Status:	**Active**
Install Date:	08/01/2001
Total Capacity:	15000

CIRCLE K #7655 (Continued) **U003986809**

Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	55481
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported

CIRCLE K #7655 (Continued) **U003986809**

Pipe Method Description: Not reported

NPDES:

Facility Id:	15667
Facility Phone:	2259241719
Issued Date:	06/12/2009
Title Description:	Permit Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20090001

Facility Id:	15667
Facility Phone:	2259241719
Issued Date:	05/07/2004
Title Description:	LAG750389 Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20040001

Facility Id:	15667
Facility Phone:	2259241719
Issued Date:	11/30/2001
Title Description:	LAG750389 Permit
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20010001

REM:

AI Num:	15667
Evaluated And Closed:	10/21/2011
Program:	UST
EAC Type:	Comfort Letter
Comments:	EDMS ID 8174022

AI Num:	15667
Evaluated And Closed:	12/15/2003
Program:	UST
EAC Type:	Approve Investigation NFA w/ BOD
Comments:	EDMS ID 2170856

---

34 **WELSHS CLEANERS** **LA DRYCLEANERS** **S112658997**
4479 PERKINS RD **LA REM** **N/A**
BATON ROUGE, LA 70808

DRYCLEANERS:

Facility ID:	5485
Owner:	James Welsh
Owner Telephone:	Not reported
Store Telephone:	225-928-5067
Mailing Address:	7517 Town S Ave
Mailing City,St,Zip:	Baton Rouge, LA 708080000
Contact:	Not reported

REM:

AI Num:	5485
Evaluated And Closed:	02/14/2003

WELSHS CLEANERS (Continued) **S112658997**

Program: Grwater
EAC Type: Approve CA NFA w/ BOD
Comments: EDMS ID 1651090.

---

34 SOUTHDOWNS MOBIL **LA HIST LUST** **S106034299**
4485 PERKINS RD **LA REM** **N/A**
BATON ROUGE, LA 70808

HIST LUST:

Facility ID:	17-007261
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE AND DIESEL
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	04/16/1999
Date Confirmed 2:	Not reported
Incident Number:	99-2-0023
Incident Date:	04/16/1999
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	GERALD WALTERS/SCHWAB & WALTERS ATTORNEY
Reported By 2:	Not reported
Owner ID:	00837600
Owner Name:	SOUTHDOWNS MOBIL, INC.
Owner Address:	4485 PERKINS ROAD
Owner City,St,Zip:	BATON ROUGE, LA 70808
Assessment Pending Info:	No
Assessment Request Date:	09/13/1999
Assessment Plan Due Date:	12/02/1999
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: PHASE II ASSESSMENT CONDUCT BY CRA/G&E ENGINEERING. CONSULTANTFOUND ELEVATED CONCENTRATIONS OF TPH-G, TPH-O IN THE SOIL AND TPH-GTPH-D AND TPH-O IN THE SOIL AND TPH-G AND MTBE IN THE GROUNDWATER.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

SOUTHDOWNS MOBIL (Continued) **S106034299**

Comments: Not reported

REM:

AI Num:	1499
Evaluated And Closed:	02/09/2001
Program:	UST
EAC Type:	Administrator approves NFA
Comments:	EDMS ID 4348786.

---

34 **CIRCLE K 8031** **LA HIST LUST** **S106033617**
4435 PERKINS RD **LA SPILLS** **N/A**
BATON ROUGE, LA 70808

HIST LUST:

Facility ID:	17-008770
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	01/01/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0023
Incident Date:	01/18/1991
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	HOL GUILDER
Reported By 2:	Not reported
Owner ID:	00062400
Owner Name:	CIRCLE K STORES INC
Owner Address:	5650 BRECKENRIDGE PK DR- STE 300
Owner City,St,Zip:	TAMPA, FL 33610
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: Not reported

CIRCLE K 8031 (Continued) **S106033617**

LA HIST LUST ASSESMENT:
Comments: DURING INSTALLATION OF FOOTINGS FOR A GASOLINE CANOPY CONTRACTORDISCOVERED CONTAMINATION. PRODUCT WAS PUMPED OUT OF THE HOLE.LEBLANC & THERIOT PUT UP NEW CANOPY.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-008770
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0023
Incident Date:	01/18/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00062400
Owner Name:	CIRCLE K STORES INC
Owner Address:	5650 BRECKENRIDGE PK DR- STE 300
Owner City,St,Zip:	TAMPA, FL 33610
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: DURING INSTALLATION OF FOOTINGS FOR A GASOLINE CANOPY CONTRACTORDISCOVERED CONTAMINATION. PRODUCT WAS PUMPED OUT OF THE HOLE.LEBLANC & THERIOT PUT UP NEW CANOPY.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

CIRCLE K 8031 (Continued) **S106033617**

SPILLS:

Region Code:	Not reported
Date Rec:	02/06/2004
Date Initiated:	Not reported
aiid:	75226
Incident Id:	67715
Incident Date:	01/26/2004
Incident Status:	**Referred to Remediation**
Media Desc:	Water
Location Description:	Conoco Circle K 4435 Perkins Rd
Incident Source Name:	Circle K #8031
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	04-0443 conducting a divestment investigation. klhl
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Gasoline
Quantity:	Not reported
Other Substance Desc:	Not reported

---

34 **RACE EXPRESS** **LA REM** **S117979751**
4435 PERKINS RD **N/A**
BATON ROUGE, LA 70808

REM:

AI Num:	75226
Evaluated And Closed:	06/11/2004
Program:	UST
EAC Type:	No Further Interest
Comments:	EDMS ID 3056092. No release occurred

---

34 **FORMER UNIVERSITY MOTORS** **LA SPILLS** **S110094990**
4395 PERKINS RD **LA REM** **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	07/16/2009
Date Initiated:	Not reported
aiid:	165894
Incident Id:	116523
Incident Date:	07/16/2009
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	4395 Perkins Rd Baton Rouge
Incident Source Name:	Former University Motors
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Not reported

FORMER UNIVERSITY MOTORS (Continued) **S110094990**

Comments: Not reported
Parameter: 0
Quantity: 0 0
Other Substance Desc: 0

REM:
AI Num: 165894
Evaluated And Closed: 07/21/2009
Program: UST
EAC Type: Comfort Letter
Comments: Not reported

---

34 A FAMILY DENTAL CARE **RCRA-CESQG** **1004712247**
4616 CONCORD AVE **FINDS** **LAD985222454**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 04/07/2000
Facility name: A FAMILY DENTAL CARE
Facility address: 4616 CONCORD AVE
BATON ROUGE, LA 70808
EPA ID: LAD985222454
Mailing address: PO BOX 14057
BATON ROUGE, LA 70898
Contact: MARY ALICE CARRIER
Contact address: PO BOX 14057
BATON ROUGE, LA 70898
Contact country: US
Contact telephone: (225) 926-4640
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: J MATTHEW RANDALL DMD
Owner/operator address: 4616 CONCORD AVE
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 926-4640
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

A FAMILY DENTAL CARE (Continued) **1004712247**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003340787

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004712247
Registry ID:	110003340787
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003340787

---

34 **PRINTING TECH OF BATON ROUGE INC** **RCRA-CESQG** **1004713902**
3112 F COLLEGE DR **FINDS** **LAR000020248**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	02/13/1997
Facility name:	PRINTING TECH OF BATON ROUGE INC
Facility address:	3112 F COLLEGE DR BATON ROUGE, LA 70808
EPA ID:	LAR000020248
Mailing address:	F COLLEGE DR BATON ROUGE, LA 70808
Contact:	MICKEY BRASWELL
Contact address:	3112 F COLLEGE DR

PRINTING TECH OF BATON ROUGE INC (Continued) **1004713902**

BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 928-5920
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: AL BOUDREAU & ROBERT HETRICK
Owner/operator address: 3112 F COLLEGE DR
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 928-5920
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003357572

PRINTING TECH OF BATON ROUGE INC (Continued) **1004713902**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004713902
Registry ID:	110003357572
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003357572

---

34 **K-MART #3012** **LA UST** **U001894924**
3121 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	20638
Subject Item ID:	1
UST Tank Num:	15365
Tank Status:	**Removed**
Install Date:	05/02/1972
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

34 PETCO STORE 1580
3535 PERKINS RD, STE 305
BATON ROUGE, LA 70808

RCRA-CESQG **1016448823**
FINDS **LAR000081596**
ECHO

RCRA-CESQG:

Date form received by agency:	03/28/2014
Facility name:	PETCO STORE 1580
Facility address:	3535 PERKINS RD, STE 305 BATON ROUGE, LA 70808
EPA ID:	LAR000081596
Mailing address:	RICHLAND HILLS DR SAN ANTONIO, TX 78245
Contact:	AMY MARTINEZ
Contact address:	RICHLAND HILLS DR SAN ANTONIO, TX 78245
Contact country:	US
Contact telephone:	(210) 201-9241
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	PETCO
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/13/2013
Owner/Op end date:	Not reported

Owner/operator name:	ACADIAN CPDC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/13/2013
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

PETCO STORE 1580 (Continued) **1016448823**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Historical Generators:
Date form received by agency: 10/30/2013
Site name: PETCO STORE 1580
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

Violation Status: No violations found

PETCO STORE 1580 (Continued) **1016448823**

FINDS:

Registry ID: 110056318391

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016448823
Registry ID: 110056318391
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110056318391

---

34 COMMERCIAL PROPERTIES REALTY TRUST **RCRA NonGen / NLR** **1004710246**
3535 PERKINS RD **FINDS** **LAD985187830**
BATON ROUGE, LA 70802 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 12/17/2010
Facility name: WALMART STORE 1206
Facility address: 3535 PERKINS RD
BATON ROUGE, LA 70808
EPA ID: LAD985187830
Mailing address: SW 8TH ST
TWYLA GARVEY 0555
BENTONVILLE, AR 727160555
Contact: FREDRICK DELAFOSSE
Contact address: SW 8TH ST TWYLA GARVEY 0555
BENTONVILLE, AR 727160555
Contact country: US
Contact telephone: (225) 343-9922
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: WALMART LOUISIANA LLC
Owner/operator address: 702 SW 8TH ST TWYLA GARVEY 0555
BENTONVILLE, AR 72716
Owner/operator country: US
Owner/operator telephone: (479) 273-6840
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 01/01/2001
Owner/Op end date: Not reported

COMMERCIAL PROPERTIES REALTY TRUST (Continued) **1004710246**

Owner/operator name: WALMART LOUISIANA LLC
Owner/operator address: 702 SW 8TH ST TWYLA GARVEY 0555
BENTONVILLE, AR 72716
Owner/operator country: Not reported
Owner/operator telephone: (479) 273-6840
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Historical Generators:
Date form received by agency: 01/15/2009
Site name: WALMART STORE 1206
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 07/28/2004
Site name: WALMART STORE 1206
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

COMMERCIAL PROPERTIES REALTY TRUST (Continued) **1004710246**

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 06/29/2001
Site name: WALMART STORE 1206
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D008
. Waste name: LEAD

Date form received by agency: 12/11/1990
Site name: WALMART STORE 1206
Classification: Conditionally Exempt Small Quantity Generator

Facility Has Received Notices of Violations:
Regulation violated: SR - LAC33V4013.D.3
Area of violation: Generators - General
Date violation determined: 09/14/2000
Date achieved compliance: 10/02/2000
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 02/20/2001
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 12/17/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

Evaluation date: 09/14/2000
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 10/02/2000
Evaluation lead agency: State

FINDS:

Registry ID: 110003319551

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

COMMERCIAL PROPERTIES REALTY TRUST (Continued) **1004710246**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Registry ID: 110055209732

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004710246
Registry ID:	110055209732
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110055209732

Envid:	1004710246
Registry ID:	110003319551
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003319551

---

34 **WALMART STORE #1206** **LA UST** **U003986720**
3535 PERKINS RD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	12712
Subject Item ID:	1
UST Tank Num:	38631
Tank Status:	**Removed**
Install Date:	04/01/1988
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

WALMART STORE #1206 (Continued) **U003986720**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Gravity Feed

---

34 **COMMERCIAL PROPERTIES REALTY TRUST - ACADIAN VILLA** **LA HIST LUST** **1000468909**
3535 PERKINS RD **LA NPDES** **N/A**
BATON ROUGE, LA 70808

HIST LUST:

Facility ID:	17-013356
Facility Parish:	EAST BATON ROUGE
Substance Name:	USED OIL
Substance Name 2:	Not reported
Quantity:	550
Quantity 2:	Not reported
Date Confirmed:	04/27/1994
Date Confirmed 2:	Not reported
Incident Number:	94-2-0059
Incident Date:	04/27/1994
Type of Incident:	SPILL RESPONSE
Type of Incident No2:	Not reported
Reported By:	LENUS PERKINS
Reported By 2:	Not reported
Owner ID:	00547600
Owner Name:	WAL-MART STORES INC DEPT 8704
Owner Address:	701 SOUTH WALTON BLVD
Owner City,St,Zip:	BENTONVILLE, AR 72716-8704
Assessment Pending Info:	Not reported
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	BHATE EVIRONMENTAL, INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

COMMERCIAL PROPERTIES REALTY TRUST - ACADIAN VILLAGE (Continued) **1000468909**

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: WHILE REMOVING USED OIL UST A NATURAL GAS LINE WAS HIT BY ACCIDENT.LOCAL GAS COMPANY WAS NOTIFIED. A WATER LINE WAS BROKEN WHILE TRYINGTO REACH THE GAS LINE. LINES WERE REPLACED. DEQ INSPECTION 4/27/94.REC'D WORK PLAN FOR SOIL REMEDIATION ON 2/17/98. REC'D REPORT OFSOIL REMEDIATION AND REQUEST FOR NO FURTHER REMEDIAL ACTION ON11/18/98.

LA HIST LUST CORRECTIVE ACTION:
Comments: RECEIVED UST REMOVAL AND CLOSURE ASSESSMENT 6-23-94, (1) 550GALLON UST WAS REMOVED ON OR ABOUT 4-28-94.

Facility ID:	17-013356
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	94-2-0059
Incident Date:	04/27/1994
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00547600
Owner Name:	WAL-MART STORES INC DEPT 8704
Owner Address:	701 SOUTH WALTON BLVD
Owner City,St,Zip:	BENTONVILLE, AR 72716-8704
Assessment Pending Info:	Not reported
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	BHATE EVIRONMENTAL, INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

COMMERCIAL PROPERTIES REALTY TRUST - ACADIAN VILLAGE (Continued) **1000468909**

LA HIST LUST ASSESMENT:
Comments: WHILE REMOVING USED OIL UST A NATURAL GAS LINE WAS HIT BY ACCIDENT.LOCAL GAS COMPANY WAS NOTIFIED. A WATER LINE WAS BROKEN WHILE TRYINGTO REACH THE GAS LINE. LINES WERE REPLACED. DEQ INSPECTION 4/27/94.REC'D WORK PLAN FOR SOIL REMEDIATION ON 2/17/98. REC'D REPORT OFSOIL REMEDIATION AND REQUEST FOR NO FURTHER REMEDIAL ACTION ON11/18/98.

LA HIST LUST CORRECTIVE ACTION:
Comments: RECEIVED UST REMOVAL AND CLOSURE ASSESSMENT 6-23-94, (1) 550GALLON UST WAS REMOVED ON OR ABOUT 4-28-94.

NPDES:

Facility Id:	185726
Facility Phone:	Not reported
Issued Date:	02/26/2013
Title Description:	Gen Const. Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20130001

Facility Id:	185727
Facility Phone:	Not reported
Issued Date:	04/03/2013
Title Description:	Constr. Gen Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20130001

---

34 **WALMART SUPERCENTER #1206** **RCRA-SQG** **1007448772**
3132 COLLEGE DR **LAR000055525**
BATON ROUGE, LA 70808

RCRA-SQG:

Date form received by agency:	06/01/2016
Facility name:	WALMART SUPERCENTER #1206
Facility address:	3132 COLLEGE DR BATON ROUGE, LA 70808
EPA ID:	LAR000055525
Mailing address:	PO BOX 8041 BENTONVILLE, AR 72712
Contact:	REBECCA HAYNIE
Contact address:	PO BOX 8041 BENTONVILLE, AR 72712
Contact country:	US
Contact telephone:	(479) 258-6810
Contact email:	Not reported
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	WALMART LA LLC
Owner/operator address:	Not reported

WALMART SUPERCENTER #1206 (Continued) **1007448772**

Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 04/20/2004
Owner/Op end date: Not reported

Owner/operator name: WALMART LA LLC
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 04/20/2004
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P046
. Waste name: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U182
. Waste name: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Historical Generators:
Date form received by agency: 08/20/2014
Site name: WALMART SUPERCENTER #1206
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D043
. Waste name: VINYL CHLORIDE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P046
. Waste name: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U112
. Waste name: ACETIC ACID, ETHYL ESTER (I) (OR) ETHYL ACETATE (I)

. Waste code: U122

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U134
. Waste name: HYDROFLUORIC ACID (C,T) (OR) HYDROGEN FLUORIDE (C,T)

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U182
. Waste name: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U210
. Waste name: ETHENE, TETRACHLORO- (OR) TETRACHLOROETHYLENE

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 10/18/2010
Site name: WALMART SUPERCENTER #1206
Classification: Small Quantity Generator

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P046
. Waste name: ALPHA,ALPHA-DIMETHYLPHENETHYLAMINE (OR) BENZENEETHANAMINE, ALPHA, ALPHA-DIMETHYL-

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U034
. Waste name: ACETALDEHYDE, TRICHLORO- (OR) CHLORAL

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U072
. Waste name: BENZENE, 1,4-DICHLORO- (OR) P-DICHLOROBENZENE

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U182
. Waste name: 1,3,5-TRIOXANE, 2,4,6-TRIMETHYL- (OR) PARALDEHYDE

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 11/21/2008
Site name: WALMART SUPERCENTER #1206
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D026
. Waste name: CRESOL

. Waste code: D027
. Waste name: 1,4-DICHLOROBENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U080
. Waste name: METHANE, DICHLORO- (OR) METHYLENE CHLORIDE

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U159
. Waste name: 2-BUTANONE (I,T) (OR) METHYL ETHYL KETONE (MEK) (I,T)

. Waste code: U165
. Waste name: NAPHTHALENE

. Waste code: U249
. Waste name: ZINC PHOSPHIDE ZN3P2, WHEN PRESENT AT CONCENTRATIONS OF 10% OR LESS

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

. Waste code: U409
. Waste name: CARBAMIC ACID, [1,2-PHENYLENEBIS (IMINOCARBONOTHIOYL)]BIS-, DIMETHYL ESTER (OR) THIOPHANATE-METHYL

. Waste code: U411
. Waste name: PHENOL, 2-(1-METHYLETHOXY)-, METHYLCARBAMATE (OR) PROPOXUR

Date form received by agency: 07/15/2004
Site name: WALMART SUPERCENTER #1206
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011

WALMART SUPERCENTER #1206 (Continued) **1007448772**

. Waste name: SILVER

Violation Status: No violations found

---

34 COLORTEC IMAGING INC **RCRA-CESQG** **1004707293**
3084 COLLEGE DR **FINDS** **LA0000464636**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	07/10/2000
Facility name:	COLORTEC IMAGING INC
Facility address:	3084 COLLEGE DR BATON ROUGE, LA 70808
EPA ID:	LA0000464636
Mailing address:	COLLEGE DR BATON ROUGE, LA 70808
Contact:	FORREST FLOYD
Contact address:	3084 COLLEGE DR BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 928-4825
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	COLOR TEC IMAGING
Owner/operator address:	4851 KELLER SPRINGS RD #204 DALLAS, TX 75248
Owner/operator country:	Not reported
Owner/operator telephone:	(214) 732-8588
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No

COLORTEC IMAGING INC (Continued) **1004707293**

Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003261381

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707293
Registry ID: 110003261381
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003261381

---

34 **1 HR COLOR DEVELOPMENTS** **EDR Hist Cleaner** **1019916471**
3084 COLLEGE DR F **N/A**
BATON ROUGE, LA 70808

EDR Hist Cleaner

Year:	Name:	Type:
1991	1 HR COLOR DEVELOPMENTS	Drycleaning Plants, Except Rugs, NEC
1992	1 HR COLOR DEVELOPMENTS	Drycleaning Plants, Except Rugs, NEC
1993	1 HR COLOR DEVELOPMENTS	Drycleaning Plants, Except Rugs, NEC

---

34 **CIRCLE K STORES, INC.** **LA SPILLS** **S118842788**
2959 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

SPILLS:
Region Code: CR
Date Rec: 08/05/2016
Date Initiated: Not reported
aiid: 13684
Incident Id: 172096

CIRCLE K STORES, INC. (Continued) **S118842788**

Incident Date:	08/04/2016
Incident Status:	**Open**
Media Desc:	Soil
Location Description:	Circle K# 97252959 College Dr.Baton Rouge
Incident Source Name:	Circle K #9725
Reporter Name:	Cheri Robbins
Mailing Address 1:	25 W Cedar St
Mailing City:	Baton Rouge
Mailing State:	LA
Mailing Zip:	70808
Incident Desc:	s16-84519UST - SIR Inconclusive on Both Regular Unleaded Tanks; Tank 1 was not configured in our system and through our inventory #'s way off. col
Incident Type Desc:	UST Release, Other / Other
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

34 **STAR ENT** **RCRA-SQG** **1000622427**
2959 COLLEGE DR **FINDS** **LAD985197243**
BATON ROUGE, LA 70808 **ECHO**

RCRA-SQG:

Date form received by agency:	09/08/2011
Facility name:	STAR ENT
Facility address:	2959 COLLEGE DR BATON ROUGE, LA 70808
EPA ID:	LAD985197243
Mailing address:	PO BOX 2099 HOUSTON, TX 772522099
Contact:	JENA HENRY
Contact address:	PO BOX 2099 HOUSTON, TX 772522099
Contact country:	US
Contact telephone:	(713) 241-0236
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	MOTIVA ENTERPRISES LLC
Owner/operator address:	PO BOX 4540 HOUSTON, TX 77210
Owner/operator country:	Not reported
Owner/operator telephone:	(713) 241-0236
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

STAR ENT (Continued) **1000622427**

Owner/operator name: MOTIVA ENTERPRISES LLC
Owner/operator address: PO BOX 4540
HOUSTON, TX 77210
Owner/operator country: US
Owner/operator telephone: (713) 241-0236
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 09/08/2011
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Historical Generators:
Date form received by agency: 03/21/2000
Site name: STAR ENT
Classification: Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/07/2011
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003325232

STAR ENT (Continued) **1000622427**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000622427
Registry ID:	110003325232
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003325232

---

34 **SHELL #101218** **LA RGA LUST** **S115492902**
2959 COLLEGE DR **N/A**
BATON ROUGE, LA

RGA LUST:

2008	SHELL #101218	2959 COLLEGE DR
2006	SHELL #101218	2959 COLLEGE DR

---

34 **TEXACO SELF SERVICE** **EDR Hist Auto** **1013758752**
2959 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1975	TEXACO SELF SERVICE	GASOLINE STATIONS
1980	TEXACO SELF SERVICE	GASOLINE STATIONS
1986	TEXACO SELF SERVE	Gasoline Service Stations
1987	TEXACO SELF SERVE	Gasoline Service Stations
1988	TEXACO SELF SERVE	Gasoline Service Stations
1989	TEXACO SELF SERVE	Gasoline Service Stations
1990	TEXACO SELF SERVICE	GASOLINE STATIONS
1990	TEXACO SELF SERVE	Gasoline Service Stations
1991	TEXACO SELF SERVE	Gasoline Service Stations
1992	STAR ENTERPRISE	Gasoline Service Stations
1993	STAR ENTERPRISE	Gasoline Service Stations
1994	STAR ENTERPRISE	Gasoline Service Stations
1995	TEXACO SELF SERVICE	GASOLINE STATIONS
1995	STAR ENTERPRISE	Gasoline Service Stations, NEC
1996	STAR ENTERPRISE	Gasoline Service Stations, NEC
1997	STAR ENTERPRISE	Gasoline Service Stations, NEC
1998	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC
1999	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC
2000	TEXACO SELF SERVICE GAS SERV ST	GASOLINE STATIONS
2000	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC
2001	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC
2002	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC

TEXACO SELF SERVICE (Continued) **1013758752**

2003	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC
2004	MOTIVA ENTERPRISES LLC	Gasoline Service Stations, NEC
2005	WHITFIELD SHARON	Gasoline Service Stations, NEC
2006	WHITFIELD SHARON	Gasoline Service Stations, NEC
2007	WHITFIELD SHARON	Gasoline Service Stations, NEC
2008	WHITFIELD SHARON	Gasoline Service Stations, NEC
2009	WHITFIELD SHARON	Gasoline Service Stations, NEC
2010	WHITFIELD SHARON	Gasoline Service Stations, NEC

---

34 **CIRCLE K STORES, INC. #9725** **LA SPILLS** **S109961287**
2959 COLLEGE DR BATON ROUGE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	05/22/2009
Date Initiated:	Not reported
aiid:	13684
Incident Id:	115181
Incident Date:	05/21/2009
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Circle K Stores, Inc. #9725 2959 College Dr Baton Rouge
Incident Source Name:	Circle K #2709725
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0

Region Code:	Not reported
Date Rec:	05/22/2009
Date Initiated:	Not reported
aiid:	13684
Incident Id:	115181
Incident Date:	05/21/2009
Incident Status:	**Closed**
Media Desc:	Soil
Location Description:	Circle K Stores, Inc. #9725 2959 College Dr Baton Rouge
Incident Source Name:	Circle K #2709725
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	0

CIRCLE K STORES, INC. #9725 (Continued) **S109961287**

Quantity: 0 0
Other Substance Desc: 0
Parameter: 0
Quantity: 0 0
Other Substance Desc: 0

---

34 **CIRCLE K #2709725** **LA RGA LUST** **S115490853**
2959 COLLEGE DR **N/A**
BATON ROUGE, LA

RGA LUST:

2009	CIRCLE K #2709725	2959 COLLEGE DR
2007	CIRCLE K #2709725	2959 COLLEGE DR

---

34 **CIRCLE K #9725** **LA UST** **U003986762**
2959 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	13684
Subject Item ID:	2
UST Tank Num:	30432
Tank Status:	**Active**
Install Date:	02/14/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

CIRCLE K #9725 (Continued) **U003986762**

UST Tank Num:	30433
Tank Status:	**Active**
Install Date:	02/14/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	30434
Tank Status:	**Active**
Install Date:	02/14/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

CIRCLE K #9725 (Continued) **U003986762**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	30435
Tank Status:	**Active**
Install Date:	02/14/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

34 **TEXACO 44-398-0101** **LA HIST LUST** **S106034350**
2959 COLLEGE DR **LA SPILLS** **N/A**
BATON ROUGE, LA 70808 **LA REM**

HIST LUST:

Facility ID:	17-011411	
Facility Parish:	EAST BATON ROUGE	
Substance Name:	GASOLINE	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	05/24/1991	
Date Confirmed 2:	Not reported	
Incident Number:	91-2-0170	
Incident Date:	05/24/1991	
Type of Incident:		UST LEAK
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00369200	

TEXACO 44-398-0101 (Continued) **S106034350**

Owner Name: STAR ENTERPRISE
Owner Address: 3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip: METAIRIE, LA 70002
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: GROUNDWATER TECHNOLOGY INC.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 11/06/1992
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: DEQ LETTER 11-8-95 CONTINUE QTLY SAMMPLING. QTLY REPORTS SUBMITTED.DEQ RECORD OF COMMUNICATION REPORT 12/29/97 INCIDENT NO. 91-2-0170 ISASSIGNED TO TEXACO AT 2276 COLLEGE DR. BATON ROUGE AND TEH TEXACO AT2959 COLLEGE DR., BATON ROUGE IS 89-2-0130.

LA HIST LUST ASSESMENT:
Comments: DEQ APPROVED WORK PLAN ON 7/26/94. DEQ LETTER 11/1/94 CONTINUE QTLYREPORTS. REC'D CONSTRUCTION ACTIVITIES REPORT ON 2/14/95.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ LETTER 8/1/95: ELEVATED LEVELS OF BTEX REAPPEARED NEED WORK PLAN.

Facility ID: 17-011411
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-2-0170
Incident Date: 05/24/1991
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00369200
Owner Name: STAR ENTERPRISE
Owner Address: 3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip: METAIRIE, LA 70002
Assessment Pending Info: No
Assessment Request Date: Not reported

TEXACO 44-398-0101 (Continued) **S106034350**

Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	GROUNDWATER TECHNOLOGY INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	11/06/1992
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: DEQ LETTER 11-8-95 CONTINUE QTLY SAMMPLING. QTLY REPORTS SUBMITTED.DEQ RECORD OF COMMUNICATION REPORT 12/29/97 INCIDENT NO. 91-2-0170 ISASSIGNED TO TEXACO AT 2276 COLLEGE DR. BATON ROUGE AND TEH TEXACO AT2959 COLLEGE DR., BATON ROUGE IS 89-2-0130.

LA HIST LUST ASSESMENT:

Comments: DEQ APPROVED WORK PLAN ON 7/26/94. DEQ LETTER 11/1/94 CONTINUE QTLYREPORTS. REC'D CONSTRUCTION ACTIVITIES REPORT ON 2/14/95.

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 8/1/95: ELEVATED LEVELS OF BTEX REAPPEARED NEED WORK PLAN.

Facility ID:	17-011411
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	09/19/1996
Date Confirmed 2:	Not reported
Incident Number:	96-2-0085
Incident Date:	09/19/1996
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	BILLY PROCHASKA
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	EMS ENVIRONMENTAL, INC.
Assess Date Add Info Due:	Not reported

TEXACO 44-398-0101 (Continued) **S106034350**

Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/12/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: PSH DISCOVERED BY SOILS & FOUNDATION ENGINEERS, INC. WHILE DOING AGEO TECHNICAL INVESTIGATION. REMEDIATION HAD BEEN PERFORMED AT THISSITE AND INCIDENT WAS TERMINATED ON 6-25-93 (91-2-0170).REC'D SOIL & GW ASSESSMENT REPORT: THERE WERE MINIMAL LEVELS OFIMPACT FOUND IN SOIL & GW & NO IMPACT ABOVE STATE LEVELS.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ LETTER 12-12-96 TERMINATION OF REMEDIATION BASED ON REVIEW OFNOV. 96 SOIL & GW ANALYSIS REPORT. DEQ LETTER 12-18-96 TO CONSULTANTTHEM THAT THE DEQ SOLID WASTE DIVISION NEEDS TO BE CONTACTED PRIOR TOREMOVING THE SOIL.

Facility ID:	17-011411
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	96-2-0085
Incident Date:	09/19/1996
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	EMS ENVIRONMENTAL, INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported

TEXACO 44-398-0101 (Continued) **S106034350**

Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/12/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: PSH DISCOVERED BY SOILS & FOUNDATION ENGINEERS, INC. WHILE DOING AGEO TECHNICAL INVESTIGATION. REMEDIATION HAD BEEN PERFORMED AT THISSITE AND INCIDENT WAS TERMINATED ON 6-25-93 (91-2-0170).REC'D SOIL & GW ASSESSMENT REPORT: THERE WERE MINIMAL LEVELS OFIMPACT FOUND IN SOIL & GW & NO IMPACT ABOVE STATE LEVELS.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ LETTER 12-12-96 TERMINATION OF REMEDIATION BASED ON REVIEW OFNOV. 96 SOIL & GW ANALYSIS REPORT. DEQ LETTER 12-18-96 TO CONSULTANTTHEM THAT THE DEQ SOLID WASTE DIVISION NEEDS TO BE CONTACTED PRIOR TOREMOVING THE SOIL.

SPILLS:

Region Code:	Not reported
Date Rec:	03/18/2009
Date Initiated:	Not reported
aiid:	13684
Incident Id:	113597
Incident Date:	03/18/2009
Incident Status:	**Referred to USTD for TL Assignment**
Media Desc:	Soil
Location Description:	Circle K #2709725 2959 College Dr Baton Rouge
Incident Source Name:	Circle K #2709725
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	0
Quantity:	0 0
Other Substance Desc:	0

Region Code:	Not reported
Date Rec:	03/07/2006
Date Initiated:	Not reported
aiid:	13684
Incident Id:	86292
Incident Date:	03/07/2006
Incident Status:	**Referred to Remediation**
Media Desc:	Water/Soil
Location Description:	2959 College Dr Baton Rouge

TEXACO 44-398-0101 (Continued) **S106034350**

Incident Source Name:	Shell #101218
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s06-0679 Petroleum hydrocarons were found in the soil above RECAP. CMD
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

REM:

AI Num:	13684
Evaluated And Closed:	12/21/2009
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 6135504.

---

34 **JOHNSON MELVIN 0 AUTO REPR** **EDR Hist Auto** **1013757662**
2982 BALIS DR **N/A**
BATON ROUGE, LA

EDR Hist Auto

Year:	Name:	Type:
1960	JOHNSON MELVIN 0 AUTO REPR	AUTOMOBILE REPAIRING
1966	JOHNSON MELVIN AUTO REPR	AUTOMOBILE REPAIRING
1970	JOHNSON MELVIN AUTO REPR	AUTOMOBILE REPAIRING
1975	JOHNSON MELVIN AUTO REPR	AUTOMOBILE REPAIRING
1980	JOHNSON MELVIN AUTO REPR	AUTOMOBILE REPAIRING

---

34 **MAGINNIS IMPORTS INC** **EDR Hist Auto** **1021884395**
2857 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1975	MAGINNIS IMPORTS INC	New And Used Car Dealers
1976	MAGINNIS IMPORTS INC	New And Used Car Dealers
1977	MAGINNIS IMPORTS INC	New And Used Car Dealers
1978	MAGINNIS IMPORTS INC	New And Used Car Dealers
1979	MAGINNIS IMPORTS INC	New And Used Car Dealers
1980	MAGINNIS IMPORTS INC	New And Used Car Dealers
1982	MAGINNIS IMPORTS INC	New And Used Car Dealers
1983	MAGINNIS IMPORTS INC	New And Used Car Dealers

34 ALBERTSONS 2709 — **RCRA-CESQG, FINDS, ECHO** — **1016676293 / LAR000082370**
2950 COLLEGE DR
BATON ROUGE, LA 70808

RCRA-CESQG:

Date form received by agency:	03/13/2014
Facility name:	ALBERTSONS 2709
Facility address:	2950 COLLEGE DR BATON ROUGE, LA 70808
EPA ID:	LAR000082370
Mailing address:	PO BOX 20 BOISE, ID 83726
Contact:	ERICA FRANSEN
Contact address:	PO BOX 20 BOISE, ID 83726
Contact country:	US
Contact telephone:	(208) 395-4793
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALBERTSONS
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/02/2006
Owner/Op end date:	Not reported

Owner/operator name:	ALBERTSONS
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/02/2006
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

ALBERTSONS 2709 (Continued) **1016676293**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Violation Status: No violations found

FINDS:

Registry ID: 110058886139

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016676293
Registry ID: 110058886139
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058886139

34 COLLEGE CHEVRON
2929 COLLEGE DR & I-10
BATON ROUGE, LA 70802

LA AUL
LA HIST LUST
LA UST
LA NPDES
LA REM

U001893408
N/A

AUL:

Facility ID:	20619
Type:	Not reported
Incident Number:	Not reported
Agency Interest Id:	Not reported
PPM Project Number:	Not reported
Parish:	East Baton Rouge
Comments:	UST
Custom Tank Desc:	Conveyance Notice Required

HIST LUST:

Facility ID:	17-001998
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	100 GALLON
Quantity 2:	Not reported
Date Confirmed:	05/30/1989
Date Confirmed 2:	Not reported
Incident Number:	89-2-0008
Incident Date:	05/25/1989
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00061700
Owner Name:	CHEVRON USA PRODUCTS COMPANY
Owner Address:	2300 WINDY RIDGE PARKWAY #800
Owner City,St,Zip:	ATLANTA, GA 30339
Assessment Pending Info:	No
Assessment Request Date:	05/31/1989
Assessment Plan Due Date:	08/21/1991
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ZIMMERMAN ENVIROMENTAL CONSULTANTS INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/15/1994
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

COLLEGE CHEVRON (Continued) **U001893408**

Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: CONTRACTOR WAS DRILLING MONITOR WELL IN TANK PIT WHEN DRILL HIT USTAND MADE A HOLE IN TANK.

LA HIST LUST CORRECTIVE ACTION:
Comments: QUARTERLY REPORTS CONTINUE. DEQ LETTER 10/26/93 APPROVES WORK PLAN.REC'D REQUEST FROM CONSULTANT FOR NO FURTHER ACTION. DEQ APPROVES NOFURTHER ACTION ON 9/15/94.

Facility ID:	17-001998
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	89-2-0008
Incident Date:	05/25/1989
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00061700
Owner Name:	CHEVRON USA PRODUCTS COMPANY
Owner Address:	2300 WINDY RIDGE PARKWAY #800
Owner City,St,Zip:	ATLANTA, GA 30339
Assessment Pending Info:	No
Assessment Request Date:	05/31/1989
Assessment Plan Due Date:	08/21/1991
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ZIMMERMAN ENVIROMENTAL CONSULTANTS INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/15/1994
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: CONTRACTOR WAS DRILLING MONITOR WELL IN TANK PIT WHEN DRILL HIT USTAND MADE A HOLE IN TANK.

COLLEGE CHEVRON (Continued) **U001893408**

LA HIST LUST CORRECTIVE ACTION:

Comments: QUARTERLY REPORTS CONTINUE. DEQ LETTER 10/26/93 APPROVES WORK PLAN.REC'D REQUEST FROM CONSULTANT FOR NO FURTHER ACTION. DEQ APPROVES NOFURTHER ACTION ON 9/15/94.

UST:

Master Agency Id:	20619
Subject Item ID:	1
UST Tank Num:	6535
Tank Status:	**Removed**
Install Date:	04/28/1984
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	6536
Tank Status:	**Active**
Install Date:	04/28/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

COLLEGE CHEVRON (Continued) **U001893408**

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	6537
Tank Status:	**Active**
Install Date:	04/28/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	6538
Tank Status:	**Active**
Install Date:	04/28/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes

COLLEGE CHEVRON (Continued) **U001893408**

Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	6539
Tank Status:	**Active**
Install Date:	04/28/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NPDES:

Facility Id:	20619

COLLEGE CHEVRON (Continued) **U001893408**

Facility Phone: 2259789307
Issued Date: 05/07/2004
Title Description: LAG750251 Reauthorization
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20040002

Facility Id: 20619
Facility Phone: 2259789307
Issued Date: 05/07/1999
Title Description: Fiscal Migration: LAG750251
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN19990001

Facility Id: 20619
Facility Phone: 2259789307
Issued Date: 05/04/2004
Title Description: LAG750251 Mod Permit
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20040001

Facility Id: 20619
Facility Phone: 2259789307
Issued Date: 06/12/2009
Title Description: Permit Reauthorization
Permit Type Description: Gen-LAG75-Exterior Vehicle Wash
Program: Water
Activity Number: GEN20090001

REM:
AI Num: 20619
Evaluated And Closed: 12/30/2004
Program: UST
EAC Type: Approve Investigation NFA w/ BOD
Comments: EDMS ID 2536429

---

34 **CHEVRON #109060** **RCRA-CESQG** **1004714414**
2929 COLLEGE DR **FINDS** **LAR000031633**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 09/22/2004
Facility name: CHEVRON #109060
Facility address: 2929 COLLEGE DR
BATON ROUGE, LA 70808
EPA ID: LAR000031633
Mailing address: PO BOX 6004
SAN RAMON, CA 94583
Contact: KATHY NORRIS
Contact address: PO BOX 6004
SAN RAMON, CA 94583
Contact country: US
Contact telephone: (925) 842-5931
Contact email: Not reported
EPA Region: 06

CHEVRON #109060 (Continued) **1004714414**

Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: CHEVRON PRODUCTS CO
Owner/operator address: PO BOX 6004
SAN RAMON, CA 94583
Owner/operator country: Not reported
Owner/operator telephone: (925) 842-9500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Historical Generators:
Date form received by agency: 08/28/1998
Site name: CHEVRON #109060
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001

CHEVRON #109060 (Continued) **1004714414**

. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110003363182

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004714414
Registry ID: 110003363182
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003363182

---

34 **COLLEGE CHEVRON** **EDR Hist Auto** **1013768606**
2929 COLLEGE DR **N/A**
BATON ROUGE, LA 70808

EDR Hist Auto

Year:	Name:	Type:
1972	SAMSON CHARLES	Gasoline Service Stations
1975	COLLEGE DRIVE GULF SERVICE	GASOLINE STATIONS
1980	COLLEGE DRIVE GULF	GASOLINE STATIONS
1983	LOOPER ENTERPRISES INC	Gasoline Service Stations
1985	LOOPER ENTERPRISES BATON ROUG*	Gasoline Service Stations
1986	LOOPER ENTERPRISES BATON ROUG*	Gasoline Service Stations
1986	LOOPERS COOLING SYSTEMS SVC	General Automotive Repair Shops
1987	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1987	LOOPERS COOLING SYSTEMS SVC	General Automotive Repair Shops
1988	LOOPERS COOLING SYSTEMS SVC	General Automotive Repair Shops
1988	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1989	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1990	COLLEGE DRIVE CHEVRON	GASOLINE STATIONS
1990	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1991	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1992	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1993	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1994	LOOPER ENTPS OF BATON ROUGE	Gasoline Service Stations
1995	COLLEGE DRIVE CHEVRON	GASOLINE STATIONS
2000	CHEVRON STATIONS	GASOLINE STATIONS
2004	COLLEGE CHEVRON	Gasoline Service Stations
2005	COLLEGE CHEVRON	Gasoline Service Stations
2006	COLLEGE CHEVRON	Gasoline Service Stations

COLLEGE CHEVRON (Continued) **1013768606**

2007	COLLEGE CHEVRON	Gasoline Service Stations
2008	COLLEGE CHEVRON	Gasoline Service Stations
2009	COLLEGE CHEVRON	Gasoline Service Stations
2010	SAMIS AUTO PLACE INC	General Automotive Repair Shops
2010	COLLEGE CHEVRON	Gasoline Service Stations
2011	COLLEGE CHEVRON	Gasoline Service Stations
2011	SAMIS AUTO PLACE INC	General Automotive Repair Shops
2012	COLLEGE CHEVRON	Gasoline Service Stations
2012	SAMIS AUTO PLACE INC	General Automotive Repair Shops
2013	COLLEGE CHEVRON	Gasoline Service Stations
2013	SAMIS AUTO PLACE INC	General Automotive Repair Shops
2014	COLLEGE CHEVRON	Gasoline Service Stations, NEC
2014	SAMIS AUTO PLACE INC	General Automotive Repair Shops

---

35 **BATON ROUGE COUNTRY CLUB** **LA UST** **U003073815**
BRENTWOOD DR **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	78826
Subject Item ID:	1
UST Tank Num:	46428
Tank Status:	**Active**
Install Date:	10/01/1988
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

36 RONALD D LANDRY DDS A PROF DENT CORP — **RCRA-CESQG, FINDS, ECHO** — **1004709599 / LAD982551756**
2726 CONTINENTAL DR STE A
BATON ROUGE, LA 70808

RCRA-CESQG:

Date form received by agency:	03/19/1991
Facility name:	RONALD D LANDRY DDS A PROF DENT CORP
Facility address:	2726 CONTINENTAL DR STE A BATON ROUGE, LA 70808
EPA ID:	LAD982551756
Mailing address:	CONTINENTAL DR STE A BATON ROUGE, LA 70808
Contact:	LANDRY RONALD
Contact address:	2726 CONTINENTAL DR STE A BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 926-5102
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAL KIEBHCH LANDRY
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

RONALD D LANDRY DDS A PROF DENT CORP (Continued) **1004709599**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110009580300

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004709599
Registry ID: 110009580300
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009580300

---

36 PARKWAY LIMITED PARTNERSHIP **RCRA-CESQG** **1004709566**
2726 CONTINENTAL DR STE 2 **FINDS** **LAD982549651**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 05/09/1988
Facility name: PARKWAY LIMITED PARTNERSHIP
Facility address: 2726 CONTINENTAL DR STE 2
BATON ROUGE, LA 70808
EPA ID: LAD982549651
Mailing address: CONTINENTAL DR
BATON ROUGE, LA 70808
Contact: IRENE GILLESPIE
Contact address: 2726 CONTINENTAL DR
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 926-4133
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

PARKWAY LIMITED PARTNERSHIP (Continued) **1004709566**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BILLY C. MICHAL
Owner/operator address:	2726 CONTINENTAL BATON ROUGE, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110009580257

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

PARKWAY LIMITED PARTNERSHIP (Continued) **1004709566**

ECHO:

Envid:	1004709566
Registry ID:	110009580257
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009580257

---

36 THOMAS J KIEBACH DDS **RCRA-CESQG** **1004708107**
2726 CONTINENTAL DR NO2 **FINDS** **LAD069309870**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	11/01/1988
Facility name:	THOMAS J KIEBACH DDS
Facility address:	2726 CONTINENTAL DR NO2 BATON ROUGE, LA 70808
EPA ID:	LAD069309870
Mailing address:	CONTINENTAL DR NO2 BATON ROUGE, LA 70808
Contact:	IRENE GILLESPIE
Contact address:	2726 CONTINENTAL DR NO2 BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 926-4133
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	MICHAL KIEBACH & LANDRY
Owner/operator address:	UNKNOWN UNKNOWN, LA 00000
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No

THOMAS J KIEBACH DDS (Continued) **1004708107**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003277150

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004708107
Registry ID: 110003277150
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003277150

---

37 PARKLAND HOSPITAL **RCRA NonGen / NLR** **1004707718**
2414 BUNKER HILL DR **FINDS** **LAD001241405**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 03/09/2010
Facility name: PARKLAND HOSPITAL
Facility address: 2414 BUNKER HILL DR
BATON ROUGE, LA 70808
EPA ID: LAD001241405
Mailing address: BUNKER HILL DR
BATON ROUGE, LA 70808
Contact: MARK BELIN
Contact address: 2414 BUNKER HILL DR
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 927-9050
Contact email: Not reported
EPA Region: 06
Land type: Private

PARKLAND HOSPITAL (Continued) **1004707718**

Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HOSPITAL CORP AMERICA
Owner/operator address: ONE PARK PLAZA PO BOX 550
NASHVILLE, TN 37202
Owner/operator country: US
Owner/operator telephone: (615) 279-9551
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/09/2010
Owner/Op end date: Not reported

Owner/operator name: HOSPITAL CORP AMERICA
Owner/operator address: ONE PARK PLAZA PO BOX 550
NASHVILLE, TN 37202
Owner/operator country: Not reported
Owner/operator telephone: (615) 279-9551
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes

PARKLAND HOSPITAL (Continued) **1004707718**

Generated waste on-site: Not reported

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 02/21/1989
Site name: PARKLAND HOSPITAL
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/09/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003267090

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707718
Registry ID: 110003267090
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003267090

---

37 **CENIKOR** **LA UST** **U003921211**
2414 BUNKER HILL DR **N/A**
BATON ROUGE, LA 70808

UST:
Master Agency Id: 10125
Subject Item ID: 1

UST Tank Num: 42977
Tank Status: **Removed**
Install Date: 01/01/1980
Total Capacity: 500
Number Of Compartments: 1
Gasoline: Not reported

CENIKOR (Continued) **U003921211**

Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

UST Tank Num:	42978
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

38 GULF COAST UTILITIES — **EDR Hist Auto** — **1021593397**
8664 FOREST HILL DR — **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2008	GULF COAST UTILITIES	Gasoline Service Stations, NEC
2009	GULF COAST UTILITIES	Gasoline Service Stations, NEC
2010	GULF COAST UTILITIES	Gasoline Service Stations, NEC
2011	GULF COAST UTILITIES	Gasoline Service Stations, NEC

---

38 AUTOMOTIVE LIQUIDATORS INC — **EDR Hist Auto** — **1020670389**
8658 QUARTERS LAKE RD — **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2008	AUTOMOTIVE LIQUIDATORS INC	General Automotive Repair Shops
2010	AUTOMOTIVE LIQUIDATORS INC	General Automotive Repair Shops
2011	AUTOMOTIVE LIQUIDATORS INC	General Automotive Repair Shops
2012	AUTOMOTIVE LIQUIDATORS INC	General Automotive Repair Shops
2013	AUTOMOTIVE LIQUIDATORS INC	General Automotive Repair Shops
2014	AUTOMOTIVE LIQUIDATORS INC	General Automotive Repair Shops

---

38 SOUTHERN ENVIRONMENTAL SERVICE INC — **RCRA NonGen / NLR** — **1000408905**
8922 JEFFERSON HWY — **FINDS** — **LAD981046949**
BATON ROUGE, LA 70809 — **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	12/17/1984
Facility name:	SOUTHERN ENVIRONMENTAL SERVICE INC
Facility address:	8922 JEFFERSON HWY BATON ROUGE, LA 70809
EPA ID:	LAD981046949
Mailing address:	PO BOX 45212 BATON ROUGE, LA 70809
Contact:	ENV-SVC SOUTHERN
Contact address:	PO BOX 45212 BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 927-0094
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	UNKNOWN
Owner/operator address:	8922 JERFFERSON HWY BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

SOUTHERN ENVIRONMENTAL SERVICE INC (Continued) **1000408905**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110003287452

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000408905
Registry ID:	110003287452
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003287452

---

38 **SOUTHERN ENVIRONMENTAL SERVICE** **TX Ind. Haz Waste** **S102746048**
8922 JEFFERSON HWY **N/A**
BATON ROUGE, LA 70809

Ind. Haz Waste:

Registration Number:	40683
Registration Initial Notification Date:	02/05/1985
Registration Last Amendment Date:	11/13/2003
EPA Identification:	LAD981046949
Primary NAICS Code:	484121
Status Change Date:	19850205
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Site Primary SIC Description:	Not reported
Registration is Generator of Waste:	No
Registration is Receivers of Waste:	No

SOUTHERN ENVIRONMENTAL SERVICE (Continued) **S102746048**

Registration is Transporter of Waste:	Yes
Registration is Transfer Facility:	No
Facility is STEERS Reporter:	No
Reqired to Submit Annual Waste Summary:	No
Facility Involved In Recycling:	No
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator:	Not reported
TNRCC Region:	Not reported
Company Name:	SOUTHERN ENVIRONMENTAL INC
Contact Name:	ERNEST T BEAUCHAMP
Contact Telephone Number:	504-9240608
Mailing Address:	PO BOX 867
Mailing Address2:	Not reported
Mailing City,St,Zip:	CANTONMENT, FL 325330867
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	17098
Site Owner Tax ID:	592871699
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20100329
Ind. waste permit Number:	Not reported
Mun waste permit Number:	Not reported
Non Notifier:	No

Business Records Not Found for this RegNo/Year:

Owner:

Owner Mailing Address:	PO BOX 867
Owner Mailing Address2:	Not reported
Owner Mailing Address3:	Not reported
Owner City,St,Zip:	CANTONMENT, FL 32533 0867
Owner Country:	UNITED STA
Owner Phone Number:	1-504-9240608
Owner Fax Number:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax Id:	15928716990
Owner Bankruptcy Code:	Not reported

Operator Records Not Found for this RegNo/Year:

Contact:

Contact Name:	ERNEST BEAUCHAMP
Contact Title:	ENVIRONMENTAL CONTACT
Contact Role:	PRICONT
Contact Address:	PO BOX 867
Contact Address2:	Not reported
Conact City,St,Zip:	CANTONMENT, FL 32533 0867
Contact Phone:	1-504-9240608
Contact Fax:	Not reported
Contact Email:	Not reported

Contact:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 867
Contact Address2:	Not reported

SOUTHERN ENVIRONMENTAL SERVICE (Continued) **S102746048**

Conact City,St,Zip:	CANTONMENT, FL 32533 0867
Contact Phone:	1-504-9240608
Contact Fax:	Not reported
Contact Email:	Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:

Receiver Type:	Not reported
Transporter for hire:	1
Transport own waste:	0
Eq 01, if transport waste type = 1:	Not reported
Eq 02, if transport waste type = 2:	Not reported
Eq 03, if transport waste type = 3:	Not reported
Eq 04, if transport waste type = H:	04
Target TCEQ unique facid for discarded(merged) facility:	Not reported

Waste Records Not Found for this RegNo/Year:

---

38 **LOUISIANA LUBRICANTS LUB SERV** **EDR Hist Auto** **1013761020**
8768 QUARTERS LAKE RD **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2000	LOUISIANA LUBRICANTS LUB SERV	AUTOMOBILE LUBRICATION SERVICE

---

38 **CIRCLE K #3778** **LA UST** **U004222149**
8894 JEFFERSON HWY **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	75283
Subject Item ID:	1
UST Tank Num:	6693
Tank Status:	**Removed**
Install Date:	04/23/1977
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported

CIRCLE K #3778 (Continued) **U004222149**

Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	6694
Tank Status:	**Removed**
Install Date:	04/23/1977
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	6695
Tank Status:	**Removed**
Install Date:	04/23/1977
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

CIRCLE K #3778 (Continued) **U004222149**

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

38 **FASHION CLNR** **LA DRYCLEANERS** **S107446201**
8895 JEFFERSON HWY **N/A**
BATON ROUGE, LA

DRYCLEANERS:

Facility ID:	39314
Owner:	ROBERT E SCHNELLER
Owner Telephone:	Not reported
Store Telephone:	225-922-9259
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact:	Not reported

---

38 **EASTERN LAUNDRY & CLNR** **LA DRYCLEANERS** **S107446406**
8883 JEFFERSON HWY **N/A**
BATON ROUGE, LA

DRYCLEANERS:

Facility ID:	39302
Owner:	THI TRAN
Owner Telephone:	Not reported
Store Telephone:	225-927-3140
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact:	Not reported

---

38 **TUNE UP 2 INC** **RCRA NonGen / NLR** **1001487872**
8859 JEFFERSON HWY **FINDS** **LAD069540201**
BATON ROUGE, LA 70809 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	09/24/1986
Facility name:	TUNE UP 2 INC
Facility address:	8859 JEFFERSON HWY BATON ROUGE, LA 70809
EPA ID:	LAD069540201
Mailing address:	JEFFERSON HWY BATON ROUGE, LA 70809
Contact:	STANLEY WARD

TUNE UP 2 INC (Continued) **1001487872**

Contact address: 8859 JEFFERSON HWY
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 927-0121
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: WARD STANLEY
Owner/operator address: 8859 JEFFERSON HWY
BATON ROUGE, LA 70809
Owner/operator country: Not reported
Owner/operator telephone: (225) 927-0121
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 06/30/1999
Evaluation: FOCUSED COMPLIANCE INSPECTION

TUNE UP 2 INC (Continued) **1001487872**

Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003277463

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001487872
Registry ID: 110003277463
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003277463

---

38 JEFFERSON ANIMAL HOSP **RCRA NonGen / NLR** **1006930615**
8774 JEFFERSON HWY **LAD096048202**
BATON ROUGE, LA 70809

RCRA NonGen / NLR:
Date form received by agency: 02/26/2003
Facility name: JEFFERSON ANIMAL HOSP
Facility address: 8774 JEFFERSON HWY
BATON ROUGE, LA 70809
EPA ID: LAD096048202
Mailing address: JEFFERSON HWY
BATON ROUGE, LA 70809
Contact: AS HAASE
Contact address: JEFFERSON HWY
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 927-2344
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: HAASE & MICHAELSON
Owner/operator address: JEFFERSON HWY
BATON ROUGE, LA 70809
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 03/22/1988

JEFFERSON ANIMAL HOSP (Continued) **1006930615**

Owner/Op end date: Not reported

Owner/operator name: JEFFERSON ANIMAL HOSPITAL
Owner/operator address: JEFFERSON HIGHWAY
BATON ROUGE, LA 70809
Owner/operator country: US
Owner/operator telephone: (225) 927-2344
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 03/22/1988
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Historical Generators:
Date form received by agency: 01/13/2003
Site name: JEFFERSON ANIMAL HOSP
Classification: Conditionally Exempt Small Quantity Generator

Date form received by agency: 10/30/2000
Site name: JEFFERSON ANIMAL HOSP
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 03/25/1988
Site name: JEFFERSON ANIMAL HOSP
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/26/2003
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

38 **GULF SOUTH RECOVERY CORP** **EDR Hist Auto** **1022204882**
3490 SAN FELIPE DR **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2010	GULF SOUTH RECOVERY CORP	Gasoline Service Stations, NEC
2011	GULF SOUTH RECOVERY CORP	Gasoline Service Stations, NEC
2012	GULF SOUTH RECOVERY CORP	Gasoline Service Stations, NEC

---

38 **ACTION TUNE INSPECTIONS** **EDR Hist Auto** **1013771151**
8775 JEFFERSON HWY STE G **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2006	ACTION TUNE INSPECTIONS	Automotive Repair Shops, NEC, NEC
2007	ACTION TUNE AUTO RPR & SERV	AUTOMOBILE REPAIRING & SERVICE
2013	ACTION TUNE INSPECTIONS	Automotive Repair Shops, NEC, NEC
2014	ACTION TUNE INSPECTIONS	Automotive Repair Shops, NEC, NEC

---

38 **ACTION TUNE** **EDR Hist Auto** **1013774223**
8759 JEFFERSON HWY **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
1969	JEFFERSON 66 SERVICE	Gasoline Service Stations
1970	JEFFERSON 66 SERVICE	Gasoline Service Stations
1971	JEFFERSON 66 SERVICE	Gasoline Service Stations
1972	JEFFERSON 66 SERVICE	Gasoline Service Stations
1973	JEFFERSON 66 SERVICE	Gasoline Service Stations
1974	JEFFERSON 66 SERVICE	Gasoline Service Stations
1975	JEFFERSON SERVICE STATION	GASOLINE STATIONS
1975	BRUMFIELD VICTOR	Gasoline Service Stations
1976	BRUMFIELD VICTOR	Gasoline Service Stations
1977	BRUMFIELD VICTOR	Gasoline Service Stations
1978	BRUMFIELD VICTOR	Gasoline Service Stations
1979	BRUMFIELD VICTOR	Gasoline Service Stations
1979	BRUMFIELD VICTOR	Gasoline Service Stations
1980	ACTION TUNE	AUTOMOBILE REPAIRING
1980	BRUMFIELD VICTOR	Gasoline Service Stations
1982	ACTION TUNE OF LA INC	General Automotive Repair Shops
1983	ACTION TUNE OF LA INC	General Automotive Repair Shops
1985	ACTION TUNE OF LA INC	General Automotive Repair Shops
1986	ACTION TUNE OF LA INC	General Automotive Repair Shops
1987	ACTION TUNE OF LA INC	General Automotive Repair Shops
1988	ACTION TUNE OF LA INC	General Automotive Repair Shops
1989	ACTION TUNE OF LA INC	General Automotive Repair Shops
1990	ACTION TUNE AUTO REPR	AUTOMOBILE REPAIRING
1990	ACTION TUNE OF LA INC	General Automotive Repair Shops
1991	ACTION TUNE OF LA INC	General Automotive Repair Shops
1992	ACTION TUNE OF LA INC	General Automotive Repair Shops
1993	ACTION TUNE OF LA INC	General Automotive Repair Shops
1994	ACTION TUNE OF LA INC	General Automotive Repair Shops

ACTION TUNE (Continued) **1013774223**

1995	ACTION TUNE AUTO REPR	AUTOMOBILE REPAIRING & SERVICE
1995	ACTION TUNE OF LA INC	General Automotive Repair Shops
1996	ACTION TUNE OF LA INC	General Automotive Repair Shops
1997	ACTION TUNE OF LA INC	General Automotive Repair Shops
1998	ACTION TUNE OF LA INC	General Automotive Repair Shops
1999	ACTION TUNE OF LA INC	General Automotive Repair Shops
2000	ACTION TUNE OF LA GENL AUTO REP	AUTOMOBILE REPAIRING & SERVICE
2000	ACTION TUNE OF LA INC	General Automotive Repair Shops
2001	ACTION TUNE OF LA INC	General Automotive Repair Shops
2002	ACTION TUNE OF LA INC	General Automotive Repair Shops
2003	ACTION TUNE OF LA INC	General Automotive Repair Shops

---

38 **ACTION TUNE UP** **LA UST** **U002114930**
8759 JEFFERSON HWY **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	78252
Subject Item ID:	1
UST Tank Num:	44285
Tank Status:	**Removed**
Install Date:	05/01/1965
Total Capacity:	6000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection
UST Tank Num:	44286
Tank Status:	**Removed**
Install Date:	05/01/1965
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported

ACTION TUNE UP (Continued) **U002114930**

Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

UST Tank Num:	44287
Tank Status:	**Removed**
Install Date:	05/01/1965
Total Capacity:	4000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection

38 CIRCLE K #9726
3536 DRUSILLA LN
BATON ROUGE, LA 70809

LA HIST LUST
LA SPILLS
LA NPDES
LA REM

S103490121
N/A

HIST LUST:

Facility ID:	17-011412
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	03/25/1993
Date Confirmed 2:	Not reported
Incident Number:	93-2-0071
Incident Date:	03/25/1993
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	BRENDA SPEARS/DRUSILLA TEXACO
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	R.L. HALL AND ASSOCIATES INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	06/19/1997
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: TRUCK DROVE INTO A UNLEADED PLUS DISPENSER. TRUCK BURST INTO FLAMESBUT ACCORDING TO TEXACO PERSONNELL NO GAS FROM THE UST SYSTEM WASINVOLVED. CONTRACTOR WILL REPAIR DISPENSER.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 6/19/97 APPROVES REQUEST FOR TERMINATION OF REMEDIATIONBUT CONTINUE TO MONITOR RELEASE DETECTION DEVICES (RDD'S)

Facility ID:	17-011412
Facility Parish:	EAST BATON ROUGE

CIRCLE K #9726 (Continued) **S103490121**

Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	93-2-0071
Incident Date:	03/25/1993
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	R.L. HALL AND ASSOCIATES INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	06/19/1997
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:

Comments: TRUCK DROVE INTO A UNLEADED PLUS DISPENSER. TRUCK BURST INTO FLAMESBUT ACCORDING TO TEXACO PERSONNELL NO GAS FROM THE UST SYSTEM WASINVOLVED. CONTRACTOR WILL REPAIR DISPENSER.

LA HIST LUST ASSESMENT:

Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:

Comments: DEQ LETTER 6/19/97 APPROVES REQUEST FOR TERMINATION OF REMEDIATIONBUT CONTINUE TO MONITOR RELEASE DETECTION DEVICES (RDD'S)

SPILLS:

Region Code:	Not reported
Date Rec:	03/07/2006
Date Initiated:	Not reported
aiid:	70008
Incident Id:	86291
Incident Date:	03/07/2006

CIRCLE K #9726 (Continued) **S103490121**

Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	3536 Drusilla Ln Baton Rouge
Incident Source Name:	Shell #101249
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s06-0678 Petroleum hydrocarbons were found above RECAP in the soil. CMD
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

NPDES:

Facility Id:	70008
Facility Phone:	8139106830
Issued Date:	01/23/2007
Title Description:	LAG750575 Permit
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20060001

Facility Id:	70008
Facility Phone:	8139106830
Issued Date:	06/12/2009
Title Description:	Permit
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20090001

Facility Id:	70008
Facility Phone:	8139106830
Issued Date:	07/25/2014
Title Description:	Renewed Coverage
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20140001

REM:

AI Num:	70008
Evaluated And Closed:	01/07/2010
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 6157948.

38 CONNELLY PRESS & COPY INC — **RCRA-CESQG, FINDS, ECHO** — **1004707324 / LA0000554584**
8737 JEFFERSON HWY
BATON ROUGE, LA 70809

RCRA-CESQG:

Date form received by agency:	08/03/1994
Facility name:	CONNELLY PRESS & COPY INC
Facility address:	8737 JEFFERSON HWY BATON ROUGE, LA 70809
EPA ID:	LA0000554584
Mailing address:	JEFFERSON HWY BATON ROUGE, LA 70809
Contact:	PETER CONNELLY
Contact address:	8737 JEFFERSON HWY BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 927-3022
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	PETER CONNELLY
Owner/operator address:	8737 JEFFERSON HWY BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 927-3022
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

CONNELLY PRESS & COPY INC (Continued) **1004707324**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003261719

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707324
Registry ID: 110003261719
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003261719

---

38 **CIRCLE K #8040** **LA UST** **U003925298**
8731 JEFFERSON HWY **N/A**
BATON ROUGE, LA 70809

UST:
Master Agency Id: 75236
Subject Item ID: 1

UST Tank Num: 23561
Tank Status: Removed
Install Date: 02/18/1964
Total Capacity: 6015
Number Of Compartments: 1
Gasoline: Not reported
Diesel: Not reported
Gasohol: Yes
Kerosene: Not reported
Heating Oil: Not reported
New Used Oil: Not reported
MS Aviation Fuel: Not reported
MS Additive: Not reported
MS Antifreeze: Not reported
MS Naptha: Not reported
MS Varsol: Not reported

CIRCLE K #8040 (Continued) **U003925298**

Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	23562
Tank Status:	**Removed**
Install Date:	02/18/1964
Total Capacity:	6015
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	23563
Tank Status:	**Removed**
Install Date:	02/18/1964
Total Capacity:	6015
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported

CIRCLE K #8040 (Continued) **U003925298**

Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

38 **DRUSILLA CLEANER** **LA VCP** **S106895587**
3406 DRUSILLA LN **LA DRYCLEANERS** **N/A**
BATON ROUGE, LA 70809 **LA REM**

VCP:

DEQ AI #:	5567
Date Closed:	Not reported
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	2
Applicant name:	Drusilla Village, LLC
DEQ Contact:	Celeste Bonnecaze
Date of Applicantion:	04/17/2015
Remedial Investigaton/Action Phase:	Action Phase - Partial
Status:	Active
Unrestricted Use:	Not reported
Investigation Approval Date:	Not reported
Use Restrictions/Institutional Controls A:	Not reported
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.36805600
Longitude:	30.17361100

DEQ AI #:	5567
Date Closed:	Not reported
Site Also Known As:	Not reported
Facility Parish:	East Baton Rouge
Acres:	2
Applicant name:	Drusilla Village, LLC
DEQ Contact:	Celeste Bonnecaze

DRUSILLA CLEANER (Continued) **S106895587**

Date of Applicantion:	03/25/2014
Remedial Investigaton/Action Phase:	Remedial Investigaton - Partial
Status:	Active
Unrestricted Use:	Not reported
Investigation Approval Date:	12/01/2014
Use Restrictions/Institutional Controls A:	Not reported
Use Restrictions/Institutional Controls B:	Not reported
Use Restrictions/Institutional Controls C:	Not reported
Use Restrictions/Institutional Controls D:	Not reported
Use Restrictions/Institutional Controls E:	Not reported
Use Restrictions/Institutional Controls F:	Not reported
Use Restrictions/Institutional Controls G:	Not reported
Use Restrictions/Institutional Controls H:	Not reported
Use Restrictions/Institutional Controls I:	Not reported
Latitude:	-91.36805600
Longitude:	30.17361100

DRYCLEANERS:

Facility ID:	5567
Owner:	DARRYL ZACHARY
Owner Telephone:	Not reported
Store Telephone:	225-927-9298
Mailing Address:	Not reported
Mailing City,St,Zip:	Not reported
Contact:	Not reported

REM:

AI Num:	5567
Evaluated And Closed:	Not reported
Program:	VRP
EAC Type:	Not reported
Comments:	Not reported

AI Num:	5567
Evaluated And Closed:	Not reported
Program:	VRP
EAC Type:	Not reported
Comments:	Not reported

---

38 **JIFFY LUBE #470** **LA HIST LUST** **1000231324**
3311 DRUSILLA LN **LA UST** **N/A**
BATON ROUGE, LA 70809

HIST LUST:

Facility ID:	17-007209
Facility Parish:	EAST BATON ROUGE
Substance Name:	WASTE OIL
Substance Name 2:	Not reported
Quantity:	30 GAL
Quantity 2:	Not reported
Date Confirmed:	10/31/1989
Date Confirmed 2:	Not reported
Incident Number:	89-2-0054
Incident Date:	10/31/1989
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	JAMES DEDEAUX/ GULF COSTAL LUBRICATORS

JIFFY LUBE #470 (Continued) **1000231324**

Reported By 2: Not reported
Owner ID: 00407200
Owner Name: GULF COAST LUBRICATION, INC.
Owner Address: 3445 N. CAUSEWAY BLVD SUITE 536
Owner City,St,Zip: METAIRIE, LA 70002
Assessment Pending Info: Yes
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 04/30/1996
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: A VENT PIPE BROKE, LEAKING OIL. TANK WAS REMOVED 1-NOV-89AND SAMPLES TAKEN. SITE CLOSED 4-JAN-90.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ APPROVED REQUEST FOR NO FURTHER ASSESS/OR REMEDIATION ON4-30-96.

Facility ID: 17-007209
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 89-2-0054
Incident Date: 10/31/1989
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00407200
Owner Name: GULF COAST LUBRICATION, INC.
Owner Address: 3445 N. CAUSEWAY BLVD SUITE 536
Owner City,St,Zip: METAIRIE, LA 70002
Assessment Pending Info: Yes
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported

JIFFY LUBE #470 (Continued) **1000231324**

Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	04/30/1996
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: A VENT PIPE BROKE, LEAKING OIL. TANK WAS REMOVED 1-NOV-89AND SAMPLES TAKEN. SITE CLOSED 4-JAN-90.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ APPROVED REQUEST FOR NO FURTHER ASSESS/OR REMEDIATION ON4-30-96.

UST:

Master Agency Id:	7457
Subject Item ID:	1
UST Tank Num:	19658
Tank Status:	**Closed**
Install Date:	05/21/1984
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported

JIFFY LUBE #470 (Continued) **1000231324**

Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

39 **ARBOR TECH** **LA SPILLS** **S109559559**
3769 SHOLAR COURT **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	05/16/2008
Date Initiated:	Not reported
aiid:	83561
Incident Id:	105669
Incident Date:	05/15/2008
Incident Status:	**Closed**
Media Desc:	Soil/Air
Location Description:	Arbor Tech 3769 Sholar Court Baton Rouge
Incident Source Name:	East Baton Rouge Parish
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c08-1677 Several containers of hydraulic fluid in his back yard that are leaking fluid onto the ground...jd
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

39 **TOWNHOMES OF SHERWOOD** **FINDS** **1010454355**
FOREST **ECHO** **N/A**
BATON ROUGE, LA 70808

FINDS:

Registry ID: 110032945712

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

TOWNHOMES OF SHERWOOD (Continued) **1010454355**

ECHO:
Envid: 1010454355
Registry ID: 110032945712
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110032945712

---

40 **LA LUBRICANTS DBA JIFFY LUBE #468** **LA SWRCY** **S105571308**
4815 PERKINS ROAD **N/A**
BATON ROUGE, LA 70809

LA SWRCY:
Mailing Address: 8768 Quarters Lake Road
Parish: East Baton Rouge
Contact: Wayne Davis, Manager
Contact Phone: 225-928-1975
Contact Fax: 225-922-9114
Contact Email: Not reported
Material Accepted: Used Oil

---

40 **JIFFY LUBE #468** **LA HIST LUST** **U001898373**
4815 PERKINS RD **LA UST** **N/A**
BATON ROUGE, LA 70808 **LA SPILLS**

HIST LUST:
Facility ID: 17-007212
Facility Parish: EAST BATON ROUGE
Substance Name: USED OIL
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 03/30/1994
Date Confirmed 2: Not reported
Incident Number: 94-2-0045
Incident Date: 03/30/1994
Type of Incident: UST LEAK
Type of Incident No2: Not reported
Reported By: DEQ HOTLINE
Reported By 2: Not reported
Owner ID: 00607100
Owner Name: JIFFY LUBE INTERNATIONAL INC
Owner Address: POST OFFICE BOX 2967
Owner City,St,Zip: HOUSTON, TX 77252-2967
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 10/02/1998
Corr Act Date Add Info Due: Not reported

JIFFY LUBE #468 (Continued) **U001898373**

Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: UST FAILED TIGHTNESS TEST. OWNER DOES NOT THINK THE UST IS LEAKING.TANKS REMOVED FROM SERVICE ON/ABOUT 3/30/94. UST TO BE REMOVED FROMGROUND IN JUNE 1994. RESULTS OF CLOSURE SAMPLES WILL DETERMINEFURTHER ACTION.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-007212
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 94-2-0045
Incident Date: 03/30/1994
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00607100
Owner Name: JIFFY LUBE INTERNATIONAL INC
Owner Address: POST OFFICE BOX 2967
Owner City,St,Zip: HOUSTON, TX 77252-2967
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 10/02/1998
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

JIFFY LUBE #468 (Continued) **U001898373**

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: UST FAILED TIGHTNESS TEST. OWNER DOES NOT THINK THE UST IS LEAKING.TANKS REMOVED FROM SERVICE ON/ABOUT 3/30/94. UST TO BE REMOVED FROMGROUND IN JUNE 1994. RESULTS OF CLOSURE SAMPLES WILL DETERMINEFURTHER ACTION.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:

Master Agency Id:	7642
Subject Item ID:	1
UST Tank Num:	19661
Tank Status:	**Removed**
Install Date:	05/21/1981
Total Capacity:	3000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	56258
Tank Status:	**Active**
Install Date:	12/01/1994
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported

JIFFY LUBE #468 (Continued) **U001898373**

New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

SPILLS:

Region Code:	Not reported
Date Rec:	11/28/2003
Date Initiated:	Not reported
aiid:	7642
Incident Id:	66293
Incident Date:	11/28/2003
Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	Jiffy Lube (Louisiana Lubricants) 4815 Perkins Rd
Incident Source Name:	Jiffy Lube #468
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s03-4798 UST (underground storage tank) holds 2000 gallons of waste oil and water - drain off water from rain got through the neck of the tank which pushed the oil out - tj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	used motor oil - 4-5 barrels
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	used motor oil - 4-5 barrels

Region Code:	Not reported
Date Rec:	11/28/2003
Date Initiated:	Not reported
aiid:	7642
Incident Id:	66293
Incident Date:	11/28/2003
Incident Status:	**Closed**
Media Desc:	Water/Soil

JIFFY LUBE #468 (Continued) **U001898373**

Location Description:	Jiffy Lube (Louisiana Lubricants) 4815 Perkins Rd
Incident Source Name:	Jiffy Lube
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s03-4798 UST (underground storage tank) holds 2000 gallons of waste oil and water - drain off water from rain got through the neck of the tank which pushed the oil out - tj
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	used motor oil - 4-5 barrels
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	used motor oil - 4-5 barrels

---

41 **SHAW TRANSM DIST SVCS INTL INC** **EDR Hist Auto** **1022135293**
4171 ESSEN LN **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2009	SHAW TRANSM & DIST SVCS INC	Automotive Transmission Repair Shops
2009	SHAW TRANSM DIST SVCS INTL INC	Automotive Transmission Repair Shops
2010	SHAW TRANSM DIST SVCS INTL INC	Automotive Transmission Repair Shops

---

41 **SHAW ENV & INFRASTRUCTURE INC/THROOP** **PA AIRS** **S116498648**
4171 ESSEN LN **N/A**
BATON ROUGE, PA 70809

AIRS:

Primary Facility ID:	512949
Contact Name:	STEVE MARTIN
Contact Phone:	2259877133
Particulate Matter:	.4
Nitrogen Oxides:	34.0
Sulfur Oxides:	4.9
Volatile Organic Compound:	3.3
Carbon Monoxide:	170.9
Lat/Long:	41 Deg. 26 Min. 12.8 / -75 Deg. 35 Min. 54.
NAICS Code:	562212
SIC Code:	4953
Year:	2013

41 REHABILITATION HOSPITAL OF BATON ROUGE — **RCRA-CESQG** — **1004709683**
8595 UNITED PLAZA BLVD — **FINDS** — **LAD982758658**
BATON ROUGE, LA 70809 — **ECHO**

RCRA-CESQG:

Date form received by agency:	02/13/2001
Facility name:	REHABILITATION HOSPITAL OF BATON ROUGE
Facility address:	8595 UNITED PLAZA BLVD BATON ROUGE, LA 70809
EPA ID:	LAD982758658
Mailing address:	UNITED PLAZA BLVD BATON ROUGE, LA 70809
Contact:	JIMMY RHODES
Contact address:	8595 UNITED PLAZA BLVD BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 927-0567
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	CONTINENTAL MED SYS INC
Owner/operator address:	600 WILSON LANE MECHANICSBURG, PA 17055
Owner/operator country:	Not reported
Owner/operator telephone:	(717) 790-8300
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

REHABILITATION HOSPITAL OF BATON ROUGE (Continued) **1004709683**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 03/19/1991
Site name: REHABILITATION HOSPITAL OF BATON ROUGE
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

FINDS:

Registry ID: 110003312282

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004709683
Registry ID: 110003312282
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003312282

---

41 **LA SPILLS** **S108598151**
4200 ESSEN LN **N/A**
BATON ROUGE, LA

SPILLS:
Region Code: Not reported
Date Rec: 12/12/2005
Date Initiated: Not reported
aiid: 113876
Incident Id: 84493
Incident Date: 12/12/2005
Incident Status: Closed
Media Desc: Soil
Location Description: 4200 Essen Ln Baton Rouge
Incident Source Name: Franciscan Missionaries of Our Lady
Reporter Name: Not reported
Mailing Address 1: Not reported
Mailing City: Not reported
Mailing State: Not reported
Mailing Zip: Not reported
Incident Desc: s05-4587 TPH concentrations in the soil were above RECAP standards.

(Continued) **S108598151**

	CMD
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

41 **FRANCISCAN MISSIONARIES OF OUR LADY** **LA UST** **U004021885**
4200 ESSEN LN **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	113876
Subject Item ID:	1
UST Tank Num:	56557
Tank Status:	**Removed**
Install Date:	06/01/1965
Total Capacity:	500
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

41 **TWO UNITED PLAZA** **LA UST** **U003073379**
8550 UNITED PLAZA BLVD **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	78770
Subject Item ID:	1
UST Tank Num:	46200
Tank Status:	**Removed**

TWO UNITED PLAZA (Continued) **U003073379**

Install Date:	01/01/1984
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

---

41 **UNITED COS** **LA UST** **U003667055**
4041 ESSEN LN **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	79892
Subject Item ID:	1
UST Tank Num:	52852
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	550
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Yes
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported

UNITED COS (Continued) **U003667055**

A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

41 **LA STATE RETIREMENT SYSTEMS BUILDING** **LA REM** **S116492288**
8401 UNITED PLAZA BLVD **N/A**
BATON ROUGE, LA 70809

REM:

AI Num:	79956
Evaluated And Closed:	Not reported
Program:	UST
EAC Type:	Not reported
Comments:	Not reported

---

41 **LA STATE RETIREMENT SYSTEMS BUILDING** **LA LUST** **S116492271**
8401 UNITED PLAZA BLVD **N/A**
BATON ROUGE, LA 70809

LUST:

Facility ID:	79956
Comments:	UST

---

41 **LA STATE RETIREMENT SYSTEMS BUILDING** **LA UST** **U003667093**
8401 UNITED PLAZA BLVD **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	79956
Subject Item ID:	1
UST Tank Num:	53049
Tank Status:	**Removed**
Install Date:	03/01/1985
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported

LA STATE RETIREMENT SYSTEMS BUILDING (Continued) **U003667093**

MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

---

41 **LA SECRETARY OF STATE - ARCHIVES** **LA UST** **U003925581**
3851 ESSEN LN **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	7621
Subject Item ID:	1
UST Tank Num:	52781
Tank Status:	**Active**
Install Date:	01/01/1987
Total Capacity:	2000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

41 LA SECRETARY OF STATE ARCHIVES — **RCRA-CESQG, FINDS, ECHO** — **1000262911 / LAD982288946**
3851 ESSEN LN
BATON ROUGE, LA 70809

RCRA-CESQG:

Date form received by agency:	08/13/1987
Facility name:	LA SECRETARY OF STATE ARCHIVES
Facility address:	3851 ESSEN LN BATON ROUGE, LA 70809
EPA ID:	LAD982288946
Mailing address:	PO BOX 94125 BATON ROUGE, LA 70804
Contact:	KIRK MENIER
Contact address:	PO BOX 94125 BATON ROUGE, LA 70804
Contact country:	US
Contact telephone:	(225) 925-3654
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SECRETARY OF STATE
Owner/operator address:	PO BOX 94125 BATON ROUGE, LA 70804
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 922-1200
Legal status:	State
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

LA SECRETARY OF STATE ARCHIVES (Continued) **1000262911**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Facility Has Received Notices of Violations:
Regulation violated: Not reported
Area of violation: Generators - General
Date violation determined: 11/05/1987
Date achieved compliance: 08/06/2001
Violation lead agency: State
Enforcement action: WRITTEN INFORMAL
Enforcement action date: 01/04/1988
Enf. disposition status: Not reported
Enf. disp. status date: Not reported
Enforcement lead agency: State
Proposed penalty amount: Not reported
Final penalty amount: Not reported
Paid penalty amount: Not reported

Evaluation Action Summary:
Evaluation date: 11/05/1987
Evaluation: COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of violation: Generators - General
Date achieved compliance: 08/06/2001
Evaluation lead agency: State

FINDS:

Registry ID: 110003307458

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000262911
Registry ID: 110003307458
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003307458

41 **STATE ARCHIVES BLDG.** **LA SPILLS** **S108597569**
3851 ESSEN LANE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	09/04/2003
Date Initiated:	Not reported
aiid:	7621
Incident Id:	64015
Incident Date:	09/04/2003
Incident Status:	**Closed**
Media Desc:	Air
Location Description:	State Archives Bldg. 3851 Essen Lane Baton Rouge
Incident Source Name:	Secretary of State - Archives
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s03-3275 plastic lines going to film machine broke - cs
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Ammonia
Quantity:	1 gallons
Other Substance Desc:	Not reported

---

42 **LOUISIANA EDUCATIONAL TELEVISION AUTHORITY** **LA SPILLS** **S111221518**
7733 PERKINS RD **LA REM** **N/A**
BATON ROUGE, LA 70810

SPILLS:

Region Code:	CR
Date Rec:	07/06/2011
Date Initiated:	07/08/2011
aiid:	0
Incident Id:	132200
Incident Date:	07/03/2011
Incident Status:	**Open**
Media Desc:	Soil
Location Description:	LPB 7733 Perkins Rd Baton Rouge
Incident Source Name:	0
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	0
Incident Type Desc:	Release/Spill, Miscellaneous
Comments:	0
Parameter:	Diesel
Quantity:	0 0
Other Substance Desc:	0

REM:

AI Num:	172470
Evaluated And Closed:	08/07/2012
Program:	UST
EAC Type:	No Further Interest

LOUISIANA EDUCATIONAL TELEVISION AUTHORITY (Continued) **S111221518**

Comments: No release occurred.

---

42 **N-N-OUT** **LA REM** **S117979753**
2147 STARING LN **N/A**
BATON ROUGE, LA 70810

REM:

AI Num:	75234
Evaluated And Closed:	05/27/2004
Program:	UST
EAC Type:	No Further Interest
Comments:	EDMS ID 2349302

---

42 **FORMER SIMPLE SIMON** **LA HIST LUST** **S106034371**
2157 STARING LN **LA REM** **N/A**
BATON ROUGE, LA 70810

HIST LUST:

Facility ID:	17-012634
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	07/09/1998
Date Confirmed 2:	Not reported
Incident Number:	98-2-0061
Incident Date:	07/09/1998
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	RICHARD BROWN
Reported By 2:	Not reported
Owner ID:	00471400
Owner Name:	SIMPLE SIMON, INC.
Owner Address:	2157 STARING LANE
Owner City,St,Zip:	BATON ROUGE, LA 70810
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	CRA SERVICES G&E ENGINEERING DIVISION
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	10/29/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported

FORMER SIMPLE SIMON (Continued) **S106034371**

Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: FACILITY AKA SIMPLE SIMON. USTS REMOVED IN 1994. CONSULTANT DID ALIMITED PHASE II ASSESSMENT AND FOUND ELEVATED BTEX IN A GROUNDWATERSAMPLE NEAR THE OLD PUMP ISLAND. REC'D WRITTEN NOTIFICATION FORM ANDPHASE II LIMITED ASSESSMENT ON 7/16/98. DEQ LETTER 8/14/98 REQUESTFURTHER ACTION. REC'D GROUNDWATER CHARACTERIZATION PROPOSAL ON 8/28/98

LA HIST LUST ASSESMENT:
Comments: DEQ LETTER 10/29/98 BASED ON 9/98 MONITORING WELL REPORT TERMINATIONOF REMEDIATION IS APPROVED.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

REM:
AI Num: 69183
Evaluated And Closed: 09/27/1999
Program: Solid Waste
EAC Type: Approve Completion NFA w/ BOD
Comments: EDMS ID 1614832

---

42 **RITE AID 7318** **RCRA-CESQG** **1016141694**
2159 STARING LN **FINDS** **LAR000078501**
BATON ROUGE, LA 70810 **ECHO**

RCRA-CESQG:
Date form received by agency: 12/21/2015
Facility name: RITE AID 7318
Facility address: 2159 STARING LN
BATON ROUGE, LA 70810
EPA ID: LAR000078501
Mailing address: HUNTER LN
CAMP HILL, PA 17011
Contact: DAVID W CROZIER
Contact address: HUNTER LN
CAMP HILL, PA 17011
Contact country: US
Contact telephone: (717) 975-8643
Contact email: EHS@RITEAID
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

RITE AID 7318 (Continued) **1016141694**

Owner/Operator Summary:

Owner/operator name:	RITE AID
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/28/2013
Owner/Op end date:	Not reported

Owner/operator name:	RITE AID
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	01/28/2013
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

RITE AID 7318 (Continued) **1016141694**

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U058
. Waste name: 2H-1,3,2-OXAZAPHOSPHORIN-2-AMINE, N,N-BIS(2-CHLOROETHYL)TETRAHYDRO-, 2-OXIDE (OR) CYCLOPHOSPHAMIDE

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U240
. Waste name: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

RITE AID 7318 (Continued) **1016141694**

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Historical Generators:
Date form received by agency: 07/31/2015
Site name: RITE AID 7318
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D016
. Waste name: 2,4-D (2,4-DICHLOROPHENOXYACETIC ACID)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

RITE AID 7318 (Continued) **1016141694**

. Waste code: U002
. Waste name: 2-PROPANONE (I) (OR) ACETONE (I)

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U154
. Waste name: METHANOL (I) (OR) METHYL ALCOHOL (I)

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U240
. Waste name: 2,4-D, SALTS & ESTERS (OR) ACETIC ACID, (2,4-DICHLOROPHENOXY)-, SALTS & ESTERS (OR) DICHLOROPHENOXYACETIC ACID 2,4-D

. Waste code: U279
. Waste name: CARBARYL (OR) 1-NAPHTHALENOL, METHYLCARBAMATE

Date form received by agency: 01/28/2013
Site name: RITE AID 7318
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075

RITE AID 7318 (Continued) **1016141694**

. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Violation Status: No violations found

FINDS:

Registry ID: 110055446272

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016141694
Registry ID: 110055446272
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110055446272

---

42 BR VA OUTPATIENT CLINIC **RCRA-CESQG** **1000122764**
7850 ANSELMO LANE **LAD008187882**
BATON ROUGE, LA 70896

RCRA-CESQG:
Date form received by agency: 08/01/2011
Facility name: BR VA OUTPATIENT CLINIC
Facility address: 7850 ANSELMO LANE
BATON ROUGE, LA 70896
EPA ID: LAD008187882
Mailing address: SLVHCS, OSM
PO BOX 61011
NEW ORLEANS, LA 70161
Contact: JOHN E HEPPEL
Contact address: SLVHCS, OSM PO BOX 61011
NEW ORLEANS, LA 70161
Contact country: US
Contact telephone: (504) 566-8425
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any

BR VA OUTPATIENT CLINIC (Continued) **1000122764**

time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BANK ONE LOUISIANA NA
Owner/operator address:	7850 ANSELMO LN BATON ROUGE, LA 70810
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 332-3120
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	SLVHCS
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Operator
Owner/Op start date:	08/01/2011
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D011
. Waste name: SILVER

Historical Generators:

Date form received by agency:	08/18/1980
Site name:	BANK ONE LOUISIANA NA
Classification:	Not a generator, verified

. Waste code: D011
. Waste name: SILVER

BR VA OUTPATIENT CLINIC (Continued) **1000122764**

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 12/28/1998
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

---

42 EXXON CO 56174 **RCRA-CESQG 1004711099**
5857 ESSEN LN **FINDS LAD985202563**
BATON ROUGE, LA 70808

RCRA-CESQG:
Date form received by agency: 02/23/2000
Facility name: EXXON CO 56174
Facility address: 5857 ESSEN LN
BATON ROUGE, LA 70808
EPA ID: LAD985202563
Mailing address: PO BOX 2180 RM 2753
HOUSTON, TX 772522180
Contact: ALDA POOL
Contact address: PO BOX 2180 RM 2753
HOUSTON, TX 772522180
Contact country: US
Contact telephone: (713) 656-7709
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: EXXON CO USA
Owner/operator address: PO BOX 2180
HOUSTON, TX 77252
Owner/operator country: Not reported
Owner/operator telephone: (713) 656-7761
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

EXXON CO 56174 (Continued) **1004711099**

Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D018
. Waste name: BENZENE

Violation Status: No violations found

FINDS:

Registry ID: 110003329014

Environmental Interest/Information System

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

---

42 **CIRCLE K #7656** **LA UST** **U003986871**
5857 ESSEN LN **LA NPDES** **N/A**
BATON ROUGE, LA 70806 **LA REM**

UST:

Master Agency Id:	22658
Subject Item ID:	2
UST Tank Num:	11982
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	12000
Number Of Compartments:	1

CIRCLE K #7656 (Continued) **U003986871**

Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	11983
Tank Status:	**Removed**
Install Date:	04/12/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

CIRCLE K #7656 (Continued) **U003986871**

UST Tank Num:	11984
Tank Status:	**Removed**
Install Date:	05/01/1984
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	11985
Tank Status:	**Removed**
Install Date:	05/01/1984
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported

CIRCLE K #7656 (Continued) **U003986871**

Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	11986
Tank Status:	**Removed**
Install Date:	05/01/1984
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Yes
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	55415
Tank Status:	**Active**
Install Date:	01/10/2002
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported

CIRCLE K #7656 (Continued) **U003986871**

Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	55416
Tank Status:	**Active**
Install Date:	01/10/2002
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	55417
Tank Status:	**Active**
Install Date:	01/10/2002
Total Capacity:	20000
Number Of Compartments:	2
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported

CIRCLE K #7656 (Continued) **U003986871**

MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

NPDES:

Facility Id:	22658
Facility Phone:	2257676880
Issued Date:	02/20/2002
Title Description:	LAG750403 Permit
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20010001

Facility Id:	22658
Facility Phone:	2257676880
Issued Date:	06/12/2009
Title Description:	Automatic Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20090001

Facility Id:	22658
Facility Phone:	2257676880
Issued Date:	05/07/2004
Title Description:	LAG750403 Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20040001

REM:

AI Num:	22658
Evaluated And Closed:	11/08/2011
Program:	UST
EAC Type:	No Further Interest
Comments:	EDMS ID 8196146

42 ALBERTSONS 2711 — **RCRA-CESQG, FINDS, ECHO** — **1016676294 / LAR000082388**
7515 PERKINS RD
BATON ROUGE, LA 70808

RCRA-CESQG:

Date form received by agency:	03/13/2014
Facility name:	ALBERTSONS 2711
Facility address:	7515 PERKINS RD BATON ROUGE, LA 70808
EPA ID:	LAR000082388
Mailing address:	PO BOX 20 BOISE, ID 83726
Contact:	ERICA FRANSEN
Contact address:	PO BOX 20 BOISE, ID 83726
Contact country:	US
Contact telephone:	(208) 395-4793
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	ALBERTSONS
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/02/2006
Owner/Op end date:	Not reported

Owner/operator name:	ALBERTSONS
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/02/2006
Owner/Op end date:	Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No

ALBERTSONS 2711 (Continued) **1016676294**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

Violation Status: No violations found

FINDS:

Registry ID: 110058886148

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016676294
Registry ID: 110058886148
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110058886148

42 **VALERO CORNER STORE #1725** **LA UST** **U003926879**
7515 PERKINS RD **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	89100
Subject Item ID:	2
UST Tank Num:	54983
Tank Status:	**Active**
Install Date:	05/09/2001
Total Capacity:	15000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	54984
Tank Status:	**Active**
Install Date:	05/09/2001
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

VALERO CORNER STORE #1725 (Continued) **U003926879**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

42 **ACOSTA CLEANERS** **EDR Hist Cleaner** **1013785195**
5743 ESSEN LN **N/A**
BATON ROUGE, LA 70809

EDR Hist Cleaner

Year:	Name:	Type:
1990	ACOSTA CLEANERS	CLEANERS AND DYERS

---

42 **KADAIRS CAMERA AUDIO & VIDEO INC** **RCRA NonGen / NLR** **1000768591**
5713 ESSEN LN **FINDS** **LAD985227370**
BATON ROUGE, LA 70810 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	05/27/1993
Facility name:	KADAIRS CAMERA AUDIO & VIDEO INC
Facility address:	5713 ESSEN LN BATON ROUGE, LA 70810
EPA ID:	LAD985227370
Mailing address:	S DONMOOR BATON ROUGE, LA 70806
Contact:	JAMES-HOWARD KADAIR
Contact address:	124 S DONMOOR BATON ROUGE, LA 70806
Contact country:	US
Contact telephone:	(225) 231-9900
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JAMES HOWARD KADAIR
Owner/operator address:	9727 JEFFERSON HWY BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 927-4416
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

KADAIRS CAMERA AUDIO & VIDEO INC (Continued) **1000768591**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:

Evaluation date:	07/02/1998
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

FINDS:

Registry ID: 110003344462

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000768591
Registry ID:	110003344462
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003344462

42 **DRY CLEANING ONE** **EDR Hist Cleaner** **1018864570**
5703 ESSEN LN **N/A**
BATON ROUGE, LA 70810

EDR Hist Cleaner

Year:	Name:	Type:
1986	DRY CLEANING ONE	Garment Pressing And Cleaners' Agents
1987	DRY CLEANING ONE	Garment Pressing And Cleaners' Agents
1988	DRY CLEANING ONE	Garment Pressing And Cleaners' Agents

---

42 **RAPID LUBE & TUNE UP** **RCRA NonGen / NLR** **1004710042**
5615 ESSEN LN **FINDS** **LAD985184704**
BATON ROUGE, LA 70809 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	09/17/1990
Facility name:	RAPID LUBE & TUNE UP
Facility address:	5615 ESSEN LN BATON ROUGE, LA 70809
EPA ID:	LAD985184704
Mailing address:	ESSEN LN BATON ROUGE, LA 70809
Contact:	JERRY HIX
Contact address:	5615 ESSEN LN BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 767-5754
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	JERRY HIX
Owner/operator address:	5615 ESSEN BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 767-5754
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No

RAPID LUBE & TUNE UP (Continued) **1004710042**

Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D018
. Waste name: BENZENE

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 04/13/2000
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003317287

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004710042
Registry ID: 110003317287
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003317287

42 **EDR Hist Auto** **1013755460**
5615 ESSEN LN **N/A**
BATON ROUGE, LA 70810

EDR Hist Auto

Year:	Name:	Type:
1990	SPEE DEE OIL CHANGE & TUNE UP	AUTOMOBILE OIL AND LUBRICATING SERVICE

---

42 **ENTERGY SERVICE CENTER** **LA ASBESTOS** **S117439396**
5564 ESSEN LN **N/A**
BATON ROUGE, LA

ASBESTOS:

Asbestos Disposal Facility Id:	Not reported
Site Location:	site wide
Issue Date:	09/22/2014
Expire Date:	12/21/2014
Qty Rec By Disposal Facility (CY):	2.00
AI#:	193683
Contractor AI Id:	Not reported
Alternate AI Id:	Not reported
Amount:	2
Unit:	Not reported
Scheduled Start:	09/20/2014
Scheduled End:	09/21/2014
Asbestos Contractors:	Air Environmental Services Inc
Transporter Name:	Air Environmental Services Inc
SW Disposal Facility Name:	Reliable Landfill LLC
SW Disposal Facility AI Id:	Not reported
SW Disposal Facility Address:	Not reported
SW Disposal Facility City:	Not reported
SW Disposal Facility State:	Not reported
SW Disposal Facility Zip:	Not reported
Parish:	Not reported
Deq Copy Received:	Not reported
Days Elapsed Since Issuance:	Not reported
Days To Expiration:	Not reported
Type Of Notification:	Not reported
Type Of Operation:	Not reported
Ordered By:	Not reported
Ordered Date:	Not reported
# Of Floors:	Not reported
Age In Years:	Not reported
Present Use:	Not reported
Prior Use:	Not reported
Mailing Address Line 1:	Not reported
Mailing Address City/State/Zip:	Not reported
Transporter AI Id:	Not reported
Transporter Id:	Not reported
Transporter Address:	Not reported
Transporter Physical Address Line 2:	Not reported
Transporter City/Statae/Zip:	Not reported
Total ADVFs Issued:	Not reported
Total Emergency ADVFs Issued:	Not reported
Total Emergency ADVF Revenue Generated:	Not reported
ADVF #:	ADVF-0032117
Total Non-Emergency ADVFs Issued:	Not reported
Total Non-Emergency ADVF Revenue Generated:	Not reported
Total ADVF Revenue Generated:	Not reported

ENTERGY SERVICE CENTER (Continued) **S117439396**

Comments: Not reported

---

42 KWIK KOPY PRINTING **RCRA NonGen / NLR** **1004713185**
5555 ESSEN LN STE B **LAR000007880**
BATON ROUGE, LA 70809

RCRA NonGen / NLR:

Date form received by agency:	12/12/2011
Facility name:	KWIK KOPY PRINTING
Facility address:	5555 ESSEN LN STE B BATON ROUGE, LA 70809
EPA ID:	LAR000007880
Mailing address:	ESSEN LN STE B BATON ROUGE, LA 70809
Contact:	FLOYD WHITE
Contact address:	5555 ESSEN LN STE B BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 767-5679
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	W FLOYD WHITE
Owner/operator address:	5555 ESSEN LANE STE B BATON ROUGE, LA 70809
Owner/operator country:	US
Owner/operator telephone:	(225) 767-5679
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	12/19/2006
Owner/Op end date:	Not reported

Owner/operator name:	W FLOYD WHITE
Owner/operator address:	5555 ESSEN LANE STE B BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 767-5679
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No

KWIK KOPY PRINTING (Continued) **1004713185**

User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 12/19/2006
Site name: KWIK KOPY PRINTING
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 10/11/1995
Site name: KWIK KOPY PRINTING
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 12/12/2011
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

---

42 **MED AID WALK IN MEDICAL CENTER** **RCRA-CESQG** **1004709352**
5475 ESSEN LANE **FINDS** **LAD981913148**
BATON ROUGE, LA 70809 **ECHO**

RCRA-CESQG:
Date form received by agency: 04/28/1987
Facility name: MED AID WALK IN MEDICAL CENTER
Facility address: 5475 ESSEN LANE
BATON ROUGE, LA 70809
EPA ID: LAD981913148
Mailing address: ESSEN LANE
BATON ROUGE, LA 70809
Contact: WARREN PERIOUX
Contact address: 5475 ESSEN LANE
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 767-2750
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or

MED AID WALK IN MEDICAL CENTER (Continued) **1004709352**

other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	TESSIER CHARLES MD
Owner/operator address:	5475 ESSEN LN BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 767-2750
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003305628

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

MED AID WALK IN MEDICAL CENTER (Continued) **1004709352**

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004709352
Registry ID:	110003305628
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003305628

---

42 **BATON ROUGE CLINIC** **RCRA-CESQG** **1014916845**
7373 PERKINS RD **LAR000073726**
BATON ROUGE, LA 70808

RCRA-CESQG:

Date form received by agency:	06/24/2011
Facility name:	BATON ROUGE CLINIC
Facility address:	7373 PERKINS RD BATON ROUGE, LA 70808
EPA ID:	LAR000073726
Mailing address:	PERKINS RD BATON ROUGE, LA 70808
Contact:	ASHLEY POURCIAU
Contact address:	PERKINS RD BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 246-9292
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	OLOL RMC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	10/01/1999
Owner/Op end date:	Not reported
Owner/operator name:	BR CLINIC
Owner/operator address:	Not reported

BATON ROUGE CLINIC (Continued) **1014916845**

	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/01/1999
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D001
. Waste name:	IGNITABLE WASTE

Violation Status: No violations found

---

42 **DIGITAL DIAGNOSTIC CNTR** **RCRA-CESQG** **1004710251**
7703 PICARDY AVE **FINDS** **LAD985187913**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	12/11/1990
Facility name:	DIGITAL DIAGNOSTIC CNTR
Facility address:	7703 PICARDY AVE BATON ROUGE, LA 70808
EPA ID:	LAD985187913
Mailing address:	PICARDY AVE BATON ROUGE, LA 70808
Contact:	JOHNNY ST JOHN
Contact address:	7703 PICARDY AVE BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 767-3620
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting

DIGITAL DIAGNOSTIC CNTR (Continued) **1004710251**

from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	DIGITAL DIAGNOSTIC CENTER
Owner/operator address:	7703 PICARDY AVE BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 767-3620
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003319622

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

DIGITAL DIAGNOSTIC CNTR (Continued) **1004710251**

ECHO:
Envid: 1004710251
Registry ID: 110003319622
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003319622

---

42 WILLIAM A COUVILLION DDS **RCRA-CESQG** **1004709557**
7612 PICARDY SUITE C **FINDS** **LAD982549487**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 03/25/1988
Facility name: WILLIAM A COUVILLION DDS
Facility address: 7612 PICARDY SUITE C
BATON ROUGE, LA 70808
EPA ID: LAD982549487
Mailing address: PICARDY SUITE C
BATON ROUGE, LA 70808
Contact: WILLIAM COUVILLION
Contact address: 7612 PICARDY SUITE C
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 767-7212
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: WILLIAM COUVILLION
Owner/operator address: 7612 PICARDY
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (000) 000-0000
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No

WILLIAM A COUVILLION DDS (Continued) **1004709557**

Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003309875

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004709557
Registry ID: 110003309875
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003309875

---

42 **KATHY M WOODY DDS** **RCRA-CESQG** **1004710809**
7612 PICARDY AVE STE M **FINDS** **LAD985198084**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 02/07/1991
Facility name: KATHY M WOODY DDS
Facility address: 7612 PICARDY AVE STE M
BATON ROUGE, LA 70808
EPA ID: LAD985198084
Mailing address: PICARDY AVE STE M
BATON ROUGE, LA 70808
Contact: KATHY WOODY
Contact address: 7612 PICARDY AVE STE M
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 767-5370
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator

KATHY M WOODY DDS (Continued) **1004710809**

Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	KATHY M WOODY
Owner/operator address:	7612 PICARDY AVE BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 767-5370
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110009581416

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA

KATHY M WOODY DDS (Continued) **1004710809**

program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004710809
Registry ID:	110009581416
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009581416

---

42 ORTHOPAEDIC SURGERY ASSOCIATES **RCRA-CESQG** **1004709336**
5408 FLANDERS DR. **FINDS** **LAD981909096**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	04/13/1987
Facility name:	ORTHOPAEDIC SURGERY ASSOCIATES
Facility address:	5408 FLANDERS DR. BATON ROUGE, LA 70808
EPA ID:	LAD981909096
Mailing address:	FLANDERS DR. BATON ROUGE, LA 70808
Contact:	MAURICE ALLEN
Contact address:	5408 FLANDERS DR. BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(504) 709-0173
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	DRS. CRANOR, K. & IRWIN, S.
Owner/operator address:	5408 FLANDERS DR BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

ORTHOPAEDIC SURGERY ASSOCIATES (Continued) **1004709336**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003305272

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004709336
Registry ID:	110003305272
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003305272

---

42 BATON ROUGE CLINIC **RCRA-CESQG** **1004710340**
5304 FLANDERS DR **FINDS** **LAD985189729**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	12/24/1990
Facility name:	BATON ROUGE CLINIC
Facility address:	5304 FLANDERS DR BATON ROUGE, LA 70808
EPA ID:	LAD985189729
Mailing address:	FLANDERS DR BATON ROUGE, LA 70808
Contact:	LISA PERRY
Contact address:	5304 FLANDERS DR

BATON ROUGE CLINIC (Continued) **1004710340**

BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 769-4044
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:
Owner/operator name: BATON ROUGE CLINIC
Owner/operator address: 8415 GOODWOOD BLVD
BATON ROUGE, LA 70806
Owner/operator country: Not reported
Owner/operator telephone: (225) 923-1515
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003320638

BATON ROUGE CLINIC (Continued) **1004710340**

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004710340
Registry ID:	110003320638
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003320638

---

42 **DRS BRYAN HATCHER VICK & HASTINGS** **RCRA-CESQG** **1004709350**
5345 BRITTANY DR **LAD981913098**
BATON ROUGE, LA 70809

RCRA-CESQG:

Date form received by agency:	04/28/1987
Facility name:	DRS BRYAN HATCHER VICK & HASTINGS
Facility address:	5345 BRITTANY DR BATON ROUGE, LA 70809
EPA ID:	LAD981913098
Mailing address:	BRITTANY DR BATON ROUGE, LA 70809
Contact:	WILLIAM NORRIS
Contact address:	5345 BRITTANY DR BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 769-2500
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	BRYAN HATCHER VICK
Owner/operator address:	5345 BRITTANY DR BATON ROUGE, LA 70809
Owner/operator country:	Not reported

DRS BRYAN HATCHER VICK & HASTINGS (Continued) **1004709350**

Owner/operator telephone: (225) 769-2500
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

---

42 **DRS BRYAN HATCHER VICK & HASTINGS** **RCRA-CESQG** **1016141738**
5345 BRITTANY DR **FINDS** **LAR000078998**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 03/28/2013
Facility name: OUR LADY OF THE LAKE COLLEGE
Facility address: 5345 BRITTANY DR
BATON ROUGE, LA 70808
EPA ID: LAR000078998
Mailing address: BRITTANY DR
BATON ROUGE, LA 70808
Contact: DENISE GILLESPIE
Contact address: BRITTANY DR
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 768-1755
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any

DRS BRYAN HATCHER VICK & HASTINGS (Continued) **1016141738**

time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	OLOL COLLEGE
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Operator
Owner/Op start date:	05/30/1989
Owner/Op end date:	Not reported

Owner/operator name:	OLOL RMC
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Municipal
Owner/Operator Type:	Owner
Owner/Op start date:	05/30/1989
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D004
. Waste name: ARSENIC

. Waste code: D006

DRS BRYAN HATCHER VICK & HASTINGS (Continued) **1016141738**

. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D011
. Waste name: SILVER

. Waste code: D014
. Waste name: METHOXYCHLOR (1,1,1-TRICHLORO-2,2-BIS [P-METHOXYPHENYL] ETHANE)

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D035
. Waste name: METHYL ETHYL KETONE

. Waste code: D038
. Waste name: PYRIDINE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Violation Status: No violations found

FINDS:

Registry ID: 110003305575

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1016141738
Registry ID: 110003305575
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003305575

42 DRS WALL TOWNS & HORNSBY — **RCRA-CESQG** — **1004707225**
5227 FLANDERS DR — **FINDS** — **LA0000367656**
BATON ROUGE, LA 70808 — **ECHO**

RCRA-CESQG:

Date form received by agency:	06/16/1994
Facility name:	DRS WALL TOWNS & HORNSBY
Facility address:	5227 FLANDERS DR BATON ROUGE, LA 70808
EPA ID:	LA0000367656
Mailing address:	FLANDERS DR BATON ROUGE, LA 70808
Contact:	DR HORNSBY
Contact address:	5227 FLANDERS DR BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 769-3600
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	DRS WALL TOWNS & HORNSBY
Owner/operator address:	5227 FLANDERS DR BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

DRS WALL TOWNS & HORNSBY (Continued) **1004707225**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003260621

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707225
Registry ID: 110003260621
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003260621

---

42 KIRBY PERRY DDS LLC **RCRA-CESQG 1004709840**
5211 ESSEN LN STE 5 **FINDS LAD985173483**
BATON ROUGE, LA 70809 **ECHO**

RCRA-CESQG:
Date form received by agency: 07/27/1990
Facility name: KIRBY PERRY DDS LLC
Facility address: 5211 ESSEN LN STE 5
BATON ROUGE, LA 70809
EPA ID: LAD985173483
Mailing address: ESSEN LN STE 5
BATON ROUGE, LA 70809
Contact: KELLI LAVIGNE
Contact address: ESSEN LN STE 5
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 769-7710
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

KIRBY PERRY DDS LLC (Continued) **1004709840**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	DR KIRBY PERRY
Owner/operator address:	5211 ESSEN LN STE 5 BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	DR KIRBY PERRY
Owner/operator address:	5211 ESSEN LN STE 5 BATON ROUGE, LA 70809
Owner/operator country:	US
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code:	D011
. Waste name:	SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003314850

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource

KIRBY PERRY DDS LLC (Continued) **1004709840**

Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004709840
Registry ID:	110003314850
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003314850

---

42 SAGE REHABILITATION HOSPITAL **RCRA-SQG** **1018156775**
8000 SUMMA AVENUE **FINDS** **LAR000088088**
BATON ROUGE, LA 70809 **ECHO**

RCRA-SQG:

Date form received by agency:	11/10/2015
Facility name:	SAGE REHABILITATION HOSPITAL
Facility address:	8000 SUMMA AVENUE BATON ROUGE, LA 70809
EPA ID:	LAR000088088
Mailing address:	SUMMA AVENUE BATON ROUGE, LA 70809
Contact:	CAROLINE STASSI
Contact address:	SUMMA AVENUE BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 906-4900
Contact email:	CSTASSI@SAGE-REHAB.ORG
EPA Region:	06
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CARE PLAN OVERSIGHT, LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Other
Owner/Operator Type:	Operator
Owner/Op start date:	01/09/2012
Owner/Op end date:	Not reported
Owner/operator name:	FAEC HOLDINGS, LLC
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported

SAGE REHABILITATION HOSPITAL (Continued) **1018156775**

Legal status: Other
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

SAGE REHABILITATION HOSPITAL (Continued) **1018156775**

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL--YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

. Waste code: P204
. Waste name: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

. Waste code: U010
. Waste name: AZIRINO [2',3':3,4]PYRROLO[1,2-A]INDOLE-4,7-DIONE, 6-AMINO-8-[[(AMINOCARBONYL)OXY]METHYL]-1,1A,2,8,8A,8B-HEXAHYDRO-8A-METOXY-5-METHYL-, [1AS-(1AALPHA, 8BETA, 8AALPHA, 8BALPHA)]- (OR) MITOMYCIN C

. Waste code: U035
. Waste name: BENZENEBUTANOIC ACID, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) CHLORAMBUCIL

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U122
. Waste name: FORMALDEHYDE

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U150
. Waste name: L-PHENYLALANINE, 4-[BIS(2-CHLOROETHYL)AMINO]- (OR) MELPHALAN

. Waste code: U187
. Waste name: ACETAMIDE, N-(4-ETHOXYPHENYL)- (OR) PHENACETIN

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL (OR) RESORCINOL

. Waste code: U202
. Waste name: 1,2-BENZISOTHIAZOL-3(2H)-ONE, 1,1-DIOXIDE, & SALTS (OR) SACCHARIN, & SALTS

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U206

SAGE REHABILITATION HOSPITAL (Continued) **1018156775**

. Waste name: D-GLUCOSE, 2-DEOXY-2-[[(METHYLNITROSOAMINO)-CARBONYL]AMINO]- (OR) GLUCOPYRANOSE, 2-DEOXY-2-(3-METHYL-3-NITROSOUREIDO)-,D- (OR) STREPTOZOTOCIN

. Waste code: U237
. Waste name: 2,4-(1H,3H)-PYRIMIDINEDIONE, 5-[BIS(2-CHLOROETHYL)AMINO]- (OR) URACIL MUSTARD

Violation Status: No violations found

FINDS:

Registry ID: 110067049054

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018156775
Registry ID: 110067049054
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067049054

---

42 STEPHEN L SHERMAN DDS **RCRA-CESQG** **1004707229**
7922 SUMMA STE A3 **FINDS** **LA0000370718**
BATON ROUGE, LA 70809 **ECHO**

RCRA-CESQG:
Date form received by agency: 06/21/1994
Facility name: STEPHEN L SHERMAN DDS
Facility address: 7922 SUMMA STE A3
BATON ROUGE, LA 70809
EPA ID: LA0000370718
Mailing address: SUMMA STE A3
BATON ROUGE, LA 70809
Contact: WHITE POPPY
Contact address: 7922 SUMMA STE A3
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 769-1276
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less

STEPHEN L SHERMAN DDS (Continued) **1004707229**

of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	STEPHEN L SHERMAN
Owner/operator address:	7922 SUMMA STE A3 BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 769-1276
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003260667

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

STEPHEN L SHERMAN DDS (Continued) **1004707229**

ECHO:

Envid:	1004707229
Registry ID:	110003260667
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003260667

---

42 **WVLA-TV STUDIOS** **LA UST** **U000879912**
5220 ESSEN LN **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	76525
Subject Item ID:	1
UST Tank Num:	38992
Tank Status:	**Removed**
Install Date:	05/01/1984
Total Capacity:	1000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

---

42 **HANSBROUGH PETERS AMA** **RCRA NonGen / NLR** **1004709805**
5344 BRITTANY DR **FINDS** **LAD985172907**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	10/20/2003
Facility name:	HANSBROUGH PETERS AMA
Facility address:	5344 BRITTANY DR BATON ROUGE, LA 70808
EPA ID:	LAD985172907
Mailing address:	BRITTANY DR BATON ROUGE, LA 70808

HANSBROUGH PETERS AMA (Continued) **1004709805**

Contact:	ERMYNE COLLURA
Contact address:	BRITTANY DR BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 767-7200
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	THOMAS A HANSBROUGH MD & STANLY E PETERS
Owner/operator address:	5344 BRITTANY DR BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 767-7200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	ERMYNE TEEKELL
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	10/20/2003
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	07/17/1990
Site name:	HANSBROUGH PETERS AMA
Classification:	Conditionally Exempt Small Quantity Generator

. Waste code:	D011
. Waste name:	SILVER

HANSBROUGH PETERS AMA (Continued) **1004709805**

Violation Status: No violations found

FINDS:

Registry ID: 110003314397

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004709805
Registry ID: 110003314397
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003314397

---

42 LLOYD PAUL CHAMPAGNE MD **RCRA NonGen / NLR** **1000441288**
5131 ESSEN LN **FINDS** **LAD982562241**
BATON ROUGE, LA 70809 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 01/13/1989
Facility name: LLOYD PAUL CHAMPAGNE MD
Facility address: 5131 ESSEN LN
BATON ROUGE, LA 70809
EPA ID: LAD982562241
Mailing address: ESSEN LN
BATON ROUGE, LA 70809
Contact: SARAJEAN CHAMPAGNE
Contact address: 5131 ESSEN LN
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 769-2637
Contact email: Not reported
EPA Region: 06
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LLOYD P CHAMPAGNE
Owner/operator address: 5131 ESSEN LN
BATON ROUGE, LA 70809
Owner/operator country: Not reported
Owner/operator telephone: (225) 769-2637
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

LLOYD PAUL CHAMPAGNE MD (Continued) **1000441288**

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003311577

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000441288
Registry ID:	110003311577
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003311577

---

42 **WALGREEN DRUG STORE 3047** **RCRA-CESQG** **1001196345**
5112 ESSEN LN **FINDS** **LAR000004648**
BATON ROUGE, LA 70809 **ECHO**

RCRA-CESQG:

Date form received by agency:	08/02/2013
Facility name:	WALGREEN DRUG STORE 3047
Facility address:	5112 ESSEN LN BATON ROUGE, LA 70809
EPA ID:	LAR000004648
Mailing address:	WILMOT RD DEERFIELD, IL 60015
Contact:	ANDREW J MARKS
Contact address:	WILMOT RD

WALGREEN DRUG STORE 3047 (Continued) **1001196345**

	DEERFIELD, IL 60015
Contact country:	US
Contact telephone:	(847) 315-2602
Contact email:	Not reported
EPA Region:	06
Land type:	Private
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	WALGREENS
Owner/operator address:	200 WILMOT RD DEERFIELD, IL 60015
Owner/operator country:	Not reported
Owner/operator telephone:	(847) 940-2500
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	WALGREENS
Owner/operator address:	200 WILMOT RD DEERFIELD, IL 60015
Owner/operator country:	US
Owner/operator telephone:	(847) 940-2500
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No

WALGREEN DRUG STORE 3047 (Continued) **1001196345**

Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D003
. Waste name: REACTIVE WASTE

. Waste code: D005
. Waste name: BARIUM

. Waste code: D006
. Waste name: CADMIUM

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 01/23/2004
Site name: WALGREENS 3047
Classification: Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 06/01/1995
Site name: WALGREENS 3047
Classification: Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 08/29/2007
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported

WALGREEN DRUG STORE 3047 (Continued) **1001196345**

Evaluation lead agency: State

FINDS:

Registry ID: 110003348609

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1001196345
Registry ID: 110003348609
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003348609

---

42 BATON ROUGE CARDIOLOGY CENTER **RCRA-CESQG** **1004707132**
5231 BRITTANY DR **FINDS** **LA0000203224**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:
Date form received by agency: 04/12/1994
Facility name: BATON ROUGE CARDIOLOGY CENTER
Facility address: 5231 BRITTANY DR
BATON ROUGE, LA 70808
EPA ID: LA0000203224
Mailing address: BRITTANY DR
BATON ROUGE, LA 70808
Contact: WENDY KERN
Contact address: 5231 BRITTANY DR
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 769-0933
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

BATON ROUGE CARDIOLOGY CENTER (Continued) **1004707132**

Owner/Operator Summary:

Owner/operator name:	JAMES R CALVIN
Owner/operator address:	5231 BRITTANY BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 769-0933
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003259624

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004707132
Registry ID:	110003259624
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003259624

42 SURGI CTR OF BATON ROUGE
5222 BRITTANY DR
BATON ROUGE, LA 70808

RCRA-CESQG
FINDS
ECHO

1004708442
LAD139235485

RCRA-CESQG:

Date form received by agency:	11/14/2007
Facility name:	SURGI CTR OF BATON ROUGE
Facility address:	5222 BRITTANY DR BATON ROUGE, LA 70808
EPA ID:	LAD139235485
Mailing address:	BRITTANY DR BATON ROUGE, LA 70808
Contact:	DENISE T FORTENBERRY
Contact address:	BRITTANY DR BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 767-5636
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	SURGI CTR LTD PTNR
Owner/operator address:	5222 BRITANY DR BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	SURGI CTR LTD PTNR
Owner/operator address:	5222 BRITANY DR BATON ROUGE, LA 70808
Owner/operator country:	US
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No

SURGI CTR OF BATON ROUGE (Continued) **1004708442**

Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 02/24/1988
Site name: SURGI CTR OF B ROUGE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003284758

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004708442
Registry ID: 110003284758
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003284758

42 HEALTHSOUTH SURGI CENTER OF BATON ROUGE **LA UST** **U003922544**
5222 BRITTANY DR **N/A**
BATON ROUGE, LA 70808

UST:

Master Agency Id:	35811
Subject Item ID:	6
UST Tank Num:	39548
Tank Status:	**Removed**
Install Date:	01/01/1980
Total Capacity:	300
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: With Release Detection
UST Tank Num:	53612
Tank Status:	**Removed**
Install Date:	03/01/1999
Total Capacity:	560
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

HEALTHSOUTH SURGI CENTER OF BATON ROUGE (Continued) **U003922544**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

---

42 **OLOL EAST TOWER & ED TRAUMA ADDITIONS & OFFSITE ST** **LA NPDES** **S111284488**
5050 ESSEN LN (E TOWER & ED TRAUMA) **N/A**
BATON ROUGE, LA 70808

NPDES:

Facility Id:	177088
Facility Phone:	2259248050
Issued Date:	10/12/2011
Title Description:	Gen Constr. Permit
Permit Type Description:	Gen-LAR10-Construction
Program:	Water
Activity Number:	GEN20110001

---

42 **TAU CENTER** **LA HIST LUST** **U001898486**
8080 MARGARET ANN DR **LA UST** **N/A**
BATON ROUGE, LA 70800

HIST LUST:

Facility ID:	17-014316
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	07/28/1993
Date Confirmed 2:	Not reported
Incident Number:	93-2-0193
Incident Date:	07/28/1993
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00627800
Owner Name:	TAU CENTER
Owner Address:	8080 MARGARET ANN DRIVE
Owner City,St,Zip:	BATON ROUGE, LA 70800
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported

TAU CENTER (Continued) **U001898486**

Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/10/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: RELEASE NOTIFICATION NOT IN FILE FOLDER. 1 TANK WAS REMOVEDIN JULY 93 BY PETROCHEM. SOIL SAMPLES TAKEN. TANK CLOSUREGRANTED 09 SEP 93.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-014316
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	93-2-0193
Incident Date:	07/28/1993
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00627800
Owner Name:	TAU CENTER
Owner Address:	8080 MARGARET ANN DRIVE
Owner City,St,Zip:	BATON ROUGE, LA 70800
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	09/10/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported

TAU CENTER (Continued) **U001898486**

Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: RELEASE NOTIFICATION NOT IN FILE FOLDER. 1 TANK WAS REMOVEDIN JULY 93 BY PETROCHEM. SOIL SAMPLES TAKEN. TANK CLOSUREGRANTED 09 SEP 93.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

UST:

Master Agency Id:	77177
Subject Item ID:	1
UST Tank Num:	41223
Tank Status:	**Closed**
Install Date:	01/01/1980
Total Capacity:	200
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Yes
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Suction: Without Release Detection

42 NEURO MEDICAL CENTER — **RCRA-CESQG, FINDS, ECHO** — **1004707223, LA0000367615**
7777 HENNESSY STE 1000
BATON ROUGE, LA 70808

RCRA-CESQG:

Date form received by agency:	11/16/2005
Facility name:	NEURO MEDICAL CENTER
Facility address:	7777 HENNESSY STE 1000 BATON ROUGE, LA 70808
EPA ID:	LA0000367615
Mailing address:	HENNESSY STE 1000 BATON ROUGE, LA 70808
Contact:	NANCY KELLY
Contact address:	7777 HENNESSY STE 1000 BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 769-2200
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	NEURO MEDICAL CENTER
Owner/operator address:	7777 HENNESSEY STE 1000 BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 769-2200
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

NEURO MEDICAL CENTER (Continued) **1004707223**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 06/16/1994
Site name: NEURO MEDICAL CENTER
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110003260603

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004707223
Registry ID: 110003260603
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003260603

---

42 **BATON ROUGE UROLOGY GROUP** **RCRA-CESQG** **1014390668**
7777 HENNESSY BLVD, STE 2004 **LAR000070961**
BATON ROUGE, LA 70808

RCRA-CESQG:
Date form received by agency: 06/09/2010
Facility name: BATON ROUGE UROLOGY GROUP
Facility address: 7777 HENNESSY BLVD, STE 2004
BATON ROUGE, LA 70808
EPA ID: LAR000070961
Mailing address: HENNESSY BLVD, STE 2004
BATON ROUGE, LA 70808
Contact: BECKY A VAMPRAN
Contact address: HENNESSY BLVD, STE 2004
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 768-0715
Contact email: Not reported

BATON ROUGE UROLOGY GROUP (Continued) **1014390668**

EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name: BR UROLOGY
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 08/01/1993
Owner/Op end date: Not reported

Owner/operator name: BR UROLOGY
Owner/operator address: Not reported
Not reported
Owner/operator country: US
Owner/operator telephone: Not reported
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 08/01/1993
Owner/Op end date: Not reported

Handler Activities Summary:

U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

BATON ROUGE UROLOGY GROUP (Continued) **1014390668**

Universal Waste Summary:

Waste type:	Batteries
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
Waste type:	Lamps
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
Waste type:	Pesticides
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
Waste type:	Thermostats
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported
. Waste code:	D001
. Waste name:	IGNITABLE WASTE
Violation Status:	No violations found

---

42 **CHARLIE H BRIDGES MD** **RCRA-CESQG** **1004709540**
7777 HENNESSY BLVD STE 608 **FINDS** **LAD982548059**
BATON ROUGE, LA 70808 **ECHO**

RCRA-CESQG:

Date form received by agency:	02/24/1988
Facility name:	CHARLIE H BRIDGES MD
Facility address:	7777 HENNESSY BLVD STE 608 BATON ROUGE, LA 70808
EPA ID:	LAD982548059
Mailing address:	HENNESSY BLVD STE 608 BATON ROUGE, LA 70808
Contact:	CHARLIE H BRIDGES
Contact address:	HENNESSY BLVD STE 608 BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 767-0394
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

CHARLIE H BRIDGES MD (Continued) **1004709540**

Owner/Operator Summary:

Owner/operator name:	CHARLIE H BRIDGES
Owner/operator address:	7777 HENNESSY BLVD STE 608 BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(504) 767-0394
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

FINDS:

Registry ID: 110009580220

Environmental Interest/Information System

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1004709540
Registry ID:	110009580220
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110009580220

42 EYE SURGERY CENTER LLC — **RCRA-CESQG, FINDS, ECHO** — **1018275285 / LAR000090217**
7777 HENNESSY BLVD, STE 5000
BATON ROUGE, LA 70808

RCRA-CESQG:

Date form received by agency:	04/15/2016
Facility name:	REGIONAL EYE SURGERY CENTER LLC
Facility address:	7777 HENNESSY BLVD, STE 5000 A PORTION OF BATON ROUGE, LA 70808
EPA ID:	LAR000090217
Mailing address:	HENNESSY BLVD, STE 5000 BATON ROUGE, LA 70808
Contact:	TRACI S D'ANTONI
Contact address:	HENNESSY BLVD, STE 5000 BATON ROUGE, LA 70808
Contact country:	US
Contact telephone:	(225) 214-6688
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	OLOL
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	06/01/2011
Owner/Op end date:	Not reported

Owner/operator name:	EYE SURG
Owner/operator address:	Not reported Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	06/01/2011
Owner/Op end date:	Not reported

Handler Activities Summary:

EYE SURGERY CENTER LLC (Continued) **1018275285**

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D002
. Waste name: CORROSIVE WASTE

. Waste code: D007
. Waste name: CHROMIUM

. Waste code: D009
. Waste name: MERCURY

. Waste code: D010
. Waste name: SELENIUM

. Waste code: D011
. Waste name: SILVER

. Waste code: D013
. Waste name: LINDANE (1,2,3,4,5,6-HEXA-CHLOROCYCLOHEXANE, GAMMA ISOMER)

. Waste code: D018
. Waste name: BENZENE

. Waste code: D022
. Waste name: CHLOROFORM

. Waste code: D024
. Waste name: M-CRESOL

. Waste code: D026
. Waste name: CRESOL

. Waste code: P001
. Waste name: 2H-1-BENZOPYRAN-2-ONE, 4-HYDROXY-3-(3-OXO-1-PHENYLBUTYL)-, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3% (OR) WARFARIN, & SALTS, WHEN PRESENT AT CONCENTRATIONS GREATER THAN 0.3%

. Waste code: P012
. Waste name: ARSENIC OXIDE AS2O3 (OR) ARSENIC TRIOXIDE

EYE SURGERY CENTER LLC (Continued) **1018275285**

. Waste code: P042
. Waste name: 1,2-BENZENEDIOL, 4-[1-HYDROXY-2-(METHYLAMINO)ETHYL]-, (R)- (OR) EPINEPHRINE

. Waste code: P075
. Waste name: NICOTINE, & SALTS (OR) PYRIDINE, 3-(1-METHYL-2-PYRROLIDINYL)-,(S)-, & SALTS

. Waste code: P081
. Waste name: 1,2,3-PROPANETRIOL, TRINITRATE (R) (OR) NITROGLYCERINE (R)

. Waste code: P188
. Waste name: BENZOIC ACID, 2-HYDROXY-, COMPD. WITH (3AS-CIS)-1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYLPYRROLO[2,3-B]INDOL--YL METHYLCARBAMATE ESTER (1:1) (OR) PHYSOSTIGMINE SALICYLATE

. Waste code: P204
. Waste name: PHYSOSTIGMINE (OR) PYRROLO[2,3-B]INDOL-5-OL, 1,2,3,3A,8,8A-HEXAHYDRO-1,3A,8-TRIMETHYL-METHYLCARBAMATE (ESTER), (3AS-CIS)-

. Waste code: U044
. Waste name: CHLOROFORM (OR) METHANE, TRICHLORO-

. Waste code: U129
. Waste name: CYCLOHEXANE, 1,2,3,4,5,6-HEXACHLORO-, (1ALPHA, 2ALPHA, 3BETA, 4ALPHA, 5ALPHA, 6BETA)- (OR) LINDANE

. Waste code: U132
. Waste name: HEXACHLOROPHENE (OR) PHENOL, 2,2'-METHYLENEBIS[3,4,6-TRICHLORO-

. Waste code: U188
. Waste name: PHENOL

. Waste code: U200
. Waste name: RESERPINE (OR) YOHIMBAN-16-CARBOXYLIC ACID, 11,17-DIMETHOXY-18-[(3,4,5-TRIMETHOXYBENZOYL)OXY]-, METHYL ESTER, (3BETA, 16BETA, 17ALPHA, 18BETA, 20ALPHA)-

. Waste code: U201
. Waste name: 1,3-BENZENEDIOL (OR) RESORCINOL

. Waste code: U204
. Waste name: SELENIOUS ACID (OR) SELENIUM DIOXIDE

. Waste code: U205
. Waste name: SELENIUM SULFIDE (OR) SELENIUM SULFIDE SES2 (R,T)

. Waste code: U236
. Waste name: 2,7-NAPHTHALENEDISULFONIC ACID,3,3'-[(3,3'-DIMETHYL[1,1'-BIPHENYL]-4,4'-DIYL)BIS(AZO)BIS[5-AMINO 4-HYDROXY]-, TETRASODIUM SALT (OR) TRYPAN BLUE

Violation Status: No violations found

FINDS:

Registry ID: 110067679809

EYE SURGERY CENTER LLC (Continued) **1018275285**

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1018275285
Registry ID: 110067679809
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110067679809

---

42 PULMONARY DISEASE CLINIC **RCRA NonGen / NLR** **1004709642**
7777 HENNESSY STE 701 **FINDS** **LAD982559320**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 03/30/2010
Facility name: PULMONARY DISEASE CLINIC
Facility address: 7777 HENNESSY STE 701
BATON ROUGE, LA 70808
EPA ID: LAD982559320
Mailing address: HENNESSY STE 701
BATON ROUGE, LA 70808
Contact: ANN HANNA
Contact address: 7777 HENNESSY STE 701
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 769-5864
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: PULMONARY DISEASE CLINIC
Owner/operator address: 777 HENNESSY
BATON ROUGE, LA 70806
Owner/operator country: Not reported
Owner/operator telephone: (225) 769-5864
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: PULMONARY DISEASE CLINIC
Owner/operator address: 777 HENNESSY
BATON ROUGE, LA 70806
Owner/operator country: US
Owner/operator telephone: (225) 769-5864
Legal status: Private

PULMONARY DISEASE CLINIC (Continued) **1004709642**

Owner/Operator Type: Operator
Owner/Op start date: 03/30/2010
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

Universal Waste Summary:
Waste type: Batteries
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Lamps
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 10/24/1988
Site name: PULMONARY DISEASE CLINIC
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 03/30/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported

PULMONARY DISEASE CLINIC (Continued) **1004709642**

Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110009580408

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1004709642
Registry ID: 110009580408
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110009580408

---

42 **L & L FETTERS INC** **EDR Hist Cleaner** **1020022413**
7777 HENNESSY BLVD **N/A**
BATON ROUGE, LA 70808

EDR Hist Cleaner

Year:	Name:	Type:
1996	FETTERS CLEANERS	Drycleaning Plants, Except Rugs
1997	L & L FETTERS CLEANERS	Drycleaning Plants, Except Rugs
1998	L & L FETTERS INC	Drycleaning Plants, Except Rugs
2002	L & L FETTERS INC	Drycleaning Plants, Except Rugs
2003	L & L FETTERS INC	Drycleaning Plants, Except Rugs

---

42 **LYNN J PHILIPPE** **RCRA NonGen / NLR** **1004714489**
7777 HENNESSY BLVD STE 610 **LAR000033555**
BATON ROUGE, LA 70808

RCRA NonGen / NLR:
Date form received by agency: 02/17/2012
Facility name: LYNN J PHILIPPE
Facility address: 7777 HENNESSY BLVD STE 610
BATON ROUGE, LA 708084390
EPA ID: LAR000033555
Mailing address: HENNESSY BLVD STE 610
BATON ROUGE, LA 708084390
Contact: LYNN PHILIPPE
Contact address: 7777 HENNESSY BLVD STE 610
BATON ROUGE, LA 708084390
Contact country: US
Contact telephone: (225) 769-2278
Contact email: Not reported
EPA Region: 06

LYNN J PHILIPPE (Continued) **1004714489**

Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: LYNN J PHILIPPE
Owner/operator address: 7777 HENNESSY BLVD STE 610
BATON ROUGE, LA 70808
Owner/operator country: Not reported
Owner/operator telephone: (225) 769-2278
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: Not reported
Owner/Op end date: Not reported

Owner/operator name: LYNN J PHILIPPE
Owner/operator address: 7777 HENNESSY BLVD STE 610
BATON ROUGE, LA 70808
Owner/operator country: US
Owner/operator telephone: (225) 769-2278
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 10/01/2007
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D011
. Waste name: SILVER

Historical Generators:
Date form received by agency: 10/01/2007
Site name: LYNN J PHILIPPE
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D011
. Waste name: SILVER

Date form received by agency: 12/21/1998
Site name: LYNN J PHILIPPE
Classification: Conditionally Exempt Small Quantity Generator

LYNN J PHILIPPE (Continued) **1004714489**

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 02/17/2012
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

---

42 **FETTER'S CLEANERS** **LA DRYCLEANERS** **S107446410**
7777 HENNESSY BLVD **N/A**
BATON ROUGE, LA 70815

DRYCLEANERS:
Facility ID: 39318
Owner: Lonnie Fetter
Owner Telephone: Not reported
Store Telephone: --
Mailing Address: PO Box 87159
Mailing City,St,Zip: Baton Rouge, LA 70879
Contact: Not reported

Facility ID: 39318
Owner: LONNIE FETTER
Owner Telephone: Not reported
Store Telephone: 225-769-8090
Mailing Address: PO BOX 87159
Mailing City,St,Zip: BATON ROUGE 70879
Contact: Not reported

---

42 **DRS BRAUD & BREAUX MEDICAL PLAZA** **RCRA NonGen / NLR** **1000105215**
7777 HENNESSY BLVD #4000 **FINDS** **LAD985175611**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:
Date form received by agency: 11/03/2003
Facility name: DRS BRAUD & BREAUX MEDICAL PLAZA
Facility address: 7777 HENNESSY BLVD #4000
BATON ROUGE, LA 70808
EPA ID: LAD985175611
Mailing address: HENNESSY BLVD #4000
BATON ROUGE, LA 70808
Contact: DANNA LASTRAPES
Contact address: HENNESSY BLVD #4000
BATON ROUGE, LA 70808
Contact country: US
Contact telephone: (225) 769-2222
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

DRS BRAUD & BREAUX MEDICAL PLAZA (Continued) **1000105215**

Owner/Operator Summary:

Owner/operator name:	DANNA LASTRAPES
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	Not reported
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	11/03/2003
Owner/Op end date:	Not reported

Owner/operator name:	DRS BRAUD BREAUX & MURPHY
Owner/operator address:	7777 HENNESSY BLVD #4000
	BATON ROUGE, LA 70808
Owner/operator country:	Not reported
Owner/operator telephone:	(225) 769-2222
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Historical Generators:

Date form received by agency:	09/07/1990
Site name:	DRS BRAUD & BREAUX MEDICAL PLAZA
Classification:	Conditionally Exempt Small Quantity Generator
. Waste code:	D011
. Waste name:	SILVER
Violation Status:	No violations found

Evaluation Action Summary:

Evaluation date:	07/26/2005
Evaluation:	FOCUSED COMPLIANCE INSPECTION
Area of violation:	Not reported
Date achieved compliance:	Not reported
Evaluation lead agency:	State

DRS BRAUD & BREAUX MEDICAL PLAZA (Continued) **1000105215**

FINDS:

Registry ID: 110003316340

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000105215
Registry ID: 110003316340
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003316340

---

42 **JACOBS PLAZA** **RCRA-CESQG** **1004710824**
4949 ESSEN LN **FINDS** **LAD985198308**
BATON ROUGE, LA 70809 **LA NPDES**
ECHO

RCRA-CESQG:
Date form received by agency: 06/18/2009
Facility name: JACOBS ENGINEERING GROUP INC
Facility address: 4949 ESSEN LN
BATON ROUGE, LA 70809
EPA ID: LAD985198308
Mailing address: PO BOX 98033
BATON ROUGE, LA 70898
Contact: PHIL DUNLAP
Contact address: PO BOX 98033
BATON ROUGE, LA 70898
Contact country: US
Contact telephone: (225) 768-5204
Contact email: Not reported
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

JACOBS PLAZA (Continued) **1004710824**

Owner/Operator Summary:

Owner/operator name:	JACOBS GROUP
Owner/operator address:	251 S LAKE AVE PASADENA, CA 91101
Owner/operator country:	Not reported
Owner/operator telephone:	(818) 449-2171
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Owner/operator name:	JACOBS GROUP
Owner/operator address:	251 S LAKE AVE PASADENA, CA 91101
Owner/operator country:	US
Owner/operator telephone:	(818) 449-2171
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	01/01/2001
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

. Waste code: D001
. Waste name: IGNITABLE WASTE

Historical Generators:

Date form received by agency:	04/18/1991
Site name:	JACOBS ENGINEERING GROUP INC
Classification:	Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

Violation Status: No violations found

FINDS:

Registry ID: 110003326071

Environmental Interest/Information System

JACOBS PLAZA (Continued) **1004710824**

RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

US National Pollutant Discharge Elimination System (NPDES) module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

NPDES:

Facility Id:	20321
Facility Phone:	2257685204
Issued Date:	04/01/2011
Title Description:	Permit Reauthorization
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20110001

Facility Id:	20321
Facility Phone:	2257685204
Issued Date:	02/28/2005
Title Description:	LAG480427 Mod Permit
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20050001

Facility Id:	20321
Facility Phone:	2257685204
Issued Date:	08/02/2004
Title Description:	LAG480427 Permit
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20040001

Facility Id:	20321
Facility Phone:	2257685204
Issued Date:	03/28/2016
Title Description:	LAG48 Renewal
Permit Type Description:	Gen-LAG48-Light Commercial
Program:	Water
Activity Number:	GEN20150001

ECHO:

Envid:	1004710824
Registry ID:	110003326071

JACOBS PLAZA (Continued) **1004710824**

DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003326071

---

42 MARY BIRD PERKINS CANCER CENTER **RCRA-SQG** **1000439620**
4950 ESSEN LANE **FINDS** **LAD062649249**
BATON ROUGE, LA 70809 **ECHO**

RCRA-SQG:

Date form received by agency:	02/18/1987
Facility name:	MARY BIRD PERKINS CANCER CENTER
Facility address:	4950 ESSEN LANE BATON ROUGE, LA 70809
EPA ID:	LAD062649249
Mailing address:	ESSEN LANE BATON ROUGE, LA 70809
Contact:	MICHAEL MARTIN
Contact address:	4950 ESSEN LANE BATON ROUGE, LA 70809
Contact country:	US
Contact telephone:	(225) 767-0847
Contact email:	Not reported
EPA Region:	06
Land type:	Other land type
Classification:	Small Small Quantity Generator
Description:	Handler: generates more than 100 and less than 1000 kg of hazardous waste during any calendar month and accumulates less than 6000 kg of hazardous waste at any time; or generates 100 kg or less of hazardous waste during any calendar month, and accumulates more than 1000 kg of hazardous waste at any time

Owner/Operator Summary:

Owner/operator name:	CANCER, RADIATION & RESEARCH FOUND
Owner/operator address:	4950 ESSEN LN BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

MARY BIRD PERKINS CANCER CENTER (Continued) **1000439620**

. Waste code: D011
. Waste name: SILVER

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 09/05/2007
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003276231

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:
Envid: 1000439620
Registry ID: 110003276231
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003276231

---

42 BATON ROUGE VA OUTPATIENT CLINIC **RCRA-CESQG** **1014390681**
7968 ESSEN PARK AVE **LAR000071118**
BATON ROUGE, LA 70809

RCRA-CESQG:
Date form received by agency: 07/13/2010
Facility name: BATON ROUGE VA OUTPATIENT CLINIC
Facility address: 7968 ESSEN PARK AVE
BATON ROUGE, LA 70809
EPA ID: LAR000071118
Mailing address: ESSEN PARK AVE
BATON ROUGE, LA 70809
Contact: WILLIAM IVEY
Contact address: ESSEN PARK AVE
BATON ROUGE, LA 70809
Contact country: US
Contact telephone: (225) 761-3469
Contact email: WILLIAM.IVEY2@VA.GOV
EPA Region: 06
Classification: Conditionally Exempt Small Quantity Generator
Description: Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous

BATON ROUGE VA OUTPATIENT CLINIC (Continued) **1014390681**

waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	VA
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Owner
Owner/Op start date:	07/13/2010
Owner/Op end date:	Not reported

Owner/operator name:	VA
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Federal
Owner/Operator Type:	Operator
Owner/Op start date:	07/13/2010
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Universal Waste Summary:

Waste type:	Batteries
Accumulated waste on-site:	Yes
Generated waste on-site:	Not reported

Waste type:	Lamps
Accumulated waste on-site:	Yes

BATON ROUGE VA OUTPATIENT CLINIC (Continued) **1014390681**

Generated waste on-site: Not reported

Waste type: Pesticides
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

Waste type: Thermostats
Accumulated waste on-site: Yes
Generated waste on-site: Not reported

. Waste code: D009
. Waste name: MERCURY

Violation Status: No violations found

---

42 **SCOTT LEONARD F** **EDR Hist Auto** **1013770353**
4912 ESSEN LN **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
1995	SCOTT LEONARD F	AUTOMOBILE REPAIRING & SERVICE

---

42 **LA SPILLS** **S110100440**
4900 ESSEN LANE AND SUMMA AVE. **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	11/27/2000
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	38233
Incident Date:	11/21/2000
Incident Status:	**Open**
Media Desc:	Water
Location Description:	4900 Essen Lane and Summa Ave.
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s00-4596 Overflowing main hole. Stoppage in main line.
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Sewage
Quantity:	30 gallons
Other Substance Desc:	Not reported

42 **CITY OF BATON ROUGE/SEWER OPERATIONS** **LA SPILLS** **S109961384**
4898 ESSEN LANE BATON ROUGE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	05/27/2009
Date Initiated:	Not reported
aiid:	4841
Incident Id:	115289
Incident Date:	05/20/2009
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	City of Baton Rouge/Sewer Operations 4898 Essen Lane Baton Rouge
Incident Source Name:	East Baton Rouge City Parish - South WWTP
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	Facility submitted written report--incident closed.
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Sewage
Quantity:	500 gallons
Other Substance Desc:	0

---

42 **SUMMA PLACE** **LA SPILLS** **S110100363**
4898 ESSEN LANE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	11/17/2000
Date Initiated:	Not reported
aiid:	Not reported
Incident Id:	38040
Incident Date:	11/16/2000
Incident Status:	**Open**
Media Desc:	Water
Location Description:	Summa Place 4898 Essen Lane Baton Rouge
Incident Source Name:	Not reported
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s00-4462 Sewage bypass - stoppage due to heavy rain
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	sewage

42 **CITY OF BATON ROUGE PUMP STATION 58** **LA SPILLS** **S110137446**
4890 ESSEN LANE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	12/21/2009
Date Initiated:	Not reported
aiid:	4841
Incident Id:	120296
Incident Date:	12/21/2009
Incident Status:	**Closed**
Media Desc:	Water
Location Description:	City of Baton Rouge Pump Station 58 4890 Essen Lane
Incident Source Name:	East Baton Rouge City Parish - South WWTP
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	Facility submitted written report--incident closed.
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Sewage
Quantity:	108000 gallons
Other Substance Desc:	0

---

42 **NATIONAL TIRE & BATTERY #195** **RCRA-CESQG** **1007370706**
4675 ESSEN LN **ECHO** **LAR000055236**
BATON ROUGE, LA 70809

RCRA-CESQG:

Date form received by agency:	03/03/2015
Facility name:	NATIONAL TIRE & BATTERY #195
Facility address:	4675 ESSEN LN BATON ROUGE, LA 70809
EPA ID:	LAR000055236
Mailing address:	PROF CENTER DR, STE 400 PALM BEACH GARDENS, FL 33410
Contact:	AARON ENGL
Contact address:	PROF CENTER DR, STE 400 PALM BEACH GARDENS, FL 33410
Contact country:	US
Contact telephone:	(561) 383-3000
Telephone ext.:	2424
Contact email:	Not reported
EPA Region:	06
Classification:	Conditionally Exempt Small Quantity Generator
Description:	Handler: generates 100 kg or less of hazardous waste per calendar month, and accumulates 1000 kg or less of hazardous waste at any time; or generates 1 kg or less of acutely hazardous waste per calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste; or generates 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulates at any time: 1 kg or less of acutely hazardous waste; or 100 kg or less of any residue or contaminated soil, waste or other debris resulting from

NATIONAL TIRE & BATTERY #195 (Continued) **1007370706**

the cleanup of a spill, into or on any land or water, of acutely hazardous waste

Owner/Operator Summary:

Owner/operator name:	TIRE KINGDOM
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	02/18/2004
Owner/Op end date:	Not reported

Owner/operator name:	TIRE KINGDOM
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	02/18/2004
Owner/Op end date:	Not reported

Owner/operator name:	NTB
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	03/01/2015
Owner/Op end date:	Not reported

Owner/operator name:	NTB
Owner/operator address:	Not reported
	Not reported
Owner/operator country:	US
Owner/operator telephone:	Not reported
Legal status:	Private
Owner/Operator Type:	Operator
Owner/Op start date:	03/01/2015
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No

NATIONAL TIRE & BATTERY #195 (Continued) **1007370706**

Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D009
. Waste name: MERCURY

. Waste code: D018
. Waste name: BENZENE

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

. Waste code: D040
. Waste name: TRICHLORETHYLENE

. Waste code: F001
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLORETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

. Waste code: F002
. Waste name: THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2, TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F004, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.

Historical Generators:
Date form received by agency: 10/21/2009
Site name: TIRE KINGDOM LLC #195
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

NATIONAL TIRE & BATTERY #195 (Continued) **1007370706**

. Waste code: D040
. Waste name: TRICHLORETHYLENE

Date form received by agency: 02/18/2004
Site name: TIRE KINGDOM INC #195
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D008
. Waste name: LEAD

. Waste code: D039
. Waste name: TETRACHLOROETHYLENE

Violation Status: No violations found

ECHO:
Envid: 1007370706
Registry ID: 110017872113
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110017872113

---

42 **LA SPILLS** **S109566804**
ESSEN LANE BETWEEN MARGARET ANN AND ESSEN PARK **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	08/16/2007
Date Initiated:	Not reported
aiid:	83561
Incident Id:	98710
Incident Date:	08/16/2007
Incident Status:	**Closed**
Media Desc:	Water/Soil/Air
Location Description:	Essen Lane between Margaret ann and Essen Park Baton Rouge
Incident Source Name:	East Baton Rouge Parish
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c07-2726 Canal along Margaret Ann and Essen Park smells like sewage every morning--source unknown...jd
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

42 GULF INTERCOASTAL MARINE INC — **RCRA NonGen / NLR** — **1000226979**
8116 ONE CALAIS SUITE 1C — **FINDS** — **LAD072609274**
BATON ROUGE, LA 70809 — **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	03/14/1984
Facility name:	GULF INTERCOASTAL MARINE INC
Facility address:	8116 ONE CALAIS SUITE 1C BATON ROUGE, LA 70809
EPA ID:	LAD072609274
Mailing address:	P.O. BOX 14956 BATON ROUGE, LA 70898
Contact:	FRED-H-JR FENN
Contact address:	P.O. BOX 14956 BATON ROUGE, LA 70898
Contact country:	US
Contact telephone:	(225) 766-7205
Contact email:	Not reported
EPA Region:	06
Classification:	Non-Generator
Description:	Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:

Owner/operator name:	DAVID M. NEHER & FRED H. FENN JR.
Owner/operator address:	8116 ONE CALAIS SUITE 1C BATON ROUGE, LA 70809
Owner/operator country:	Not reported
Owner/operator telephone:	(000) 000-0000
Legal status:	Private
Owner/Operator Type:	Owner
Owner/Op start date:	Not reported
Owner/Op end date:	Not reported

Handler Activities Summary:

U.S. importer of hazardous waste:	No
Mixed waste (haz. and radioactive):	No
Recycler of hazardous waste:	No
Transporter of hazardous waste:	No
Treater, storer or disposer of HW:	No
Underground injection activity:	No
On-site burner exemption:	No
Furnace exemption:	No
Used oil fuel burner:	No
Used oil processor:	No
User oil refiner:	No
Used oil fuel marketer to burner:	No
Used oil Specification marketer:	No
Used oil transfer facility:	No
Used oil transporter:	No

Violation Status: No violations found

FINDS:

Registry ID: 110003277999

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of

GULF INTERCOASTAL MARINE INC (Continued) **1000226979**

events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

ECHO:

Envid:	1000226979
Registry ID:	110003277999
DFR URL:	http://echo.epa.gov/detailed-facility-report?fid=110003277999

---

42 **GULF INTRACOASTAL MARINE** **TX Ind. Haz Waste** **S105478415**
8116 ONE CALAIS AVE **N/A**
BATON ROUGE, LA 70809

Ind. Haz Waste:

Registration Number:	40616
Registration Initial Notification Date:	10/02/1984
Registration Last Amendment Date:	02/13/2001
EPA Identification:	LAD072609274
Primary NAICS Code:	484121
Status Change Date:	19841002
Land Type:	Not reported
Description of Facility Site Location:	Not reported
Site Primary Standard Industrial Code:	Not reported
Site Primary SIC Description:	Not reported
Registration is Generator of Waste:	No
Registration is Receivers of Waste:	No
Registration is Transporter of Waste:	Yes
Registration is Transfer Facility:	No
Facility is STEERS Reporter:	No
Reqired to Submit Annual Waste Summary:	No
Facility Involved In Recycling:	No
Revcr Has Monthly Reporting Requirement:	0
Mexican Facility:	Not reported
Type of Generator:	Not reported
TNRCC Region:	Not reported
Company Name:	GULF INTRACOASTAL MARINE INC
Contact Name:	FRED H FENN
Contact Telephone Number:	504-7667205
Mailing Address:	PO BOX 14956
Mailing Address2:	Not reported
Mailing City,St,Zip:	BATON ROUGE, LA 708984956
Mailing County:	UNITED STATES
Facility Country:	UNITED STATES
TNRCC Facility ID:	17032
Site Owner Tax ID:	0
Site Location Latitude:	-00.000
Site Location Longitude:	-000.000
Last Update to NOR Data:	20030303
Ind. waste permit Number:	Not reported
Mun waste permit Number:	Not reported
Non Notifier:	No

GULF INTRACOASTAL MARINE (Continued) **S105478415**

Business Records Not Found for this RegNo/Year:

Owner:

Owner Mailing Address:	PO BOX 14956
Owner Mailing Address2:	Not reported
Owner Mailing Address3:	Not reported
Owner City,St,Zip:	BATON ROUGE, LA 70898 4956
Owner Country:	UNITED STA
Owner Phone Number:	1-504-7667205
Owner Fax Number:	Not reported
Owner Email Address:	Not reported
Owner Business Type:	Unknown
Owner Tax Id:	17207226709
Owner Bankruptcy Code:	Not reported

Operator Records Not Found for this RegNo/Year:

Contact:

Contact Name:	FRED FENN
Contact Title:	ENVIRONMENTAL CONTACT
Contact Role:	PRICONT
Contact Address:	PO BOX 14956
Contact Address2:	Not reported
Conact City,St,Zip:	BATON ROUGE, LA 70898 4956
Contact Phone:	1-504-7667205
Contact Fax:	Not reported
Contact Email:	Not reported

Contact:

Contact Name:	Not reported
Contact Title:	Not reported
Contact Role:	OWNCON
Contact Address:	PO BOX 14956
Contact Address2:	Not reported
Conact City,St,Zip:	BATON ROUGE, LA 70898 4956
Contact Phone:	1-504-7667205
Contact Fax:	Not reported
Contact Email:	Not reported

Unit Records Not Found for this RegNo/Year:

One Time Shipper Records Not Found for this RegNo/Year:

Receiver Type:	Not reported
Transporter for hire:	1
Transport own waste:	0
Eq 01, if transport waste type = 1:	Not reported
Eq 02, if transport waste type = 2:	Not reported
Eq 03, if transport waste type = 3:	Not reported
Eq 04, if transport waste type = H:	04
Target TCEQ unique facid for discarded(merged) facility:	Not reported

Waste Records Not Found for this RegNo/Year:

42 **RT #492 ESSEN LANE** **LA UST** **U003987526**
4665 ESSEN LN **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	78516
Subject Item ID:	2
UST Tank Num:	45176
Tank Status:	**Active**
Install Date:	10/01/1995
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	45177
Tank Status:	**Active**
Install Date:	10/01/1995
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

RT #492 ESSEN LANE (Continued) **U003987526**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	45178
Tank Status:	**Active**
Install Date:	10/01/1995
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Yes
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Yes
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

---

42 **RACETRAC PETROLEUM INC** **EDR Hist Auto** **1013761303**
4665 ESSEN LN **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
1998	RACETRAC PETROLEUM INC	Gasoline Service Stations
1999	RACETRAC PETROLEUM INC	Gasoline Service Stations
2000	RACETRAC PETRO GAS SERV STA	GASOLINE STATIONS
2000	RACETRAC PETROLEUM INC	Gasoline Service Stations
2001	RACETRAC PETROLEUM INC	Gasoline Service Stations
2002	RACETRAC PETROLEUM INC	Gasoline Service Stations
2003	RACETRAC PETROLEUM INC	Gasoline Service Stations

RACETRAC PETROLEUM INC (Continued) **1013761303**

2004	RACETRAC PETROLEUM INC	Gasoline Service Stations
2005	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2006	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2007	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2008	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2009	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2010	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2011	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2012	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2013	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC
2014	RACETRAC PETROLEUM INC	Gasoline Service Stations, NEC

---

42 **GULF SOUTH LTD** **EDR Hist Auto** **1021894277**
8048 ONE CALAIS AVE STE D **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
2011	GULF SOUTH LTD	Gasoline Service Stations, NEC

---

42 **LSU AGRICULTURE CENTER - BURDEN CENTER** **LA SWF/LF** **S110176290**
4560 ESSEN LN **N/A**
BATON ROUGE, LA 70802

LF:

Facility Id:	163330
Telephone:	Not reported
Issue Date:	02/25/2009
Title Desc:	Emergency Debris Site Approval
Permit Type Desc:	Pre-2009 EDS
Program:	Solid Waste
Activity NUmber:	PER20090001
EDR Link ID:	163330

---

42 **LSU AGRICULTURE CENTER - BURDEN CENTER** **LA RGA LF** **S115489717**
4560 ESSEN LN **N/A**
BATON ROUGE, LA

RGA LF:

2012	LSU AGRICULTURE CENTER - BURDEN CENTER	4560 ESSEN LN
2011	LSU AGRICULTURE CENTER - BURDEN CENTER	4560 ESSEN LN
2010	LSU AGRICULTURE CENTER - BURDEN CENTER	4560 ESSEN LN

42 **EXXON STATION 5-0608** **LA HIST LUST** **S106033745**
4555 ESSEN LN **N/A**
BATON ROUGE, LA 70816

HIST LUST:

Facility ID:	17-004224
Facility Parish:	EAST BATON ROUGE
Substance Name:	UNKNOWN
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	10/26/1998
Date Confirmed 2:	Not reported
Incident Number:	98-2-0106
Incident Date:	10/26/1998
Type of Incident:	UNKNOWN
Type of Incident No2:	Not reported
Reported By:	UNKNOWN
Reported By 2:	Not reported
Owner ID:	00109200
Owner Name:	EXXON MOBIL COMPANY, U.S.A.
Owner Address:	P. O. BOX 4386
Owner City,St,Zip:	HOUSTON,, TX 77210-4386
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	Not reported
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: Not reported

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

42 **CALAIS EXXON** **LA SPILLS** **S108598666**
4555 ESSEN LANE **N/A**
BATON ROUGE, LA

SPILLS:

Region Code:	Not reported
Date Rec:	11/01/2005
Date Initiated:	Not reported
aiid:	13366
Incident Id:	83584
Incident Date:	07/18/2005
Incident Status:	**Closed**
Media Desc:	Water/Soil
Location Description:	Calais Exxon 4555 Essen Lane Baton Rouge
Incident Source Name:	ExxonMobil Oil Corp 50608
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s05-4107 UST...soil and groundwater contamination found during tank closure and DISI...diesel. col
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

Region Code:	Not reported
Date Rec:	04/21/2005
Date Initiated:	Not reported
aiid:	13366
Incident Id:	78436
Incident Date:	04/21/2005
Incident Status:	**Referred to Remediation**
Media Desc:	Soil
Location Description:	4555 Essen Lane Baton Rouge
Incident Source Name:	ExxonMobil Oil Corp 50608
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	s05-1277 Gasoline/diesel was released from a UST. CMD
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

Region Code:	Not reported
Date Rec:	02/03/2006
Date Initiated:	Not reported
aiid:	13366
Incident Id:	85625
Incident Date:	02/03/2006
Incident Status:	**Closed**
Media Desc:	Not reported
Location Description:	4555 Essen Lane Baton Rouge

CALAIS EXXON (Continued) **S108598666**

Incident Source Name:	ExxonMobil Oil Corp 50608
Reporter Name:	Not reported
Mailing Address 1:	Not reported
Mailing City:	Not reported
Mailing State:	Not reported
Mailing Zip:	Not reported
Incident Desc:	c06-0354 5-7 barrels were left on vacant property. col
Incident Type Desc:	Not reported
Comments:	Not reported
Parameter:	Not reported
Quantity:	Not reported
Other Substance Desc:	Not reported

---

42 **EXXONMOBIL OIL CORP #50608** **LA RGA LUST** **S115491516**
4555 ESSEN LN **N/A**
BATON ROUGE, LA

RGA LUST:

2007	EXXONMOBIL OIL CORP #50608	4555 ESSEN LN

---

42 **EDR Hist Auto** **1013759752**
4555 ESSEN LN **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
1990	CALAIS EXXON STATION	GASOLINE STATIONS
1991	EXXON STATION	Gasoline Service Stations
1992	EXXON STATION	Gasoline Service Stations
1993	EXXON STATION	Gasoline Service Stations
1995	CALAIS EXXON STATION	GASOLINE STATIONS
1997	CALAIS EXXON	Gasoline Service Stations
1998	CALAIS EXXON	Gasoline Service Stations
1999	CALAIS EXXON	Gasoline Service Stations
2000	CALAIS EXXON GAS SERV STA	GASOLINE STATIONS
2000	CALAIS EXXON	Gasoline Service Stations
2001	CALAIS EXXON	Gasoline Service Stations
2002	CALAIS EXXON	Gasoline Service Stations
2003	CALAIS EXXON	Gasoline Service Stations
2004	CALAIS EXXON	Gasoline Service Stations
2005	CALAIS EXXON	Gasoline Service Stations, NEC
2006	CALAIS EXXON	Gasoline Service Stations, NEC
2007	CALAIS EXXON	Gasoline Service Stations, NEC
2008	CALAIS EXXON	Gasoline Service Stations, NEC

42 **EXXONMOBIL OIL CORP #50608** **LA UST** **U003986732**
4555 ESSEN LN **LA NPDES** **N/A**
BATON ROUGE, LA 70809 **LA REM**

UST:

Master Agency Id:	13366
Subject Item ID:	2
UST Tank Num:	11995
Tank Status:	**Removed**
Install Date:	07/17/1985
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	11996
Tank Status:	**Removed**
Install Date:	07/17/1985
Total Capacity:	8000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported

EXXONMOBIL OIL CORP #50608 (Continued) **U003986732**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	11997
Tank Status:	**Removed**
Install Date:	07/17/1985
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	11998
Tank Status:	**Removed**
Install Date:	07/17/1985
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

EXXONMOBIL OIL CORP #50608 (Continued) **U003986732**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

NPDES:

Facility Id:	13366
Facility Phone:	2816548470
Issued Date:	08/28/1998
Title Description:	Fiscal Migration: LAG750108
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN19950001

Facility Id:	13366
Facility Phone:	2816548470
Issued Date:	05/07/2004
Title Description:	LAG750108 Reauthorization
Permit Type Description:	Gen-LAG75-Exterior Vehicle Wash
Program:	Water
Activity Number:	GEN20040001

REM:

AI Num:	13366
Evaluated And Closed:	08/31/2009
Program:	UST
EAC Type:	Approve Completion NFA w/ BOD
Comments:	EDMS ID 6541535.

---

42 **EXXONMOBIL OIL CORP #50608** **RCRA NonGen / NLR** **1004515295**
4555 ESSEN LANE **FINDS** **LAD985194380**
BATON ROUGE, LA 70808 **ECHO**

RCRA NonGen / NLR:

Date form received by agency:	12/17/2010
Facility name:	EXXONMOBIL OIL CORP #50608
Facility address:	4555 ESSEN LANE BATON ROUGE, LA 70808
EPA ID:	LAD985194380
Mailing address:	NORTHCHASE DR, RM 538 HOUSTON, TX 77060
Contact:	DALE VIATOR
Contact address:	NORTHCHASE DR, RM 538

EXXONMOBIL OIL CORP #50608 (Continued) **1004515295**

HOUSTON, TX 77060
Contact country: US
Contact telephone: (281) 654-8470
Contact email: Not reported
EPA Region: 06
Land type: Private
Classification: Non-Generator
Description: Handler: Non-Generators do not presently generate hazardous waste

Owner/Operator Summary:
Owner/operator name: EXXONMOBIL CORP
Owner/operator address: 3225 GALLOWS RD
FAIRFAX, VA 22037
Owner/operator country: US
Owner/operator telephone: (713) 656-9075
Legal status: Private
Owner/Operator Type: Operator
Owner/Op start date: 05/22/2001
Owner/Op end date: Not reported

Owner/operator name: EXXONMOBIL CORP
Owner/operator address: 3225 GALLOWS RD
FAIRFAX, VA 22037
Owner/operator country: Not reported
Owner/operator telephone: (713) 656-9075
Legal status: Private
Owner/Operator Type: Owner
Owner/Op start date: 05/22/2001
Owner/Op end date: Not reported

Handler Activities Summary:
U.S. importer of hazardous waste: No
Mixed waste (haz. and radioactive): No
Recycler of hazardous waste: No
Transporter of hazardous waste: No
Treater, storer or disposer of HW: No
Underground injection activity: No
On-site burner exemption: No
Furnace exemption: No
Used oil fuel burner: No
Used oil processor: No
User oil refiner: No
Used oil fuel marketer to burner: No
Used oil Specification marketer: No
Used oil transfer facility: No
Used oil transporter: No

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Historical Generators:
Date form received by agency: 12/15/2008
Site name: EXXONMOBIL OIL CORP #50608

EXXONMOBIL OIL CORP #50608 (Continued) **1004515295**

Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Date form received by agency: 10/20/2004
Site name: EXXONMOBIL OIL CORP #50608
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Date form received by agency: 05/22/2001
Site name: EXXON CO USA 50608
Classification: Conditionally Exempt Small Quantity Generator

. Waste code: D001
. Waste name: IGNITABLE WASTE

. Waste code: D018
. Waste name: BENZENE

Date form received by agency: 02/23/2000
Site name: EXXON CO USA 50608
Classification: Conditionally Exempt Small Quantity Generator

Violation Status: No violations found

Evaluation Action Summary:
Evaluation date: 12/17/2010
Evaluation: FOCUSED COMPLIANCE INSPECTION
Area of violation: Not reported
Date achieved compliance: Not reported
Evaluation lead agency: State

FINDS:

Registry ID: 110003323225

Environmental Interest/Information System
RCRAInfo is a national information system that supports the Resource Conservation and Recovery Act (RCRA) program through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA.

Click this hyperlink while viewing on your computer to access additional FINDS: detail in the EDR Site Report.

EXXONMOBIL OIL CORP #50608 (Continued) **1004515295**

ECHO:
Envid: 1004515295
Registry ID: 110003323225
DFR URL: http://echo.epa.gov/detailed-facility-report?fid=110003323225

---

42 **EXXONMOBIL OIL CORP (EMOC) 50608** **LA RGA LUST** **S115491532**
4555 ESSEN LN **N/A**
BATON ROUGE, LA

RGA LUST:

2002	EXXONMOBIL OIL CORP (EMOC) 50608	4555 ESSEN LN

---

42 **EXXONMOBIL OIL CORP 50608** **LA RGA LUST** **S115491536**
4555 ESSEN LN **N/A**
BATON ROUGE, LA

RGA LUST:

2008	EXXONMOBIL OIL CORP 50608	4555 ESSEN LN
2006	EXXONMOBIL OIL CORP 50608	4555 ESSEN LN

---

42 **EDR Hist Auto** **1013775417**
7931 ONE CALAIS AVE **N/A**
BATON ROUGE, LA 70809

EDR Hist Auto

Year:	Name:	Type:
1986	ONE CALAIS SELF SERVE INC	Gasoline Service Stations
1987	ONE CALAIS SELF SERVE INC	Gasoline Service Stations
1988	ONE CALAIS SELF SERVE INC	Gasoline Service Stations
1989	ESSEN EXPRESS	Gasoline Service Stations, NEC
1990	ESSEN EXPRESS	Gasoline Service Stations, NEC
1991	ESSEN EXPRESS	Gasoline Service Stations, NEC
1992	ESSEN EXPRESS	Gasoline Service Stations, NEC
1993	ESSEN EXPRESS	Gasoline Service Stations, NEC
1994	ESSEN EXPRESS	Gasoline Service Stations, NEC
2000	ESSEN CHEVRON GAS SERV STA	GASOLINE STATIONS
2001	ESSEN CHEVRON	Gasoline Service Stations
2002	ESSEN CHEVRON	Gasoline Service Stations
2003	ESSEN CHEVRON	Gasoline Service Stations
2004	ESSEN CHEVRON	Gasoline Service Stations
2005	ESSEN CHEVRON	Gasoline Service Stations
2006	ESSEN CHEVRON	Gasoline Service Stations
2007	ESSEN CHEVRON	Gasoline Service Stations
2008	ESSEN CHEVRON	Gasoline Service Stations

42 **ESSEN CHEVRON** **LA HIST LUST** **U000880213**
7931 ONE CALAIS AVE **N/A**
BATON ROUGE, LA 70821

HIST LUST:

Facility ID:	17-010765	
Facility Parish:	EAST BATON ROUGE	
Substance Name:	GASOLINE	
Substance Name 2:	Not reported	
Quantity:	UNKNOWN	
Quantity 2:	Not reported	
Date Confirmed:	12/21/1990	
Date Confirmed 2:	Not reported	
Incident Number:	90-2-0275	
Incident Date:	12/21/1990	
Type of Incident:		PIPING LEAK
Type of Incident No2:		Not reported
Reported By:	Not reported	
Reported By 2:	Not reported	
Owner ID:	00346700	
Owner Name:	KELLER OIL CO., INC.	
Owner Address:	P. O. BOX 74264	
Owner City,St,Zip:	BATON ROUGE, LA 70874	
Assessment Pending Info:		No
Assessment Request Date:		Not reported
Assessment Plan Due Date:		03/15/1991
Assessment Plan Received Date:		Not reported
Assessment Approved Date:		Not reported
Assessment Contractor:		PETROCHEM MAINTENANCE INC.
Assess Date Add Info Due:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due2:		Not reported
Assess Date Add Info Recd:		Not reported
Assess Date Add Info Due3:		Not reported
Corrective Plan Due Date:		Not reported
Corrective Plan Received Date:		Not reported
Corrective Plan Approved Date:		12/11/1998
Corr Act Date Add Info Due:		Not reported
Corr Act Date Add Info Recd:		Not reported
Corr Act Date Add Info Due2:		Not reported
Corr Act Date Add Info Recd2:		Not reported
Corr Act Date Add Info Due3:		Not reported
Remediation Method:		Not reported
Remediation Date:		Not reported
Remediation Terminated Date:		Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SUPERUNLEADED LINE LEAK DETECTOR ACTIVATED. PETROCHEM MAINTREPAIRED LINE. SEE DEQ'S DENNIS S. INSPECTION REPORT DATED21-DEC-90. SEE INCIDENT #91-2-0197

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-010765
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported

ESSEN CHEVRON (Continued) **U000880213**

Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	90-2-0275
Incident Date:	12/21/1990
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00346700
Owner Name:	KELLER OIL CO., INC.
Owner Address:	P. O. BOX 74264
Owner City,St,Zip:	BATON ROUGE, LA 70874
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	03/15/1991
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	PETROCHEM MAINTENANCE INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/11/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: SUPERUNLEADED LINE LEAK DETECTOR ACTIVATED. PETROCHEM MAINTREPAIRED LINE. SEE DEQ'S DENNIS S. INSPECTION REPORT DATED21-DEC-90. SEE INCIDENT #91-2-0197

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-010765
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	200 GAL
Quantity 2:	Not reported
Date Confirmed:	05/15/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0002
Incident Date:	05/15/1991
Type of Incident:	PIPING LEAK
Type of Incident No2:	Not reported
Reported By:	DONNA LORRES

ESSEN CHEVRON (Continued) **U000880213**

Reported By 2: Not reported
Owner ID: 00591900
Owner Name: HARRIS GLENN
Owner Address: 7931 ONE CALAIS AVENUE
Owner City,St,Zip: BATON ROUGE, LA 70809
Assessment Pending Info: No
Assessment Request Date: 07/15/1991
Assessment Plan Due Date: 10/05/1991
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: ENVIROCORP SERIVCES & TECHNOLOGY INC.
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 12/11/1998
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: OWNER NAME IS CHEVRON/ GULF STATION. CITIZEN REPORTED STRONGODOR OF GASOLINE. PETRO-CHEM DUG TRENCH. 200 GALLONS OF FREE PHASEGASOLINE HAS BEEN REMOVED AS OF 6/21/91. FIBERGLASS PIPES INSTALLEDIN THE TRENCHES.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-010765
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-2-0002
Incident Date: 05/15/1991
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00591900
Owner Name: HARRIS GLENN
Owner Address: 7931 ONE CALAIS AVENUE
Owner City,St,Zip: BATON ROUGE, LA 70809
Assessment Pending Info: No
Assessment Request Date: 07/15/1991

ESSEN CHEVRON (Continued) **U000880213**

Assessment Plan Due Date:	10/05/1991
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	ENVIROCORP SERIVCES & TECHNOLOGY INC.
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/11/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: OWNER NAME IS CHEVRON/ GULF STATION. CITIZEN REPORTED STRONGODOR OF GASOLINE. PETRO-CHEM DUG TRENCH. 200 GALLONS OF FREE PHASEGASOLINE HAS BEEN REMOVED AS OF 6/21/91. FIBERGLASS PIPES INSTALLEDIN THE TRENCHES.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-010765
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	06/10/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0197
Incident Date:	06/10/1991
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00591900
Owner Name:	HARRIS GLENN
Owner Address:	7931 ONE CALAIS AVENUE
Owner City,St,Zip:	BATON ROUGE, LA 70809
Assessment Pending Info:	No
Assessment Request Date:	06/15/1991
Assessment Plan Due Date:	09/05/1991
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported

ESSEN CHEVRON (Continued) **U000880213**

Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/11/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: AS A RESULT OF HEAVY RAINFALL, GASOLINE THAT HAD LEAKED FROM A USTENTERED A SEWER LINE. SEE INCIDENT NO. 91-2-0002.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-010765
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	91-2-0197
Incident Date:	06/10/1991
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00591900
Owner Name:	HARRIS GLENN
Owner Address:	7931 ONE CALAIS AVENUE
Owner City,St,Zip:	BATON ROUGE, LA 70809
Assessment Pending Info:	No
Assessment Request Date:	06/15/1991
Assessment Plan Due Date:	09/05/1991
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/11/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported

ESSEN CHEVRON (Continued) **U000880213**

Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: AS A RESULT OF HEAVY RAINFALL, GASOLINE THAT HAD LEAKED FROM A USTENTERED A SEWER LINE. SEE INCIDENT NO. 91-2-0002.

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID: 17-010765
Facility Parish: EAST BATON ROUGE
Substance Name: GASOLINE
Substance Name 2: Not reported
Quantity: UNKNOWN
Quantity 2: Not reported
Date Confirmed: 06/17/1932
Date Confirmed 2: Not reported
Incident Number: 93-2-0151
Incident Date: 06/16/1993
Type of Incident: PIPING LEAK
Type of Incident No2: Not reported
Reported By: TERRY/ENERGY EQUIPMENT
Reported By 2: Not reported
Owner ID: 00591900
Owner Name: HARRIS GLENN
Owner Address: 7931 ONE CALAIS AVENUE
Owner City,St,Zip: BATON ROUGE, LA 70809
Assessment Pending Info: Yes
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 12/11/1998
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

ESSEN CHEVRON (Continued) **U000880213**

LA HIST LUST ASSESMENT:
Comments: LEAK DETECTOR SHUT DOWN. LINE LEAK. PENDING MORE INFORMATION

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

Facility ID:	17-010765
Facility Parish:	EAST BATON ROUGE
Substance Name:	Not reported
Substance Name 2:	Not reported
Quantity:	Not reported
Quantity 2:	Not reported
Date Confirmed:	Not reported
Date Confirmed 2:	Not reported
Incident Number:	93-2-0151
Incident Date:	06/16/1993
Type of Incident:	Not reported
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00591900
Owner Name:	HARRIS GLENN
Owner Address:	7931 ONE CALAIS AVENUE
Owner City,St,Zip:	BATON ROUGE, LA 70809
Assessment Pending Info:	Yes
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	12/11/1998
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported
Corr Act Date Add Info Due2:	Not reported
Corr Act Date Add Info Recd2:	Not reported
Corr Act Date Add Info Due3:	Not reported
Remediation Method:	Not reported
Remediation Date:	Not reported
Remediation Terminated Date:	Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: LEAK DETECTOR SHUT DOWN. LINE LEAK. PENDING MORE INFORMATION

LA HIST LUST CORRECTIVE ACTION:
Comments: Not reported

42 **ESSEN CHEVRON** **LA UST** **U004222237**
7931 ONE CALAIS AVE **N/A**
BATON ROUGE, LA 70809

UST:

Master Agency Id:	70297
Subject Item ID:	2
UST Tank Num:	28629
Tank Status:	**Removed**
Install Date:	04/28/1979
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure
UST Tank Num:	28630
Tank Status:	**Removed**
Install Date:	04/28/1979
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes

ESSEN CHEVRON (Continued) **U004222237**

Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	28631
Tank Status:	**Removed**
Install Date:	04/28/1979
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Yes
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Pressure

UST Tank Num:	28632
Tank Status:	**Removed**
Install Date:	04/28/1979
Total Capacity:	5000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported

ESSEN CHEVRON (Continued) **U004222237**

MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Yes
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Not reported
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

---

43 **TEXACO #44-398-0034** **LA HIST LUST** **U000878837**
1831 STARING LN **LA UST** **N/A**
BATON ROUGE, LA 70810

HIST LUST:

Facility ID:	17-011408
Facility Parish:	EAST BATON ROUGE
Substance Name:	GASOLINE
Substance Name 2:	Not reported
Quantity:	UNKNOWN
Quantity 2:	Not reported
Date Confirmed:	06/26/1991
Date Confirmed 2:	Not reported
Incident Number:	91-2-0206
Incident Date:	06/26/1991
Type of Incident:	UST LEAK
Type of Incident No2:	Not reported
Reported By:	Not reported
Reported By 2:	Not reported
Owner ID:	00369200
Owner Name:	STAR ENTERPRISE
Owner Address:	3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip:	METAIRIE, LA 70002
Assessment Pending Info:	No
Assessment Request Date:	Not reported
Assessment Plan Due Date:	Not reported
Assessment Plan Received Date:	Not reported
Assessment Approved Date:	Not reported
Assessment Contractor:	Not reported
Assess Date Add Info Due:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due2:	Not reported
Assess Date Add Info Recd:	Not reported
Assess Date Add Info Due3:	Not reported
Corrective Plan Due Date:	Not reported
Corrective Plan Received Date:	Not reported
Corrective Plan Approved Date:	11/06/1992
Corr Act Date Add Info Due:	Not reported
Corr Act Date Add Info Recd:	Not reported

TEXACO #44-398-0034 (Continued) **U000878837**

Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:
Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: TANKS WERE REMOVED ON 8/22/90. MONITRING WELLS SET 6/27/91. FURTHERASSESSMENT WAS REQUESTED. OWNER TO CLOSE TANKS.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ LETTER DATED 25 JAN 93 APPROVES ABANDONING AND CAPPINGMONITORING WELLS

Facility ID: 17-011408
Facility Parish: EAST BATON ROUGE
Substance Name: Not reported
Substance Name 2: Not reported
Quantity: Not reported
Quantity 2: Not reported
Date Confirmed: Not reported
Date Confirmed 2: Not reported
Incident Number: 91-2-0206
Incident Date: 06/26/1991
Type of Incident: Not reported
Type of Incident No2: Not reported
Reported By: Not reported
Reported By 2: Not reported
Owner ID: 00369200
Owner Name: STAR ENTERPRISE
Owner Address: 3300 W ESPLANADE AVE S, STE. 301
Owner City,St,Zip: METAIRIE, LA 70002
Assessment Pending Info: No
Assessment Request Date: Not reported
Assessment Plan Due Date: Not reported
Assessment Plan Received Date: Not reported
Assessment Approved Date: Not reported
Assessment Contractor: Not reported
Assess Date Add Info Due: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due2: Not reported
Assess Date Add Info Recd: Not reported
Assess Date Add Info Due3: Not reported
Corrective Plan Due Date: Not reported
Corrective Plan Received Date: Not reported
Corrective Plan Approved Date: 11/06/1992
Corr Act Date Add Info Due: Not reported
Corr Act Date Add Info Recd: Not reported
Corr Act Date Add Info Due2: Not reported
Corr Act Date Add Info Recd2: Not reported
Corr Act Date Add Info Due3: Not reported
Remediation Method: Not reported
Remediation Date: Not reported
Remediation Terminated Date: Not reported

LA HIST LUST INCIDENT:

TEXACO #44-398-0034 (Continued) **U000878837**

Comments: Not reported

LA HIST LUST ASSESMENT:
Comments: TANKS WERE REMOVED ON 8/22/90. MONITRING WELLS SET 6/27/91. FURTHERASSESSMENT WAS REQUESTED. OWNER TO CLOSE TANKS.

LA HIST LUST CORRECTIVE ACTION:
Comments: DEQ LETTER DATED 25 JAN 93 APPROVES ABANDONING AND CAPPINGMONITORING WELLS

UST:

Master Agency Id:	70019
Subject Item ID:	1
UST Tank Num:	30420
Tank Status:	**Closed**
Install Date:	03/25/1984
Total Capacity:	12000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported
UST Tank Num:	30421
Tank Status:	**Closed**
Install Date:	03/25/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported

TEXACO #44-398-0034 (Continued) **U000878837**

MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	30422
Tank Status:	**Closed**
Install Date:	03/25/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported
Diesel:	Not reported
Gasohol:	Yes
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

UST Tank Num:	30423
Tank Status:	**Closed**
Install Date:	03/25/1984
Total Capacity:	10000
Number Of Compartments:	1
Gasoline:	Not reported

TEXACO #44-398-0034 (Continued) **U000878837**

Diesel:	Yes
Gasohol:	Not reported
Kerosene:	Not reported
Heating Oil:	Not reported
New Used Oil:	Not reported
MS Aviation Fuel:	Not reported
MS Additive:	Not reported
MS Antifreeze:	Not reported
MS Naptha:	Not reported
MS Varsol:	Not reported
Unknown:	Not reported
Other Sub:	Not reported
Steel Tank Covered With Asphalt:	Not reported
Cathodically Protected:	Not reported
Epoxy Coated Tank:	Not reported
A Composite Of Different Materials:	Not reported
Fiberglass Or Plastic:	Y
Interior Line With Some Material:	Not reported
Double Wall As Opposed To Single Wall:	Not reported
Outside Lined w/ Polyethylen Jacket:	Not reported
Made Of Concrete:	Not reported
Liner Covering Excavation Hole:	Not reported
Other Material:	Not reported
Pipe Method Description:	Not reported

Count: 99 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BATON ROUGE	U000880236	BATON ROUGE BARGE TERMINAL	RT 5 BOX 45	70808	LA HIST LUST, LA UST
BATON ROUGE	U003925777	GOODYEAR AUTO SERVICE CENTER	536 - 538 FLORIDA ST	70801	LA UST
BATON ROUGE	U003923421	LAWRENCE ALBERT	1455 N ACADIAN	70802	LA UST
BATON ROUGE	S106033894	JET 24 FOOD STORE #42	2313 S ACADIAN THRUWAY # &I-10	70808	LA HIST LUST
BATON ROUGE	U000878579	ISAAC WALKER TEXACO	1745 N ACADIAN	70802	LA UST
BATON ROUGE	S112658740	BR-181 SMILEY HEIGHTS	ALONG LOBDELL BLVD		LA BROWNFIELDS, LA REM
BATON ROUGE	2009050303	I-10 AND I-12 SPLIT	I-10 AND I-12 SPLIT		HMIRS
BATON ROUGE	1015731186	THE ESSEN INCIDENT	I-10 AND ESSEN LANE		SEMS
BATON ROUGE	2012107475	I-10 AT ESSEN LANE MM 160	I-10 AT ESSEN LANE MM 160	70809	HMIRS
BATON ROUGE	S110445608	PLANTATION PIPE LINE COMPANY	BATON ROUGE TANK FROM		LA AUL
BATON ROUGE	S112659239	NATIONAL CAR RENTAL	BATON ROUGE METRO AIRPORT		LA REM
BATON ROUGE	S110445607	PLANTATION PIPE LINE COMPANY	BATON ROUGE TANK FARM		LA AUL
BATON ROUGE	S108627567	BEHIND HOME DEPOT AT HIGHLAND AND I-10	BEHIND HOME DEPOT AT HIGHLAND AND I-10		LA SPILLS
BATON ROUGE	S117324435	BATON ROUGE MUNICIPAL DOCKS (BR #128)	1100-1300 BLOCK OF RIVER RD		LA BROWNFIELDS, LA REM
BATON ROUGE	S117324458	BAJON PROPERTY	900 BLOCK RIVER RD		LA BROWNFIELDS, LA REM
BATON ROUGE	S118443184	JONES HASTINGS CO INC - HARVESTON WAY	S BLUEBONNET BLVD	70810	LA NPDES
BATON ROUGE	1001968232	EXXON CO 51305	6060 BLUEBONNET & I10	70808	RCRA NonGen / NLR, FINDS, ECHO
BATON ROUGE	S118246549	PORT ROYAL APARTMENTS	BOUNDED BY EVANGELINE ST, AIRLINE HWY, E BROOKSTOWN DR, AND		LA REM
BATON ROUGE	S112658599	VACANT LOT	BOUNDED: SPANISH TOWN RD, 11TH ST, NORTH ST, CANAL ST		LA REM
BATON ROUGE	S108622785	E OF I-10 SIEGEN	BR		LA SPILLS
BATON ROUGE	S108615119	CARRIAGE WAY - PLANTATION TRACE SUBDIVISION	CARRIAGE WAY - PLANTATION TRACE SUBDIVISION		LA SPILLS
BATON ROUGE	1004713515	BELLE OF BATON ROUGE CASINO	CATFISH TOWN DOCK MS RIVER	70802	RCRA-CESQG
BATON ROUGE	S112658543	RIVER ROAD PROPERTY SITE	SE CORNER RIVER RD AND OKLAHOMA ST AND NE CORNER OKLAHOMA &		LA REM
BATON ROUGE	U004222281	GALVEZ PARKING GARAGE SITE	CORNER OF MAIN ST & N FIFTH ST	70802	LA UST
BATON ROUGE	2010011115	I-10 EAST BOUND AT EXIT 156	I-10 EAST BOUND AT EXIT 156	70801	HMIRS
BATON ROUGE	S108615104	I-10 EAST BOUND AT THE SPLIT	I-10 EAST BOUND AT THE SPLIT BATON ROUGE		LA SPILLS
BATON ROUGE	2010111375	I-10 EAST MILE MARKER 158	I-10 EAST MILE MARKER 158		HMIRS
BATON ROUGE	2007433588	I-10 EAST	I-10 EAST		HMIRS
BATON ROUGE	S108625726	I-10 EASTBOUND BETWEEN MM 170 AND 171	I-10 EASTBOUND BETWEEN MM 170 AND 171 BATON ROUGE		LA SPILLS
BATON ROUGE	S108622055	END OF ST IRMA LEE WAY	END OF ST IRMA LEE WAY		LA SPILLS
BATON ROUGE	S106704896	EXXON #5-8066	FLORIDA & SHERWOOD		LA AUL, LA REM
BATON ROUGE	1000415828	CUSTOM FUEL SVC	FOOT OF NORTH ST	70802	RCRA NonGen / NLR
BATON ROUGE	S110445142	BOH BROS CONSTRUCTION CO LLC - I-10 WIDENING DESIGN-BUILLD P	I-10 FR SIEGEN LN TO HIGHLAND RD	70809	LA NPDES
BATON ROUGE	S108619887	ON I-10 FROM PRAIRIEVILLE TO BLUEBONNET	ON I-10 FROM PRAIRIEVILLE TO BLUEBONNET		LA SPILLS
BATON ROUGE	S117979716	NELSON ESTATE	W LEE DR & BURBANK		LA REM
BATON ROUGE	U003923181	TRIANGLE TRUCK TERMINAL	MAIN & TENTH ST	70802	LA UST
BATON ROUGE	S112659023	TRIANGLE TRUCK TERMINAL	MAIN & TENTH ST		LA REM
BATON ROUGE	S110445609	PLANTATION PIPELINE COMPANY, BATON ROUGH TANK FARM	2004 SOUTH MANIFOLD,PUMP BUILDING, 2009 SOUYTH MANIFOLD, 220		LA AUL

Count: 99 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
BATON ROUGE	S117439994	PROPOSED LOUISIANA BLACK HISTTORY HALL OF FAME	MYRTLE ST, E OF EDDIE ROBINSON DR		LA BROWNFIELDS, LA REM
BATON ROUGE	S108624558	I-10 NEAR EVANGELINE	I-10 NEAR EVANGELINE BATON ROUGE		LA SPILLS
BATON ROUGE	S108627300	I-10 NEAR HIGHLAND RD.	I-10 NEAR HIGHLAND RD. BATON ROUGE, PRAIRIEVILLE		LA SPILLS
BATON ROUGE	S112658628	SULFURIC ACID PIPELINE RELEASE	NEAR AIRLINE HWY & SANCHEZ ST		LA REM
BATON ROUGE	1003873460	CAPITOL LAKE	NEAR INTERSTATE 10-CAPITOL LAKE DV.	70802	SEMS-ARCHIVE
BATON ROUGE	S112658440	NICHOLSON DRIVE SHOPPING CENTER	NICHOLSON DR & MCCLUNG ST		LA REM
BATON ROUGE	S118443260	SHELL PIPELINE CO LP - CHOCTAW PUMP STATION	OFF OF S CHOCTAW RD NEXT TO ILLINOIS	70806	LA REM
BATON ROUGE	S108613337	SIEGEN LN AT I-10	SIEGEN LN AT I-10		LA SPILLS
BATON ROUGE	S118096959	ALLEN & LEBLANC LLC - SIEGEN LANE/ I-10 AREA SEWER REHABILIT	SIEGEN LANE/ I-10 AREA	70810	LA NPDES
BATON ROUGE	S112658617	EAST SPANISH TOWN SITES	SPANISH TOWN		LA REM
BATON ROUGE	1016356320	BR 164 SPANISH TOWN SITE 'D'	V1100-1200 SPANISH TOWN RD.	70802	US BROWNFIELDS, FINDS
BATON ROUGE	S117324405	EAST SPANISH TOWN SITES	SPANISH TOWN		LA DEL SHWS
BATON ROUGE	1016356316	BR 165 SPANISH TOWN SITE 'E'	V1400-1500 SPANISH TOWN RD.	70802	US BROWNFIELDS, FINDS
BATON ROUGE	S112658970	NORTH STREET MECHANIC SHOP	NORTH ST		LA VCP, LA REM
BATON ROUGE	S114040187	MCCLUNG ST SITE	SWC MCCLUNG ST & AZTEC ST		LA REM
BATON ROUGE	U000875399	CIRCLE K #8057	6369 VAN GOGH DR	70806	LA HIST LUST, LA UST
BATON ROUGE	S108626555	I-10 WESTBOUND MILE MARKER 173 - BLUE BAYOU AREA	I-10 WESTBOUND MILE MARKER 173 - BLUE BAYOU AREA		LA SPILLS
BATON ROUGE	S117042372	5073 WOODSTOCK WAY DR.	4940 WOODSTOCK WAY	70809	LA SPILLS
EAST BATON ROUGE COU	M300006101	EXXON MOBIL CORP	BATON ROUGE REFINERY		US MINES
LABADIEVILLE	S113887560	LADOTD - 321 HWY 663 DEBRIS SITE	321 HWY 663	70802	LA SWF/LF
PORT ALLEN	S116735044	COMMAND CONSTRUCTION INDUSTRIES LLC - I-10 INTERCHANGE REPAI	LA 1 & LA 415	70767	LA NPDES
PORT ALLEN	S105201122	MC NAIR TRANSPORT	HWY 1 S	70767	LA SHWS, LA REM
PORT ALLEN	U001898014	POPLAR GROVE SUGAR MILL	HWY 1	70767	LA HIST LUST, LA UST
PORT ALLEN	1004707703	WESTERN COMPANY OF NORTH AMERICA	HWY 1 NORTH	70767	RCRA-CESQG
PORT ALLEN	U003987553	SACHE ELECTRIC	HWY 1 S	70767	LA UST
PORT ALLEN	U001965551	WESTSIDE SERVICE STATION	HWY 190 W	70767	LA UST
PORT ALLEN	U000878035	EARL WOOD	HWY 190	70767	LA UST
PORT ALLEN	1004710513	BROWN & FERRIS INDUSTRIES	HWY 190 W 1132 AT RIVER BRIDGE	70767	RCRA NonGen / NLR
PORT ALLEN	U004222201	DAY BROTHERS TIRE CO	1626 HWY 190W	70767	LA UST
PORT ALLEN	U000875896	SMITHFIELD FUELS	HWY 415	70767	LA UST
PORT ALLEN	U003987464	TIRE/TRUCK REPAIR	HWY 415	70767	LA LUST, LA UST, LA REM
PORT ALLEN	U003987568	NICHOLS SHELL YARD	HWY 415	70767	LA UST
PORT ALLEN	U000880730	ROGER CHUSTZ	HWY 620	70767	LA UST
PORT ALLEN	U001899196	ALMA CHUSTZ	HWY 985	70767	LA UST
PORT ALLEN	U003925030	LADOTD - PORT ALLEN UNIT	HWY 987-05 (OAK ST)	70767	LA UST
PORT ALLEN	1000624086	MPC WILKINSON GATE	HWY 987-3 AT MPC PORT ALLEN WH	70767	RCRA NonGen / NLR
PORT ALLEN	1003873456	MCLEAN TRUCKING CO	10250 DARADELLE DR	70767	SEMS-ARCHIVE, LA SHWS, LA REM
PORT ALLEN	1014390771	EXXONMOBIL P/L BR GAS PLANT	1601 ENERGY DR (A PORTION OF)	70767	RCRA-SQG
PORT ALLEN	2014005005	I-10 EXIT 151	I-10 EXIT 151	70767	HMIRS
PORT ALLEN	1000893494	TIGER MARINE	FORT OF RIVERVIEW DR., P.O. BOX 770	70767	SEMS, ICIS, PRP
PORT ALLEN	U000880135	TIRE/TRUCK REPAIR	LA HIGHWAY 415	70767	LA HIST LUST
PORT ALLEN	1015734295	LOUISIANA VACUUM SERVICE	ON HWY 190, 7 MI E OF CITY	70767	SEMS-ARCHIVE, RCRA-CESQG

Count: 99 records

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)
PORT ALLEN	1015734266	MCNAIR TRANSPORT INC	JCT HWY 1 & LA 988 S OF TOWN	70767	SEMS-ARCHIVE, RCRA NonGen / NL
PORT ALLEN	S106898848	BARRY MOORE AUTO SALVAGE DUMP	LEVEE RD AT US 190 BRIDGE	70767	LA SHWS, LA REM
PORT ALLEN	1016957223	SHAWCOR PIPE PROTECTION LLC	3197 N LINE RD	70767	RCRA-CESQG
PORT ALLEN	1000395180	DELTA INDUSTRIAL SERVICES INC	MAHAFFEY ROAD	70767	RCRA NonGen / NLR
PORT ALLEN	U003922722	CATALYST HANDLING SYSTEMS INC	719 MAIN ST	70767	LA SHWS, LA UST, LA REM
PORT ALLEN	1016957226	LA DOTD, I-10 MISSISSIPPI RIVER BRIDGE	I-10, MM153-154	70767	RCRA-LQG
PORT ALLEN	1017406619	LA DOTD, I-10 MISSISSIPPI RIVER BRIDGE	I-10, MM153-154	70767	FINDS, ECHO
PORT ALLEN	S108601197	ENVIRONMENTAL INDUSTRIES RECYCLING INC	7122 NOLAN DAVID RD	70767	LA SWF/LF, LA SPILLS, LA NPDES
PORT ALLEN	S113887555	LADOTD - OLD LINE RD DEBRIS SITE	OLD LINE RD (2 MI W OF LA 1)	70767	LA SWF/LF
PORT ALLEN	1015743190	CAMTRACO ENTERPRISES INC	2707 PARISH LN	70767	RCRA NonGen / NLR
PORT ALLEN	U001899666	WESTWAY INC	RIVER RD	70767	LA UST
PORT ALLEN	1000192197	WALDROUP PUMP SVC INC	SCALLAN RD 2 M W HWY 415	70767	RCRA NonGen / NLR
PORT ALLEN	1005443612	A&Z MARINE INC	2425 SUN PLUS PKWY	70767	RCRA-CESQG, LA NPDES
PORT ALLEN	S111869223	LADOTD - SUN PLUS PARKWAY DEBRIS SITE	SUN PLUS PKWY	70767	LA SWF/LF
PORT ALLEN	U004228900	WEST BATON ROUGE PARISH COUNCIL MAINTENANCE SHED	3001 TED DENSTEL	70767	LA UST
PORT ALLEN	S112272126	WEST BATON ROUGE PARISH COUNCIL - TURNER RD DEBRIS SITE	TURNER RD	70767	LA SWF/LF
PORT ALLEN	1000623118	TETCO MP 154.78 BATON ROUGE	5.7 M W PORT ALLEN ON HWY 76	70767	RCRA-SQG
PORT ALLEN	2011009958	I-10 W/B MP 135	I-10 W/B MP 135	70767	HMIRS
PORT ALLEN (BATON ROU	1015734196	EXXON CO USA ANCHORAGE TANK FARM	LA HWY 1	70767	SEMS-ARCHIVE, RCRA-LQG

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Number of Days to Update: Provides confirmation that EDR is reporting records that have been updated within 90 days from the date the government agency made the information available to the public.

FEDERAL RECORDS

NPL: National Priority List

National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC) and regional EPA offices.

Date of Government Version: 04/05/2017
Date Data Arrived at EDR: 04/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 21

Source: EPA
Telephone: N/A
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

NPL Site Boundaries

Sources:

EPA's Environmental Photographic Interpretation Center (EPIC)
Telephone: 202-564-7333

EPA Region 1
Telephone 617-918-1143

EPA Region 6
Telephone: 214-655-6659

EPA Region 3
Telephone 215-814-5418

EPA Region 7
Telephone: 913-551-7247

EPA Region 4
Telephone 404-562-8033

EPA Region 8
Telephone: 303-312-6774

EPA Region 5
Telephone 312-886-6686

EPA Region 9
Telephone: 415-947-4246

EPA Region 10
Telephone 206-553-8665

Proposed NPL: Proposed National Priority List Sites

A site that has been proposed for listing on the National Priorities List through the issuance of a proposed rule in the Federal Register. EPA then accepts public comments on the site, responds to the comments, and places on the NPL those sites that continue to meet the requirements for listing.

Date of Government Version: 04/05/2017
Date Data Arrived at EDR: 04/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 21

Source: EPA
Telephone: N/A
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

Delisted NPL: National Priority List Deletions

The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

Date of Government Version: 04/05/2017
Date Data Arrived at EDR: 04/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 21

Source: EPA
Telephone: N/A
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NPL LIENS: Federal Superfund Liens

Federal Superfund Liens. Under the authority granted the USEPA by CERCLA of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner received notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/1991
Date Data Arrived at EDR: 02/02/1994
Date Made Active in Reports: 03/30/1994
Number of Days to Update: 56

Source: EPA
Telephone: 202-564-4267
Last EDR Contact: 08/15/2011
Next Scheduled EDR Contact: 11/28/2011
Data Release Frequency: No Update Planned

SEMS: Superfund Enterprise Management System

SEMS (Superfund Enterprise Management System) tracks hazardous waste sites, potentially hazardous waste sites, and remedial activities performed in support of EPA's Superfund Program across the United States. The list was formerly know as CERCLIS, renamed to SEMS by the EPA in 2015. The list contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). This dataset also contains sites which are either proposed to or on the National Priorities List (NPL) and the sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 02/07/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

SEMS-ARCHIVE: Superfund Enterprise Management System Archive

SEMS-ARCHIVE (Superfund Enterprise Management System Archive) tracks sites that have no further interest under the Federal Superfund Program based on available information. The list was formerly known as the CERCLIS-NFRAP, renamed to SEMS ARCHIVE by the EPA in 2015. EPA may perform a minimal level of assessment work at a site while it is archived if site conditions change and/or new information becomes available. Archived sites have been removed and archived from the inventory of SEMS sites. Archived status indicates that, to the best of EPA's knowledge, assessment at a site has been completed and that EPA has determined no further steps will be taken to list the site on the National Priorities List (NPL), unless information indicates this decision was not appropriate or other considerations require a recommendation for listing at a later time. The decision does not necessarily mean that there is no hazard associated with a given site; it only means that. based upon available information, the location is not judged to be potential NPL site.

Date of Government Version: 02/07/2017
Date Data Arrived at EDR: 04/19/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 16

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 06/08/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

LIENS 2: CERCLA Lien Information

A Federal CERCLA ('Superfund') lien can exist by operation of law at any site or property at which EPA has spent Superfund monies. These monies are spent to investigate and address releases and threatened releases of contamination. CERCLIS provides information as to the identity of these sites and properties.

Date of Government Version: 02/18/2014
Date Data Arrived at EDR: 03/18/2014
Date Made Active in Reports: 04/24/2014
Number of Days to Update: 37

Source: Environmental Protection Agency
Telephone: 202-564-6023
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

CORRACTS: Corrective Action Report

CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: EPA
Telephone: 800-424-9346
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

RCRA-TSDF: RCRA - Treatment, Storage and Disposal

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Transporters are individuals or entities that move hazardous waste from the generator offsite to a facility that can recycle, treat, store, or dispose of the waste. TSDFs treat, store, or dispose of the waste.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

RCRA-LQG: RCRA - Large Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Large quantity generators (LQGs) generate over 1,000 kilograms (kg) of hazardous waste, or over 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

RCRA-SQG: RCRA - Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Small quantity generators (SQGs) generate between 100 kg and 1,000 kg of hazardous waste per month.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Quarterly

RCRA-CESQG: RCRA - Conditionally Exempt Small Quantity Generators

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Conditionally exempt small quantity generators (CESQGs) generate less than 100 kg of hazardous waste, or less than 1 kg of acutely hazardous waste per month.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Varies

RCRA NonGen / NLR: RCRA - Non Generators / No Longer Regulated

RCRAInfo is EPA's comprehensive information system, providing access to data supporting the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984. The database includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA). Non-Generators do not presently generate hazardous waste.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 44

Source: Environmental Protection Agency
Telephone: 214-665-6444
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Varies

US ENG CONTROLS: Engineering Controls Sites List

A listing of sites with engineering controls in place. Engineering controls include various forms of caps, building foundations, liners, and treatment methods to create pathway elimination for regulated substances to enter environmental media or effect human health.

Date of Government Version: 02/13/2017
Date Data Arrived at EDR: 02/28/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 101

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

US INST CONTROL: Sites with Institutional Controls

A listing of sites with institutional controls in place. Institutional controls include administrative measures, such as groundwater use restrictions, construction restrictions, property use restrictions, and post remediation care requirements intended to prevent exposure to contaminants remaining on site. Deed restrictions are generally required as part of the institutional controls.

Date of Government Version: 02/13/2017
Date Data Arrived at EDR: 02/28/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 101

Source: Environmental Protection Agency
Telephone: 703-603-0695
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

ERNS: Emergency Response Notification System

Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 09/26/2016
Date Data Arrived at EDR: 09/29/2016
Date Made Active in Reports: 11/11/2016
Number of Days to Update: 43

Source: National Response Center, United States Coast Guard
Telephone: 202-267-2180
Last EDR Contact: 03/29/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Annually

HMIRS: Hazardous Materials Information Reporting System

Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 12/28/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 37

Source: U.S. Department of Transportation
Telephone: 202-366-4555
Last EDR Contact: 03/29/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Annually

DOT OPS: Incident and Accident Data

Department of Transporation, Office of Pipeline Safety Incident and Accident data.

Date of Government Version: 07/31/2012
Date Data Arrived at EDR: 08/07/2012
Date Made Active in Reports: 09/18/2012
Number of Days to Update: 42

Source: Department of Transporation, Office of Pipeline Safety
Telephone: 202-366-4595
Last EDR Contact: 05/02/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

US CDL: Clandestine Drug Labs

A listing of clandestine drug lab locations. The U.S. Department of Justice ("the Department") provides this web site as a public service. It contains addresses of some locations where law enforcement agencies reported they found chemicals or other items that indicated the presence of either clandestine drug laboratories or dumpsites. In most cases, the source of the entries is not the Department, and the Department has not verified the entry and does not guarantee its accuracy. Members of the public must verify the accuracy of all entries by, for example, contacting local law enforcement and local health departments.

Date of Government Version: 02/09/2017
Date Data Arrived at EDR: 03/08/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 93

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Quarterly

US BROWNFIELDS: A Listing of Brownfields Sites

Brownfields are real property, the expansion, redevelopment, or reuse of which may be complicated by the presence or potential presence of a hazardous substance, pollutant, or contaminant. Cleaning up and reinvesting in these properties takes development pressures off of undeveloped, open land, and both improves and protects the environment. Assessment, Cleanup and Redevelopment Exchange System (ACRES) stores information reported by EPA Brownfields grant recipients on brownfields properties assessed or cleaned up with grant funding as well as information on Targeted Brownfields Assessments performed by EPA Regions. A listing of ACRES Brownfield sites is obtained from Cleanups in My Community. Cleanups in My Community provides information on Brownfields properties for which information is reported back to EPA, as well as areas served by Brownfields grant programs.

Date of Government Version: 03/02/2017
Date Data Arrived at EDR: 03/02/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 202-566-2777
Last EDR Contact: 03/02/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Semi-Annually

DOD: Department of Defense Sites

This data set consists of federally owned or administered lands, administered by the Department of Defense, that have any area equal to or greater than 640 acres of the United States, Puerto Rico, and the U.S. Virgin Islands.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 11/10/2006
Date Made Active in Reports: 01/11/2007
Number of Days to Update: 62

Source: USGS
Telephone: 888-275-8747
Last EDR Contact: 04/14/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Semi-Annually

FUDS: Formerly Used Defense Sites

The listing includes locations of Formerly Used Defense Sites properties where the US Army Corps of Engineers is actively working or will take necessary cleanup actions.

Date of Government Version: 01/31/2015
Date Data Arrived at EDR: 07/08/2015
Date Made Active in Reports: 10/13/2015
Number of Days to Update: 97

Source: U.S. Army Corps of Engineers
Telephone: 202-528-4285
Last EDR Contact: 02/24/2017
Next Scheduled EDR Contact: 06/05/2017
Data Release Frequency: Varies

LUCIS: Land Use Control Information System

LUCIS contains records of land use control information pertaining to the former Navy Base Realignment and Closure properties.

Date of Government Version: 12/28/2016
Date Data Arrived at EDR: 01/04/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 93

Source: Department of the Navy
Telephone: 843-820-7326
Last EDR Contact: 05/15/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

CONSENT: Superfund (CERCLA) Consent Decrees

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: 09/30/2016
Date Data Arrived at EDR: 11/18/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 77

Source: Department of Justice, Consent Decree Library
Telephone: Varies
Last EDR Contact: 03/27/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Varies

ROD: Records Of Decision

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 11/25/2013
Date Data Arrived at EDR: 12/12/2013
Date Made Active in Reports: 02/24/2014
Number of Days to Update: 74

Source: EPA
Telephone: 703-416-0223
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Annually

UMTRA: Uranium Mill Tailings Sites

Uranium ore was mined by private companies for federal government use in national defense programs. When the mills shut down, large piles of the sand-like material (mill tailings) remain after uranium has been extracted from the ore. Levels of human exposure to radioactive materials from the piles are low; however, in some cases tailings were used as construction materials before the potential health hazards of the tailings were recognized.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 10/07/2011
Date Made Active in Reports: 03/01/2012
Number of Days to Update: 146

Source: Department of Energy
Telephone: 505-845-0011
Last EDR Contact: 05/22/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Varies

DEBRIS REGION 9: Torres Martinez Reservation Illegal Dump Site Locations

A listing of illegal dump sites location on the Torres Martinez Indian Reservation located in eastern Riverside County and northern Imperial County, California.

Date of Government Version: 01/12/2009
Date Data Arrived at EDR: 05/07/2009
Date Made Active in Reports: 09/21/2009
Number of Days to Update: 137

Source: EPA, Region 9
Telephone: 415-947-4219
Last EDR Contact: 04/24/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: No Update Planned

ODI: Open Dump Inventory

An open dump is defined as a disposal facility that does not comply with one or more of the Part 257 or Part 258 Subtitle D Criteria.

Date of Government Version: 06/30/1985
Date Data Arrived at EDR: 08/09/2004
Date Made Active in Reports: 09/17/2004
Number of Days to Update: 39

Source: Environmental Protection Agency
Telephone: 800-424-9346
Last EDR Contact: 06/09/2004
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

US MINES 3: Active Mines & Mineral Plants Database Listing

Active Mines and Mineral Processing Plant operations for commodities monitored by the Minerals Information Team of the USGS.

Date of Government Version: 04/14/2011
Date Data Arrived at EDR: 06/08/2011
Date Made Active in Reports: 09/13/2011
Number of Days to Update: 97

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 06/02/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

US MINES: Mines Master Index File

Contains all mine identification numbers issued for mines active or opened since 1971. The data also includes violation information.

Date of Government Version: 02/08/2017
Date Data Arrived at EDR: 02/28/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 38

Source: Department of Labor, Mine Safety and Health Administration
Telephone: 303-231-5959
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Semi-Annually

US MINES 2: Ferrous and Nonferrous Metal Mines Database Listing

This map layer includes ferrous (ferrous metal mines are facilities that extract ferrous metals, such as iron ore or molybdenum) and nonferrous (Nonferrous metal mines are facilities that extract nonferrous metals, such as gold, silver, copper, zinc, and lead) metal mines in the United States.

Date of Government Version: 12/05/2005
Date Data Arrived at EDR: 02/29/2008
Date Made Active in Reports: 04/18/2008
Number of Days to Update: 49

Source: USGS
Telephone: 703-648-7709
Last EDR Contact: 05/31/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

TRIS: Toxic Chemical Release Inventory System

Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 11/24/2015
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 133

Source: EPA
Telephone: 202-566-0250
Last EDR Contact: 05/26/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Annually

TSCA: Toxic Substances Control Act

Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site.

Date of Government Version: 12/31/2012
Date Data Arrived at EDR: 01/15/2015
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 14

Source: EPA
Telephone: 202-260-5521
Last EDR Contact: 03/24/2017
Next Scheduled EDR Contact: 07/03/2017
Data Release Frequency: Every 4 Years

FTTS: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

FTTS tracks administrative cases and pesticide enforcement actions and compliance activities related to FIFRA, TSCA and EPCRA (Emergency Planning and Community Right-to-Know Act). To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA/Office of Prevention, Pesticides and Toxic Substances
Telephone: 202-566-1667
Last EDR Contact: 05/19/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Quarterly

FTTS INSP: FIFRA/ TSCA Tracking System - FIFRA (Federal Insecticide, Fungicide, & Rodenticide Act)/TSCA (Toxic Substances Control Act)

A listing of FIFRA/TSCA Tracking System (FTTS) inspections and enforcements.

Date of Government Version: 04/09/2009
Date Data Arrived at EDR: 04/16/2009
Date Made Active in Reports: 05/11/2009
Number of Days to Update: 25

Source: EPA
Telephone: 202-566-1667
Last EDR Contact: 05/19/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Quarterly

HIST FTTS: FIFRA/TSCA Tracking System Administrative Case Listing

A complete administrative case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2007
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

HIST FTTS INSP: FIFRA/TSCA Tracking System Inspection & Enforcement Case Listing

A complete inspection and enforcement case listing from the FIFRA/TSCA Tracking System (FTTS) for all ten EPA regions. The information was obtained from the National Compliance Database (NCDB). NCDB supports the implementation of FIFRA (Federal Insecticide, Fungicide, and Rodenticide Act) and TSCA (Toxic Substances Control Act). Some EPA regions are now closing out records. Because of that, and the fact that some EPA regions are not providing EPA Headquarters with updated records, it was decided to create a HIST FTTS database. It included records that may not be included in the newer FTTS database updates. This database is no longer updated.

Date of Government Version: 10/19/2006
Date Data Arrived at EDR: 03/01/2007
Date Made Active in Reports: 04/10/2007
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 12/17/2008
Next Scheduled EDR Contact: 03/17/2008
Data Release Frequency: No Update Planned

SSTS: Section 7 Tracking Systems

Section 7 of the Federal Insecticide, Fungicide and Rodenticide Act, as amended (92 Stat. 829) requires all registered pesticide-producing establishments to submit a report to the Environmental Protection Agency by March 1st each year. Each establishment must report the types and amounts of pesticides, active ingredients and devices being produced, and those having been produced and sold or distributed in the past year.

Date of Government Version: 12/31/2009
Date Data Arrived at EDR: 12/10/2010
Date Made Active in Reports: 02/25/2011
Number of Days to Update: 77

Source: EPA
Telephone: 202-564-4203
Last EDR Contact: 04/26/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Annually

ICIS: Integrated Compliance Information System

The Integrated Compliance Information System (ICIS) supports the information needs of the national enforcement and compliance program as well as the unique needs of the National Pollutant Discharge Elimination System (NPDES) program.

Date of Government Version: 11/18/2016
Date Data Arrived at EDR: 11/23/2016
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 79

Source: Environmental Protection Agency
Telephone: 202-564-2501
Last EDR Contact: 04/10/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Quarterly

PADS: PCB Activity Database System

PCB Activity Database. PADS Identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 01/20/2016
Date Data Arrived at EDR: 04/28/2016
Date Made Active in Reports: 09/02/2016
Number of Days to Update: 127

Source: EPA
Telephone: 202-566-0500
Last EDR Contact: 04/10/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Annually

MLTS: Material Licensing Tracking System

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 08/30/2016
Date Data Arrived at EDR: 09/08/2016
Date Made Active in Reports: 10/21/2016
Number of Days to Update: 43

Source: Nuclear Regulatory Commission
Telephone: 301-415-7169
Last EDR Contact: 05/08/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Quarterly

RADINFO: Radiation Information Database

The Radiation Information Database (RADINFO) contains information about facilities that are regulated by U.S. Environmental Protection Agency (EPA) regulations for radiation and radioactivity.

Date of Government Version: 01/04/2017
Date Data Arrived at EDR: 01/06/2017
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 35

Source: Environmental Protection Agency
Telephone: 202-343-9775
Last EDR Contact: 04/06/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Quarterly

FINDS: Facility Index System/Facility Registry System

Facility Index System. FINDS contains both facility information and 'pointers' to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 04/04/2017
Date Data Arrived at EDR: 04/07/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 35

Source: EPA
Telephone: (214) 665-2200
Last EDR Contact: 06/07/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

RAATS: RCRA Administrative Action Tracking System

RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/1995
Date Data Arrived at EDR: 07/03/1995
Date Made Active in Reports: 08/07/1995
Number of Days to Update: 35

Source: EPA
Telephone: 202-564-4104
Last EDR Contact: 06/02/2008
Next Scheduled EDR Contact: 09/01/2008
Data Release Frequency: No Update Planned

RMP: Risk Management Plans

When Congress passed the Clean Air Act Amendments of 1990, it required EPA to publish regulations and guidance for chemical accident prevention at facilities using extremely hazardous substances. The Risk Management Program Rule (RMP Rule) was written to implement Section 112(r) of these amendments. The rule, which built upon existing industry codes and standards, requires companies of all sizes that use certain flammable and toxic substances to develop a Risk Management Program, which includes a(n): Hazard assessment that details the potential effects of an accidental release, an accident history of the last five years, and an evaluation of worst-case and alternative accidental releases; Prevention program that includes safety precautions and maintenance, monitoring, and employee training measures; and Emergency response program that spells out emergency health care, employee training measures and procedures for informing the public and response agencies (e.g the fire department) should an accident occur.

Date of Government Version: 02/01/2017
Date Data Arrived at EDR: 02/09/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 57

Source: Environmental Protection Agency
Telephone: 202-564-8600
Last EDR Contact: 04/21/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

BRS: Biennial Reporting System

The Biennial Reporting System is a national system administered by the EPA that collects data on the generation and management of hazardous waste. BRS captures detailed data from two groups: Large Quantity Generators (LQG) and Treatment, Storage, and Disposal Facilities.

Date of Government Version: 12/31/2013
Date Data Arrived at EDR: 02/24/2015
Date Made Active in Reports: 09/30/2015
Number of Days to Update: 218

Source: EPA/NTIS
Telephone: 800-424-9346
Last EDR Contact: 05/26/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Biennially

PRP: Potentially Responsible Parties
A listing of verified Potentially Responsible Parties

Date of Government Version: 10/25/2013
Date Data Arrived at EDR: 10/17/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 3

Source: EPA
Telephone: 202-564-6023
Last EDR Contact: 06/06/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Quarterly

UXO: Unexploded Ordnance Sites
A listing of unexploded ordnance site locations

Date of Government Version: 10/25/2015
Date Data Arrived at EDR: 01/29/2016
Date Made Active in Reports: 04/05/2016
Number of Days to Update: 67

Source: Department of Defense
Telephone: 571-373-0407
Last EDR Contact: 05/22/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

US HIST CDL: National Clandestine Laboratory Register
A listing of clandestine drug lab locations that have been removed from the DEAs National Clandestine Laboratory Register.

Date of Government Version: 02/09/2017
Date Data Arrived at EDR: 03/08/2017
Date Made Active in Reports: 06/09/2017
Number of Days to Update: 93

Source: Drug Enforcement Administration
Telephone: 202-307-1000
Last EDR Contact: 02/28/2017
Next Scheduled EDR Contact: 06/12/2017
Data Release Frequency: No Update Planned

IHS OPEN DUMPS: Open Dumps on Indian Land
A listing of all open dumps located on Indian Land in the United States.

Date of Government Version: 04/01/2014
Date Data Arrived at EDR: 08/06/2014
Date Made Active in Reports: 01/29/2015
Number of Days to Update: 176

Source: Department of Health & Human Serivces, Indian Health Service
Telephone: 301-443-1452
Last EDR Contact: 05/05/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners Listing
The State Coalition for Remediation of Drycleaners was established in 1998, with support from the U.S. EPA Office of Superfund Remediation and Technology Innovation. It is comprised of representatives of states with established drycleaner remediation programs. Currently the member states are Alabama, Connecticut, Florida, Illinois, Kansas, Minnesota, Missouri, North Carolina, Oregon, South Carolina, Tennessee, Texas, and Wisconsin.

Date of Government Version: 01/01/2017
Date Data Arrived at EDR: 02/03/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 63

Source: Environmental Protection Agency
Telephone: 615-532-8599
Last EDR Contact: 05/19/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

FEMA UST: Underground Storage Tank Listing
A listing of all FEMA owned underground storage tanks.

Date of Government Version: 01/01/2010
Date Data Arrived at EDR: 02/16/2010
Date Made Active in Reports: 04/12/2010
Number of Days to Update: 55

Source: FEMA
Telephone: 202-646-5797
Last EDR Contact: 04/11/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Varies

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List
A listing of coal combustion residues surface impoundments with high hazard potential ratings.

Date of Government Version: 07/01/2014
Date Data Arrived at EDR: 09/10/2014
Date Made Active in Reports: 10/20/2014
Number of Days to Update: 40

Source: Environmental Protection Agency
Telephone: N/A
Last EDR Contact: 06/05/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Varies

FEDERAL FACILITY: Federal Facility Site Information listing
A listing of National Priority List (NPL) and Base Realignment and Closure (BRAC) sites found in the Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) Database where EPA Federal Facilities Restoration and Reuse Office is involved in cleanup activities.

Date of Government Version: 11/07/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 92

Source: Environmental Protection Agency
Telephone: 703-603-8704
Last EDR Contact: 04/07/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Varies

COAL ASH DOE: Steam-Electric Plant Operation Data
A listing of power plants that store ash in surface ponds.

Date of Government Version: 12/31/2005
Date Data Arrived at EDR: 08/07/2009
Date Made Active in Reports: 10/22/2009
Number of Days to Update: 76

Source: Department of Energy
Telephone: 202-586-8719
Last EDR Contact: 06/05/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Varies

US AIRS (AFS): Aerometric Information Retrieval System Facility Subsystem (AFS)
The database is a sub-system of Aerometric Information Retrieval System (AIRS). AFS contains compliance data on air pollution point sources regulated by the U.S. EPA and/or state and local air regulatory agencies. This information comes from source reports by various stationary sources of air pollution, such as electric power plants, steel mills, factories, and universities, and provides information about the air pollutants they produce. Action, air program, air program pollutant, and general level plant data. It is used to track emissions and compliance data from industrial plants.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/07/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Annually

US AIRS MINOR: Air Facility System Data
A listing of minor source facilities.

Date of Government Version: 10/12/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 02/03/2017
Number of Days to Update: 100

Source: EPA
Telephone: 202-564-2496
Last EDR Contact: 03/07/2017
Next Scheduled EDR Contact: 04/10/2017
Data Release Frequency: Annually

US FIN ASSUR: Financial Assurance Information
All owners and operators of facilities that treat, store, or dispose of hazardous waste are required to provide proof that they will have sufficient funds to pay for the clean up, closure, and post-closure care of their facilities.

Date of Government Version: 02/13/2017
Date Data Arrived at EDR: 02/15/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 86

Source: Environmental Protection Agency
Telephone: 202-566-1917
Last EDR Contact: 05/17/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Quarterly

EPA WATCH LIST: EPA WATCH LIST

EPA maintains a "Watch List" to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. Being on the Watch List does not mean that the facility has actually violated the law only that an investigation by EPA or a state or local environmental agency has led those organizations to allege that an unproven violation has in fact occurred. Being on the Watch List does not represent a higher level of concern regarding the alleged violations that were detected, but instead indicates cases requiring additional dialogue between EPA, state and local agencies - primarily because of the length of time the alleged violation has gone unaddressed or unresolved.

Date of Government Version: 08/30/2013
Date Data Arrived at EDR: 03/21/2014
Date Made Active in Reports: 06/17/2014
Number of Days to Update: 88

Source: Environmental Protection Agency
Telephone: 617-520-3000
Last EDR Contact: 05/08/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Quarterly

LEAD SMELTER 2: Lead Smelter Sites

A list of several hundred sites in the U.S. where secondary lead smelting was done from 1931and 1964. These sites may pose a threat to public health through ingestion or inhalation of contaminated soil or dust

Date of Government Version: 04/05/2001
Date Data Arrived at EDR: 10/27/2010
Date Made Active in Reports: 12/02/2010
Number of Days to Update: 36

Source: American Journal of Public Health
Telephone: 703-305-6451
Last EDR Contact: 12/02/2009
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

LEAD SMELTER 1: Lead Smelter Sites

A listing of former lead smelter site locations.

Date of Government Version: 12/05/2016
Date Data Arrived at EDR: 01/05/2017
Date Made Active in Reports: 02/10/2017
Number of Days to Update: 36

Source: Environmental Protection Agency
Telephone: 703-603-8787
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 07/17/2017
Data Release Frequency: Varies

2020 COR ACTION: 2020 Corrective Action Program List

The EPA has set ambitious goals for the RCRA Corrective Action program by creating the 2020 Corrective Action Universe. This RCRA cleanup baseline includes facilities expected to need corrective action. The 2020 universe contains a wide variety of sites. Some properties are heavily contaminated while others were contaminated but have since been cleaned up. Still others have not been fully investigated yet, and may require little or no remediation. Inclusion in the 2020 Universe does not necessarily imply failure on the part of a facility to meet its RCRA obligations.

Date of Government Version: 04/22/2013
Date Data Arrived at EDR: 03/03/2015
Date Made Active in Reports: 03/09/2015
Number of Days to Update: 6

Source: Environmental Protection Agency
Telephone: 703-308-4044
Last EDR Contact: 05/05/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Varies

DOCKET HWC: Hazardous Waste Compliance Docket Listing

A complete list of the Federal Agency Hazardous Waste Compliance Docket Facilities.

Date of Government Version: 06/02/2016
Date Data Arrived at EDR: 06/03/2016
Date Made Active in Reports: 09/02/2016
Number of Days to Update: 91

Source: Environmental Protection Agency
Telephone: 202-564-0527
Last EDR Contact: 05/24/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

ABANDONED MINES: Abandoned Mines

An inventory of land and water impacted by past mining (primarily coal mining) is maintained by OSMRE to provide information needed to implement the Surface Mining Control and Reclamation Act of 1977 (SMCRA). The inventory contains information on the location, type, and extent of AML impacts, as well as, information on the cost associated with the reclamation of those problems. The inventory is based upon field surveys by State, Tribal, and OSMRE program officials. It is dynamic to the extent that it is modified as new problems are identified and existing problems are reclaimed.

Date of Government Version: 03/14/2017
Date Data Arrived at EDR: 03/17/2017
Date Made Active in Reports: 04/07/2017
Number of Days to Update: 21

Source: Department of Interior
Telephone: 202-208-2609
Last EDR Contact: 06/09/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Quarterly

ECHO: Enforcement & Compliance History Information
ECHO provides integrated compliance and enforcement information for about 800,000 regulated facilities nationwide.

Date of Government Version: 03/19/2017
Date Data Arrived at EDR: 03/21/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 202-564-2280
Last EDR Contact: 06/07/2017
Next Scheduled EDR Contact: 09/18/2017
Data Release Frequency: Quarterly

FUSRAP: Formerly Utilized Sites Remedial Action Program
DOE established the Formerly Utilized Sites Remedial Action Program (FUSRAP) in 1974 to remediate sites where radioactive contamination remained from Manhattan Project and early U.S. Atomic Energy Commission (AEC) operations.

Date of Government Version: 12/23/2016
Date Data Arrived at EDR: 12/27/2016
Date Made Active in Reports: 02/17/2017
Number of Days to Update: 52

Source: Department of Energy
Telephone: 202-586-3559
Last EDR Contact: 05/05/2017
Next Scheduled EDR Contact: 08/21/2017
Data Release Frequency: Varies

PCB TRANSFORMER: PCB Transformer Registration Database
The database of PCB transformer registrations that includes all PCB registration submittals.

Date of Government Version: 02/01/2011
Date Data Arrived at EDR: 10/19/2011
Date Made Active in Reports: 01/10/2012
Number of Days to Update: 83

Source: Environmental Protection Agency
Telephone: 202-566-0517
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

FUELS PROGRAM: EPA Fuels Program Registered Listing
This listing includes facilities that are registered under the Part 80 (Code of Federal Regulations) EPA Fuels Programs. All companies now are required to submit new and updated registrations.

Date of Government Version: 02/22/2017
Date Data Arrived at EDR: 02/22/2017
Date Made Active in Reports: 05/12/2017
Number of Days to Update: 79

Source: EPA
Telephone: 800-385-6164
Last EDR Contact: 05/24/2017
Next Scheduled EDR Contact: 09/04/2017
Data Release Frequency: Quarterly

STATE AND LOCAL RECORDS

SHWS: Potential and Confirmed Sites List
Confirmed status denotes that assessments have been performed and a determination made that (1) hazardous waste(s) or substance(s) are present at the site and (2) these sites are under the jurisdiction of the LDEQ/RSD. Potential status is an indicator that sites are either waiting to be assessed or the assessment is in progress.

Date of Government Version: 10/18/2016
Date Data Arrived at EDR: 10/21/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 61

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

SWF/LF: Landfill List
Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/12/2016
Date Data Arrived at EDR: 12/13/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 8

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Annually

DEBRIS: LDEQ Approved Debris Sites

A listing of LDEQ Approved Debris Sites where hurricane debris is dumped.

Date of Government Version: 11/29/2016
Date Data Arrived at EDR: 12/01/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 20

Source: Department of Environmental Quality
Telephone: 225-219-3953
Last EDR Contact: 06/02/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Varies

AUL: Listing of Institutional and/or Enginnering Controls

A notice of contamination (nature and levels of contaminants) and restriction of property to non-residential use are placed in the conveyance records for the property.

Date of Government Version: 10/18/2010
Date Data Arrived at EDR: 11/04/2010
Date Made Active in Reports: 11/12/2010
Number of Days to Update: 8

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 01/09/2017
Next Scheduled EDR Contact: 04/24/2017
Data Release Frequency: Quarterly

HIST DEBRIS: LDEQ Approved Debris Sites

A listing of LDEQ Approved Debris Sites where hurricane debris is dumped.

Date of Government Version: 02/07/2007
Date Data Arrived at EDR: 11/14/2008
Date Made Active in Reports: 11/21/2008
Number of Days to Update: 7

Source: Department of Environmental Quality
Telephone: 225-219-3070
Last EDR Contact: 03/23/2009
Next Scheduled EDR Contact: 06/22/2009
Data Release Frequency: No Update Planned

UIC: Underground Injection Wells Listing

A listing of underground injection well locations.

Date of Government Version: 07/08/2016
Date Data Arrived at EDR: 07/12/2016
Date Made Active in Reports: 08/24/2016
Number of Days to Update: 43

Source: Department of fNatural Resources
Telephone: 225-342-5515
Last EDR Contact: 05/08/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Varies

SWRCY: Recycling Directory

A listing of recycling facilities.

Date of Government Version: 09/14/2010
Date Data Arrived at EDR: 09/21/2010
Date Made Active in Reports: 10/12/2010
Number of Days to Update: 21

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Semi-Annually

LUST: Leaking Underground Storage Tanks

Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 10/18/2016
Date Data Arrived at EDR: 10/21/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 61

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

HIST LUST: Underground Storage Tank Case History Incidents

This listing includes detailed information for Leaking Underground Storage Tanks reported through November 1999. It is no longer updated. Current LUST incidents, without detail, can be found in the Leaking Underground Storage Tank Database

Date of Government Version: 11/01/1999
Date Data Arrived at EDR: 02/16/2000
Date Made Active in Reports: 05/01/2000
Number of Days to Update: 75

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 12/04/2001
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

UST: Louisiana Underground Storage Tank Database

Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 10/18/2016
Date Data Arrived at EDR: 10/21/2016
Date Made Active in Reports: 01/09/2017
Number of Days to Update: 80

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

DEL SHWS: Deleted Potential & Confirmed Sites

A listing of sites removed from the Potential and Confirmed Listing.

Date of Government Version: 10/18/2016
Date Data Arrived at EDR: 10/21/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 61

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

LIENS: Environmental Liens

An Environmental Lien is a charge, security, or encumbrance upon title to a property to secure the payment of a cost, damage, debt, obligation, or duty arising out of response actions, cleanup, or other remediation of hazardous substances or petroleum products upon a property, including (but not limited to) liens imposed pursuant to CERCLA 42 USC ? 9607(1) and similar state or local laws. In other words: a lien placed upon a property's title due to an environmental condition.

Date of Government Version: 08/25/2015
Date Data Arrived at EDR: 10/20/2015
Date Made Active in Reports: 12/02/2015
Number of Days to Update: 43

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

SPILLS: Emergency Response Section Incidents

Spills and/or releases, to land, reported to the Emergency Response Section.

Date of Government Version: 08/24/2016
Date Data Arrived at EDR: 09/15/2016
Date Made Active in Reports: 10/19/2016
Number of Days to Update: 34

Source: Department of Environmental Quality
Telephone: 225-219-3620
Last EDR Contact: 05/15/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

VCP: Voluntary Remediation Program Sites

Sites that have entered the Department of Environmental Quality's Voluntary Remediation Program

Date of Government Version: 10/11/2016
Date Data Arrived at EDR: 10/18/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 64

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

DRYCLEANERS: Drycleaner Facility Listing
A listing of drycleaner facilities.

Date of Government Version: 10/07/2016
Date Data Arrived at EDR: 10/18/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 64

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Varies

BROWNFIELDS: Brownfields Inventory
Brownfields are abandoned, idled, or underused industrial or commercial real property, the expansion, redevelopment or reuse of which may be complicated by the presence of or potential presence of a hazardous substance, pollutant, or contaminant.

Date of Government Version: 10/18/2016
Date Data Arrived at EDR: 10/21/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 61

Source: Department of Environmental Quality
Telephone: 225-219-3167
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

CDL: Clandestine Drug Lab
A list of residential real properties that have been reported as potentially contaminated.

Date of Government Version: 09/16/2016
Date Data Arrived at EDR: 09/20/2016
Date Made Active in Reports: 10/19/2016
Number of Days to Update: 29

Source: Department of Environmental Quality
Telephone: 225-219-5337
Last EDR Contact: 05/26/2017
Next Scheduled EDR Contact: 09/11/2017
Data Release Frequency: Semi-Annually

NPDES: LPDES Permits Database
A listing of sites with a Louisiana Pollutant Discharge Elimination System (LPDES) program issued permit.

Date of Government Version: 10/24/2016
Date Data Arrived at EDR: 10/26/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 56

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 04/24/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

AIRS: Air Permit List
A listing of facilities with air permits issued by the Air Permits Division

Date of Government Version: 11/17/2016
Date Data Arrived at EDR: 12/09/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 12

Source: Department of Environmental Quality
Telephone: 225-219-3417
Last EDR Contact: 05/15/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: Varies

REM: Division of Remediation Services Database
Facilities or sites come to the Underground Storage Tank and Remediation Divison either through self notification or referral. These sites are designated for remediation via the following regulatory paths: Solid Waste (SW), Hazardous Waste (Haz Waste), Groundwater (Grwater), Inactive & Abandoned Sites (Confirmed or Potential), or Underground Storage Tanks (UST).

Date of Government Version: 10/18/2016
Date Data Arrived at EDR: 10/21/2016
Date Made Active in Reports: 12/21/2016
Number of Days to Update: 61

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 04/17/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Quarterly

ASBESTOS: Asbestos Projects List
Asbestos demolition and renovation notification projects locations in the state.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 04/20/2016
Date Made Active in Reports: 07/01/2016
Number of Days to Update: 72

Source: Department of Environmental Quality
Telephone: 225-219-3181
Last EDR Contact: 04/21/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Annually

COAL ASH: Coal Ash Disposal Sites
A listing of coal ash impoundments.

Date of Government Version: 07/13/2015
Date Data Arrived at EDR: 08/04/2015
Date Made Active in Reports: 08/24/2015
Number of Days to Update: 20

Source: Department of Environmental Quality
Telephone: 225-219-3168
Last EDR Contact: 04/10/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Varies

TRIBAL RECORDS

INDIAN RESERV: Indian Reservations
This map layer portrays Indian administered lands of the United States that have any area equal to or greater than 640 acres.

Date of Government Version: 12/31/2014
Date Data Arrived at EDR: 07/14/2015
Date Made Active in Reports: 01/10/2017
Number of Days to Update: 546

Source: USGS
Telephone: 202-208-3710
Last EDR Contact: 04/14/2017
Next Scheduled EDR Contact: 07/24/2017
Data Release Frequency: Semi-Annually

INDIAN ODI: Report on the Status of Open Dumps on Indian Lands
Location of open dumps on Indian land.

Date of Government Version: 12/31/1998
Date Data Arrived at EDR: 12/03/2007
Date Made Active in Reports: 01/24/2008
Number of Days to Update: 52

Source: Environmental Protection Agency
Telephone: 703-308-8245
Last EDR Contact: 05/01/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Varies

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Alaska, Idaho, Oregon and Washington.

Date of Government Version: 10/07/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Arizona, California, New Mexico and Nevada

Date of Government Version: 10/06/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: Environmental Protection Agency
Telephone: 415-972-3372
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Colorado, Montana, North Dakota, South Dakota, Utah and Wyoming.

Date of Government Version: 10/17/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 8
Telephone: 303-312-6271
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Iowa, Kansas, and Nebraska

Date of Government Version: 09/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in Florida, Mississippi and North Carolina.

Date of Government Version: 10/14/2016
Date Data Arrived at EDR: 01/27/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 98

Source: EPA Region 4
Telephone: 404-562-8677
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Semi-Annually

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land
A listing of leaking underground storage tank locations on Indian Land.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land
Leaking underground storage tanks located on Indian Land in Michigan, Minnesota and Wisconsin.

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA, Region 5
Telephone: 312-886-7439
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land
LUSTs on Indian land in New Mexico and Oklahoma.

Date of Government Version: 10/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 6
Telephone: 214-665-6597
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R7: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 7 (Iowa, Kansas, Missouri, Nebraska, and 9 Tribal Nations).

Date of Government Version: 09/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 7
Telephone: 913-551-7003
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R1: Underground Storage Tanks on Indian Land
The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 1 (Connecticut, Maine, Massachusetts, New Hampshire, Rhode Island, Vermont and ten Tribal Nations).

Date of Government Version: 11/14/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA, Region 1
Telephone: 617-918-1313
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R8: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 8 (Colorado, Montana, North Dakota, South Dakota, Utah, Wyoming and 27 Tribal Nations).

Date of Government Version: 10/17/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 8
Telephone: 303-312-6137
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN UST R4: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 4 (Alabama, Florida, Georgia, Kentucky, Mississippi, North Carolina, South Carolina, Tennessee and Tribal Nations)

Date of Government Version: 10/14/2016
Date Data Arrived at EDR: 01/27/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 98

Source: EPA Region 4
Telephone: 404-562-9424
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Semi-Annually

INDIAN UST R5: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 5 (Michigan, Minnesota and Wisconsin and Tribal Nations).

Date of Government Version: 01/14/2017
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 5
Telephone: 312-886-6136
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Varies

INDIAN UST R10: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 10 (Alaska, Idaho, Oregon, Washington, and Tribal Nations).

Date of Government Version: 10/07/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 10
Telephone: 206-553-2857
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN UST R9: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 9 (Arizona, California, Hawaii, Nevada, the Pacific Islands, and Tribal Nations).

Date of Government Version: 10/06/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 9
Telephone: 415-972-3368
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Quarterly

INDIAN UST R6: Underground Storage Tanks on Indian Land

The Indian Underground Storage Tank (UST) database provides information about underground storage tanks on Indian land in EPA Region 6 (Louisiana, Arkansas, Oklahoma, New Mexico, Texas and 65 Tribes).

Date of Government Version: 10/01/2016
Date Data Arrived at EDR: 01/26/2017
Date Made Active in Reports: 05/05/2017
Number of Days to Update: 99

Source: EPA Region 6
Telephone: 214-665-7591
Last EDR Contact: 04/28/2017
Next Scheduled EDR Contact: 08/07/2017
Data Release Frequency: Semi-Annually

INDIAN VCP R7: Voluntary Cleanup Priority Lisitng

A listing of voluntary cleanup priority sites located on Indian Land located in Region 7.

Date of Government Version: 03/20/2008
Date Data Arrived at EDR: 04/22/2008
Date Made Active in Reports: 05/19/2008
Number of Days to Update: 27

Source: EPA, Region 7
Telephone: 913-551-7365
Last EDR Contact: 04/20/2009
Next Scheduled EDR Contact: 07/20/2009
Data Release Frequency: Varies

INDIAN VCP R1: Voluntary Cleanup Priority Listing

A listing of voluntary cleanup priority sites located on Indian Land located in Region 1.

Date of Government Version: 07/27/2015
Date Data Arrived at EDR: 09/29/2015
Date Made Active in Reports: 02/18/2016
Number of Days to Update: 142

Source: EPA, Region 1
Telephone: 617-918-1102
Last EDR Contact: 03/27/2017
Next Scheduled EDR Contact: 07/10/2017
Data Release Frequency: Varies

EDR PROPRIETARY RECORDS

EDR MGP: EDR Proprietary Manufactured Gas Plants

The EDR Proprietary Manufactured Gas Plant Database includes records of coal gas plants (manufactured gas plants) compiled by EDR's researchers. Manufactured gas sites were used in the United States from the 1800's to 1950's to produce a gas that could be distributed and used as fuel. These plants used whale oil, rosin, coal, or a mixture of coal, oil, and water that also produced a significant amount of waste. Many of the byproducts of the gas production, such as coal tar (oily waste containing volatile and non-volatile chemicals), sludges, oils and other compounds are potentially hazardous to human health and the environment. The byproduct from this process was frequently disposed of directly at the plant site and can remain or spread slowly, serving as a continuous source of soil and groundwater contamination.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: No Update Planned

EDR Hist Auto: EDR Exclusive Historic Gas Stations

EDR has searched selected national collections of business directories and has collected listings of potential gas station/filling station/service station sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include gas station/filling station/service station establishments. The categories reviewed included, but were not limited to gas, gas station, gasoline station, filling station, auto, automobile repair, auto service station, service station, etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

EDR Hist Cleaner: EDR Exclusive Historic Dry Cleaners

EDR has searched selected national collections of business directories and has collected listings of potential dry cleaner sites that were available to EDR researchers. EDR's review was limited to those categories of sources that might, in EDR's opinion, include dry cleaning establishments. The categories reviewed included, but were not limited to dry cleaners, cleaners, laundry, laundromat, cleaning/laundry, wash & dry etc. This database falls within a category of information EDR classifies as "High Risk Historical Records", or HRHR. EDR's HRHR effort presents unique and sometimes proprietary data about past sites and operations that typically create environmental concerns, but may not show up in current government records searches.

Date of Government Version: N/A
Date Data Arrived at EDR: N/A
Date Made Active in Reports: N/A
Number of Days to Update: N/A

Source: EDR, Inc.
Telephone: N/A
Last EDR Contact: N/A
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA HWS: Recovered Government Archive State Hazardous Waste Facilities List
The EDR Recovered Government Archive State Hazardous Waste database provides a list of SHWS incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LUST: Recovered Government Archive Leaking Underground Storage Tank
The EDR Recovered Government Archive Leaking Underground Storage Tank database provides a list of LUST incidents derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/03/2014
Number of Days to Update: 186

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

RGA LF: Recovered Government Archive Solid Waste Facilities List
The EDR Recovered Government Archive Landfill database provides a list of landfills derived from historical databases and includes many records that no longer appear in current government lists. Compiled from Records formerly available from the Department of Environmental Quality in Louisiana.

Date of Government Version: N/A
Date Data Arrived at EDR: 07/01/2013
Date Made Active in Reports: 01/15/2014
Number of Days to Update: 198

Source: Department of Environmental Quality
Telephone: N/A
Last EDR Contact: 06/01/2012
Next Scheduled EDR Contact: N/A
Data Release Frequency: Varies

OTHER DATABASE(S)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

CT MANIFEST: Hazardous Waste Manifest Data
Facility and manifest data. Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a tsd facility.

Date of Government Version: 07/30/2013
Date Data Arrived at EDR: 08/19/2013
Date Made Active in Reports: 10/03/2013
Number of Days to Update: 45

Source: Department of Energy & Environmental Protection
Telephone: 860-424-3375
Last EDR Contact: 05/15/2017
Next Scheduled EDR Contact: 08/28/2017
Data Release Frequency: No Update Planned

NY MANIFEST: Facility and Manifest Data
Manifest is a document that lists and tracks hazardous waste from the generator through transporters to a TSD facility.

Date of Government Version: 01/30/2017
Date Data Arrived at EDR: 02/01/2017
Date Made Active in Reports: 02/13/2017
Number of Days to Update: 12

Source: Department of Environmental Conservation
Telephone: 518-402-8651
Last EDR Contact: 05/03/2017
Next Scheduled EDR Contact: 08/14/2017
Data Release Frequency: Annually

PA MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 07/22/2016
Date Made Active in Reports: 11/22/2016
Number of Days to Update: 123

Source: Department of Environmental Protection
Telephone: 717-783-8990
Last EDR Contact: 04/18/2017
Next Scheduled EDR Contact: 07/31/2017
Data Release Frequency: Annually

WI MANIFEST: Manifest Information
Hazardous waste manifest information.

Date of Government Version: 12/31/2015
Date Data Arrived at EDR: 04/14/2016
Date Made Active in Reports: 06/03/2016
Number of Days to Update: 50

Source: Department of Natural Resources
Telephone: N/A
Last EDR Contact: 06/12/2017
Next Scheduled EDR Contact: 09/25/2017
Data Release Frequency: Annually

Oil/Gas Pipelines
Source: PennWell Corporation
Petroleum Bundle (Crude Oil, Refined Products, Petrochemicals, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)) N = Natural Gas Bundle (Natural Gas, Gas Liquids (LPG/NGL), and Specialty Gases (Miscellaneous)). This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Electric Power Transmission Line Data
Source: PennWell Corporation
This map includes information copyrighted by PennWell Corporation. This information is provided on a best effort basis and PennWell Corporation does not guarantee its accuracy nor warrant its fitness for any particular purpose. Such information has been reprinted with the permission of PennWell.

Sensitive Receptors: There are individuals deemed sensitive receptors due to their fragile immune systems and special sensitivity to environmental discharges. These sensitive receptors typically include the elderly, the sick, and children. While the location of all sensitive receptors cannot be determined, EDR indicates those buildings and facilities - schools, daycares, hospitals, medical centers, and nursing homes - where individuals who are sensitive receptors are likely to be located.

AHA Hospitals:
Source: American Hospital Association, Inc.
Telephone: 312-280-5991
The database includes a listing of hospitals based on the American Hospital Association's annual survey of hospitals.

Medical Centers: Provider of Services Listing
Source: Centers for Medicare & Medicaid Services
Telephone: 410-786-3000
A listing of hospitals with Medicare provider number, produced by Centers of Medicare & Medicaid Services, a federal agency within the U.S. Department of Health and Human Services.

Nursing Homes
Source: National Institutes of Health
Telephone: 301-594-6248
Information on Medicare and Medicaid certified nursing homes in the United States.

Public Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on elementary and secondary public education in the United States. It is a comprehensive, annual, national statistical database of all public elementary and secondary schools and school districts, which contains data that are comparable across all states.

Private Schools
Source: National Center for Education Statistics
Telephone: 202-502-7300
The National Center for Education Statistics' primary database on private school locations in the United States.

Flood Zone Data: This data was obtained from the Federal Emergency Management Agency (FEMA). It depicts 100-year and 500-year flood zones as defined by FEMA. It includes the National Flood Hazard Layer (NFHL) which incorporates Flood Insurance Rate Map (FIRM) data and Q3 data from FEMA in areas not covered by NFHL.
Source: FEMA
Telephone: 877-336-2627
Date of Government Version: 2003, 2015

NWI: National Wetlands Inventory. This data, available in select counties across the country, was obtained by EDR in 2002, 2005 and 2010 from the U.S. Fish and Wildlife Service.

Earthquake Fault Lines: The fault lines displayed on EDR's Topographic map are digitized quaternary faultlines, prepared in 1975 by the United State Geological Survey

STREET AND ADDRESS INFORMATION

© 2015 TomTom North America, Inc. All rights reserved. This material is proprietary and the subject of copyright protection and other intellectual property rights owned by or licensed to Tele Atlas North America, Inc. The use of this material is subject to the terms of a license agreement. You will be held liable for any unauthorized copying or disclosure of this material.